



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Buss.Reg.No.: 5288887X

Attn: Adrian

QUOTATION

No : QT-000133

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD
 #18-01 SUNTEC TOWER FOUR
 SINGAPORE 038986

Your Ref. : SJT6204R
 Vehicle No. : SLV6532J
 Make & Model : TOYOTA WISH
 Chassis No. : JTDGG20W50J008583
 Engine No. : 2ZR0A44685
 Accident Date : 07-05-2018
 Policy No. : P2054583
 Date : 12-05-2018
 Page : 1 of 2

TEL : 68208888

FAX :

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	REAR BUMPER <i>Deformed</i>	1.0	PCS 632.00	✓ 632.00
2	REAR BUMPER REFLECTOR (R/H) <i>new</i>	1.0	PCS 63.00	+ 63.00
3	REAR BUMPER SIDE RETAINER (SHORT) <i>new</i>	2.0	PCS 54.00	✓ 108.00
4	BUMPER SIDE RETAINER (L/H/R) (LONG) <i>new</i>	1.0	PCS 96.00	+ 96.00
5	BUMPER SIDE RETAINER (R/H/R) (LONG) <i>new</i>	1.0	PCS 96.00	+ 96.00
6	BUMPER BRACKET <i>new</i>	2.0	PCS 135.00	X 270.00
7	BUMPER CLIP <i>new</i>	4.0	PCS 6.00	✓ 24.00
8	REAR END PANEL <i>Deformed</i>	1.0	PCS 572.00	✓ 572.00
9	REAR END PANEL GARNISH <i>Deformed</i>	1.0	PCS 295.00	✓ 295.00
10	REAR BOOT WEATHERSTRIP <i>new</i>	1.0	PCS 356.00	X 356.00
11	REAR BOOT INNER LOCK <i>new</i>	1.0	PCS 431.00	X 431.00
12	REVERSE SENSOR <i>Damaged</i>	2.0	PCS 198.00	<i>200 (SW)</i> 396.00
13	SENSOR (REAR BOOT) <i>Damaged</i>	1.0	PCS 140.00	✓ 140.00
14	Discount 25 %			-869.75
15	SubTotal (L)			2,609.25
16	REAR END PANEL SEALANT <i>new</i>	1.0	BTL 50 50.00	✓ 50.00
17	SubTotal (S)			50.00
18	PANEL BEAT & REPAIR REAR DAMAGE	1.0	X	<i>500</i> 900.00
19	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X	<i>600</i> 800.00
20	TO PROVIDE UNDER TURFCODE	1.0	X	<i>40</i> 120.00
21	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0	X	<i>60</i> 150.00
22	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	X	<i>30</i> 50.00
23	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0	X	X 150.00
24	TO REMOVE AND REPLACE DAMAGED EXHAUST SYSTEM	1.0	X	X 120.00
25	SubTotal (LABOUR)			2,290.00

total: 2808.25

h/s: 22K

04 Days



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Buss.Reg.No.: 52888887X

Attn: Adrian

QUOTATION

No : QT-000133

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER FOUR

SINGAPORE 038986

TEL : 68208888

FAX :

Your Ref. : SJT6204R
Vehicle No. : SLV6532J
Make & Model : TOYOTA WISH
Chassis No. : JTDGG20W50J008583
Engine No. : 2ZR0A44685
Accident Date : 07-05-2018
Policy No. : P2054583
Date : 12-05-2018
Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE DOLLAR FOUR THOUSAND NINE HUNDRED FORTY NINE AND CENTS TWENTY FIVE ONLY

E. & O.E

Total	S\$	4,949.25
Discount	S\$	0.00
Net Total	S\$	4,949.25

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.