

INS. CASE OWNER:

CC 4/1111800

LKK:

IDAC:

Surveyor:

Sebastian

DOI:

ASSIGNMENT

11/5/18

Date / Time:

11/5/18

Registered in Merimen:

11/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 4274A

Name of Insured:

UPR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

11/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Lynn An Bony

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

ML1804195

Policy No.:

ML000015

Make / Model:

TOYOTA

Place of Accident:

Main from Admiralty RD  
West to Woodlands Ave 8

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final? Yes / No

FBL 3758R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sin Boon



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

27/5/18

Amhar

20.5.18

01.06.18

8/8/19

12/8/19

PBL 3758R - 4

SHA 4274A - 4

Issue from Data 308 Liability.

Mandate Liability Clear.

Email WSP Liability Clear.

No P.S. TP pass lawyer

File -&gt; Shuperto close (cup).

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

5

Repair Cost:

SS

DID TUBA PH &amp; CORNER, WINDY

Loss of Rental (LOR):

SS

( days)

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

\$250.00

COPY SENT

11/8/19

164

REF: To WP

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Web No: BL 3755KYr Regn: 20/9/2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Sniper T150 C.C. 150Colour: Red A/C: Insured / Std / NI / NASp. Reading: 1762 T/Radio: Insured / Std / NI / NA

Engi/No: \_\_\_\_\_

C/No: M14349074090030892

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NA / S/Rim / STD A/Rim orTyre Size: F: 90/80-11 inch budget  
R: 120/90-2R17 of Continental

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 1 mm L/Bal. 6 mmD.O.A. 18/4/18 D.O.I. 11/5/18Survey held at Sin BoonDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$ 3069.60 (Red \$ 70 / 0.1 %).

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee

Transportation

1. S - R - S

2. Photos

3. Others

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC4/III18008645/Seb3

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 11-05-2018



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4274A	Veh. Inspected	FBL 3758R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	28/04/2018	Inspection Date	11/05/2018
Survey held at	SIN BOON MOTOR CO 10, ADMIRALTY STREET #01-10/11 NORTHLINK BUILDING SINGAPORE 757695		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**SIN BOON MOTOR CO**  
 10, ADMIRALTY STREET,  
 #01-10, NORTHLINK BUILDING,  
 SINGAPORE 757695.  
 TEL: 62578404, FAX 67556214

Sebastian  
 11/5/18  
 - Part by part repair  
 - Question Mark Item  
 Photo  
 Photo Before Paint  
 90036121  
 Sebastian Yang @  
 11/5/18

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 approved for final approval from Insurance Company  
 7-May-2018

**FBL3758R- ESTIMATED REPAIR BILL**  
**MODEL: YAMAHA SNIPER T150**  
**YEAR OF MANUFACTURE: 2016**

1	1 pc	Handlebar	✓ BT			
2	1 pc	Headlamp	✓ SCR			
3	2 pcs	Top & Lower Light Casing	✓ CRK	@	\$48.00	\$96.00
4	1 pc	Front Cover	✓ SCR / cut			\$55.00
5	1 pc	P/O Light Assy	✓ CRK			\$128.00
6	1 pc	P/O Light Casing	✓ TN			\$58.00
7	1 pc	Front Fender	✓ cut			\$55.00
8	1 pc	RH Front Signal	✓ MS			\$48.00
9	1 pc	Centre Frame Panel	✓ CRK			\$65.00
10	1 pc	Rear Frame Panel	✓ CRK			\$68.00
11	1 pc	Inner Cowling	✓ TN			\$48.00
12	1 pc	Radiator	✓ BT			\$285.00
13	1 pc	Fork Underbracket	✓ BT			\$145.00
14	2 pcs	LH & RH Fork Tube	✓ BT	@	\$110.00	\$220.00
15	1 pc	RH Leg Shield	✓ MS			\$85.00
16	1 pc	Muffler Assy	✓ cut			\$245.00
17	1 pc	Muffler Protector	✓ cut			\$55.00
18	1 pc	RH Side Cover	✓ cut			\$115.00
18	1 pc	wind screen	✓ CRK			\$1,956.00
				Less 10%		\$195.60
						\$1,760.40

19	1 pc	Front Number Plate	✓ CRK	[Nett]		\$14.00
20	1 pc	RH Brake Lever	✓ cut			\$90.00
21	1 pc	RH Lever Guard	✓ MS			\$80.00
22	1 pc	RH Mirror	✓ MS			\$90.00
23	1 bot	Coolant	✓ NEC			\$30.00
24	1 pc	Carrier	✓ BT			\$65.00
25	1 pc	Cargo Box	✓ MS			\$180.00
26	1 pc	Footrest Bracket w/Footrest Comp	✓ MS			\$190.00
27	1 pc	Centre Basket	✓ CRK			\$35.00
28	1 pc	Lower Spoiler	✓ CRK			\$90.00
29	1 set	Emblem	✓ NEC			\$80.00
30	3 trips	Towing Charge	✓			\$90.00
31		Labour Charges			250	\$280.00

Sub Total \$3,074.40  
 GST \$215.21  
**Total \$3,289.61**

3049.60



3141.987

## Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	FBL3758R
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	YAMAHA
Vehicle Model:	SNIPER T150
Chassis No.:	MH3UG0740G0030842
Propellant:	Petrol
Engine No.:	G3E6E0222640
Engine Capacity:	150 cc
Maximum Power Output:	-
Maximum Laden Weight:	266 kg
Unladen Weight:	116 kg
Year Of Manufacture:	2016
Original Registration Date:	20 Sep 2016
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
Quota Premium:	\$6,452.00
COE Expiry Date:	19 Sep 2026
Road Tax Expiry Date:	19 Sep 2018
Inspection Due Date:	19 Sep 2019
Intended Transfer Date:	07 May 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	

Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

SIN BOON MOTOR CO  
10, ADMIRALTY STREET,  
#01-10, NORTHLINK BUILDING,  
SINGAPORE 757695.  
TEL: 62578404, FAX 67556214

Sebastian  
11/5/18  
- Part by part repair.  
- Question Mark Item  
Photo  
Before Paint  
90036121

Sebastianyeang @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FBL3758R- ESTIMATED REPAIR BILL  
MODEL: YAMAHA SNIPER T150  
YEAR OF MANUFACTURE: 2016

Acknowledged by Repairer

Signature:

Date:

\$95.00

1	1 pc	Handlebar ✓ BT			
2	1 pc	Headlamp ✓ SCR			\$90.00
3	2 pcs	Top & Lower Light Casing ✓ CRK	@	\$48.00	\$96.00
4	1 pc	Front Cover ✓ SCR / cut			\$55.00
5	1 pc	P/O Light Assy ✓ CRK			\$128.00
6	1 pc	P/O Light Casing ✓ TN			\$58.00
7	1 pc	Front Fender ✓ cut			\$55.00
8	1 pc	RH Front Signal ✓ MS			\$48.00
9	1 pc	Centre Frame Panel ✓ CRK			\$65.00
10	1 pc	Rear Frame Panel ✓ CRK			\$68.00
11	1 pc	Inner Cowling ✓ TN			\$48.00
12	1 pc	Radiator ✓ BT			\$285.00
13	1 pc	Fork Underbracket ? ✓ BT ✓			\$145.00
14	2 pcs	LH & RH Fork Tube ? ✓ BT ✓	@	\$110.00	\$220.00
15	1 pc	RH Leg Shield ✓ MS			\$85.00
16	1 pc	Muffler Assy ✓ cut			\$245.00
17	1 pc	Muffler Protector ✓ cut			\$55.00
18	1 pc	RH Side Cover ✓ cut			\$115.00
18	1 pc	wind screen \$28/- CRK.			\$1,956.00
				Less 10%	\$195.60
					\$1,760.40

19	1 pc	Front Number Plate ✓ CRK	[Nett]	\$14.00
20	1 pc	RH Brake Lever ✓ cut		\$90.00
21	1 pc	RH Lever Guard ✓ MS		\$80.00
22	1 pc	RH Mirror ✓ MS		\$90.00
23	1 bot	Coolant ✓ NEC		\$30.00
24	1 pc	Carrier ✓ BT		\$65.00
25	1 pc	Cargo Box ✓ MS		\$180.00
26	1 pc	Footrest Bracket w/Footrest Comp ✓ MS		\$190.00
27	1 pc	Centre Basket ✓ CRK		\$35.00
28	1 pc	Lower Spoiler ✓ CRK		\$90.00
29	1 set	Emblem ✓ NEC		\$80.00
30	3 Trips	Towing Charge ✓		\$90.00
31		Labour Charges	250	\$250.00
				<del>\$280.00</del>
			Sub Total	\$3,074.40
			GST	\$215.21
			Total	\$3,289.61



**Catherine Chong (LKK Auto)**

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Friday, 11 May, 2018 9:30 AM  
**To:** sbmotor@singnet.com.sg; 'sur@lkkauto.com'; Nivitha (LKK Auto)  
**Cc:** Natalie Lee  
**Subject:** RE: Accident Claim for Vehicle No: FBL3758R  
**Attachments:** img-507114853.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle FBL3758R and let us have your report urgently.

This claim will be handled by Ms Natalie.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*  
**Gabriel Wee**  
Motor Claims Dept.  
**India International Insurance Pte Ltd**  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

11.05.2018 @ 9:55am  
Jenny veh in  
Sebastian

---

**From:** sbmotor@singnet.com.sg [mailto:sbmotor@singnet.com.sg]  
**Sent:** 11 May, 2018 8:32 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** RE: Accident Claim for Vehicle No: FBL3758R

Mr. Gabriel Wee,

We wish to appoint LKK Auto consultants to conduct the survey

Thanks

Have a nice day

Jenny

Tel: 62578404

---

**From:** Motor Claim - III [mailto:motorclaim@iii.com.sg]  
**Sent:** Thursday, May 10, 2018 8:58 AM  
**To:** sbmotor@singnet.com.sg  
**Subject:** RE: Accident Claim for Vehicle No: FBL3758R

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

---

**From:** [sbmotor@singnet.com.sg](mailto:sbmotor@singnet.com.sg) [<mailto:sbmotor@singnet.com.sg>]

**Sent:** 07 May, 2018 11:54 AM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Subject:** Accident Claim for Vehicle No: FBL3758R

To Whom It May Concern,

Vehicle No: FBL3758R

DOA: 27-04-2018

Kindly send your surveyor to survey the above mentioned motorcycle at your earliest convenience.

Any queries please contact us.

Best Regards

Jenny

Tel: 62578404

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling



and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## Print Received Message

This mail is associated with :

**\*FBL3758R (MCT18040795)**  
**[SHA4274A]**

TP

OH KENG MENG

Apr 28 2018 9:00AM

[COMFORT TRANSPORTATION PTE LTD]

Sin Boon Motor Co

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 28/05/2018 17:04 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$0.00) - FBL3758R - Claim Handler: NATALIE LEE

Approved:0.00.

## Print Sent Message

This mail is associated with :

**\*FBL3758R (MCT18040795)**

**[SHA4274A]**

TP

OH KENG MENG

Apr 28 2018 9:00AM

[COMFORT TRANSPORTATION PTE LTD]

Sin Boon Motor Co

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 09/08/2019 08:23 AM.  
**To** motorclaim@iii.com.sg  
**CC** III\_SG; chewht@lkkauto.com; admin-a@lkkauto.com  
**Subject** <Submit wp Report> MCT18040795

Dear Sirs/Mdm,

We refer to the above matter.

We were informed by third party repairer that thier client had passed the case to lawyer for further handling. No DS.

In view of this, we will proceed to close file and submit survey report to your good office soon.

Thank you.

Hsiao Tong

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 May 2018 <a href="#">Edit Reg</a>		11 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$53,069.60</b> <a href="#">Edit Estimates</a>	<b>\$53,069.60</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: -								
Main Claimant:	<b>OH KENG MENG</b> , ID: S69805011								
Vehicle Reg. No.:	<b>FBL3758R</b>	Date of Loss:	28/04/2018 09:00 - :59 [19 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT18040795</b>	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	<b>SHA4274A</b>	Policy No. (Claimant):	MSD/VMS/17-371891-CA						
		Excess:							
Repairer:	<b>Sin Boon Motor Co (HQ)</b> 10 Admiralty Street, #01-10/11, Northlink Building, 757695 Woodlands - Tel: 62578404								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>NATALIE LEE</b> - 63476100 ext 243]								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Sebastian Yeang Wai Keen</b> ] ... [Final Rpt due 22/05/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• III_SG (28/05/2018): Alert - Adj Mandate Approved (\$0.00) - FBL3758R - Claim Handler: NATALIE LEE									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBL3758R (MCT18040795)  
[SHA4274A]  
TP  
OH KENG MENG  
Apr 28 2018 9:00AM  
[COMFORT TRANSPORTATION PTE LTD]  
Sin Boon Motor Co

Upload Documents

Upload Photos






































Compose New Letter

















































View








































View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
2	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
3	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
4	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
5	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
6	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
7	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
8	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
9	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
10	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
11	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
12	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
13	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
14	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
15	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
16	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
17	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
18	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
19	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
20	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
21	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
22	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
23	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
24	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
25	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
26	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
27	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
28	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
29	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
30	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
31	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
32	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
33	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
34	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
35	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
36	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>
37	08/06/18 09:41	General View		 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
52	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
53	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
54	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
55	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
56	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
57	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
58	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
59	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
60	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
61	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
62	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
63	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
64	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
65	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
66	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
67	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
68	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
69	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
70	08/06/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
71	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	08/06/18 09:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
106	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
107	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
108	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
109	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
110	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
111	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
112	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
113	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
114	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
115	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
116	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
117	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
118	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
119	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
120	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
121	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
122	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
123	08/06/18 09:41	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/05/18 12:44	EMAIL FROM III DD 11052018	 Load PDF	
2	11/05/18 12:44	TP EST & GIA REPORT	 Load PDF	
3	22/05/18 08:40	TP ESTIMATE- MARKED	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	14/05/18 08:43	Singapore Accident Statement	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18008645/SPB3Q2

Date: 19/08/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: FBL3758R Insured Vehicle No: SHA4274A  
 Date of Loss: 28/04/2018 Nature of Claim: TP Claim No: MCT18040795

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBL3758R  
 Make & Model: YAMAHA Y152R, 150cc Engine No: G3E6E0222640  
 Reg. Date: 20/09/2016 (Man. Year: 2016) Chassis No: MH3UG0740G0030842  
 Colour: Red Odometer: 19622 km  
 Engine Capacity: 150 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 90/80-17 Rear Tyre Size: 120/70Z R17  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Continental 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,729.60	2,729.60	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	370.00	340.00	30.00	8.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,099.60</b>	<b>3,069.60</b>	<b>30.00</b>	<b>0.97</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>216.97</b>	<b>214.87</b>	<b>2.10</b>	<b>0.97</b>
<b>Nett Amount (S\$)</b>	<b>3,316.57</b>	<b>3,284.47</b>	<b>32.10</b>	<b>0.97</b>

## INSPECTION

Date of Assignment: 11/05/2018  
 Date Inspected: 11/05/2018 Inspected At: Sin Boon Motor Co (HQ)  
 10 Admiralty Street, #01-10/11, Northlink Building  
 Singapore 757695  
 Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 19 Aug 2019)	
<b>Parts:</b>	N/A	YAMAHA Y152R 150cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL3758R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLEBAR	Bent	95.00 FL	*95.00 FL
2	1		*HEADLAMP	Scratched	90.00 FL	*90.00 FL
3	2		*TOP & LOWER LIGHT CASING	Cracked	96.00 FL	*96.00 FL
4	1		*FRONT COVER	Scratched / Cut	55.00 FL	*55.00 FL
5	1		*P/O LIGHT ASSY	Cracked	128.00 FL	*128.00 FL
6	1		*P/O LIGHT CASING	Torn	58.00 FL	*58.00 FL
7	1		*FRONT FENDER	Cut	55.00 FL	*55.00 FL
8	1		*RH FRONT SIGNAL	Missing	48.00 FL	*48.00 FL
9	1		*CENTRE FRAME PANEL	Cracked	65.00 FL	*65.00 FL
10	1		*REAR FRAME PANEL	Cracked	68.00 FL	*68.00 FL
11	1		*INNER COWLING	Torn	48.00 FL	*48.00 FL
12	1		*RADIATOR	Bent	285.00 FL	*285.00 FL
13	1		*FORK UNDERBRACKET	Bent	145.00 FL	*145.00 FL
14	2		*LH & RH FORK TUBE	Bent	220.00 FL	*220.00 FL
15	1		*RH LEG SHIELD	Missing	85.00 FL	*85.00 FL
16	1		*MUFFLER ASSY	Cut	245.00 FL	*245.00 FL
17	1		*MUFFLER PROTECTOR	Cut	55.00 FL	*55.00 FL
18	1		*RH SIDE COVER	Cut	115.00 FL	*115.00 FL
19	1		*WINDSCREEN	Cracked	28.00 FL	*28.00 FL
20	1		*FRONT NUMBER PLATE	Cracked	14.00 FS	*14.00 FS
21	1		*RH BRAKE LEVER	Cut	90.00 FS	*90.00 FS
22	1		*RH LEVER GUARD	Missing	80.00 FS	*80.00 FS
23	1		*RH MIRROR	Missing	90.00 FS	*90.00 FS
24	1		*BOT COOLANT	Necessary	30.00 FS	*30.00 FS
25	1		*CARRIER	Bent	65.00 FS	*65.00 FS
26	1		*CARGO BOX	Missing	180.00 FS	*180.00 FS
27	1		*FOOTREST BRACKET W/FOOTREST COMP	Missing	190.00 FS	*190.00 FS
28	1		*CENTRE BRACKET	Cracked	35.00 FS	*35.00 FS
29	1		*LOWER SPOILER	Cracked	90.00 FS	*90.00 FS
30	1		*SET EMBLEM	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,928.00</b>	<b>2,928.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>198.40</b>	<b>198.40</b>
<b>Total Parts (\$\$)</b>	<b>2,729.60</b>	<b>2,729.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGE	New	90.00	90.00
2	LABOUR CHARGES	New	280.00	250.00
Gross Labour Cost (S\$)			370.00	340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >