

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8896T

DATE 10/5/2018 15:43

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>x repair</i>			\$ 1,681.40
	Boot Lid Rubber <i>x</i>			\$ 115.80
	Boot Lid Lock Upper <i>x</i>			\$ 137.90
	Boot Lid Lock Lower <i>x</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>/</i>			\$ 27.20
	Boot Lid CRDI Plate <i>/</i>			\$ 41.00
	Boot Lid Lamp (RH) <i>/</i>			\$ 556.80
	Rear Bumper <i>/</i>			\$ 603.60
	Rear Bumper Reinforcement <i>?</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>?</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket <i>?</i>		\$ 49.00	\$ 98.00
	Rear Bumper Clips <i>/</i>			\$ 22.00
	Rear Bumper Sponge <i>?</i>			\$ 143.40
	Rear Bumper Under Cover <i>/</i>			\$ 225.00
	Rear Bumper Reflector Lamp (RH) <i>/</i>			\$ 32.00
	Tail Lamp (RH) <i>/</i>			\$ 565.60
	Rear Panel <i>x repair</i>			\$ 592.30
	Rear Panel Garnish <i>?</i>			\$ 57.70
	Rear Panel Lower Panel <i>x repair</i>			\$ 495.50
	Rear Fender (RH) <i>/</i>			\$ 2,020.10
	Rear Fender Inner Lining (RH) <i>x</i>			\$ 164.40
	Rear Windscreen Moulding <i>/</i>			\$ 60.00
	SUB TOTAL			\$ 8,535.75
	LESS 20%			\$ 1,707.15
	DISCOUNTED TOTAL			\$ 6,828.60
	Boot Lid Comfort Logo & Tel No. Sticker <i>/</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>/</i>			\$ 135.70
	Rear Bumper Rubber Mat <i>/</i>			\$ 50.00
	Rear Windscreen Sealant <i>/</i>			\$ 46.00
	Labour Charge			\$ 261.70
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Fees			\$ 60.00
	Remove/Refix Cushion & Upholstery			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 2,550.00
	ESTIMATE TOTAL			\$ 9,640.30
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company.				

LKK/Kalvin

PbyT

AIG

Kahar Alvin

10/5/18 16:00h

4 hrs

PIP

Before Repair P/Ltd.

LKK Auto Consultants here by the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental(s) must be surveyed and is subject to final approval from Insurance Company

Nett
Nett
Nett
Nett

800
700
20
20
50
100
20