

15/05/2011

INS. CASE OWNER:

CC 3/CTI1800 8649, F2j6302

LKK:

IDAC:

Surveyor:

Edwin

DOI:

10/5/18

Date / Time:

10/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBD 2829D

Name of Insured:

EVERETT WORKS P/L

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A:

Nature of Accident:

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

ALAN SARWAR

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SNM/8012H7602

Policy No.:

DMLVSN 1754911701

Make / Model:

Toyota

Place of Accident:

STIRLING RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

premier



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
27/5/18	44010767-X	Non-Reporting ltr (1st):	
	GBD 2829D-X	Non-Reporting ltr (2nd):	
	OLD CHANGED LANE	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	204 25-5-18
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Towing Invoice	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	\$5	(days) Reduction:	%
FINAL SETTLEMENT Date/Time: 27-11-18		Confirm with: GALY	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	T.4
Repair Cost:	\$5 3,638		
Loss of Rental (LOR):	\$5 608.54	(days) 101.44	
Loss of Use (LOU):	\$5 x	(\$ x days)	
Loss of Income (LOI):	\$5 x	(\$ x days)	
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/> [Tick only one]
GIA/LTA Search	\$5 2 x 1		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		
Total:	\$5 4,248.64	Global Sum \$5:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	\$5 4,248.64	Name 1:	PREMIER AUTOMOTIVE SERVICES PTE LTD
Payee 2: (Strike if N.A.)	\$5 X	Name 2:	X
Payee 3: (Strike if N.A.)	\$5 X	Name 3:	X




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18008649/K1jb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 11-05-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 2825D	Veh. Inspected	SHD 1076J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/05/2018	Inspection Date	10/05/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18008649/K1jb3

Date: 11.05.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD1076J


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10.05.2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,631.70
Revised Estimate Amount	: S\$	4,273.50
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

10-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1076 J

1 pc	Rear bumper <i>Refer</i>	\$	696.00
2 pcs	Rear bumper n/s & o/s side bracket @ \$29.00 <i>X see</i>	\$	58.00
1 pc	Rear n/s fender <i>Ref</i>	\$	1,205.00
1 pc	Rear n/s fender inner shield <i>X see</i>	\$	120.00
1 pc	Rear windscreen moulding <i>see</i>	\$	87.00
1 pc	Rear n/s door <i>Ref</i>	\$	791.00
1 pc	Rear n/s wheel cover <i>head</i>	\$	116.00
		\$	3,073.00
		Less 10%	\$ 307.30
		\$	2,765.70

S/NETT

1 set	Rear n/s fender inner shield clips <i>X see</i>	\$	28.00
1 set	Rear bumper clips <i>see</i>	\$	48.00
1 pc	rear n/s fender sticker <i>see</i>	\$	60.00
1 pc	n/s door sticker <i>see</i>	\$	100.00
1 pc	Rear bumper top protector <i>see</i>	\$	80.00 <i>50</i>
Sundry <i>see</i>		\$	50.00 <i>20</i>
To check wheel alignment		\$	80.00 <i>X see</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs		\$	180.00 <i>50</i>
To dismantle and refit the inner component of rear n/s door into new shell door		\$	150.00 <i>50</i>
To dismantle and refit the rear windscreen		\$	120.00 <i>140</i>
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of same		\$	1,000.00 <i>600</i>
To putty and spray painting on rear n/s door, n/s rocker panel garnish, rear n/s fender, rear bumper		\$	850.00 <i>500</i>
To apply rustproofing on the repaired and replaced panels.		\$	120.00 <i>50</i>
		\$	5,631.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kalvin 11/11/14
10/5/18 1620h.
5 Day.
PIP Before Pay pth

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

10-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1076 J

1 pc	Rear bumper	\$	696.00
2 pcs	Rear bumper n/s & o/s side bracket @ \$29.00	\$	58.00
1 pc	Rear n/s fender	\$	1,205.00
1 pc	Rear n/s fender inner shield	\$	120.00
1 pc	Rear windscreen moulding	\$	87.00
1 pc	Rear n/s door	\$	791.00
1 pc	Rear n/s wheel cover	\$	116.00
		\$	3,073.00
	Less 10%	\$	307.30
		\$	2,765.70

S/NETT

1 set	Rear n/s fender inner shield clips	\$	28.00
1 set	Rear bumper clips	\$	48.00
1 pc	rear n/s fender sticker	\$	60.00
1 pc	n/s door sticker	\$	100.00
1 pc	Rear bumper top protector	\$	80.00
	Sundry		
	To check wheel alignment	\$	50.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs	\$	80.00
	To dismantle and refit the inner component of rear n/s door into new shell door	\$	180.00
	To dismantle and refit the rear windscreen	\$	150.00
	To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of same	\$	120.00
	To putty and spray painting on rear n/s door, n/s rocker panel garnish, rear n/s fender, rear bumper	\$	600
	To apply rustproofing on the repaired and replaced panels.	\$	1,000.00
		\$	850.00
		\$	120.00
		\$	5,631.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

12/6/18

41583400/15 Rpi

Kalvin 11/11/14

10/5/18 1620h.

5 Day.

PIP Before Pay phd

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 11 May 2018 3:53 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBD2825D (OI : CTI - SNM18D02376C02) and SHD1076J (TP : LKK REF - CC3/CTI18008649/K1jb3) on 09.05.2018
Attachments: leeSZ_SNM18D02376C02-GBD2825D-LKKDirectSettlementAccidentLtr_CLCR95.835.pdf; MCCA18061046-GBD2825D.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Friday, 11 May, 2018 3:03 PM
To: Claims Dept of CTI
Cc: Lucas Lee; Elaine Cheong; Admin A; Joy Irene (LKKAUTO)
Subject: Direct Settlement - Accident Involving GBD2825D (OI : CTI - TBA) and SHD1076J (TP : LKK REF - CC3/CTI18008649/K1jb3) on 09.05.2018

WITHOUT PREJUDICE

Dear Elaine,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHD 1076J at M/s Premier Automotive Services Pte Ltd - Changi.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409 .

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079900

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM18D02376/C02/5**

Date: **11 MAY 2018**

via Ordinary & Registered Mail

**EVORICH WORKS PTE LTD
16 TAMPINES STREET 92**

SINGAPORE 528873

Dear Sir / Madam

**ACCIDENT INVOLVING GBD2825D AND SHD1076J ON 09 MAY 2018
ALONG STIRLING ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHD1076J**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JOY

Ref : CC3/CT118008649/K1JB3

Contact No : 68412409

via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0481A) - EE GUAN SOON KEVIN

F01/LKKDS-2013

Gary Shi

From: Gary Shi
Sent: Wednesday, 5 December, 2018 4:03 PM
To: 'Joy Irene (LKKAUTO)'
Cc: AccReport
Subject: RE: LOD / Accident involving SHD1076J & GBD2825D on 09.05.18 (China Taiping case)
Attachments: SHD1076J - DV.pdf

WITHOUT PREJUDICE

Dear Joy,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHD1076J, our client agreed to direct settle the above claims at \$4248.64

We enclosed hereby Discharge voucher & ATA for your kind attention, original copies will pass to Mr Calvin.

Kindly let us have your settlement sum of S\$4248.64 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Wednesday, 5 December, 2018 2:53 PM
To: Gary Shi
Cc: AccReport
Subject: RE: LOD / Accident involving SHD1076J & GBD2825D on 09.05.18 (China Taiping case)

WITHOUT PREJUDICE

Dear Gary,

Attached DV and ATA for your necessary action.

Kindly lend the original copy to our surveyor.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18008649/K1jb3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-12-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 2825D	Veh. Inspected	SHD 1076J
Policy No.	DMCVSN1754911700	Coverage (\$)	0.00
Claim No.	SNM18D02376/C02/5	Excess (\$)	0.00
Assign From		Assign Date	10/05/2018

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNAGM414MF5659205	Colour	SILVER
Odometer	289407	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65R16	MAXXIS	7 mm
L/H Front Tyre	205/65R16	MAXXIS	7 mm
R/H Rear Tyre	205/65R16	MAXXIS	7 mm
L/H Rear Tyre	205/65R16	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/05/2018	Inspection Date	10/05/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1076J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	696.00	696.00
2	REAR BUMPER N/S & O/S SIDE BRACKET @ \$29.00	SERVICEABLE	58.00	-
1	REAR N/S FENDER	DENTED	1,205.00	1,205.00
1	REAR N/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	87.00	87.00
1	REAR N/S DOOR	DENTED	791.00	791.00
1	REAR N/S WHEEL DOOR	GRAZED	116.00	116.00
	LESS 10% DISCOUNT		-307.30	-289.50
			2,765.70	2,605.50
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			366.00	278.00
<u>LABOUR</u>				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF REAR N/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO DISMANTLE AND REFIT THE REAR WINDSCREEN.		120.00	100.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO CUT / WELD AND HEAT ON THE REAR N/S FENDER. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF SAME.		1,000.00	600.00
	TO PUTTY AND SPRAY PAINTING ON REAR N/S DOOR, N/S ROCKER PANEL GARNISH, REAR N/S FENDER, REAR BUMPER.		850.00	540.00

Report Ref No. CC3/CTI18008649/K1jb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	50.00
			2,500.00	1,390.00
GRAND TOTAL			5,631.70	4,273.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CC3/CT118008649/K1jb3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.