PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

10-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1076 J

1 pc	Rear bumper		\$	696.00
2 pcs	Rear bumper n/s & o/s side bracket @ \$2	9.00 🗡	\$	58.00
1pc	Rear n/s fender		\$	1,205.00
1 pc	Rear n/s fender inner shield 🔀		\$	120.00
1 pc	Rear windscreen moulding —		\$	87.00
1 pc	Rear n/s door		\$	791.00
1 pc	Rear n/s wheel cover /		\$	116.00
			\$	3,073.00
		Less 10%	\$	307.30
			\$	2,765.70
S/NETT				
1 set	Rear n/s fender inner shield clips 💹		\$	28.00
1 set	Rear bumper clips		\$	48.00
1 pc	rear n/s fender sticker	LKK Auto Consultants hence notify	\$	60.00
1 pc	n/s door sticker		\$	100.00
1 pc	Rear bumper top protector	To resurvey before after spray To display damaged part(s) during resurvey	\$ pasis	80.0053
	Sundry	Third party survey is on a sullowed.	\$	50.00 2
	To check wheel alignment	No illegal modification(s) is allowed. Supplementary item(s) must be resurveyed a is subject to final approval from Insurance Co.	1U	80.00 7
	To dismantle / refit the inner garnishes, inner linings, inner leading trims, cushion seat, carpet, etc to facilitate repairer signature:			180.00 50
	To dismantle and refit the inner componer into new shell door	nt of Peear n∕s door	\$	150.00 50
	To dismantle and refit the rear windscreen		\$	120:00 /20
	To labour charge for dismantle and renew damaged parts. To cut/weld and heat on t Including knock-out, straighten, repair, ressame	he rear n/s fender.	\$	1,000.00
	To putty and spray painting on rear n/s door, n/s rocker panel garnish, rear n/s fender, rear bumper		\$	850.00
	To apply rustproofing on the repaired and	replaced panels.	\$	120:00 50
		Kalm (Cl	(4	5,631.70 1620L. Refore Pary pla
	(ALL THE REPAIR COSTS ARE SUBJECT	CTED TO GST) // /o/3	10	16204.
	THE ABOVE ESTIMATED COST OF REPAIR ANY UNFORESEEN DAMAGES.	R DO NOT INCLUDE	6	Refore Pary pla