

ASS. REC. BY:

REF:

CS/FCI18008655/Aqbn2

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

WS Luene Jan

of

FCI

Date/Time:

10052018 739pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 222G

Insured:

SHA 9988R

at Workshop m/s

United Sci Automobile

Tel:

6747 4454

of

53 Ubi Are 1 #01-56

Policy No:

Claim No:

D18003732MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08052018

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

11052018 956am

Person Contacted:

Vicky

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJX 222G - NA / INC 18008515/74

Dof: 08052018

SHA 9988R - CC3 / III 1609807 / M1wb392

Dof: 1510-2016

11-05-2018

Received estimate from wksp, pass to Adrian.

14/5/18 @ 1.42pm Informed Luene, we are pending estimate from repairer.

04/7/18 @ 4.41pm revised to Luene by email.

4 65700, 4 days (Red \$20097.30, 78%)

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJX2229 Yr Regn: 2010 / FebType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz S300 c.c. 2997Colour: Black A/C: Insured / Std / NI / NASp. Reading: 263513 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2211542A289205Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 255/40R19R: 255/40R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 11/05/18Survey held at United SG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cp

RECEIVED 04 JUL 2018

Date/Time, File Pass to?

1) 04/7/18 TP

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

15X15=225

170+225

50

50+50

40

585

Report Format : TPLump Sum / I.B.I. (\$) 5700



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003732MFSH

Date: 04 July 2018

Our Ref: CS/FCII8008655/Aqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJX 222G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/05/2018 at the premises of M/s UNITED SG AUTOMOBILE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>25,797.30</u> .
Revised Estimate Amount	: S\$ <u>5,700.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the front o/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	10-05-2018	Our Ref No. D18003732MFSH
Accident Date	08-05-2018	Claim Type. Third Party
Insured Vehicle	SHA9988R	Third Party Vehicle. SJX222G
Survey Location	53 UBI AVE 1 #01-56 PAYA UBI INDUSTRIAL PARK	
Contact Person.	VICKY	
Contact No.	67474454/ 67474454	Fax No. 67477752
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	UNITED SG AUTOMOBILE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 4 July 2018 4:41 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D18003732MFSH/1
Attachments: CSFCI18008655Aqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SJX 222G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 14 May 2018 1:42 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003732MFSH/1

Dear Lurene,

Please be informed that we have inspected the vehicle SJX 222G on 11/05/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Friday, 11 May, 2018 9:57 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18003732MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 14 May 2018 1:42 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D18003732MFSH/1

Dear Lurene,

Please be informed that we have inspected the vehicle SJX 222G on 11/05/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Friday, 11 May, 2018 9:57 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18003732MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 10 May, 2018 7:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003732MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

United SG Automobile Pte Ltd

"We are always in your journey"...

53 Ubi Ave 1, #01-56 Paya Ubi Industrial Park, Singapore 408934.
Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg
UEN No. 201729521C | GST No: 201729521C

ESTIMATION QUOTE

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
ATTN: MOTOR CLAIMS DEPARTMENT

Xico Chen
WDD2211542A28 9205

VEHICLE NO : SJX222G
MAKE MODEL : MERCEDES S300
REFERENCE : USG-201805-05
DOA : 8-May-18
CLAIM TYPE : 3P CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT BUMPER <i>Missing</i>	1	\$ 2,180.00	✓
FRONT BUMPER LOWER GRILLE <i>Missing</i>	1	\$ 188.00	✓
FRONT SIDE GRILLE <i>Missing</i>	2	\$ 98.00	✓
FRONT SIDE RETAINER <i>Missing</i>	2	\$ 68.00	✓
FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 1,533.00	X
FRONT BUMPER NOZZLE <i>Missing</i>	2	\$ 194.00	✓
FRONT BUMPER NOZZLE MOTOR <i>new</i>	2	\$ 294.00	+
FRONT BUMPER FOAM - CENTRE <i>called</i>	1	\$ 182.00	✓
FRONT BUMPER SENSOR <i>missing</i>	4	\$ 600.00	✓
FRONT BUMPER FOG LAMP COVER <i>Missing</i>	2	\$ 350.00	✓
FRONT BUMPER FOG LAMP	2	\$ 930.00	✓ 872
FRONT GRILLE <i>new</i>	1	\$ 835.00	+
FRONT RH HEADLAMP <i>called</i>	1	\$ 4,150.00	2283.
FRONT RH HEADLAMP BRACKET <i>new</i>	1	\$ 150.00	X
FRONT RH HEADLAMP PANEL <i>new</i>	1	\$ 252.00	X
FRONT RH HEADLAMP CONTROL UNIT <i>new</i>	1	\$ 1,480.00	X
FRONT RH FENDER <i>Repair</i>	1	\$ 1,457.00	X
FRONT RH FENDER INNER SHIELD - INNER <i>new</i>	1	\$ 185.00	+
FRONT RH FENDER INNER SHIELD - OUTER <i>new</i>	1	\$ 139.00	+
FRONT TOW COVER <i>new</i>	1	\$ 85.00	+
FRONT SENSOR	4	\$ 1,064.00	+
FRONT RH SHOCK ABSORBER	1	\$ 3,415.00	+
FRONT RH KNUCKLE ARM <i>new</i>	1	\$ 814.00	X
FRONT WHEEL HUB C/W BEATING RH	1	\$ 1,092.00	X
FRONT LOWER ARM RH	1	\$ 814.00	+
FRONT CONTROL ARM RH	1	\$ 648.00	+

\$ 23,197.00

LESS 10% \$ 2,319.70

SUBTOTAL \$ 20,877.30

BALANCE C/F \$ 20,877.30

7015

less 10%: 6313.50

ESTIMATION QUOTE

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SJX222G
MAKE MODEL : MERCEDES S300
REFERENCE : USG-201805-05
DOA : 8-May-18
CLAIM TYPE : 3P CLAIM

PAGE 2 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 20,877.30	
FRONT BUMPER CLIP <i>Ken</i>	1 SET	\$ 60.00	30
FRONT FENDER INNER TRIM CLIP <i>Ken</i>	1 SET	\$ 50.00	*
RIM <i>Ken</i>	1	\$ 1,500.00	*
BRAKE FUILD <i>Ken</i>	1	\$ 50.00	*
SUBTOTAL		\$ 1,660.00	
BALANCE C/F		\$ 22,537.30	

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 22,537.30	
CHECK FROMT WIRING AND LIGHTNING SYSTEM	1	\$ 60.00	30
DIAGNOIS CHECK AND CLEAR FAULT CODE	2	\$ 500.00	100
CHECK FRONT WHEEL ALIGNMENT	3	\$ 150.00	*
REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	4	\$ 200.00	*
PANEL BEATING ON AFFECTED AREAS	5	\$ 1,200.00	250
SPRAY PAINTING ON AFFECTED AREAS	6	\$ 1,000.00	500
APPLY ANTI RUST ON AFFECTED AREAS	7	\$ 150.00	*
SUBTOTAL		\$ 3,260.00	

GRAND TOTAL \$ 25,797.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Adrian King
11/05/18. ✓

04 Days.

total: 7223.50

r/s: S.T.K.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18008655/Aqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9988R	Veh. Inspected	SJX 222G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003732MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	10/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ S300	c.c	2997	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2211542A289205	Colour	BLACK	
Odometer	263513	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/40 R19	MICHELIN	6 mm	
L/H Front Tyre	255/40 R19	MICHELIN	6 mm	
R/H Rear Tyre	255/40 R19	MICHELIN	6 mm	
L/H Rear Tyre	255/40 R19	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2018	Inspection Date	11/05/2018	
Survey held at	UNITED SG AUTOMOBILE PTE LTD 53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 222G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	MISSING	2,180.00	2,180.00
1	FRONT BUMPER LOWER GRILLE	MISSING	188.00	188.00
2	FRONT SIDE GRILLE	MISSING	98.00	98.00
2	FRONT SIDE RETAINER	MISSING	68.00	68.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	1,533.00	-
2	FRONT BUMPER NOZZLE	MISSING	194.00	194.00
2	FRONT BUMPER NOZZLE MOTOR	NOT NECESSARY	294.00	-
1	FRONT BUMPER FOAM-CENTRE	CRACKED	182.00	182.00
4	FRONT BUMPER SENSOR	MISSING	600.00	600.00
2	FRONT BUMPER FOG LAMP COVER	MISSING	350.00	350.00
2	FRONT BUMPER FOG LAMP	MISSING	930.00	872.00
1	FRONT GRILLE	NOT NECESSARY	835.00	-
1	FRONT RH HEADLAMP	CRACKED	4,150.00	2,283.00
1	FRONT RH HEADLAMP BRACKET	NOT NECESSARY	150.00	-
1	FRONT RH HEADLAMP PANEL	NOT NECESSARY	252.00	-
1	FRONT RH HEADLAMP CONTROL UNIT	NOT NECESSARY	1,480.00	-
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	1,457.00	-
1	FRONT RH FENDER INNER SHIELD-INNER	NOT NECESSARY	185.00	-
1	FRONT RH FENDER INNER SHIELD-OUTER	NOT NECESSARY	139.00	-
1	FRONT TOW COVER	NOT NECESSARY	85.00	-
4	FRONT SENSOR	NOT NECESSARY	1,064.00	-
1	FRONT RH SHOCK ABSORBER	NOT NECESSARY	3,415.00	-
1	FRONT RH KNUCKLE ARM	NOT NECESSARY	814.00	-
1	FRONT WHEEL HUB C/W BEATING RH	NOT NECESSARY	1,092.00	-
1	FRONT LOWER ARM RH	NOT NECESSARY	814.00	-
1	FRONT CONTROL ARM RH	NOT NECESSARY	648.00	-
	LESS 10% DISCOUNT		-2,319.70	-701.50
			20,877.30	6,313.50
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	30.00

Report Ref No. CS/FCI18008655/Aqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	RIM (SN)	NOT NECESSARY	1,500.00	-
1	BRAKE FULID (SN)	NOT NECESSARY	50.00	-
			1,660.00	30.00
	LABOUR			
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	DIAGNOIS CHECK AND CLEAR FAULT CODE.		500.00	100.00
	CHECK FRONT WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.	NOT NECESSARY	200.00	-
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT RH FENDER.		1,200.00	250.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	500.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			3,260.00	880.00
	GRAND TOTAL		25,797.30	7,223.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,700.00

Report Ref No. CS/FC118008655/Aqbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.