



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SHC5603S
Date of Accident : 10 May 2018

*Not Allowed
due
2/5 \$5100?
5 day.
11/5/18
The photo attached*

Mr Teo Hue Chuang

Date : 10 May 2018

Estimate To Repair SKV2284M - Toyota Estima Aeras 2.4A
Chassis No : ACR500077796

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>50d300</i>	\$ 1,855.40
02	1 pc	tailgate lid Aeras badge <i>rec</i>	\$ 54.80
03	1 pc	tailgate lid Estima badge <i>rec</i>	\$ 47.00
04	1 pc	tailgate lid centre logo badge <i>rec</i>	\$ 72.00
05	1 pc	tailgate lid lock top <i>no</i>	\$ 395.80
06	1 pc	tailgate lid lock striker bottom <i>11</i>	\$ 39.20
07	1 pc	tailgate lid weatherstirp <i>11</i>	\$ 356.40
08	1 pc	tailgate lid inner trimboard <i>del to 11</i>	\$ 530.00
09	2 pc	tailgate lid rubber stopper @ \$18.60 <i>11</i>	\$ 37.20
10	2 pc	tailgate lid side catch @ \$45.50 <i>11</i>	\$ 91.00
11	2 pc	tailgate lid side catch latch @ \$45.50 <i>11</i>	\$ 91.00
12	1 pc	tailgate lid outer garnish handle <i>11</i>	\$ 211.60
13	1 pc	tailgate lid inner closing handle garnish <i>11</i>	\$ 29.30
14	1 pc	tailgate lid keyless sensor <i>11</i>	\$ 158.60
15	1 pc	rear windshield weatherstirp <i>rec</i>	\$ 97.30
16	1 pc	rear end panel <i>30d300</i>	\$ 611.70
17	1 pc	rear end panel inner trim - top <i>11/11</i>	\$ 295.70
18	1 pc	rear end panel inner trim - bottom <i>11</i>	\$ 205.10
19	10 pc	rear end panel inner trim clips @ \$4.30 <i>11</i>	\$ 43.00
20	1 pc	rear bumper <i>11</i>	\$ 546.20
21	2 pc	rear bumper tow cover @ \$21.70 <i>0/50e</i>	\$ 43.40
22	2 pc	rear bumper reflector @ \$98.90 <i>2/50e</i>	\$ 197.80
23	2 pc	rear bumper side reatiner @ \$55.20 <i>2/50e</i>	\$ 110.40
24	10 pc	rear bumper clips @ \$4.30 <i>rec</i>	\$ 43.00
25	2 pc	rear bumper absorber foam @ \$69.80 <i>11</i>	\$ 139.60
26	2 pc	rear bumper side holder @ \$38.80 <i>11</i>	\$ 77.60
27	1 pc	rear bumper end splashield cover <i>11</i>	\$ 102.00
28	2 pc	rear seat bracket @ \$.00 <i>11</i>	\$ 0.00
29	1 pc	rear floor panel <i>11</i>	\$ 774.90
			\$ 7,257.00
Less 25 %			\$ 1,814.25
			\$ 5,442.75
<u>SPECIAL NETT ITEMS</u>			
30	1 pc	rear windshield glass sealant <i>rec</i>	\$ 120.00
31	1 pc	rear windshield glass inner sponge seal <i>rec</i>	\$ 80.00
32	1 pc	rear bumper parking sensor <i>shid</i>	\$ 450.00
			\$ 650.00

Handwritten notes and marks on the right side of the table, including vertical lines, 'X' marks, and numerical values like 5341.4, 4006.05, 40, 30, 200.