



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SHC5603S  
Date of Accident : 10 May 2018

*Not Allowed  
dla  
2/5/18  
5 day  
11/5/18  
The photo attached*

Mr Teo Hue Chuang

Date : 10 May 2018

Estimate To Repair SKV2284M - Toyota Estima Aeras 2.4A  
Chassis No : ACR500077796

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>505.00</i>	\$ 1,855.40
02	1 pc	tailgate lid Aeras badge <i>rec</i>	\$ 54.80
03	1 pc	tailgate lid Estima badge <i>rec</i>	\$ 47.00
04	1 pc	tailgate lid centre logo badge <i>rec</i>	\$ 72.00
05	1 pc	tailgate lid lock top <i>to</i>	\$ 395.80
06	1 pc	tailgate lid lock striker bottom <i>11</i>	\$ 39.20
07	1 pc	tailgate lid weatherstirp <i>twi</i>	\$ 356.40
08	1 pc	tailgate lid inner trimboard	\$ 530.00
09	2 pc	tailgate lid rubber stopper @ \$18.60 <i>11</i>	\$ 37.20
10	2 pc	tailgate lid side catch @ \$45.50 <i>11</i>	\$ 91.00
11	2 pc	tailgate lid side catch latch @ \$45.50 <i>11</i>	\$ 91.00
12	1 pc	tailgate lid outer garnish handle <i>11</i>	\$ 211.60
13	1 pc	tailgate lid inner closing handle garnish <i>11</i>	\$ 29.30
14	1 pc	tailgate lid keyless sensor	\$ 158.60
15	1 pc	rear windshield weatherstirp <i>rec</i>	\$ 97.30
16	1 pc	rear end panel <i>Body</i>	\$ 611.70
17	1 pc	rear end panel inner trim - top <i>twi/rec</i>	\$ 295.70
18	1 pc	rear end panel inner trim - bottom	\$ 205.10
19	10 pc	rear end panel inner trim clips @ \$4.30 <i>11</i>	\$ 43.00
20	1 pc	rear bumper <i>to</i>	\$ 546.20
21	2 pc	rear bumper tow cover @ \$21.70 <i>0/50e</i>	\$ 43.40
22	2 pc	rear bumper reflector @ \$98.90 <i>2/50e</i>	\$ 197.80
23	2 pc	rear bumper side reatiner @ \$55.20 <i>2/50e</i>	\$ 110.40
24	10 pc	rear bumper clips @ \$4.30 <i>rec</i>	\$ 43.00
25	2 pc	rear bumper absorber foam @ \$69.80	\$ 139.60
26	2 pc	rear bumper side holder @ \$38.80 <i>11</i>	\$ 77.60
27	1 pc	rear bumper end splashield cover <i>11</i>	\$ 102.00
28	2 pc	rear seat bracket @ \$.00 <i>2</i>	\$ 0.00
29	1 pc	rear floor panel <i>2</i>	\$ 774.90
			\$ 7,257.00
Less 25 %			\$ 1,814.25
			\$ 5,442.75
<u>SPECIAL NETT ITEMS</u>			
30	1 pc	rear windshield glass sealant <i>rec</i>	\$ 120.00
31	1 pc	rear windshield glass inner sponge seal <i>rec</i>	\$ 80.00
32	1 pc	rear bumper parking sensor <i>shred</i>	\$ 450.00
			\$ 650.00

*Handwritten notes and markings on the right side of the table, including checkmarks, question marks, and numbers (40, 30, 200).*



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

51 Defu Lane 10 Singapore 539216  
 Tel : 68585151 ( 24 Hours ) Fax : 68580877  
 GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SHC5603S  
 Date of Accident : 10 May 2018

Mr Teo Hue Chuang

Date : 10 May 2018

Estimate To Repair SKV2284M - Toyota Estima Aeras 2.4A  
 Chassis No : ACR500077796

S/No	Quantity	Description	Amount
		<b>LABOUR &amp; MISC. CHARGES</b>	
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To remove and refit rear windscreen glass.	\$ 180.00
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00
04		To rust-proofing of the affected areas.	\$ 150.00
05		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
06		To check electrical lighting concerned.	\$ 80.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 2,700.00
08		Putty and spray painting of the affected portion.	\$ 2,200.00
			\$ 5,700.00
		<b>Total</b>	<b>\$ 11,792.75</b>

50  
120  
60  
60  
80  
20  
880  
900

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts processes subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: