

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 14 May 2018

Preliminary Advice

Vehicle No	: SJM1035G	Accident Date	: 10/05/2018
Make	: HONDA STREAM	Policy No.	: Z18VP05016906
Assignment Date	: 11/05/2018	Excess	: S\$0.00
Date of Inspection	: 11/05/2018	Est. Duration of Repair	: -
Inspection At	: Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,850.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	19,000.00
COE / PARF Rebate	:S\$	14,003.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,997.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :