REPAIR ESTIMATE*

VEHICLE NO

SHD4271S

DATE 05/10/18 11:46 AM

MAKE

DEL	: HYUNDAI i40				,
Qty	Parts Description/ Labour	Туре	Unit Price	Amount	
	Rear Bumper Cover / Juhrel			\$603.60	
	Rear Bumper Sponge X1 12		7.1	\$143.40	
	Rear Bumper Reinforcement 🐉			\$504.35	
	Rear Bumper clips			\$22.00	
	Bootlid cover			\$1,681.40	
	Bootlid 'H' emblem			\$27.20	
	Bootlid 'CRDI' emblem × **			\$41.00	
	Bootlid 'I40' emblem × **			\$41.00	
	SUB TOTAL			\$3,063.95	
		- (0/		\$612.79	
	LESS 20%	1			1
	DISCOUNTED TOTAL			\$2,451.16	
	Bootlid comfort logo & Tel. No			\$30.00	Ne
				\$30.00	
	Labour Charge			200	
	Panel Beating			\$500.00	
	Spray Painting Charge			\$500.00	4
	Check wiring		- '4	\$50.00	X
	Remove/refix reverse sensor			\$50.00	20
	TOTAL LABOUR	8		\$1,100.00	-
	ESTIMATE TOTAL			\$3,581.16	
	1. 1/164				
	Kalar 10104 10/5/8 1345 hs. 2 Ryo.				
	10/5/10 1545 10				
	2 lyo.	LKK Auto Co	onsultants hence notify		
		the Repairer	of the following:		
	Before Part pl	To display day	paged spray painting		
		Parts prices ar	e subject to confirmation		
	Ratore Part pl		vey is on a "Without Prejudice" fication(s) is allowed	basis	
	De	Supplementa	ita-strong is allowed		
		is subject to fire	nem(s) must be resurveyed at all approval from Insurance Cor	npany	
		Acknowledged by	Repairer	any	
		Signature:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.