



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO-06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

car at workshop

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 FRONT BONNET		1 PC	✓ 210.00	
2 FRONT BONNET HINGE LH		1 PC	✗ 25.00	
3 FRONT BONNET HINGE RH		1 PC	✗ 25.00	
4 FRONT BONNET INSULATOR CLIPS X 10		10 PC	✗ 15.00	
5 FRONT BONNET INNER LOCK		1 PC	✗ 30.00	
6 HEADLAMP LH		1 PC	✓ 130.00	
7 HEADLAMP RH		1 PC	✗ 130.00	
8 FRONT BUMPER		1 PC	✓ 160.00	
9 FRONT BUMPER SIDE RETAINER LH		1 PC	✓ 25.00	
10 FRONT BUMPER SIDE RETAINER RH		1 PC	✗ 25.00	
11 FRONT BUMPER CLIPS X 15		15 PC	✓ 15.00	
12 FRONT BUMPER REINFORCEMENT		1 PC	✗ 110.00	
13 FRONT FENDER LH		1 PC	✓ 120.00	
14 FRONT FENDER COWLING LH		1 PC	✓ 40.00	
15 FRONT FENDER COWLING CLIPS X 8		8 PC	✓ 8.00	
16 FRONT FENDER VVTI LOGO		1 PC	✓ 15.00	
17 FRONT FENDER TOP QUARTER GARNISH LH		1 PC	✓ 15.00	
18 RADIATOR SUPPORT PANEL		1 PC	✗ 180.00	
19 FRONT WHEELHOUSE PANEL LH		1 PC	✗ 150.00	
20 SIDE MIRROR ASSY LH		1 PC	✓ 240.00	
21 SIDE MIRROR COVER LH		1 PC	✓ 22.00	
22 AIR DUCT		1 PC	✗ 48.00	
23 RESONATOR TANK		1 PC	✗ 60.00	
24 FUSE & RELAY BOX TOP HOUSING		1 PC	✗ 40.00	
25 FUSE & RELAY BOX LOWER HOUSING		1 PC	✗ 45.00	
26 FRONT DOOR LH		1 PC	✓ 380.00	
27 FRONT DOOR HINGE TOP		1 PC	✓ 35.00	
28 FRONT DOOR HINGE BOTTOM		1 PC	✓ 35.00	
29 FRONT DOOR CHECKER		1 PC	✓ 60.00	
30 FRONT DOOR PROTECTOR		1 PC	✓ 35.00	
31 FRONT DOOR PROTECTOR CHROME MOULDING		1 PC	✓ 15.00	
32 FRONT DOOR RUBBER (AT DOOR)		1 PC	✓ 68.00	
33 FRONT DOOR RUBBER (AT BODY)		1 PC	✗ 140.00	
34 FRONT DOOR INNER LOCK		1 PC	✓ 165.00	
35 FRONT DOOR POWER WINDOW MOTOR		1 PC	✓ 155.00	
36 FRONT DOOR POWER WINDOW REGULATOR		1 PC	✓ 55.00	
37 FRONT DOOR INNER TRIMBOARD - CHECK PRICE		1 PC	✗ 0.0000	
38 FRONT DOOR OUTER HANDLE		1 PC	✓ 25.00	
39 FRONT DOOR OUTER HANDLE SMALL COVER		1 PC	✓ 12.00	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
 GST-M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
40 FRONT DOOR OUTER LOCK CYLINDER		1 PC	X 45.00	
41 FRONT DOOR STICKER (BLACK)		1 PC	✓ 30.00	
42 FRONT DOOR PILLAR LH		1 PC	X 180.00	
43 REAR DOOR LH		1 PC	✓ 320.00	
44 REAR DOOR HINGE TOP LH		1 PC	X 35.00	
45 REAR DOOR HINGE LOWER		1 PC	✓ 35.00	
46 REAR DOOR CHECKER		1 PC	X 60.00	
47 REAR DOOR PROTECTOR		1 PC	✓ 25.00	
48 REAR DOOR PROTECTOR CHROME MOULDING		1 PC	✓ 10.00	
49 REAR DOOR RUBBER (AT DOOR)		1 PC	✓ 50.00	
50 REAR DOOR INNER LOCK		1 PC	X 170.00	
51 REAR DOOR POWER WINDOW MOTOR		1 PC	✓ 160.00	
52 REAR DOOR POWER WINDOW REGULATOR		1 PC	✓ 75.00	
53 REAR DOOR OUTER HANDLE		1 PC	✓ 25.00	
54 REAR DOOR OUTER HANDLE SMALL COVER		1 PC	X 12.00	
55 SIDE SKIRT LH		1 PC	X 250.00	
56 SIDE SKIRT CLIPS X 10		10 PC	X 25.00	
57 REAR BUMPER		1 PC	X 165.00	
58 REAR BUMPER SIDE RETAINER LH		1 PC	X 22.00	
59 REAR BUMPER CLIPS X 10		10 PC	X 10.00	
60 FRONT WINDSCREEN MOULDING TOP		1 PC	X 45.00	
61 FRONT WHEEL BEARING LH		1 PC	✓ 35.00	
62 FRONT WHEEL HUB LH		1 PC	✓ 95.00	
63 FRONT KNUCKLE ARM LH		1 PC	✓ 170.00	
64 FRONT LOWER ARM LH		1 PC	✓ 90.00	
65 FRONT STABILISER BAR		1 PC	✓ 115.00	
66 FRONT STABILISER LINKAGE LH		1 PC	✓ 55.00	
67 FRONT STABILISER LINKAGE RH		1 PC	X 55.00	
68 FRONT DRIVE SHAFT LH		1 PC	✓ 460.00	
69 FRONT STEERING RACK		1 PC	✓ 550.00	
70 FRONT TIE ROD LH - CHECK PRICE		1 PC	✓ 0.0000	
71 FRONT TIE ROD END BALL JOINT LH		1 PC	✓ 40.00	
72 FRONT SHOCK ABSORBER LH		1 PC	✓ 120.00	
73 FRONT SHOCK ABSORBER TOP MOUNTING LH		1 PC	✓ 55.00	
74 FRONT SHOCK ABSORBER DAMPER LH		1 PC	✓ 10.00	
75 FRONT ABS SENSOR LH		1 PC	✓ 145.00	
76 FRONT CROSSMEMBER		1 PC	✓ 700.00	
77 FRONT LOWER ARM BALL JOINT LH		1 PC	✓ 65.00	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO-06470300B

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
				7,572.00
Special Nett				
78 COOLANT		1 PC	X 30.00	
79 TYRE LHF & LHR - CHECK PRICE		2 PC	0.0000	
80 SPORT RIM LHF & LHR - CHECK PRICE		2 PC	0.0000	
81 INNER SEAL		1 PC	20.00	
82 SEALANT		1 PC	40.00	
				90.00
LABOUR				
83 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	
84 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
85 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	80.00	
86 LABOUR TO REMOVE & REFIT FRONT WINDSCREEN		1 EA	120.00	
87 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.		1 PC	280.00	
88 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.(2 DOORS)		1 PC	120.00	
89 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	180.00	
90 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.		1 PC	250.00	
91 TO REMOVE AND REINSTALL REAR BUMPER SENSORS.		1 PC	60.00	
92 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	280.00	
93 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL,FRONT WHEELHOUSE PANEL LH,FRONT DOOR PILLAR LH, TO KNOCK & REPAIR FRONT FENDER RH,ROCKER PANEL LH, CENTER DOOR PILLAR LH, REAR FENDER LH		1 PC	1,600.00	
94 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH & RH,RADIATOR SUPPORT PANEL,FRONT WHEELHOUSE PANEL LH,FRONT DOOR LH,REAR DOOR LH,SIDE SKIRT LH,FRONT DOOR PILLAR LH,ROCKER PANEL LH,CENTER PILLAR LH, REAR FENDER LH,REAR BUMPER, SIDE MIRROR LH		1 PC	1,800.00	

Front only cut fenders

86%

300

X

100

X

80

200

X

1700

1600



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
				5,010.00

Amount Before Excess SS 12,672.00

Add GST @ 7% 887.04

Total Amount payable SS 13,559.04

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED FIFTY NINE AND CENTS FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Revert
No
EXCESS xli
LKK Auto (MA)
PIP Repair
Before paint PWD
10 w/days