

ASS. REC. BY:

REF:

CS/ASM/8008665/DS bet

Special Instruction:

Surveyor

Smart claim

From (Person):

Ma
Kitty Teo

ASSIGNMENT (Office)

Estimated Cost:

of

HSM

Date/Time

11052018 1024am

Bill to:

① / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SJR 69033

Insured:

at Workshop m/s

An Lim Motor

Tel:

6493 1244

of

Blk 10 AMK Ind Park 2F #01-09

Policy No:

Claim No:

58M00FTP

Sum Insured

Excess:

NIL

Make of Vch

(Client's Record)

D.O.A.

30042018

CA / REV

/ REP.

/ REV 24 HRS

Date/Time:

11052018 11:22am

Person Contacted:

Eileen

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓)

Estimate

estimate not yet done, will arrange survey when done.

SJR 69033 -

CS/TNC/8011350/016c2-1

SIR: 360615

25/05/18

@ 11:25 a.m.

Authorisation repair approved by Kitty Teo via smart claim.

25/05/18

@ 12:12 p.m.

revised to Eileen Chue (painter) authorised repair via email.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 at: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: **\$17k**

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lim Sum: _____ % 3 Val: Yes or No

CA / REV / REP.. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SJR6903S** Yr Regn: **JUL 2009**
 Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
☐ Truck / ☐ Trailer or

Make: **DAEWOO ACES** CC: **1592**Colour: **WHITE** A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: **NOREADING** T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng No: _____

C/F No: **MR0537EE106149248**Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: **205/50/R16**
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Yokomo**

Front

R/Bal: **8** mmL/Bal: **8** mm

D.O.A:

Survey held at: _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

14/11/13 Confirmed P/P \$ 6,996.00 @ 10 days
 with ~~Tom~~ Mui Hong, checked by
 Simon
 (\$ 5,740.00 red - 45%)

Tow in 10/05/13
 2/12/06/13
 4/5

RECEIVED 22 NOV 2013

Date/Time: File Page 1 of 1

22/11/13

11 7/11/13

Date/Time: File Return 1 of 1

22

☐ Prel. Report☒ Final ReportDays Of Repair: **10**Resurvey No. of Trip: **1**

Survey Fee

Transportation

1. S - R - S

2. M - S

3. S - S

4. S - S

5. S - S

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Insp (\$)☐ Wheel-and (\$)

Report Format:

Lump Sum / I.B.t: (\$ **6,996.00 P/P**)

250

250

Propellant:	Petrol
Engine No.:	CCZ485331
Engine Capacity:	1984 cc
Maximum Power Output:	147.0 kW (197 bhp)
Maximum Laden Weight:	2530 kg
Unladen Weight:	1790 kg
Year Of Manufacture:	2015
Original Registration Date:	11 Jan 2016
Lifespan Expiry Date:	-
COE Category:	B - Car above 1600cc or 97kW (130bhp)
Quota Premium :	\$54,920.00
COE Expiry Date:	10 Jan 2026
Road Tax Expiry Date:	10 Jan 2019
PARF Eligibility Expiry Date:	10 Jan 2026
Inspection Due Date:	10 Jan 2019
Intended Transfer Date:	09 Apr 2018
CO2 Emission :	198.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission:	-
HC Emission:	-



Service Request Details

Claim

S8M00FTP

Reference

None 

Loss Date

April 30, 2018

Request Date

May 11, 2018

Due Date

May 18, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJR69035

Make

TOYOTA

Service Address

10 Ang Mo Kio Ind. Park 2A, , 568047

Primary Contact/Insured

WOON SHAW DONG

BLK 316D PUNGGOL WAY, #12-685 WATERWAY CASCADIA, 824316, Singapore
91696476

WOONSHAWDONG@HOTMAIL.COM

Claim Handler

TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

EXCESS NIL

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

5/11/18 10:26 AM

FROM

TEO Kitty

SUBJECT

SJR6903S - VEH @ AH LIM(AMK)

BODY

Hi Please survey WP and get the estimate from wor...



IS YOUR CAR DUE FOR
SCRAP OR EXPORT?

Use Our **FREE** Service To Get
The Best Selling Price!



SGCARMART
QUOTZ
Car Valuation Service

Audi Min Price: to No Max: Depreciation: Vehicle Type: Category:

Advanced
Search

Home > New Cars > New Car Brands > Audi > Audi A3 Sedan

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.
Do you know? We are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale!
We have over 10,000 plates available.

Audi A3 Sedan

Overview Pricing Photos Research Reviews Specs Features Similar Accessories Promo

Add to Shortlist Submit a Review Report Error Share



USER RATINGS: (12 reviews)

Details

Distributor Premium Automobiles
Hotline 68362223
Built in Hungary (launched 2013, facelifted Jan-2017)
Pricelist **17-May Pricelist** Select Another Date
Promotion No current promotions. Alert me when new promotions are inserted

View all other promotions Download Brochure Add to Shortlist

Submodel	Price	Depreciation F	Fuel Economy	Power	Transmission	Detailed Info
1.0 TFSI S tronic (A) FACELIFT + Read facelift article	\$141,380	\$12,800 /yr	21.3km/L	116hp	T-speed (A) S tronic	Specs Features

Price updated 17-May-2018

Audi A3 Sedan Photos



View All 35 Audi A3 Sedan Photos

Audi A3 Sedan Review

Car Review - Audi A3 Sedan 1.4 TFSI S-tronic Ambiente (A)

14 Apr 2014 | Audi Reviews

The Audi A3 sedan looks smart inside and out, drives exceptionally well and is positively frugal, distinguishing itself from the rest in its segment.

The Good

- It makes you look sharp
- It's well-aimed in practicality and style
- You can look handsome & feel a twinkle and feel rewarded

The Bad

- Not as frugal as the Sportback

FACELIFT The Audi A3 Sedan was facelifted on Jan 2017. Read more

CONSUMER REVIEWS

No bang for the buck

Test drove the A3 among other cars and I felt the A3 was overpriced for what it was being packaged with. Engine seemed smooth and enthusiastic but I did not try on an spiral car-park incline, which these eng...

Read More +

Great luxury car for a first continental...

Got my A3 during end Nov and love the ride since. Ride performance has been great given that it is only a 1.0L car. Overtaking and pick up is now much better than my previous non-turbo charged cars. Space is a...

Read More +

Submit a review Receive 3 MCF points when you submit a review

View All 12 Consumer Reviews

Items for Audi



HID Conversion Kit Set



Rear Bumper Plate



Car Mat



3D Royal MAXpider Car Mat



Day Running Light



Car Mat

Compare

Related Articles



Audi unveils facelifted A3



A cabriolet that is sporty, elegant and compact



Audi models star in 'Fifty Shades of Grey'



14 tyre myths you shouldn't believe

View More

[+ View All 558 Suitable Items for Audi](#)

Similar New Cars Similar Used Cars



Audi A3 Sportback
From : \$139,180



Toyota Camry
From : \$146,988



Toyota Camry Hybrid
Trust Motoring Edition
(PI)
From : \$136,800



Mercedes-Benz CLA-Class
F1 Auto Cars
Edition (PI)
From : \$146,000



Volvo S60
From : \$148,000



Toyota Camry Hybrid (PI)
From : \$141,000

Audi A3 Sedan Discussion

[+ View All](#)

Topic Title	Replies	Last Action
Audi A3 Sedan/Sportsback Owners - Check In	3470	15-May-2018
Wtb: Audi A3 2010 windows magnet shield	0	08-Apr-2018
Audi A3 2017	9	05-Sep-2017
New Audi A3 Sedan - "only premium petrol sedan under Cat A"	301	23-Sep-2016
Audi A3 S Line in London with a Poem	4	06-Jul-2015
BMW 218i Cabriolet or Audi A3 Cabriolet?	22	16-Apr-2015

MYCARFORUM
WHERE CAR ENTHUSIASTS CONVERGE

Above discussions are extracted from MyCarForum.com
You may login to MyCarForum using your sgCarMart username & password.

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

Authorized Distributor Audi cars are Audi A3 Cabriolet, Audi A3 Sportback, Audi A4, Audi A4 Avant, Audi A5 Cabriolet, Audi A5 Coupe, Audi A5 Sportback, Audi A6, Audi A6 Avant, Audi A7 Sportback, Audi A8, Audi Q2, Audi Q3, Audi Q5, Audi Q7, Audi R8, Audi R8 Spider, Audi RS3 Sedan, Audi RS3 Sportback, Audi RS5 Coupe, Audi RS6 Avant, Audi S3 Sedan, Audi S3 Sportback, Audi S4, Audi S4 Avant, Audi S5 Cabriolet, Audi S5 Coupe, Audi S5 Sportback, Audi SQ5, Audi TT Coupe, Audi TT Roadster. Parallel Imported Audi cars are Audi A5 Cabriolet, Audi Q5, Audi Q7, Audi S5 Cabriolet.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does NOT assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2018 sgCarMart. All rights reserved.

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4048B

Vehicle Details

Vehicle No.: SJR6903S
Vehicle to be Exported: Yes
Intended De-registration Date: 10 May 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: White
Manufacturing Year: 2009
Engine No.: 3ZZ4909483
Chassis No.: MR053ZEE106149248
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$17,500.00
Original Registration Date: 08 Jul 2009
First Registration Date: 08 Jul 2009
Transfer Count: 0
Actual ARF Paid: \$17,500.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 Jul 2019
PARF Rebate Amount: \$9,625.00

Intended COE Rebate Details

COE Expiry Date: 07 Jul 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$11,690.00
COE Rebate Amount: \$1,353.00
Total Rebate Amount: \$10,978.00

The information contained herein is correct as at 10 May 2018

OK

Shirley Hiew (LKK Auto)

From: muihong@ahlimmotor.com.sg
Sent: Wednesday, 14 November 2018 11:43 AM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: Re: Reminder : Draft Finalisation - SJR69035

Dear Shirley,

Noted and will amend and submit as such

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, November 14, 2018 10:51 AM
To: muihong@ahlimmotor.com.sg
Cc: SUR
Subject: RE: Reminder : Draft Finalisation - SJR69035

Hi Mui Hong,

As spoken, please re-confirm the final fig \$ 6,996.00 @ 10 days of repairs before excess \$0/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: muihong@ahlimmotor.com.sg [mailto:muihong@ahlimmotor.com.sg]
Sent: Saturday, 10 November 2018 11:18 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Reminder : Draft Finalisation - SJR69035

Dear Shirley,

Pls do let us know your recommended amended amount.

Thanks

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

From: muihong@ahlimmotor.com.sg
Sent: Saturday, November 3, 2018 10:14 AM
To: SUR - LKK ; Shirley Hiew (LKK Auto)
Subject: Draft Finalisation - SJR6903S

Dear Shirley,

Pls see attached the draft finalisation for SJR6903S for your approval.

Thanks

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170



Re:RE: Re:MV RANGE 17K - 19K

Type

🔔 Question

Message

Hi Shirley Please authorise.

Reply

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 25 May 2018 12:12 PM
To: 'Eileen Chua'
Cc: 'SUR'
Subject: RE: OD SJR 6903S (AXA)

Hi Eileen,

As instructed by our client, please proceed at repair cost not more than \$8,000.00 to repair the insured vehicle **SJR 6903S (Excess \$ NIL/-)** on part by part basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Eileen Chua [mailto:ahlimmc@singnet.com.sg]
Sent: Tuesday, 22 May 2018 10:18 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: Re: OD SJR 6903S (AXA)

Hi Shirley,

We are unable to accept the offer for repair @ \$6,000.00. We request to have \$8,000.00 for the repair.

Please advise soonest.

Best Regards,
Eileen Chua
Ah Lim Motor Company
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint S(568047)
Tel: 64831244 Fax: 64836170

From: Shirley Hiew (LKK Auto)
Sent: Thursday, May 17, 2018 5:57 PM

To: ahlimmc@singnet.com.sg
Cc: 'SUR'
Subject: OD SJR 6903S (AXA)

Dear Eelain,

Kindly check the repair cost whether you are able to repair the vehicle not over \$6,000.00

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Immediate Advice

To : AXA Insurance Pte Ltd**Date: 17/05/2018**

Survey Details:

Date of loss	30-Apr-18
Date of appointment	11-May-18
Date of survey	15-May-18
Location of survey	NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SJR 69035
Make and Model	TOYOTA COROLLA ALTIS
Date of registration	8/7/2009
Excess	0
Market Value	\$17,000
Part Rebate	\$10,978
Nett Loss	\$6,022

Repair details:

Initial Estimate	12,672.00
------------------	-----------

Proposed/Revised repair cost:

Parts	\$2,930
Check items (estimate)	\$2,510
Labour	\$3,410
Total	\$8,850
Lump Sum(if applicable)	\$

Number of days for repair	<u>10 Days</u>
---------------------------	----------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

31 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408033 TEL : (665) 62563561 FAX : (665) 62564315

Remarks:

PENDING PARTS PRICES.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	02/05/2018 15:42
Date Of Accident	30/04/2018 19:45
Exact Location Of Accident	ALONG ANG MO KIO AVE 3 UNDER THE FLYOVER
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJR6903S
Insured/Policyholder	
Name Of Registered Owner	WOON SHAW DONG
NRIC No	S6864048B
Email Address	WOONSHAWDONG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91696476
Alternative Phone No	OTHERS-91696476
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA112171
Cover Note Number	08/07/2017 - 07/07/2018
Driver	
Name of Driver	WOON SHAW DONG
NRIC No	S6864048B
Date Of Birth	24/05/1968
Occupation	INDOOR
Date Of Driving Pass	23/11/2001
Driving Experience	16 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91696476
Fax Number	
Contact Number	OTHERS-91696476
Email Address	WOONSHAWDONG@HOTMAIL.COM

Address	BLK 316D PUNGGOL WAY #12-685
Postcode	824316
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	ANG MO KIO SOUTH N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GK8822B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

Date of accident: 30/4/18 Time: 1945 Location: AMK Ave 3, Under the Flyover
 My Vehicle A: SJR 69035 Vehicle B: GK 88223 Vehicle C: -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the Police Report No.
T/20180501/2039
T/20180502/2035

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :
 Email address : massivctrd@gmail.com
 & myself
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



AH LIM MOTOR COMPANY

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180501/2039

1 of 4

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20180501/2039

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/05/2018 12:24	Vide Report No.:	Station Diary No.: 26
--	------------------	--------------------------

Informant's Particulars

Name of Informant: WOON SHAW DONG			Address: APT BLK 316D PUNGGOL WAY #12-685 SINGAPORE 824316	
ID Type / ID No.: NRIC NO / S6864048B			Contact No.: Home/Office: Mobile: 91696476	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 49	Date of Birth: 24/05/1968	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Bus Captain			Driving Licence Information: Class: 2B,2A,2,3,4A,4,5 Date of Expiry:	

General Information of the Accident

General Information of the Accident:				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/04/2018 19:45	Type of Location: X-Junction
Location: Along Road 1 ANG MO KIO AVENUE 3 Under Ang Mo Kio Avenue 3 Flyover				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GK8822B	Van	TOYOTA		Silver	Slightly Damaged	0
SJR6903S	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	White	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20180501/2039

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

2 of 4

Report No. T/20180501/2039

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJR6903S	AXA INSURANCE SINGAPORE PTE LTD	GA112171	08/07/2017	07/07/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Unknown Driver		ID No.	NIL
Related Vehicle	GK8822B (Van)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	WOON SHAW DONG		ID No.	S6864048B
Related Vehicle	SJR6903S (Car)		Contact No.	91696476
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4A,4,5 Date of Expiry: NIL
Date Treatment	30/04/2018		Date Discharge	30/04/2018
No. of Days granted Medical Leave	04		Degree of Injury	Slight

Brief Details.

On 30/04/2018 at about 1945hrs, I was driving my car SJR6903S along CTE and exited at Ang Mo Kio Avenue 3. While approaching the traffic before I merge into Ang Mo Kio Ave 3, the traffic light turns Red. As such, I stopped. When the traffic turns green, I accelerated and made the right turn under the flyover and out of a sudden, a Silver Van GK8822B came from the opposite direction and hit on to my vehicle front left side. I was still conscious but I couldn't remember much. I then went to call for Police and a moment later the Ambulance came as well. I was then conveyed to Tan Tock Seng Hospital. I was issued with 4 days MC. I suffered pain on my left chest area.

On 01/05/2018 at 0517hrs, SGT Desmond from the Police called and told me to proceed to the Police station and make a report. As such, I am lodging this report. I wish to state that I do not have a in-car camera in my vehicle.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999



T/20180501/2039

3 of 4

Report No. T/20180501/2039

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999



T/20180501/2039

4 of 4

Report No. T/20180501/2039

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 MOHAMMAD AZUAN BIN MOHD KAMAR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 01/05/2018 12:24
Officer In Charge Of Case: TP / GIT / SI MOHAMMED FADZLY BIN ABDUL AZIZ Contact No.: 65472078	Classification Of Case:
Authentication Stamp NP168 	



T/20180502/2055

1 of 3

Report No. T/20180502/2055

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No T/20180501/2039

Report Number T/20180502/2055

Vide Report Number

Date/Time of Report Made 02/05/2018 12:11

Place Report Lodged Traffic Police Division HQ

Type of Informant Driver

Name of Informant WOON SHAW DONG

ID Type / ID No. NRIC NO / S6864048B

Home/Office

Mobile 91696476

Email

Type of Accident Injury / Conveyed By Ambulance

Drink Drive No

Anyone conveyed by ambulance No

Date/Time of Accident 01/05/2018 12:25

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GK8822B	Van	TOYOTA	LITEACE 5DR		Slightly Damaged	0
SJR6903S	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	White	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20180502/2055

3 of 3

Report No. T/20180502/2055

Continuation of CSF For NP168

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Case Sensitivity	No
Officer-In-Charge of Case	TP / GIT /
Classification of Case	1) INJURY / CONVEYED BY AMBULANCE



T/20180502/2055

2 of 3

Report No. T/20180502/2055

Continuation of CSF For NP168

Driver			
Name	WOON SHAW DONG	ID No.	S6864048B
Related Vehicle	SJR6903S (Car)	Contact No.	91696476
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Facts.

On 30/4/18 at about 1945hrs, I was driving my car along TPE to CTE, and exited at Ang Mo Kio Avenue 3. While approaching the traffic before I merge into Ang Mo Kio Avenue 3, the traffic light turns red. As such, I stopped. When the traffic turns green, I accelerated and went straight under the flyover and out of the sudden, a van came from the opposite direction and hit onto my vehicle front left side. I was still conscious but I couldn't remember much. I then went to call for police and a moment later the ambulance came as well. I was then conveyed to Tan Tock Seng Hospital. I was issued with 4 days MC. I suffered pain on my left chest area.

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S6864048B**

Name: **WOON SHAW DONG**

Date of Birth: **24 May 1968**

Issue Date: **16 Jul 2013**

002202833H

REPUBLIC OF SINGAPORE

IDENTITY CARD NO: **S6864048B**

Name: **WOON SHAW DONG**

溫紹棟

Race: **CHINESE**

Date of Birth: **24-05-1968**

Country/Place of Birth: **MALAYSIA**

Sex: **M**

hp: 9169 6476

Email: WOON SHAW DONG@hotmail.com

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

	EFFECTIVE DATE
Class 2B Motorcycles < 200 cc	23 Nov 2001
Class 2A Motorcycles between 201 cc and 400 cc	23 Nov 2001
Class 2 Motorcycles > 400 cc	23 Nov 2001
Class 3 Motor Cars < 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	23 Nov 2001
Class 4A Omnibuses	06 Apr 2003
Class 4 Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg	06 Sep 2007
Class 5 Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg	
Class 5 Motor vehicles not constructed to carry any load and the unladen weight > 7250kg	21 Feb 2008



NP 428A

5201487

Barcode

NRIC No: **S6864048B**

APR 07 2013

APT BLK 318D PUNGGOL WAY #12-885
SINGAPORE 624316

NRIC No: **S6864048B**

Date: **01/09/2016**

Dry

W: 100

B: 100

A: chest & leg

Ca: NO

Total: 1.



redefining / insurance

AXA Insurance Pte Ltd
 ☎ 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 ☎ (65) 6880 4740
 ✉ customer.care@axa.com.sg
 🌐 www.axa.com.sg

Certificate of Insurance

account number
 11618

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 169) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1990 - Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	WOON SHAW DONG	Certificate number	GA112171 / 1
Cover	Comprehensive	Chassis number	MR0532EE108149248
Plan name	Essential	Engine number	3Z24909453
NCD applicable	30%		
Vehicle registration number	SJR6903S		
Period of Insurance	from 08/07/2017 to 07/07/2018 (both dates inclusive)		
Finance loan company	OCBC BANK LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
- (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations imposed imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 169) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

1. S\$500 for unnamed Authorised Driver
2. S\$500 for declared Young and Inexperienced Driver
3. S\$2,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 169) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 169).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047

TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg

GST.M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
1 FRONT BONNET		1 PC	210.00 DD	
2 FRONT BONNET HINGE LH		1 PC	X 25.00 SVC	
3 FRONT BONNET HINGE RH		1 PC	X 25.00 SVC	
4 FRONT BONNET INSULATOR CLIPS X 10		10 PC	X 15.00 NN	
5 FRONT BONNET INNER LOCK		1 PC	X 30.00 NU	
6 HEADLAMP LH		1 PC	130.00 BR	
7 HEADLAMP RH		1 PC	X 130.00 NN	
8 FRONT BUMPER		1 PC	160.00 CUT	
9 FRONT BUMPER SIDE RETAINER LH		1 PC	25.00 BR	
10 FRONT BUMPER SIDE RETAINER RH		1 PC	X 25.00 SVC	
11 FRONT BUMPER CLIPS X 15		15 PC	15.00 NEC	
12 FRONT BUMPER REINFORCEMENT		1 PC	X 110.00 SVC	
13 FRONT FENDER LH		1 PC	120.00 CRU	
14 FRONT FENDER COWLING LH		1 PC	40.00 CUT	
15 FRONT FENDER COWLING CLIPS X 8		8 PC	8.00 NEC	
16 FRONT FENDER VVTI LOGO		1 PC	15.00 NEC	
17 FRONT FENDER TOP QUARTER GARNISH LH		1 PC	15.00 LRA	
18 RADIATOR SUPPORT PANEL		1 PC	X 180.00 SVC	
19 FRONT WHEELHOUSE PANEL LH		1 PC	X 150.00 SVC	
20 SIDE MIRROR ASSY LH		1 PC	240.00 SVC BRO	
21 SIDE MIRROR COVER LH		1 PC	22.00 BR	
22 AIR DUCT		1 PC	X 48.00 SVC	
23 RESONATOR TANK		1 PC	60.00 CCA	
24 FUSE & RELAY BOX TOP HOUSING		1 PC	X 40.00 SVC	
25 FUSE & RELAY BOX LOWER HOUSING		1 PC	X 45.00 SVC	
26 FRONT DOOR LH		1 PC	380.00 DIS	
27 FRONT DOOR HINGE TOP		1 PC	35.00 BT	
28 FRONT DOOR HINGE BOTTOM		1 PC	35.00 BT	
29 FRONT DOOR CHECKER		1 PC	60.00 BR	
30 FRONT DOOR PROTECTOR		1 PC	35.00 CUT	
31 FRONT DOOR PROTECTOR CHROME MOULDING		1 PC	15.00 CUT	
32 FRONT DOOR RUBBER (AT DOOR)		1 PC	68.00 CUT X 2/3 X	
33 FRONT DOOR RUBBER (AT BODY)		1 PC	X 140.00 SVC	
34 FRONT DOOR INNER LOCK		1 PC	165.00 JM	
35 FRONT DOOR POWER WINDOW MOTOR		1 PC	155.00 SVC	
36 FRONT DOOR POWER WINDOW REGULATOR		1 PC	55.00 SVC	
37 FRONT DOOR INNER TRIMBOARD - CHECK PRICE		1 PC	X 0.0000 SVC	
38 FRONT DOOR OUTER HANDLE		1 PC	25.00 BT	
39 FRONT DOOR OUTER HANDLE SMALL COVER		1 PC	12.00 JM	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
40 FRONT DOOR OUTER LOCK CYLINDER		1 PC	45.00	DM 40 BT/
41 FRONT DOOR STICKER (BLACK)		1 PC	30.00	NNX
42 FRONT DOOR PILLAR LH		1 PC	180.00	SVC
43 REAR DOOR LH		1 PC	320.00	DT
44 REAR DOOR HINGE TOP LH		1 PC	35.00	SVC
45 REAR DOOR HINGE LOWER		1 PC	35.00	SVC
46 REAR DOOR CHECKER		1 PC	60.00	SVC
47 REAR DOOR PROTECTOR		1 PC	25.00	
48 REAR DOOR PROTECTOR CHROME MOULDING		1 PC	10.00	CUT
49 REAR DOOR RUBBER (AT DOOR)		1 PC	50.00	NNX
50 REAR DOOR INNER LOCK		1 PC	170.00	SVC
51 REAR DOOR POWER WINDOW MOTOR		1 PC	160.00	NN
52 REAR DOOR POWER WINDOW REGULATOR		1 PC	75.00	NN
53 REAR DOOR OUTER HANDLE		1 PC	25.00	BT
54 REAR DOOR OUTER HANDLE SMALL COVER		1 PC	12.00	
55 SIDE SKIRT LH		1 PC	250.00	
56 SIDE SKIRT CLIPS X 10		10 PC	25.00	
57 REAR BUMPER		1 PC	165.00	NN
58 REAR BUMPER SIDE RETAINER LH		1 PC	22.00	
59 REAR BUMPER CLIPS X 10		10 PC	10.00	
60 FRONT WINDSCREEN MOULDING TOP		1 PC	45.00	
61 FRONT WHEEL BEARING LH		1 PC	35.00	NEC
62 FRONT WHEEL HUB LH		1 PC	95.00	NEC
63 FRONT KNUCKLE ARM LH		1 PC	170.00	BT
64 FRONT LOWER ARM LH		1 PC	90.00	BT
65 FRONT STABILISER BAR		1 PC	115.00	NNX
66 FRONT STABILISER LINKAGE LH		1 PC	55.00	BT
67 FRONT STABILISER LINKAGE RH		1 PC	55.00	
68 FRONT DRIVE SHAFT LH		1 PC	460.00	SVC
69 FRONT STEERING RACK		1 PC	550.00	
70 FRONT TIE ROD LH - CHECK PRICE		1 PC	0.0000	
71 FRONT TIE ROD END BALL JOINT LH		1 PC	40.00	
72 FRONT SHOCK ABSORBER LH		1 PC	120.00	JM
73 FRONT SHOCK ABSORBER TOP MOUNTING LH		1 PC	55.00	BT
74 FRONT SHOCK ABSORBER DAMPER LH		1 PC	10.00	NEC
75 FRONT ABS SENSOR LH		1 PC	145.00	DM
76 FRONT CROSSMEMBER		1 PC	700.00	NNX
77 FRONT LOWER ARM BALL JOINT LH		1 PC	65.00	CUT



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 63382522
 ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

Your Ref No: S8M00FTP
 Claim Type: Own Damage
 Accident Date: 30/04/2018

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
				7,572.00

Special Nett

78	COOLANT	1 PC	X 30.00	30.00
79	TYRE LHF & LHR - CHECK PRICE	2 PC	1 PC cut 0.0000	0.00
80	SPORT RIM LHF & LHR - CHECK PRICE	2 PC	1 PC 0.0000	0.00
81	INNER SEAL	1 PC	20.00	20.00
82	SEALANT	1 PC	X 40.00	40.00
				90.00
				560

LABOUR

83	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	30
84	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	NN
85	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	1
86	LABOUR TO REMOVE & REFIT FRONT WINDSCREEN	1 EA	120.00	100
87	TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 PC	280.00	NN
88	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.(2 DOORS)	1 PC	120.00	1
89	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	80
90	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	350.00	200
91	TO REMOVE AND REINSTALL REAR BUMPER SENSORS.	1 PC	60.00	NN
92	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	280.00	NN
93	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL,FRONT WHEELHOUSE PANEL LH,FRONT DOOR PILLAR LH. TO KNOCK & REPAIR FRONT FENDER RH,ROCKER PANEL LH, CENTER DOOR PILLAR LH, REAR FENDER LH	1 PC	1,600.00	1200
94	TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH & RH,RADIATOR SUPPORT PANEL,FRONT WHEELHOUSE PANEL LH,FRONT DOOR LH,REAR DOOR LH,SIDE SKIRT LH,FRONT DOOR PILLAR LH,ROCKER PANEL LH,CENTER PILLAR LH, REAR FENDER LH,REAR BUMPER, SIDE MIRROR LH	1 PC	1,800.00	1600



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
				5,010.00
				12,736.00
			Amount Before Excess	SS 12,672.00
			Add GST @ 7%	887.04
			Total Amount payable	SS 13,559.04

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED FIFTY NINE AND CENTS FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



[Handwritten signature]
13/6/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Report
No excess claim
LKK Auto (MA)
App Repair
Before paint work
10 w/days

14526



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST: M9-0009639-E RCB NO: 06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Your Ref No: S8M00FTP
Claim Type: Own Damage
Accident Date: 30/04/2018

Estimate No: MC0913082

Date: 06 Jun 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost S\$	Amount S\$
-------------	---------	----------	-------------	---------------

Supplementary Parts to Repair

SPARE PARTS

- 1 STABILIZER BAR BUSH
- 2 DOOR GLASS MOULDING
- 3 DOOR HANDLE GASKET

BT
OL
MCL

2 PC	30.00	A
1 PC	30.00	A
1 PC	4.00	A

64.00

Gino Q. A.
LKK
07/6/18

Amount Before Excess	S\$ 64.00
GST Amount	S\$ 4.48
Total Amount payable	S\$ 68.48

The above vehicle was surveyed by LKK - MR MA on 15/05/2018

For AH LIM MOTOR COMPANY

AUTHORIZED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

car and workshop

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
SPARE PARTS				
1 FRONT BONNET		1 PC	210.00	
2 FRONT BONNET HINGE LH		1 PC	X 25.00	
3 FRONT BONNET HINGE RH		1 PC	X 25.00	
4 FRONT BONNET INSULATOR CLIPS X 10		10 PC	X 15.00	
5 FRONT BONNET INNER LOCK		1 PC	X 30.00	
6 HEADLAMP LH		1 PC	130.00	
7 HEADLAMP RH		1 PC	X 130.00	
8 FRONT BUMPER		1 PC	160.00	
9 FRONT BUMPER SIDE RETAINER LH		1 PC	25.00	
10 FRONT BUMPER SIDE RETAINER RH		1 PC	X 25.00	
11 FRONT BUMPER CLIPS X 15		15 PC	15.00	
12 FRONT BUMPER REINFORCEMENT		1 PC	X 110.00	
13 FRONT FENDER LH		1 PC	120.00	
14 FRONT FENDER COWLING LH		1 PC	40.00	
15 FRONT FENDER COWLING CLIPS X 8		8 PC	8.00	
16 FRONT FENDER VVTI LOGO		1 PC	15.00	
17 FRONT FENDER TOP QUARTER GARNISH LH		1 PC	15.00	
18 RADIATOR SUPPORT PANEL		1 PC	X 180.00	
19 FRONT WHEELHOUSE PANEL LH		1 PC	X 150.00	
20 SIDE MIRROR ASSY LH		1 PC	240.00	
21 SIDE MIRROR COVER LH		1 PC	22.00	
22 AIR DUCT		1 PC	X 48.00	
23 RESONATOR TANK		1 PC	X 60.00	
24 FUSE & RELAY BOX TOP HOUSING		1 PC	X 40.00	
25 FUSE & RELAY BOX LOWER HOUSING		1 PC	X 45.00	
26 FRONT DOOR LH		1 PC	380.00	
27 FRONT DOOR HINGE TOP		1 PC	35.00	
28 FRONT DOOR HINGE BOTTOM		1 PC	35.00	
29 FRONT DOOR CHECKER		1 PC	60.00	
30 FRONT DOOR PROTECTOR		1 PC	35.00	
31 FRONT DOOR PROTECTOR CHROME MOULDING		1 PC	15.00	
32 FRONT DOOR RUBBER (AT DOOR)		1 PC	68.00	
33 FRONT DOOR RUBBER (AT BODY)		1 PC	X 140.00	
34 FRONT DOOR INNER LOCK		1 PC	165.00	
35 FRONT DOOR POWER WINDOW MOTOR		1 PC	155.00	
36 FRONT DOOR POWER WINDOW REGULATOR		1 PC	55.00	
37 FRONT DOOR INNER TRIMBOARD - CHECK PRICE		1 PC	X 0.0000	
38 FRONT DOOR OUTER HANDLE		1 PC	25.00	
39 FRONT DOOR OUTER HANDLE SMALL COVER		1 PC	12.00	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmco@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			SS	SS
40 FRONT DOOR OUTER LOCK CYLINDER / DM		1 PC	X 45.00	45.00
41 FRONT DOOR STICKER (BLACK)		1 PC	X 30.00	30.00
42 FRONT DOOR PILLAR LH		1 PC	X 180.00	180.00
43 REAR DOOR LH		1 PC	X 320.00	320.00
44 REAR DOOR HINGE TOP LH		1 PC	X 35.00	35.00
45 REAR DOOR HINGE LOWER		1 PC	X 35.00	35.00
46 REAR DOOR CHECKER		1 PC	X 60.00	60.00
47 REAR DOOR PROTECTOR		1 PC	X 25.00	25.00
48 REAR DOOR PROTECTOR CHROME MOULDING		1 PC	X 10.00	10.00
49 REAR DOOR RUBBER (AT DOOR)		1 PC	X 50.00	50.00
50 REAR DOOR INNER LOCK		1 PC	X 170.00	170.00
51 REAR DOOR POWER WINDOW MOTOR		1 PC	X 160.00	160.00
52 REAR DOOR POWER WINDOW REGULATOR		1 PC	X 75.00	75.00
53 REAR DOOR OUTER HANDLE		1 PC	X 25.00	25.00
54 REAR DOOR OUTER HANDLE SMALL COVER		1 PC	X 12.00	12.00
55 SIDE SKIRT LH		1 PC	X 250.00	250.00
56 SIDE SKIRT CLIPS X 10		10 PC	X 25.00	25.00
57 REAR BUMPER		1 PC	X 165.00	165.00
58 REAR BUMPER SIDE RETAINER LH		1 PC	X 22.00	22.00
59 REAR BUMPER CLIPS X 10		10 PC	X 10.00	10.00
60 FRONT WINDSCREEN MOULDING TOP		1 PC	X 45.00	45.00
61 FRONT WHEEL BEARING LH		1 PC	X 35.00	35.00
62 FRONT WHEEL HUB LH		1 PC	X 95.00	95.00
63 FRONT KNUCKLE ARM LH		1 PC	X 170.00	170.00
64 FRONT LOWER ARM LH		1 PC	X 90.00	90.00
65 FRONT STABILISER BAR		1 PC	X 115.00	115.00
66 FRONT STABILISER LINKAGE LH / BT		1 PC	X 35.00	35.00
67 FRONT STABILISER LINKAGE RH		1 PC	X 55.00	55.00
68 FRONT DRIVE SHAFT LH		1 PC	X 460.00	460.00
69 FRONT STEERING RACK		1 PC	X 550.00	550.00
70 FRONT TIE ROD LH - CHECK PRICE		1 PC	X 0.0000	0.0000
71 FRONT TIE ROD END BALL JOINT LH		1 PC	X 40.00	40.00
72 FRONT SHOCK ABSORBER LH		1 PC	X 120.00	120.00
73 FRONT SHOCK ABSORBER TOP MOUNTING LH		1 PC	X 55.00	55.00
74 FRONT SHOCK ABSORBER DAMPER LH		1 PC	X 10.00	10.00
75 FRONT ABS SENSOR LH / DM		1 PC	X 145.00	145.00
76 FRONT CROSSMEMBER		1 PC	X 700.00	700.00
77 FRONT LOWER ARM BALL JOINT LH		1 PC	X 65.00	65.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO-06470300B

M/S: AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 63382522
 ATTN: Motor Claim Department

Your Ref No: S8M00FTP
 Claim Type: Own Damage
 Accident Date: 30/04/2018

Estimate No: MC0913082
 Date: 10 May 2018
 Policy No: GA112171
 Veh Reg No: SJR6903S
 Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost SS	Amount SS
				7,572.00

Special Nett

78 COOLANT		1 PC	X 30.00	
79 TYRE LHF & LHR - CHECK PRICE	FRONT only cut / d/c	2 PC	0.0000	80%
80 SPORT RIM LHF & LHR - CHECK PRICE		2 PC	8.0000	
81 INNER SEAL		1 PC	20.00	
82 SEALANT		1 PC	X 40.00	
				90.00

LABOUR

83 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	30
84 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	X
city 85 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	100
86 LABOUR TO REMOVE & REFIT FRONT WINDSCREEN	1 EA	120.00	X
87 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 PC	280.00	X
88 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.(2 DOORS)	1 PC	120.00	✓
89 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	130.00	80
90 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	350.00	200
91 TO REMOVE AND REINSTALL REAR BUMPER SENSORS.	1 PC	60.00	X
92 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	280.00	X
93 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL,FRONT WHEELHOUSE PANEL LH,FRONT DOOR PILLAR LH. TO KNOCK & REPAIR FRONT FENDER RH,ROCKER PANEL LH, CENTER DOOR PILLAR LH, REAR FENDER LH	1 PC	1600.00	1200
94 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH & RH,RADIATOR SUPPORT PANEL,FRONT WHEELHOUSE PANEL LH,FRONT DOOR LH,REAR DOOR LH,SIDE SKIRT LH,FRONT DOOR PILLAR LH,ROCKER PANEL LH,CENTER PILLAR LH, REAR FENDER LH,REAR BUMPER, SIDE MIRROR LH	1 PC	1800.00	1600



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmo@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913082

Date: 10 May 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Estimate Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
				5,010.00

Amount Before Excess SS 12,672.00

Add GST @ 7% 887.04

Total Amount payable SS 13,559.04

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED FIFTY NINE AND CENTS FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



Revert

No
EXCESS Nil
LKE Auto (MA)

PIP Repair
Before paint work
10 working days

6399



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18008665/Dsbe2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN : KITTY TEO

Date : 23-11-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJR 6903S
Policy No.	GA112171	Coverage (\$)	0.00
Claim No.	S8M00FTP	Excess (\$)	0.00
Assign From	KITTY TEO	Assign Date	11/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053ZEE106149248	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	YOKOHAMA	8 mm
L/H Front Tyre	205/50 R16	YOKOHAMA	8 mm
R/H Rear Tyre	205/50 R16	YOKOHAMA	8 mm
L/H Rear Tyre	205/50 R16	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/04/2018	Inspection Date	15/05/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE MARKET VALUE IS S\$17,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 6903S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET (CONSISTENT)	DENTED	210.00	210.00
1	FRONT BONNET HINGE LH (CONSISTENT)	SERVICEABLE	25.00	-
1	FRONT BONNET HINGE RH (CONSISTENT)	SERVICEABLE	25.00	-
10	FRONT BONNET INSULATOR CLIPS (CONSISTENT)	NOT NECESSARY	15.00	-
1	FRONT BONNET INNER LOCK (CONSISTENT)	NOT NECESSARY	30.00	-
1	HEADLAMP LH (CONSISTENT)	BROKEN	130.00	130.00
1	HEADLAMP RH (CONSISTENT)	NOT NECESSARY	130.00	-
1	FRONT BUMPER (CONSISTENT)	CUT	160.00	160.00
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	BROKEN	25.00	25.00
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	25.00	-
15	FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	15.00	15.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	110.00	-
1	FRONT FENDER LH (CONSISTENT)	CRUMPLED	120.00	120.00
1	FRONT FENDER COWLING LH (CONSISTENT)	CUT	40.00	40.00
8	FRONT FENDER COWLING CLIPS (CONSISTENT)	NECESSARY	8.00	8.00
1	FRONT FENDER VVTI LOGO (CONSISTENT)	NECESSARY	15.00	15.00
1	FRONT FENDER TOP QUARTER GARNISH LH (CONSISTENT)	CRACKED	15.00	15.00
1	RADIATOR SUPPORT PANEL (CONSISTENT)	SERVICEABLE	180.00	-
1	FRONT WHEELHOUSE PANEL LH (CONSISTENT)	SERVICEABLE	150.00	-
1	SIDE MIRROR ASSY LH (CONSISTENT)	BROKEN	240.00	240.00
1	SIDE MIRROR COVER LH (CONSISTENT)	BROKEN	22.00	22.00
1	AIR DUCT (CONSISTENT)	SERVICEABLE	48.00	-
1	RESONATOR TANK (CONSISTENT)	CRACKED	60.00	60.00
1	FUSE & RELAY BOX TOP HOUSING (CONSISTENT)	SERVICEABLE	40.00	-
1	FUSE & RELAY BOX LOWER HOUSING (CONSISTENT)	SERVICEABLE	45.00	-
1	FRONT DOOR LH (CONSISTENT)	DISTORTED	380.00	380.00
1	FRONT DOOR HINGE TOP (CONSISTENT)	BENT	35.00	35.00
1	FRONT DOOR HINGE BOTTOM (CONSISTENT)	BENT	35.00	35.00
1	FRONT DOOR CHECKER (CONSISTENT)	BROKEN	60.00	60.00
1	FRONT DOOR PROTECTOR (CONSISTENT)	CUT	35.00	35.00

Report Ref No. CS/ASM18008665/Dsbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR PROTECTOR CHROME MOULDING (CONSISTENT)	CUT	15.00	15.00
1	FRONT DOOR RUBBER (AT DOOR) (CONSISTENT)	NOT NECESSARY	68.00	-
1	FRONT DOOR RUBBER (AT BODY) (CONSISTENT)	SERVICEABLE	140.00	-
1	FRONT DOOR INNER LOCK (CONSISTENT)	JAMMED	165.00	165.00
1	FRONT DOOR POWER WINDOW MOTOR (CONSISTENT)	SERVICEABLE	155.00	-
1	FRONT DOOR POWER WINDOW REGULATOR (CONSISTENT)	SERVICEABLE	55.00	-
1	FRONT DOOR INNER TRIMBOARD (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	FRONT DOOR OUTER HANDLE (CONSISTENT)	BENT	25.00	25.00
1	FRONT DOOR OUTER HANDLE SMALL COVER (CONSISTENT)	JAMMED	12.00	12.00
1	FRONT DOOR OUTER LOCK CYLINDER (CONSISTENT)	DAMAGED / BENT	45.00	40.00
1	FRONT DOOR STICKER (BLACK) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT DOOR PILLAR LH (CONSISTENT)	SERVICEABLE	180.00	-
1	REAR DOOR LH (CONSISTENT)	DENTED	320.00	320.00
1	REAR DOOR HINGE TOP LH (CONSISTENT)	SERVICEABLE	35.00	-
1	REAR DOOR HINGE LOWER (CONSISTENT)	SERVICEABLE	35.00	-
1	REAR DOOR CHECKER (CONSISTENT)	SERVICEABLE	60.00	-
1	REAR DOOR PROTECTOR (CONSISTENT)	CUT	25.00	25.00
1	REAR DOOR PROTECTOR CHROME MOULDING (CONSISTENT)	CUT	10.00	10.00
1	REAR DOOR RUBBER (AT DOOR) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR DOOR INNER LOCK (CONSISTENT)	SERVICEABLE	170.00	-
1	REAR DOOR POWER WINDOW MOTOR (CONSISTENT)	NOT NECESSARY	160.00	-
1	REAR DOOR POWER WINDOW REGULATOR (CONSISTENT)	NOT NECESSARY	75.00	-
1	REAR DOOR OUTER HANDLE (CONSISTENT)	BENT	25.00	25.00
1	REAR DOOR OUTER HANDLE SMALL COVER (CONSISTENT)	NOT NECESSARY	12.00	-
1	SIDE SKIRT LH (CONSISTENT)	NOT NECESSARY	250.00	-
10	SIDE SKIRT CLIPS (CONSISTENT)	NOT NECESSARY	25.00	-
1	REAR BUMPER (CONSISTENT)	NOT NECESSARY	165.00	-
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	NOT NECESSARY	22.00	-
10	REAR BUMPER CLIPS (CONSISTENT)	NOT NECESSARY	10.00	-

Report Ref No. CS/ASM18008665/Dsbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN MOULDING TOP (CONSISTENT)	NOT NECESSARY	45.00	-
1	FRONT WHEEL BEARING LH (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT WHEEL HUB LH (CONSISTENT)	NECESSARY	95.00	95.00
1	FRONT KNUCKLE ARM LH (CONSISTENT)	BENT	170.00	170.00
1	FRONT LOWER ARM LH (CONSISTENT)	BENT	90.00	90.00
1	FRONT STABILISER BAR (CONSISTENT)	NOT NECESSARY	115.00	-
1	FRONT STABILISER LINKAGE LH (CONSISTENT)	BENT	55.00	55.00
1	FRONT STABILISER LINKAGE RH (CONSISTENT)	SERVICEABLE	55.00	-
1	FRONT DRIVE SHAFT LH (CONSISTENT)	SERVICEABLE	460.00	-
1	FRONT STEERING RACK (CONSISTENT)	SERVICEABLE	550.00	-
1	FRONT TIE ROD LH (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	FRONT TIE ROD END BALL JOINT LH (CONSISTENT)	SERVICEABLE	40.00	-
1	FRONT SHOCK ABSORBER LH (CONSISTENT)	JAMMED	120.00	120.00
1	FRONT SHOCK ABSORBER TOP MOUNTING LH (CONSISTENT)	BENT	55.00	55.00
1	FRONT SHOCK ABSORBER DAMPER LH (CONSISTENT)	NECESSARY	10.00	10.00
1	FRONT ABS SENSOR LH (CONSISTENT)	DAMAGED	145.00	145.00
1	FRONT CROSSMEMBER (CONSISTENT)	NOT NECESSARY	700.00	-
1	FRONT LOWER ARM BALL JOINT LH (CONSISTENT)	CUT	65.00	65.00
2	STABILIZER BAR BUSH (ADDITIONAL) (CONSISTENT)	BENT	30.00	30.00
1	DOOR GLASS MOULDING (ADDITIONAL) (CONSISTENT)	DEFORMED	30.00	30.00
1	DOOR HANDLE GASKET (ADDITIONAL) (CONSISTENT)	NECESSARY	4.00	4.00
			7,636.00	3,146.00
	SPECIAL NETT ITEMS			
1	COOLANT (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	TYRE LHF & LHR (SN) (80%) (CONSISTENT)	FRONT CUT / DISTORTED	150.00	120.00
2	SPORT RIM LHF & LHR (SN) (CONSISTENT)	CUT-1PC ONLY	640.00	320.00
1	INNER SEAL (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SEALANT (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
			880.00	440.00

Report Ref No. CS/ASM18008665/Dsbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	30.00
	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	NOT NECESSARY	100.00	-
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		80.00	80.00
	LABOUR TO REMOVE & REFIT FRONT WINDSCREEN.		120.00	100.00
	TO REMOVE AND REINSTALL / REPLACE DASHBOARD.	NOT NECESSARY	280.00	-
	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR / FACILITATE REPAIR. (2 DOORS)		120.00	120.00
	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		180.00	80.00
	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.		350.00	200.00
	TO REMOVE AND REINSTALL REAR BUMPER SENSORS.	NOT NECESSARY	60.00	-
	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT.	NOT NECESSARY	280.00	-
	TO DISMANTLE ALL DAMAGED PARTS, TO CUT & WELD RADIATOR SUPPORT PANEL, FRONT WHEEL HOUSE PANEL LH, FRONT DOOR PILLAR LH, TO KNOCK & REPAIR FRONT FENDER RH, ROCKER PANEL LH, CENTER DOOR PILLAR LH, REAR FENDER LH.		1,600.00	1,200.00
	TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL, FRONT WHEELHOUSE PANEL LH, FRONT DOOR LH, REAR DOOR LH, SIDE SKIRT LH, FRONT DOOR PILLAR LH, ROCKER PANEL LH, CENTER PILLAR LH, REAR FENDER LH, REAR BUMPER, SIDE MIRROR LH.		1,800.00	1,600.00
			-	-
			-	-
			5,010.00	3,410.00
	GRAND TOTAL		13,526.00	6,996.00
RECOMMENDED COST OF REPAIRS				6,996.00

Report Ref No. CS/ASM18008665/Dsbe2



Report Ref No. CS/ASM18008665/Dsbe2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.