



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0913082

Final No: AL0929229

Date: 20 Nov 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Tax Invoice-Final Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT BONNET		1 PC	210.00	
2 HEADLAMP LH		1 PC	130.00	
3 FRONT BUMPER		1 PC	160.00	
4 FRONT BUMPER SIDE RETAINER LH		1 PC	25.00	
5 FRONT BUMPER CLIPS		15 PC	15.00	
6 FRONT FENDER LH		1 PC	120.00	
7 FRONT FENDER COWLING LH		1 PC	40.00	
8 FRONT FENDER COWLING CLIPS X 8		8 PC	8.00	
9 FRONT FENDER VVTI LOGO		1 PC	15.00	
10 FRONT FENDER TOP QUARTER GARNISH LH		1 PC	15.00	
11 SIDE MIRROR ASSY LH		1 PC	240.00	
12 SIDE MIRROR COVER LH		1 PC	22.00	
13 RESONATOR TANK		1 PC	60.00	
14 FRONT DOOR LH		1 PC	380.00	
15 FRONT DOOR HINGE TOP		1 PC	35.00	
16 FRONT DOOR HINGE BOTTOM		1 PC	35.00	
17 FRONT DOOR CHECKER		1 PC	60.00	
18 FRONT DOOR PROTECTOR		1 PC	35.00	
19 FRONT DOOR PROTECTOR CHROME MOULDING		1 PC	15.00	
20 FRONT DOOR INNER LOCK		1 PC	165.00	
21 FRONT DOOR OUTER HANDLE		1 PC	25.00	
22 FRONT DOOR OUTER HANDLE SMALL COVER		1 PC	12.00	
23 FRONT DOOR OUTER LOCK CYLINDER		1 PC	40.00	
24 REAR DOOR LH		1 PC	320.00	
25 REAR DOOR PROTECTOR		1 PC	25.00	
26 REAR DOOR PROTECTOR CHROME MOULDING		1 PC	10.00	
27 REAR DOOR OUTER HANDLE		1 PC	25.00	
28 FRONT WHEEL BEARING LH		1 PC	35.00	
29 FRONT WHEEL HUB LH		1 PC	95.00	
30 FRONT KNUCKLE ARM LH		1 PC	170.00	
31 FRONT LOWER ARM LH		1 PC	90.00	
32 FRONT STABILISER LINKAGE LH		1 PC	55.00	
33 FRONT SHOCK ABSORBER LH		1 PC	120.00	
34 FRONT SHOCK ABSORBER TOP MOUNTING LH		1 PC	55.00	
35 FRONT SHOCK ABSORBER DAMPER LH		1 PC	10.00	
36 FRONT ABS SENSOR LH		1 PC	145.00	
37 FRONT LOWER ARM BALL JOINT LH		1 PC	65.00	
38 STABILIZER BAR BUSH		2 PC	30.00	
39 DOOR GLASS MOULDING		1 PC	30.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Claim No: MC0913082
Final No: AL0929229
Date: 20 Nov 2018
Policy No: GA112171
Veh Reg No: SJR6903S
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: S8M00FTP
Claim Type: Own Damage
Accident Date: 30/04/2018

Tax Invoice-Final Repair Cost to Vehicle No :SJR6903S

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
40 DOOR HANDLE GASKET		1 PC	4.00	3,146.00
Special Nett				
41 TYRE LHF (80% OF 150)		1 PC	120.00	
42 SPORT RIM LHF & LHR		2 PC	320.00	440.00
LABOUR				
43 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	30.00	
44 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	80.00	
45 LABOUR TO REMOVE & REFIT FRONT WINDSCREEN		1 EA	100.00	
46 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.(2 DOORS)		1 PC	120.00	
47 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	80.00	
48 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.		1 PC	200.00	
49 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL,FRONT WHEELHOUSE PANEL LH,FRONT DOOR PILLAR LH. TO KNOCK & REPAIR FRONT FENDER RH,ROCKER PANEL LH, CENTER DOOR PILLAR LH, REAR FENDER LH		1 PC	1,200.00	
50 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH & RH,RADIATOR SUPPORT PANEL,FRONT WHEELHOUSE PANEL LH,FRONT DOOR LH,REAR DOOR LH,SIDE SKIRT LH,FRONT DOOR PILLAR LH,ROCKER PANEL LH,CENTER PILLAR LH, REAR FENDER LH,REAR BUMPER, SIDE MIRROR LH		1 PC	1,600.00	3,410.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0913082

Final No: AL0929229

Date: 20 Nov 2018

Policy No: GA112171

Veh Reg No: SJR6903S

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Your Ref No: S8M00FTP

Claim Type: Own Damage

Accident Date: 30/04/2018

Tax Invoice-Final Repair Cost to Vehicle No :SJR6903S

Amount Before Excess	S\$ 6,996.00
Less Excess	S\$ 0.00
Amount Before GST	S\$ 6,996.00
Add GST @ 7%	489.72
Total Amount payable	S\$ 7,485.72

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED EIGHTY FIVE AND CENTS SEVENTY TWO ONLY

The above vehicle was surveyed by LKK - MR MA on 15/05/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047

E. & O. E.

AUTHORISED SIGNATURE 6483 6170