

T1+2V



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 11.05.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLN827BK TOYOTA AXIO HYBRID (2016)

To Supply

1) 1pc	Rear bumper	\$	700.00	DE
2) 1set	Rear bumper clip	\$	30.00	one
3) 1pc	Rear bumper left side retainer	\$	60.00	one
4) 1pc	Rear bumper left side reflector	\$	95.00	? x su
5) 1pc	Rear left tail lamp	\$	450.00	? x su
6) 1pc	Left tail lamp lower bracket	\$	70.00	? x su
7) 1pc	Left tail lamp housing	\$	285.60	R x su

Sub total Parts	\$	1,690.60	790.00
Less: 25% discount	\$	422.65	-197.50
	\$	1,267.95	592.50

To Supply S. Nett Parts

1) 1set Reverse sensor	\$	180.00	?
Sub total S. Nett Parts	\$	180.00	X su

L/charges

1)	To remove & refit reverse sensor & sensor cover. Check wiring	\$	40.00	/
2)	To remove rear bumper, knock / welding rear boot lid & rear end panel. Replace rear bumper, rear left side retainer & rear bumper left side reflector. Align & adjust rear bumper	\$	500.00	For

3) To putty, respray painting rear bumper, rear end panel & rear boot lid. To polish

\$ ~~600.00~~ 500

Sub total L/charges	\$ 1,140.00	940.00
Estimated Grand Total	\$ 2,587.95	1532.50
		- 306.50
		1226.00

less: 20% LS

Paul

HP 90010068

4 days

LS

11/05/18 @ 1050

Resurvey after repair

LS 1200/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date: