



**ESTEEM PERFORMANCE PTE LTD**

Blk 5039 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemp.com.sg

**Repair Estimates**

SLN 5172 M

<b>Parts</b>	(a) Cost / List Price Items	\$	<u>2,994.20</u>
	Plus/Less <u>25%</u>	\$	<u>748.55</u>
	<b>Total of Cost / List</b>	\$	<u><u>2,245.65</u></u>
	(b) Nett Price Items		_____
	Less _____		_____
	<b>Total of Nett Item</b>		_____
	(c) Special Nett Items	\$	<u>50.00</u>
<b>Total Parts Cost</b>		\$	<u><u>2,295.65</u></u>
<b>Labour</b>		\$	<u><u>1,620.00</u></u>
<b>Total</b>		\$	<u><u>3,915.65</u></u>

*Not Authorized  
1-B-1  
Recovery By paint*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : \_\_\_\_\_  
 Company : \_\_\_\_\_  
 Survey conducted on : 11/5/18 at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 11/5/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

### Spare Parts

Vehicle No. :	<b>SLN 5172 M</b>	Submit By :	<b>Carmen Lim</b>
Make & Model :	TOYOTA PRIUS	Year Manufacture :	2017
Chassis No. :	JTDKB3FU503557774	Engine No. :	

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		?
3	Rear bumper clip	10	\$40.00		?
4	Rear bumper side retainer LH <i>Sn</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>Sn</i>	1	\$112.70		X
6	Rear bumper reinforcement <i>K</i>	1	\$398.90		X
7	Rear bumper lower garnish centre <i>nd</i>	1	\$582.60		✓
8	Rear bumper lower garnish RH <i>my m</i>	1	\$149.70		✓
9	Rear bumper tow cover <i>his</i>	1	\$31.70		✓
10	Rear bumper under cover <i>Sn</i>	1	\$355.20		X
11	Rear bumper under cover RH <i>Sn</i>	1	\$187.60		X
12	Rear bumper under cover clip <i>~</i>	4	\$14.00		X
13	Tail lamp RH - LOWER	1	\$511.60		?
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

