

22/03/2002

ASS. REC. BY:

REF: CS / CT218008674 / Ktbn2 | Special Instruction:

ASSIGNMENT (Office)

SUNVIAJY
Mentor

From (Person):

Elaine Cheong

of

CTL

Date/Time:

11/05/2018 3:33pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 680U

Insured:

SCP 1718L

at Workshop m/s:

Ah Lim Motor

Tel:

6483 1244

of

81K 10 AMK Ind Park 2A #01-09

Policy No:

2MPCSN1407191804

Claim No:

SNM18D02861C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09052018

CA / REV / REP. / REV 24 HRS wpi

15/05/2018 @ 10:30am

H.O.D. Endorsement:

Date/Time:

11/05/2018 4:12pm

Person Contacted:

Wei Jie

Vehicle IN

OUT

Date/Time	Action/Instruction (☒) Estimate
	SKZ 680U - X
	SCP 1718L - X
4/7/8	83933-76 Confirm (red. 2017.20, 33%)

ASS. REC. BY:

REF: 072 /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____ Sh Lm

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1. B. 1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKZ 6804 Yr Regn: 01. 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Honda City c.c. 14P7

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 65182 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHGM 6660GP 800337

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / RIM or

Tyre Size: F: 185 / 55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 9/5/18 D.O.I. 15/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/5 File new to Customer

Date/Time, File Pass to?

1) 7/8 Typist

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B.L. (\$) 3933.76

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 May 2018		11 May 2018 15:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured:	ZULKIFLI BIN IBRAHIM, ID: S1538725D			
Main Claimant:	BACK PETER JAMES, ID: S2704261I			
Vehicle Reg. No.:	SKZ680U	Date of Loss:	09/05/2018 07:00 - :59	
Claim Type:	TP / SNM18D02361C02	Policy/Cover Note No.:	DMPCSN1407191804 (Comprehensive)	
Vehicle Reg. No. (Insured):	SCP1718L	Policy No. (Claimant):	18-MU000088	
		Excess:	S\$0.00	
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]			
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/05/2018]			
Driver/Custodian (Insured):	ZULKIFLI BIN IBRAHIM (55 / Male), NRIC: S1538725D			
Adj Asg. Remarks:	EST \$6367.53, ASSIGN XING GUO QIANG AS SJE.			
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail	
There are no mail for this case.				
ALL ASSOCIATED TASKS Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done? View All Search Tasks Create New Task Complete				
No results.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4261I

Vehicle Details

Vehicle No.: SKZ680U
Vehicle to be Exported: No
Intended De-registration Date: 09 May 2018
Vehicle Make: HONDA
Vehicle Model: CITY 1.5 SV CVT
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: L15Z12716668
Chassis No.: MRHGM6660GP000337
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$17,998.00
Original Registration Date: 07 Jan 2016
First Registration Date: 07 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$12,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 06 Jan 2026
PARF Rebate Amount: \$9,748.00

Intended COE Rebate Details

COE Expiry Date: 06 Jan 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$59,200.00
COE Rebate Amount: \$45,338.00
Total Rebate Amount: \$55,086.00

The information contained herein is correct as at 09 May 2018

OK



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : BACK PETER JAMES
BLK 209 SERANGOON CENTRAL
#04-280
SINGAPORE 550209

Estimate No: MC0913083
Date: 10 May 2018
Policy No: 18-MU000088
Veh Reg No: SKZ680U
Make/Model: HONDA CITY 1.5 SV
CVT

ATTN:

Your Ref No: SKZ680U
Claim Type: Third Party
Accident Date: 09/05/2018
TP Veh Reg No: SCP1718L

*Not Authorized
1. B.1
Recovery B4 points
7 days*

Estimate Repair Cost to Vehicle No :SKZ680U

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT	1 PC	475.00	✓
2 REAR BOOT EMBLEM	1 PC	24.20	✓
3 REAR BOOT CITY LOGO	1 PC	11.30	✓
4 REAR BOOT IVTEC LOGO	1 PC	11.90	✓
5 REAR BOOT NO PLATE GARNISH	1 PC	98.50	X
6 REAR BOOT LAMP LH & RH	2 PC	145.60	X + 72.80
7 REAR BOOT RUBBER	1 PC	71.60	✓
8 REAR BOOT INNER LOCK	1 PC	89.90	X
9 TAILAMP LH & RH	2 PC	411.40	✓ + 205.70
10 REAR BUMPER	1 PC	463.70	✓
11 REAR BUMPER SIDE RETAINERS	2 PC	23.00	✓
12 REAR BUMPER CLIPS	15 PC	52.50	✓
13 REAR BUMPER REFLECTOR LH & RH	2 PC	29.60	X
14 REAR END PANEL	1 PC	323.90	✓
15 REAR END PANEL TOP GARNISH	1 PC	66.60	✓
16 SPARE TYRE PANEL	1 PC	399.70	X
17 SPARE TYRE PANEL TOP TRIM BOARD	1 PC	89.00	X ✓
18 REAR FENDER INNER TRIM LH & RH	2 PC	93.80	X
19 REAR FENDER INNER TRIM CLIPS	20 PC	70.00	X
		2,951.20	
	Less 20%	590.24	2,360.96
Special Nett			
20 REAR BUMPER REVERSE SENSOR CTR LH & RH	1 PC	200.00	X
21 REAR BUMPER REVERSE SENSOR SIDE LH & RH	1 PC	200.00	✓
		400.00	400.00
LABOUR			
22 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	200
23 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	150.00	800
24 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	80.00	500
25 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	120.00	600
26 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	120.00	600

AH LIM MOTOR CO.
BLK 10, ANG MO KIO INDUSTRIAL PARK 2A
#01-09, AMK AUTOPOINT
SINGAPORE 568047



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : BACK PETER JAMES
BLK 209 SERANGOON CENTRAL
#04-280
SINGAPORE 550209

Estimate No: MC0913083
Date: 10 May 2018
Policy No: 18-MU000088
Veh Reg No: SKZ680U
Make/Model: HONDA CITY 1.5 SV
CVT

ATTN:

Your Ref No: SKZ680U
Claim Type: Third Party
Accident Date: 09/05/2018
TP Veh Reg No: SCP1718L

Estimate Repair Cost to Vehicle No :SKZ680U

Description	Quantity	List Price	Amount
		SS	SS
27 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	60
28 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,SPARE TYRE PANEL.TO KNOCK & REPAIR REAR FENDER LH & RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,400.00	900
29 TO SPRAY REAR BOOT,REAR BUMPER,REAR FENDER LH & RH,END PANEL,SPARE TYRE PANEL.	1 PC	1,200.00	1000
		3,190.00	3,190.00
	Total		SS 5,950.96
	Add GST @ 7%		416.57
	Total Amount Payable		SS 6,367.53

TOTAL: SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED SIXTY SEVEN AND CENTS FIFTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY
AH LIM MOTOR CO.
BLK 10, ANG MO KIO INDUSTRIAL PARK 2A
#01-09, AMK AUTOPOINT
SINGAPORE 568047
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : BACK PETER JAMES
 BLK 209 SERANGOON CENTRAL
 #04-280
 SINGAPORE 550209

Claim No: MC0913083
 No: MF0911165
 Date: 27 Jul 2018
 Policy No: 18-MU000088
 Veh Reg No: SKZ680U
 Make/Model: HONDA CITY 1.5 SV
 CVT

ATTN:

Your Ref No: SNM18D02361
 Claim Type: Third Party
 Accident Date: 09/05/2018
 TP Veh Reg No: SCPI718L

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SKZ680U

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT	1 PC	475.00	
2 REAR BOOT EMBLEM	1 PC	24.20	
3 REAR BOOT CITY LOGO	1 PC	11.30	
4 REAR BOOT IVTEC LOGO	1 PC	11.90	
5 REAR BOOT LAMP LH	1 PC	72.80	
6 REAR BOOT RUBBER	1 PC	71.60	
7 TAILAMP LH	1 PC	205.70	
8 REAR BUMPER	1 PC	463.70	
9 REAR BUMPER SIDE RETAINERS LH	1 PC	11.50	
10 REAR BUMPER CLIPS	15 PC	52.50	
11 REAR END PANEL	1 PC	323.90	
12 REAR END PANEL TOP GARNISH	1 PC	66.60	
13 SPARE TYRE PANEL TOP TRIM BOARD	1 PC	89.00	
		1,879.70	
	Less 20%	375.94	1,503.76
Special Nett			
14 REAR BUMPER REVERSE SENSOR SIDE LH & RH		200.00	
		200.00	200.00
LABOUR			
15 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIPER SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
16 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	80.00	
17 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	50.00	
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	
19 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
20 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	60.00	
21 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL. TO KNOCK & REPAIR REAR FENDER LH & RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	900.00	
22 TO SPRAY REAR BOOT, REAR BUMPER, REAR FENDER LH & RH, END PANEL, SPARE TYRE PANEL.	1 PC	1,000.00	
		2,230.00	2,230.00

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Ind. Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : BACK PETER JAMES
BLK 209 SERANGOON CENTRAL
#04-280
SINGAPORE 550209

ATTN:

Your Ref No: SNM18D02361
Claim Type: Third Party
Accident Date: 09/05/2018
TP Veh Reg No: SCP1718L

Claim No: **MC0913083**
No: **MF0911165**
Date: 27 Jul 2018
Policy No: 18-MU000088
Veh Reg No: **SKZ680U**
Make/Model: HONDA CITY 1.5 SV

DRAFT FINALISY

Repair Cost to Vehicle No (For Finalization):SKZ680U

Description	Quantity	List Price	Amount
		SS	SS
		Total	SS 3,933.76
		Less Excess	SS 0.00
		Amount Before GST	SS 3,933.76
		Add GST @ 7%	275.36
		Total Amount Payable	SS 4,209.12

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWO HUNDRED AND NINE AND CENTS TWELVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 15/05/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18008674/KTBN2

Date: 14/08/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1407191804
Claimant Vehicle No :	SKZ680U	Insured Vehicle No :	SCP1718L
Date of Loss:	09/05/2018	Nature of Claim:	TP
		Claim No:	SNM18D02361C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ680U	Engine No:	L15Z12716668
Make & Model:	HONDA CITY, 1.5 SV CVT (A)	Chassis No:	MRHGM6660GP000337
Reg. Date:	07/01/2016 (Man. Year: 2015)	Odometer:	65192 km
Colour:	Metallic Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,760.96	1,703.76	1,057.20	38.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	2,230.00	960.00	30.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,950.96	3,933.76	2,017.20	33.90
+ GST 7.00/7.00% (S\$)	416.57	275.36	141.21	33.90
Nett Amount (S\$)	6,367.53	4,209.12	2,158.41	33.90

INSPECTION

Date of Assignment: 11/05/2018

Date Inspected: 15/05/2018 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Aug 2018)
Parts:	143	HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ680U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	475.00 FL	*475.00 FL
2	1		*REAR BOOT EMBLEM	Necessary	24.20 FL	*24.20 FL
3	1		*REAR BOOT CITY LOGO	Necessary	11.30 FL	*11.30 FL
4	1		*REAR BOOT IVTEC LOGO	Necessary	11.90 FL	*11.90 FL
5	1		*REAR BOOT NO PLATE GARNISH	Serviceable	98.50 FL	*- FL
6	1		*REAR BOOT LAMP LH & RH	N/s Cracked/O/s Serviceable	145.60 FL	*72.80 FL
7	1		*REAR BOOT RUBBER	Dented	71.60 FL	*71.60 FL
8	1		*REAR BOOT INNER LOCK	Repair	89.90 FL	*- FL
9	1		*TAILLAMP LH & RH	N/s Cracked	411.40 FL	*205.70 FL
10	1		*REAR BUMPER	Bent	463.70 FL	*463.70 FL
11	1		*REAR BUMPER SIDE RETAINERS	N/s Distorted	23.00 FL	*11.50 FL
12	15		*REAR BUMPER CLIPS	Necessary	52.50 FL	*52.50 FL
13	2		*REAR BUMPER REFLECTOR LH & RH	Serviceable	29.60 FL	*- FL
14	1		*REAR END PANEL	Bent	323.90 FL	*323.90 FL
15	1		*REAR END PANEL TOP GARNISH	Dented	66.60 FL	*66.60 FL
16	1		*SPARE TYRE PANEL	Repair	399.70 FL	*- FL
17	1		*SPARE TYRE PANEL TOP TRIM BOARD	Cracked	89.00 FL	*89.00 FL
18	2		*REAR FENDER INNER TRIM LH & RH	Serviceable	93.80 FL	*- FL
19	20		*REAR FENDER INNER TRIM CLIPS	Not Necessary	70.00 FL	*- FL
20	1		*REAR BUMPER REVERSE SENSOR CTR LH & RH	Serviceable	200.00 FS	*- FS
21	1		*REAR BUMPER REVERSE SENSOR SIDE LH & RH	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,351.20	2,079.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	590.24	375.94
Total Parts (\$\$)	2,760.96	1,703.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	80.00
3	TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	New	80.00	50.00
4	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	120.00	60.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	120.00	60.00
6	TO REALIGN,DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE	New	80.00	60.00
7	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,SPARE TYRE PANEL.TO KNOCK & REPAIR REAR FENDER LH & RH INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	1,400.00	900.00
8	TO SPRAY REAR BOOT,REAR BUMPER,REAR FENDER LH & RH,END PANEL,SPARE TYRE PANEL	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			3,190.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >