

recovery on 15/5/18

ASS. REC. BY:

REF: CS/ET/118008702/Sqber

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Yee Pei Li of ETL Date/Time: 11052018 358pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 2302X Insured: GT 967Y

at Workshop m/s Carz Auto Services Tel:

of No. 61 Woodlands Ind Park E9 # 04-04

Policy No: Claim No: GT967Y/SL/pl

Sum Insured: Excess:

Make of Veh: D.O.A. 10052018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLH 2302X - X
	GT 967Y - CCG/EG/16022996/KZB92 DCA: 021216
17/5/18 @ 11.00am	raised to Steve Lim by email
26/6/18 @ 2.41pm	confirmed with Alex LS \$9300, 11 days.
	OKed \$12409.40, 57%

recovery on 15/5/18

ASS. REC. BY:

REF: CS/E6118008702/Sq608

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Yee Pei Li of E61L Date/Time: 11052018 358pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 2501X Insured: GT 967Y

at Workshop m/s Carz Auto Services Tel:

of No. 61 Woodlands Ind Park E9 # 04-04

Policy No: Claim No: GT967Y/SL/pl

Sum Insured: Excess:

Make of Veh: D.O.A. 10052018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLH 2501X - X
	GT 967Y - CCG/E6116022986/KZG32 DA: 001216
17/5/18 @ 11.00am	raised to Steve Lim by email
26/6/18 @ 2.41pm	confirmed with Alex LS \$9300, 11 days.
	Cred \$12408.40, 57%

REF:

EG1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLH 2502Xat Workshop m/s Carz Autoof No. 61 Woodlands Ind Pk E9 #04-04

Insured:

Policy No:

Claims No:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH 2502X

Yr Regn:

27/10/2016Type M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda VezelC/C 1496Colour Brown

A/C Insured / Std / NI / NA

Sp. Reading 55846

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RN11203360Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt orModi: W / S/Rim / STD A/Rim orTyre Size: F: 215/60 R16R: 215/60 R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 10/5/2018D.O.I. 14/5/18Survey held at Carz AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sebastian,Pls check all parts prices.
24/5

RECEIVED 29 JUN 2018

Date/Time, File Pass to?

1) 29/6/2018

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 11

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ - R\$ - SI

) Photos

) Others

)

TOTAL

Report Format: TPLump Sum / B.I. (\$) 9300

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

350350

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 11 May, 2018 3:58 PM
To: 'admin-d@lkkauto.com'
Subject: OI : GT967Y / TP : SLH2502X/LKK / DOA : 10/05/2018
Attachments: GT967Y - SAS.pdf; SLH2502X - SAS.pdf; SLH2502X - ESTIMATE.pdf; SLH2502X - PRS FORM.pdf

Dear Ashley,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CARZ AUTO SERVICES PTE LTD**,

ADDRESS : NO 61 WOODLANDS INDUSTRIAL PARK E9
#04-04 E9 PREMIUM
SINGAPORE 757047

PERSON TO CONTACT : ALEX @ 9380 9969 / ALLAN @ 90236692 /6493 1924

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 10.05.2018
 Our Reference: GT 967Y/SL/pl
 Your Reference: SLH 2502X
 To: CARZ AUTO SERVICES

Sent via Fax 6493 1928
 or
 Email alex@carzauto.com.sg

Fax: 11/05/2018
 Mr. Steve Lim

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLH 2502X
 Insurer's Vehicle: GT 967Y
 Date Of Accident: 10.05.2018

We acknowledge receipt of your request for PRS on: 10.05.2018


In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK Auto

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	UKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our insured's driver has not reported the accident to us to date.
☒ Others: WORKSHOP CONTACT DETAILS NOT PROVIDED

OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei U	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX: 6829 9247</u>

Assessor use only:

Assignment Date: _____
 Assignment Time: _____

Remarks:

Workshop use only:Assessor attended workshop on:

Date: _____
 Time: _____
 Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 17 May 2018 11:06 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; 'Steve Lim'
Cc: SUR
Subject: RE: OI : GT967Y / TP : SLH2502X/LKK / DOA : 10/05/2018
Attachments: CSEGI180087125qb.pdf

Dear Steve,

Enclosed herewith preliminary advice of SLH 2502X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Friday, 11 May 2018 3:58 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: OI : GT967Y / TP : SLH2502X/LKK / DOA : 10/05/2018

Dear Ashley,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CARZ AUTO SERVICES PTE LTD**,

ADDRESS : NO 61 WOODLANDS INDUSTRIAL PARK E9
#04-04 E9 PREMIUM
SINGAPORE 757047

PERSON TO CONTACT : ALEX @ 9380 9969 / ALLAN @ 90236692 /6493 1924

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GT967Y/SL/pl

Date: 17th May 2018

Our Ref: CS/EG118008712/Sqb

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLH 2502X .


We thank you for the instruction on 11/05/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/05/2018 at the premises of M/s CARZ AUTO SERVICES and have the following to report:-

Workshop Estimate Amount	: S\$ <u>21,754.96</u> .
Revised Estimate Amount	: S\$ <u>14,798.80</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 12 days.

We have NOT authorise repair.

Yours faithfully

Sebastian
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/05/2018 11:54
Date Of Accident	10/05/2018 06:45
Exact Location Of Accident	TRAFFIC JUNCTION OF TAO CHING RD TWDS JURONG WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH2502X
Insured/Policyholder	
Name Of Registered Owner	NEO CHEOW BEH
NRIC No	S7250227B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94568629
Alternative Phone No	OFFICE-88888888

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MU010162
Cover Note Number	

Driver

Name of Driver	NEO CHEOW BEH
NRIC No	S7250227B
Date Of Birth	18/12/1972
Occupation	INDOOR
Date Of Driving Pass	01/11/1994
Driving Experience	23 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94568629
Fax Number	
Contact Number	OFFICE-88888888
Email Address	NOEMAIL

Address	BLK 848 JURONG WEST STREET 81 #10-257
Postcode	640848
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 10/05/2018 AT ABOUT 6.45AM AT TRAFFIC JUNCTION OF TAO CHING RD TOWARDS JURONG WEST. I CAME TO A STOP BEFORE THE 'RED' TRAFFIC LIGHT. SUDDENLY, I HEARD A LOUD BANG FROM BEHIND AND WHEN I ALIGHTED, I REALISED THAT IT WAS VEHICLE (B) WHO HIT ONTO MY REAR PORTION OF MY VEHICLE (A), CAUSING DAMAGES TO MY VEHICLE. (A) SLH2502X (B) GT967Y

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT967Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	NEO CHEOW BEH
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLH2502X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	


SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



A - SLH 2502 X
B - GT 967 Y


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


ON 10/5/2018 at about 6:45 am, at Traffic junction of Tao Ching Rd Towards Jurong West I came to a stop before the 'Red' traffic light. Suddenly I heard a loud bang from behind and when I alighted, I realised that it was vehicle (B) who hit onto my rear portion of my vehicle (A) causing damages to my vehicle.

(A) SLH 2502 X
(B) GT 967 Y

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


5241 27/6

CARZ AUTO SERVICES PTE LTD NO 61, WOODLANDS INDUSTRIAL PARK E9 #04-04 E9 PREMIUM (757047) Tel : 90236692 Allan /93809969 Alex Email: alex@carzauto.com.sg Office 64931924 GST : 201409457D	
--	--

ERGO INSURANCE PTE. LTD. Temasek Tower Five Singapore 038985 PHONE: +65 68299199 FAX: + 65 68299247/9245 Email: ergoinsurance@ergo.com.sg	Estimate Date : 2/7/2018 Vehicle No. : SLH 2502 X Make/Model : HONDA VEZEL Chassis RU1-1203360 Date of Accident: 10/5/2018 Date of Register:
--	---

No.	Parts (List Price)	QTY	List Price (\$)	Parts Discount	Final price (\$)
	TAIL GATE ✓ DT (02616) 1345.20				
1	TAIL GATE WINDSCREEN MOULDING TOP ✓ NSE	1	\$ 1,345.20	20%	\$ 52.08 (1,076.16)
2	TAIL GATE WINDSCREEN MOULDING BOTTOM	1	\$ 65.10	20%	\$ ✓ NSE 52.08
3	TAIL GATE WINDSCREEN MOULDING SIDE RH	1	\$ 65.10	20%	\$ ✓ NSE 46.86 (52.08)
4	TAIL GATE WINDSCREEN MOULDING SIDE LH	1	\$ 58.20	20%	\$ ✓ NSE 46.56
5	TAIL GATE LOCK CATCH	1	\$ 45.90	20%	\$ ✓ Jm. 36.72
6	TAIL GATE INNER LOCK	1	\$ 235.60	20%	\$ ✓ Jm. 188.48
7	TAIL GATE INNER TRIM BOARD	1	\$ 415.20	20%	\$? ✓ CRK 332.16
8	TAIL GATE WIPER MOTOR	1	\$ 580.60	20%	\$? X 464.48
9	TAIL GATE WIPER ARM	1	\$ 65.20	20%	\$ X 52.16
10	TAIL GATE SHOCKABSOBER LH	1	\$ 205.10	20%	\$? X 164.08
11	TAIL GATE SHOCKABSOBER RH	1	\$ 205.10	20%	\$? X 164.08
12	TAIL GATE REFLECTOR LH	1	\$ 353.60	20%	\$? ✓ SCR 282.88
13	TAIL GATE REFLECTOR RH	1	\$ 353.60	20%	\$? ✓ CRK 282.88
14	TAIL GATE LOGO	1	\$ 45.20	20%	\$ ✓ NSE 36.16
15	TAIL GATE LOGO OUTER GARNISH	1	\$ 315.60	20%	\$? ✓ CRK 252.48
16	TAIL TAGE EMBLEM VEZEL	1	\$ 65.60	20%	\$ ✓ NSE 52.48
17	TAIL GATE WEATHERSTRIP	1	\$ 198.80	20%	\$? ✓ TN 159.04
18	TAIL GATE HINGE	1	\$ 88.50	20%	\$? X 70.80
19	REAR NUMBER PLATE LAMP	2	\$ 62.60	20%	\$ X 50.08
20	REAR BUMPER SIDE RH	1	\$ 593.80	20%	\$ ✓ Defon. 475.04
21	REAR BUMPER SIDE LH	1	\$ 593.80	20%	\$ R 475.04
22	REAR BUMPER SIDE RETAINER	2	\$ 52.40	20%	\$ ✓ NSE 41.92
23	REAR BUMPER BOTTOM	1	\$ 920.20	20%	\$ ✓ Defon. 736.16
24	REAR BUMPER BOTTOM REFLECTOR	1	\$ 215.60	20%	\$ ✓ CRK 172.48
25	REAR BUMPER SPONGE	1	\$ 45.60	20%	\$? X 36.48
27	REAR TAIL LAMP LH	1	\$ 695.90	20%	\$? ✓ SCR 556.72
28	REAR TAIL LAMP RH	1	\$ 695.90	20%	\$? ✓ SCR 556.72
29	REAR TAIL LAMP PANEL RH	1	\$ 258.30	20%	\$? R 206.64
30	REAR TAIL LAMP PANEL LH	1	\$ 258.30	20%	\$? R 206.64
31	REAR END PANEL INNER	1	\$ 325.40	20%	\$? ✓ Defon. 260.32
32	REAR END PANEL OUTER	1	\$ 688.90	20%	\$? ✓ Defon. 551.12
33	REAR END PANEL TOP GARNISH	1	\$ 165.60	20%	\$? ✓ Defon. 132.48
34	REAR FLOOR PANEL	1	\$ 1,458.20	20%	\$? ✓ DT 1,166.56
35	REAR FLOOR PANEL TOP BOARD	1	\$ 404.80	20%	\$? ✓ Defon. 323.84

36	REAR FLOOR PANEL TOOLS SPONGE	1	\$ 362.80	20%	\$? ✓ CRK.	290.24
37	REAR FLOOR PANEL SIDE RH	1	\$ 195.80	20%	\$? X	156.64
38	REAR FLOOR PANEL SIDE LH	1	\$ 195.80	20%	\$? X	156.64
39	REAR FLOOR CHASSIS MEMBER RH	1	\$ 945.20	20%	\$? X	756.16
40	REAR UNDER COVER	1	\$ 332.50	20%	\$? ✓ CRK.	266.00
41	REAR FENDER RH	1	\$ 985.70	20%	\$ R	788.56
42	REAR FENDER LH	1	\$ 985.70	20%	\$ X	788.56
43	REAR FENDER INNER TRIM RH	1	\$ 580.30	20%	\$? ✓ Deform.	464.24
44	REAR FENDER INNER TRIM LH	1	\$ 580.30	20%	\$ ✓ ✓ Deform.	464.24
45	REAR FENDER ARCH GARNISH RH	1	\$ 225.30	20%	\$? ✓ CRK.	180.24
46	REAR FENDER ARCH GARNISH LH	1	\$ 225.30	20%	\$ X	180.24
47	REAR FENDER SHIELD RH	1	\$ 181.90	20%	\$? ✓ TRJ	145.52
48	REAR SILENCER BOX	1	\$ 795.20	20%	\$ ✓ DT	636.16
49	REAR SILENCER BOX MOUNTING	2	\$ 65.10	20%	\$ ✓ Deform.	52.08
50	REAR SILENCER BOX TOP SEAL	1	\$ 118.60	20%	\$? X	94.88
Price:			\$18,918.00			\$15,134.40

No.	Special Nett Items	QTY	List Price (\$)	Parts Discount	Final price (\$)
1	REAR NUMBER PLATE	1	\$ 50.00	-	\$ X 50.00
2	REAR WINDSCREEN GLASS SEALANT	2	\$ 80.00	-	\$ ✓ NEC 60 80.00
3	REAR BUMPER CLIP	8	\$ 40.00	-	\$ ✓ NEC 30 40.00
4	REAR TAIL LAMP CLIP	4	\$ 32.00	-	\$ ✓ NEC 30 32.00
5	REAR END PANEL TOP GARNISH CLIP	4	\$ 32.00	-	\$ ✓ NEC 30 32.00
6	REAR UNDER COVER CLIP	8	\$ 40.00	-	\$? ✓ NEC 30 40.00
7	REAR FENDER SHIELD CLIP	8	\$ 40.00	-	\$? ✓ NEC 30 40.00
8	REAR FENDER ARCH GARNISH CLIP	10	\$ 50.00	-	\$? ✓ NEC 30 50.00
9	REAR FLOOR PANEL INSULATOR SEAL	1	\$ 150.00	-	\$? X 150.00
10	REAR REVERSE CAMERA	1SET	\$ 350.00	-	\$? ✓ DMG 350.00
11	REAR REVERSE SENSOR	1SET	\$ 280.00	-	\$ ✓ DMG 200 280.00
12	TAIL GATE OUTER GARNISH CLIP	10	\$ 50.00	-	\$ ✓ NEC 30 50.00
17	Special Nett Items Total:			-	\$ 1,194.00
	Labour Charges				1600
1	To renew damaged parts, replace ,beat ,weld realign and align all parts			-	\$ 1400 2,400.00
2	To respray affected areas				\$ 1200 1,600.00
3	Towing				\$ 60.00
4	To conduct Water leakage test				\$ 40 80.00
5	To remove & renew Tail Gate mechanism				\$ 80.00
6	Rear Chassis Alignment				\$ 80 120.00
7	To tuffcoat affect areas				\$ 80 250.00
8	To renew refix/ windscreen glass				\$ 120.00
9	To remove/replace silencer box				\$ 80 100.00
10	To remove/replace reverse sensor		12 days.		\$ 60 120.00
11	To remove/refit replace reverse camera				\$ 120 150.00
12	To remove and refit interior upholstery, cushion seat and				\$ 60 150.00
13	To remover/refit wiring check				\$ 30 150.00
					Total: \$ 5,380.00
					GRAND TOTAL 21,708.40
				<p>LKK Auto Consultants hence notify the insurer of the following:</p> <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is done "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>	
Carz Auto Services Pte Ltd					
				Sebastian 14/5/18 - Lump Sum Repair - Question Mark Item Photo After Paint	

CARZ AUTO SERVICES PTE LTD

NO 61, WOODLANDS INDUSTRIAL PARK E9

#04-04 E9 PREMIUM

S(757047)

Tel : 90236692 Allan / 93809969 Alex

Email: alex@carzauto.com.sg

Office 64931924

GST : 201409457D

Estimate

ERGO INSURANCE PTE. LTD.

5 Temasek Tower Five

Singapore 038985

PHONE: +65 68299199

FAX: + 65 68299247/9245

Email: ergoinsurance@ergo.com.sg

Date : 2/7/2018

Vehicle No. : SLH 2502 X

Make/Model : HONDA VEZEL

Chassis RU1-1203360

Date of Accident: 10/5/2018

Date of Register:

Parts (List Price)					
No.	Parts (List Price)	QTY	List Price (\$)	Parts Discount	Final price (\$)
1	TAIL GATE WINDSCREEN MOULDING TOP <i>✓ DT</i>	1	\$ 1,345.20	20%	\$ 1,076.16
2	TAIL GATE WINDSCREEN MOULDING BOTTOM	1	\$ 65.10	20%	\$ 52.08
3	TAIL GATE WINDSCREEN MOULDING SIDE RH	1	\$ 65.10	20%	\$ 52.08
4	TAIL GATE WINDSCREEN MOULDING SIDE LH	1	\$ 58.20	20%	\$ 46.56
5	TAIL GATE LOCK CATCH	1	\$ 45.90	20%	\$ 36.72
6	TAIL GATE INNER LOCK	1	\$ 235.60	20%	\$ 188.48
7	TAIL GATE INNER TRIM BOARD	1	\$ 415.20	20%	\$ 332.16
8	TAIL GATE WIPER MOTOR	1	\$ 580.60	20%	\$ 464.48
9	TAIL GATE WIPER ARM	1	\$ 65.20	20%	\$ 52.16
10	TAIL GATE SHOCKABSOBER LH	1	\$ 205.10	20%	\$ 164.08
11	TAIL GATE SHOCKABSOBER RH	1	\$ 205.10	20%	\$ 164.08
12	TAIL GATE REFLECTOR LH	1	\$ 353.60	20%	\$ 282.88
13	TAIL GATE REFLECTOR RH	1	\$ 353.60	20%	\$ 282.88
14	TAIL GATE LOGO	1	\$ 45.20	20%	\$ 36.16
15	TAIL GATE LOGO OUTER GARNISH	1	\$ 315.60	20%	\$ 252.48
16	TAIL TAGE EMBLEM VEZEL	1	\$ 65.60	20%	\$ 52.48
17	TAIL GATE WEATHERSTRIP	1	\$ 198.80	20%	\$ 159.04
18	TAIL GATE HINGE	1	\$ 88.50	20%	\$ 70.80
19	REAR NUMBER PLATE LAMP	2	\$ 62.60	20%	\$ 50.08
20	REAR BUMPER SIDE RH	1	\$ 593.80	20%	\$ 475.04
21	REAR BUMPER SIDE LH	1	\$ 593.80	20%	\$ 475.04
22	REAR BUMPER SIDE RETAINER	2	\$ 52.40	20%	\$ 41.92
23	REAR BUMPER BOTTOM	1	\$ 920.20	20%	\$ 736.16
24	REAR BUMPER BOTTOM REFLECTOR	1	\$ 215.60	20%	\$ 172.48
25	REAR BUMPER SPONGE	1	\$ 45.60	20%	\$ 36.48
27	REAR TAIL LAMP LH	1	\$ 695.90	20%	\$ 556.72
28	REAR TAIL LAMP RH	1	\$ 695.90	20%	\$ 556.72
29	REAR TAIL LAMP PANEL RH	1	\$ 258.30	20%	\$ 206.64
30	REAR TAIL LAMP PANEL LH	1	\$ 258.30	20%	\$ 206.64
31	REAR END PANEL INNER	1	\$ 325.40	20%	\$ 260.32
32	REAR END PANEL OUTER	1	\$ 688.90	20%	\$ 551.12
33	REAR END PANEL TOP GARNISH	1	\$ 165.60	20%	\$ 132.48
34	REAR FLOOR PANEL	1	\$ 1,458.20	20%	\$ 1,166.56
35	REAR FLOOR PANEL TOP BOARD	1	\$ 404.80	20%	\$ 323.84

36	REAR FLOOR PANEL TOOLS SPONGE	1	\$ 362.80	20%	\$ 7 ✓ CRK	290.24	} NN
37	REAR FLOOR PANEL SIDE RH	1	\$ 195.80	20%	\$ 7 X	156.64	
38	REAR FLOOR PANEL SIDE LH	1	\$ 195.80	20%	\$ 7 X	156.64	
39	REAR FLOOR CHASSIS MEMBER RH	1	\$ 945.20	20%	\$ 7 X	756.16	
40	REAR UNDER COVER	1	\$ 332.50	20%	\$ 7 ✓ CRK	266.00	} NN
41	REAR FENDER RH	1	\$ 985.70	20%	\$ R	788.56	
42	REAR FENDER LH	1	\$ 985.70	20%	\$ ✓	788.56	} NN
43	REAR FENDER INNER TRIM RH	1	\$ 580.30	20%	\$ 7 ✓ Defcon	464.24	
44	REAR FENDER INNER TRIM LH	1	\$ 580.30	20%	\$ ✓ ✓ Defcon	464.24	} NN
45	REAR FENDER ARCH GARNISH RH	1	\$ 225.30	20%	\$ 7 ✓ CRK	180.24	
46	REAR FENDER ARCH GARNISH LH	1	\$ 225.30	20%	\$ X	180.24	} NN
47	REAR FENDER SHIELD RH	1	\$ 181.90	20%	\$ 7 ✓ TRN	145.52	
48	REAR SILENCER BOX	1	\$ 795.20	20%	\$ ✓ DT	636.16	} NN
49	REAR SILENCER BOX MOUNTING	2	\$ 65.10	20%	\$ ✓ Defcon	52.08	
50	REAR SILENCER BOX TOP SEAL	1	\$ 118.60	20%	\$ 7 X	94.88	} NN
			\$18,918.00			\$15,134.40	

Price:

Price:					
No.	Special Nett Items	QTY	List Price (\$)	Parts Discount	Final price (\$)
1	REAR NUMBER PLATE	1	\$ 50.00	-	\$ X 50.00
2	REAR WINDSCREEN GLASS SEALANT	2	\$ 80.00	-	\$ ✓ NEC 60.80
3	REAR BUMPER CLIP	8	\$ 40.00	-	\$ ✓ NEC 30.40.00
4	REAR TAIL LAMP CLIP	4	\$ 32.00	-	\$ ✓ NEC 30.32.00
5	REAR END PANEL TOP GARNISH CLIP	4	\$ 32.00	-	\$? ✓ NEC 30.70.00
6	REAR UNDER COVER CLIP	8	\$ 40.00	-	\$? ✓ NEC 30.70.00
7	REAR FENDER SHIELD CLIP	8	\$ 40.00	-	\$? ✓ NEC 30.70.00
8	REAR FENDER ARCH GARNISH CLIP	10	\$ 50.00	-	\$? X 150.00
9	REAR FLOOR PANEL INSULATOR SEAL	1	\$ 150.00	-	\$? ✓ DMG 350.00
10	REAR REVERSE CAMERA	1SET	\$ 350.00	-	\$ ✓ DMG 200 280.00
11	REAR REVERSE SENSOR	1SET	\$ 280.00	-	\$ ✓ NEC 30.50.00
12	TAIL GATE OUTER GARNISH CLIP	10	\$ 50.00	-	\$ 1,194.00
17	Special Nett Items Total:				1600
	Labour Charges				1740 - 2,450.00
1	To renew damaged parts, replace ,beat ,weld realign and align all parts				\$ 1200 1,006.00
2	To respray affected areas				\$ 60.00
3	Towing				\$ 40 80.00
4	To conduct Water leakage test				\$ 80.00
5	To remove & renew Tail Gate mechanism				\$ 80 120.00
6	Rear Chassis Alignment				\$ 80 150.00
7	To tuffcoat affect areas				\$ 120.00
8	To renew refix/ windscreen glass				\$ 50 100.00
9	To remove/replace silencer box				\$ 60 120.00
10	To remove/replace reverse sensor				\$ 120 150.00
11	To remove/refit replace reverse camera				\$ 60 150.00
12	To remove and refit interior upholstery, cushion seat and				\$ 30 150.00
13	To remover/refit wiring check				\$ 5.380.00
					21,708.40



Carz Auto Services Pte Ltd

LKK Auto Consultants hence notify

the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is not to be prejudicial

GRAND TOTAL

Acknowledged by Reparer

Signature:

Date:

Sebastian
14/5/19
- Lap S - Repair
- Question Mark It
- Photo After Paint

CARZ AUTO SERVICES PTE LTD

NO 61, WOODLANDS INDUSTRIAL PARK E9

#04-04 E9 PREMIUM

S(757047)

Tel :90236692 Allan /93809969 Alex

Email: alex@carzauto.com.sg

Office 64931924

GST : 201409457D

Estimate

ERGO INSURANCE PTE. LTD.

5 Temasek Tower Five

Singapore 038985

PHONE:+65 68299199

FAX: + 65 68299247/9245

Email: ergoinsurance@ergo.com.sg

Date : 2/7/2018

Vehicle No. : SLH 2502 X

Make/Model : HONDA VEZEL

Chassis RU1-1203360

Date of Accident: 10/5/2018

Date of Register:

Parts (List Price)					
No.	TAIL GATE ✓ DT 1100.70	QTY	List Price (\$)	Parts Discount	Final price (\$)
1	TAIL GATE WINDSCREEN MOULDING TOP ✓ NEC	1	\$ 1,345.20	65.10 20%	\$ 1,075.16
2	TAIL GATE WINDSCREEN MOULDING BOTTOM	1	\$ 65.10	20%	\$ ✓ NEC 52.08
3	TAIL GATE WINDSCREEN MOULDING SIDE RH	1	\$ 65.10	58.20 20%	\$ ✓ NEC 52.08
4	TAIL GATE WINDSCREEN MOULDING SIDE LH	1	\$ 58.20	20%	\$ ✓ NEC 46.56
5	TAIL GATE LOCK CATCH	1	\$ 45.90	20%	\$ ✓ Jm. BT 36.72
6	TAIL GATE INNER LOCK	1	\$ 235.60	20%	\$ ✓ Jm. 188.48
7	TAIL GATE INNER TRIM BOARD 186 225.10	1	\$ 415.20	20%	\$? 464.16
8	TAIL GATE WIPER MOTOR	1	\$ 580.60	20%	\$? X NN 464.48
9	TAIL GATE WIPER ARM	1	\$ 65.20	20%	\$ X X NN 52.16
10	TAIL GATE SHOCKABSOBER LH	1	\$ 205.10	20%	\$? X NN 164.08
11	TAIL GATE SHOCKABSOBER RH	1	\$ 205.10	20%	\$? X NN 164.08
12	TAIL GATE REFLECTOR LH	1	\$ 353.60	20%	\$? ✓ SCR 282.88
13	TAIL GATE REFLECTOR RH	1	\$ 353.60	20%	\$? ✓ CRA 282.88
14	TAIL GATE LOGO	1	\$ 45.20	20%	\$ ✓ NEC 36.16
15	TAIL GATE LOGO OUTER GARNISH 198.10	1	\$ 315.60	20%	\$? ✓ CRA 252.48
16	TAIL TAGE EMBLEM VEZEL	1	\$ 65.60	20%	\$ ✓ NEC 52.48
17	TAIL GATE WEATHERSTRIP	1	\$ 198.80	20%	\$? ✓ In 159.04
18	TAIL GATE HINGE	1	\$ 88.50	20%	\$? X NN 70.80
19	REAR NUMBER PLATE LAMP	2	\$ 62.60	20%	\$ X nn 50.08
20	REAR BUMPER SIDE RH 195	1	\$ 593.80	20%	\$ ✓ Defon 475.04
21	REAR BUMPER SIDE LH 195	1	\$ 593.80	20%	\$ R 475.04
22	REAR BUMPER SIDE RETAINER	2	\$ 52.40	20%	\$ ✓ NEC 41.92
23	REAR BUMPER BOTTOM 263.70	1	\$ 920.20	20%	\$ ✓ Defon 736.16
24	REAR BUMPER BOTTOM REFLECTOR	1	\$ 215.60	20%	\$ ✓ CRK 172.48
25	REAR BUMPER SPONGE NS X	1	\$ 45.60	20%	\$? X nn 36.48
27	REAR TAIL LAMP LH 460.60	1	\$ 695.90	20%	\$? ✓ SCR 556.72
28	REAR TAIL LAMP RH 460.60	1	\$ 695.90	20%	\$? ✓ SCR 556.72
29	REAR TAIL LAMP PANEL RH 135.90	1	\$ 258.30	20%	\$? X R 206.64
30	REAR TAIL LAMP PANEL LH 135.90	1	\$ 258.30	20%	\$? X R 206.64
31	REAR END PANEL INNER X NS	1	\$ 325.40	20%	\$? ✓ DE 260.32
32	REAR END PANEL OUTER 416.60	1	\$ 688.90	20%	\$? ✓ DE 551.12
33	REAR END PANEL TOP GARNISH 82.30	1	\$ 165.60	20%	\$? ✓ DE 132.48
34	REAR FLOOR PANEL 1130.90	1	\$ 1,458.20	20%	\$? ✓ DD 1,166.56
35	REAR FLOOR PANEL TOP BOARD 230.80	1	\$ 404.80	20%	\$? ✓ DE 323.84

36	REAR FLOOR PANEL TOOLS SPONGE	1	\$ 362.80	20%	\$? ✓ CFA	290.24
37	REAR FLOOR PANEL SIDE RH	1	\$ 195.80	20%	\$? X J	156.64
38	REAR FLOOR PANEL SIDE LH	1	\$ 195.80	20%	\$? X J nn	156.64
39	REAR FLOOR CHASSIS MEMBER RH	1	\$ 945.20	20%	\$? X J	756.16
40	REAR UNDER COVER	1	\$ 332.50	20%	\$? ✓ CFA	266.00
41	REAR FENDER RH	1	\$ 985.70	20%	\$ R	788.56
42	REAR FENDER LH	1	\$ 985.70	20%	\$ X nn	788.56
43	REAR FENDER INNER TRIM RH 295	1	\$ 580.30	20%	\$? ✓ DE	464.24
44	REAR FENDER INNER TRIM LH 295	1	\$ 580.30	20%	\$ X ✓ DE	464.24
45	REAR FENDER ARCH GARNISH RH	1	\$ 225.30	20%	\$? ✓ CFA	180.24
46	REAR FENDER ARCH GARNISH LH	1	\$ 225.30	20%	\$ X nn	180.24
47	REAR FENDER SHIELD RH	1	\$ 181.90	20%	\$? ✓ nn	145.52
48	REAR SILENCER BOX 528-60	1	\$ 795.20	20%	\$ ✓ DT	636.16
49	REAR SILENCER BOX MOUNTING	2	\$ 65.10	20%	\$ ✓ Defon	52.08
50	REAR SILENCER BOX TOP SEAL 55	1	\$ 118.60	20%	\$? X nn	94.88
Price:			\$18,918.00			\$15,134.40

14985.36

No.	Special Nett Items	QTY	List Price (\$)	Parts Discount	Final price (\$)
1	REAR NUMBER PLATE	1	\$ 50.00	-	\$ X nn 50.00
2	REAR WINDSCREEN GLASS SEALANT	2	\$ 80.00	-	\$ ✓ NEC 60 80.00
3	REAR BUMPER CLIP	8	\$ 40.00	-	\$ ✓ NEC 30 40.00
4	REAR TAIL LAMP CLIP	4	\$ 32.00	-	\$ ✓ NEC 30 32.00
5	REAR END PANEL TOP GARNISH CLIP	4	\$ 32.00	-	\$ ✓ NEC 30 32.00
6	REAR UNDER COVER CLIP	8	\$ 40.00	-	\$? ✓ nec 40.00
7	REAR FENDER SHIELD CLIP	8	\$ 40.00	-	\$? ✓ nec 40.00
8	REAR FENDER ARCH GARNISH CLIP	10	\$ 50.00	-	\$? ✓ nec 50.00
9	REAR FLOOR PANEL INSULATOR SEAL	1	\$ 150.00	-	\$? X nn 150.00
10	REAR REVERSE CAMERA	1SET	\$ 350.00	-	\$? ✓ DM 250 350.00
11	REAR REVERSE SENSOR	1SET	\$ 280.00	-	\$ ✓ DMG 200 280.00
12	TAIL GATE OUTER GARNISH CLIP	10	\$ 50.00	-	\$ ✓ NEC 30 50.00
17	Special Nett Items Total:			-	\$ 1,194.00

Labour Charges

1	To renew damaged parts, replace ,beat ,weld realign and align all parts			-	\$ 1400 2,400.00
2	To respray affected areas				\$ 1200 1,600.00
3	Towing				\$ 60.00
4	To conduct Water leakage test				\$ 40 80.00
5	To remove & renew Tail Gate mechanism				\$ 60 80.00
6	Rear Chassis Alignment				\$ 80 120.00
7	To tuffcoat affect areas				\$ 80 250.00
8	To renew refix/ windscreen glass				\$ 120.00
9	To remove/replace silencer box	10			\$ 80 100.00
10	To remove/replace reverse sensor	X 2 days			\$ 60 120.00
11	To remove/refit replace reverse camera				\$ 60 120 150.00
12	To remove and refit interior upholstery, cushion seat and cleaning of the following:				\$ 60 150.00
13	To remover/refit wiring check				\$ 30 150.00

LKK Auto Consultants hence notify

the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party costs are not included

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: \$ 5,380.00
GRAND TOTAL: \$ 21,708.40



Carz Auto Services Pte Ltd

Sebastian
 14/5/18
 - Lump Sum Repair
 - Question Mark Itc
 Photo After Paint
 21559.36




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18008712/Sqbe2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 05-07-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 967Y	Veh. Inspected	SLH 2502X	
Policy No.		Coverage (\$)	0.00	
Claim No.	GT967Y/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	11/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11203360	Colour	BROWN	
Odometer	55846	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/05/2018	Inspection Date	14/05/2018	
Survey held at	CARZ AUTO - 61 WOODLANDS IND PARK E9 #04-04			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2502X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GATE	DENTED	1,100.70	1,100.70
1	TAIL GATE WINDSCREEN	NECESSARY	65.10	65.10
1	TAILGATE WINDSCREEN MOUDLING BOTTOM	NECESSARY	65.10	65.10
1	TAIL GATE WINDSCREEN MOULDING SIDE RH	NECESSARY	58.20	58.20
1	TAIL GATE WINDSCREEN MOULDING SIDE LH	NECESSARY	58.20	58.20
1	TAIL GATE LOCK CATCH	JAMMED / BENT	45.90	45.90
1	TAIL GATE INNER LOCK	JAMMED	235.60	180.00
1	TAIL GATE INNER TRIM BOARD	CRACKED	415.20	225.10
1	TAIL GATE WIPER MOTOR	NOT NECESSARY	580.60	-
1	TAIL GATE WIPER ARM	NOT NECESSARY	65.20	-
1	TAIL GATE SHOCK ABSORBER LH	NOT NECESSARY	205.10	-
1	TAIL GATE SHOCK ABSORBER RH	NOT NECESSARY	205.10	-
1	TAIL GATE REFLECTOR LH	SCRATCHED	353.60	353.60
1	TAIL GATE REFLECTOR RH	CRACKED	353.60	353.60
1	TAIL GATE LOGO	NECESSARY	45.20	45.20
1	TAIL GATE LOGO OUTER GARNISH	CRACKED	315.60	198.10
1	TAIL GATE EMBLEM VEZEL	NECESSARY	65.60	65.60
1	TAIL GATE WEATHERSTRIP	TORN	198.80	198.80
1	TAIL GATE HINGE	NOT NECESSARY	88.50	-
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	62.60	-
1	REAR BUMPER SIDE RH	DEFORMED	593.80	195.00
1	REAR BUMPER SIDE LH	TO REPAIR SEE LABOUR	593.80	-
2	REAR BUMPER SIDE RETAINER	NECESSARY	52.40	52.40
1	REAR BUMPER BOTTOM	DEFORMED	920.20	863.70
1	REAR BUMPER BOTTOM REFLECTOR	CRACKED	215.60	215.60
1	REAR BUMPER SPONGE	NOT NECESSARY	45.60	-
1	REAR TAIL LAMP LH	SCRATCHED	695.90	460.60
1	REAR TAIL LAMP RH	SCRATCHED	695.90	460.60
1	REAR TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	258.30	-

Report Ref No. CS/EG18008712/Sqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	258.30	-
1	REAR END PANEL INNER	NO SUCH PARTS	325.40	-
1	REAR END PANEL OUTER	DEFORMED	688.90	416.60
1	REAR END PANEL TOP GARNISH	DEFORMED	165.60	92.30
1	REAR FLOOR PANEL	DENTED	1,458.20	1,130.90
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	404.80	230.80
1	REAR FLOOR PANEL TOOLS SPONGE	CRACKED	362.80	362.80
1	REAR FLOOR PANEL SIDE RH	NOT NECESSARY	195.80	-
1	REAR FLOOR PANEL SIDE LH	NOT NECESSARY	195.80	-
1	REAR FLOOR CHASSIS MEMBER RH	NOT NECESSARY	945.20	-
1	REAR UNDER COVER	CRACKED	332.50	332.50
1	REAR FENDER RH	TO REPAIR SEE LABOUR	985.70	-
1	REAR FENDER LH	NOT NECESSARY	985.70	-
1	REAR FENDER INNER TRIM RH	DEFORMED	580.30	295.00
1	REAR FENDER INNER TRIM LH	DEFORMED	580.30	295.00
1	REAR FENDER ARCH GARNISH RH	CRACKED	225.30	225.30
1	REAR FENDER ARCH GARNISH LH	NOT NECESSARY	225.30	-
1	REAR FENDER SHIELD RH	TORN	181.90	181.90
1	REAR SILENCER BOX	DENTED	795.20	528.60
2	REAR SILENCER BOX MOUNTING	DEFORMED	65.10	65.10
1	REAR SILENCER BOX TOP SEAL	NOT NECESSARY	118.60	-
	LESS 20% DISCOUNT		-3,746.34	-1,883.58
			14,985.36	7,534.32
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
2	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	80.00	60.00
8	REAR BUMPER CLIP (SN)	NECESSARY	40.00	30.00
4	REAR TAIL LAMP CLIP (SN)	NECESSARY	32.00	30.00
4	REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	32.00	30.00
8	REAR UNDER COVER CLIP (SN)	NECESSARY	40.00	40.00
8	REAR FENDER SHIELD CLIP (SN)	NECESSARY	40.00	40.00

Report Ref No. CS/EGI18008712/Sqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	REAR FENDER ARCH GARNISH CLIP (SN)	NECESSARY	50.00	50.00
1	REAR FLOOR PANEL INSULATOR SEAL (SN)	NOT NECESSARY	150.00	-
1	SET REAR REVERSE CAMERA (SN)	DAMAGED	350.00	280.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
10	TAIL GATE OUTER GARNISH CLIP (SN)	NECESSARY	50.00	30.00
			1,194.00	790.00
	LABOUR			
	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD REALIGN AND ALIGN ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE LH, REAR TAIL LAMP PANEL RH, REAR TAIL LAMP PANEL LH AND REAR FENDER RH.		2,400.00	1,400.00
	TO RESPRAY AFFECTED AREAS.		1,600.00	1,200.00
	TOWING.		60.00	60.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
	TO REMOVE & RENEW TAIL GATE MECHANISM.		80.00	60.00
	REAR CHASSIS ALIGNMENT.		120.00	80.00
	TO TUFFCOAT AFFECT AREAS.		250.00	80.00
	TO RENEW REFLEX / WINDSCREEN GLASS.		120.00	120.00
	TO REMOVE / REPLACE SILENCER BOX,		100.00	80.00
	TO REMOVE / REPLACE REVERSE SENSOR.		120.00	60.00
	TO REMOVE / REFIT REPLACE REVERSE CAMERA.		150.00	60.00
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY, CUSHION SEAT.		150.00	60.00
	TO REMOVER/ REFIT WIRING CHECK.		150.00	30.00
			5,380.00	3,290.00
GRAND TOTAL			21,559.36	11,614.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,300.00

Report Ref No. CS/EGI18008712/Sqbe2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.