

ASS. REC. BY:

REF:

CS/FCL 18008714 / ^DPTV bcl

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): (W) Karen Tan

of FCL

Date/Time: 00052018 506pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGT 8051R

Insured:

SHC 3636K

at Workshop m/s

Motor Image

Tel:

9090 3323

of

19 Wrong Tou Payon 8

Policy No:

Claim No:

018003689MFAH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07052018

(Client's Record)

CA / REV / REP. / REV 24 HRS '03'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SGT 8051R - C3/EQ1 10000410/pb3xx	DA: 29/12/16
	SHC 3636K - C3/TCL 16004540 / T16c2	DA: 05/03/16
18/5/18	Email preli revised to FCI	
16/7/18	Final fig \$22,169.60 confirmed by email (Ref 5679.92, 20/9)	

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / CO RES / EVA / INV / MY

To Inspect Vehicle No. _____

at Workshop no. _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____


Excess: _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No. _____

Yr Regn: MAY 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

1998

Colour: _____

AC Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Wonder / Jammed / Leaked / Burnt or

Brake: Wonder / Jammed / Leaked / Burnt or

Mod: Nil / A/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal: _____

mm

R/Bal: _____

mm

L/Bal: _____

mm

L/Bal: _____

mm

D.O.A. _____

D.O.I. _____

Survey held at _____

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: _____

RECEIVED 17 JUL 2018

Date/Time: File Paid to?

☐

Prel. Report

ii

☐

Final Report

Date/Time: File Return to?

iii

17/7 - typst

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Insp (\$)

☐

24hrs insp (\$)

Report Format: _____

Lump Sum / I.B. (\$)

-cws

P/P \$22,169.60

Days Of Repair: 14

Resurvey No. of Trip: 1

Survey Fee

Transportation

1st Hour

2nd Hour

3rd Hour

TOTAL

18 x 15 = 270

1704 270

50

50

77

617

MOTOR SURVEY ASSIGNMENT

Date	08-05-2018	Our Ref No. D18003589MFSH
Accident Date	07-05-2018	Claim Type. Third Party
Insured Vehicle	SHC3636K	Third Party Vehicle. SGT8059R
Survey Location	19 LORONG 8 TOA PAYOH	
Contact Person.	KUAN WEI LOONG	
Contact No.	90903323/ 86113195	Fax No. 00
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED;	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOTOR IMAGE ENTERPRISES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 18 May 2018 2:01 PM
To: 'Claim Workflow System'
Cc: SUR; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: FW: SGT8059R - 3RD PARTY CLAIM - AIG - TP(SHC3636K)FIRST CAPITAL - SURVEY - 15/05/2018 - CAR NON DRIVERBLE
Attachments: SGT 8059R PRELI ADVISED.pdf(AMEND).pdf

Dear Sir/Madam,

Enclosed amend preliminary revised of vehicle SGT 8059R .

Sorry for the inconvenience caused.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 18 May 2018 1:45 PM
To: SUR <sur@lkkauto.com>; 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: RE: SGT8059R - 3RD PARTY CLAIM - AIG - TP(SHC3636K)FIRST CAPITAL - SURVEY - 15/05/2018 - CAR NON DRIVERBLE

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGT 8059R

Date of survey: 15/5/2018

Number of days:14 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kuan Wei Loong [<mailto:weiloong@motorimage.net>]
Sent: Tuesday, 15 May 2018 10:33 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Sayedinah <sayedinah@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; Daniel Jude <danieljude@motorimage.net>
Subject: SGT8059R - 3RD PARTY CLAIM - AIG - TP(SHC3636K)FIRST CAPITAL - SURVEY - 15/05/2018 - CAR NON

DRIVERBLE

Importance: High

Hi LKK,

Kindly arrange survey of the above mentioned vehicle.
(15/05/2018 – CAR NON DRIVERBLE)

Thank You,

Best Regards
Kuan Wei Loong
Claims Advisor
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:90903323 / 86113195
Email:weiloong@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

From: Kuan Wei Loong
Sent: Tuesday, May 15, 2018 9:39 AM
To: Daniel Jude <danieljude@motorimage.net>
Subject: FW: SURVEYOR APPOINTED; OUR REF : D18003589MFSH ; YOUR REF: SGT8059R

FYI

Thank You,

Best Regards
Kuan Wei Loong
Claims Advisor
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:90903323 / 86113195
Email:weiloong@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, May 10, 2018 5:57 PM
To: Kuan Wei Loong <weiloong@motorimage.net>
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: SURVEYOR APPOINTED; OUR REF : D18003589MFSH ; YOUR REF: SGT8059R

Dear Sir/Madam

PRI Request For **SGT8059R** Accident Involving **SHC3636K** On 07-05-2018 AT 08:40:00HRS.

Please find below details for your reference

- **Claim number :** D18003589MFSH
- **Insured vehicle number :** SHC3636K
- **Accident date :** 07-05-2018
- **Third-party vehicle number :** SGT8059R

- **Assignment type** : WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED
- **Surveyor** : LKK AUTO CONSULTANTS PTE LTD
- **Officer-in-Charge** : KARENT

PS: This is a system generated mail. Please do not reply to this mail.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

A horizontal banner advertisement for Subaru. On the left, there is a graphic of diagonal black and white stripes. Below this, the text reads "LESS SLIP. MORE GRIP. SYMMETRICAL AWD". In the center is a detailed illustration of a car's chassis and drivetrain, showing the engine, transmission, and wheels. To the right of the chassis, the text "SUBARU TECHNOLOGY" is displayed above a dark rectangular button with the white text "LEARN MORE". On the far right is the Subaru logo, which consists of a stylized star inside an oval, with the word "SUBARU" written in capital letters below it. Below the banner, there are three small square icons: a Facebook 'f' logo, an Instagram camera logo, and a YouTube play button logo.

Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18003589MFSH

Our ref: CS/FCI18008714/M1vb

Date : 18/5/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGT 8059R


We thank you for your instruction on 10/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/5/2018 at the premises of M/s MOTOR IMAGE ENTERPRISES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$28,514.32
Revised Estimate Amount	: S\$19,147.00
"Check" Items Amount	: S\$1,725.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MA CHIN FOOK
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2992G
Vehicle Details	
Vehicle No.:	SGT8059R
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 May 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	FA20A909107
Chassis No.:	JF15JGK85GG070757
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$18,941.00
Original Registration Date:	03 May 2016
First Registration Date:	03 May 2016
Transfer Count:	0
Actual ARF Paid:	\$18,941.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 May 2026
PARF Rebate Amount:	\$14,205.00
Intended COE Rebate Details	
COE Expiry Date:	02 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,000.00
COE Rebate Amount:	\$37,416.00
Total Rebate Amount:	\$51,621.00

The information contained herein is correct as at 15 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/05/2018 09:56
Date Of Accident	07/05/2018 08:30
Exact Location Of Accident	ECP JUNCTION 10 A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT8059R
Insured/Policyholder	
Name Of Registered Owner	TEY CHEH YVONNE
NRIC No	S7660391Z
Email Address	PATTINSONC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96266881
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 XT AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100464271
Cover Note Number	

Driver

Name of Driver	CHRISTOPHER DAVID PATTINSON
NRIC No	S7660391Z
Date Of Birth	23/10/1976
Occupation	INDOOR
Date Of Driving Pass	24/04/2014
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	+65-94236974
Fax Number	
Contact Number	
Email Address	PATTINSONC@GMAIL.COM

Address	120 TANJONG RHU ROAD #04-03 S(436904)
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HUSBAND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : 1 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO DOCUMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC3636K
Vehicle Make/Model/Colour	TAXI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE JOO HAK
NRIC/Passport Number	S1162690D
Contact Number	96568543
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2


Vehicle Registration Number	SGP942P
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LAU KUM HON GEORGE
NRIC/Passport Number	S0158663G
Contact Number	96390602
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJR8634E
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN BOON PIN ERIC
NRIC/Passport Number	S8111673C
Contact Number	96185242
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:
Date & Time:

Driver's Signature _____
 (If driver is not the policyholder)
 Date & Time: _____

07 MAY 2018
15:53

Reporting Centre Personnel's Signature
Name: DAVI D. S. DE
NRIC/TIN No.: 5000180

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: DANIEL S. DE
NRIC/IN No: 790051810

07 May 2018
15:53

Accident Sketch Plan

Date & Time: 07 May 2018, 08:30am
Incident: Rear-ending by taxi registration SHC3636K on ECP
Additional impact: Chain-collision into forward car, in-turn in to a 3rd car
Location: Junction 10A in the direction of the airport

Statement of Christopher Pattinson (S76603912): driver of vehicle SG18059R

At approximately 08:30am on 07 May 2018, whilst driving toward Changi Airport in the right-hand lane, I noticed the cars in front of me slow down suddenly. I am not sure of the reason for this as the traffic was flowing freely at that point.

A dark Honda Civic, registration SJR86434E, slowed rapidly (2nd car in front of mine) as did the light colour Nissan in front of me, registration SGP942P. I braked increasingly harder and had the presence of mind to apply my hazard lights.

As I was approaching a complete standstill, Taxi registration SHC3636K rear-ended my car heavily pushing my vehicle forward causing an impact with the car in front, who in turn impacted the car in front of him. I immediately heard the sound of the taxi radiator coolant leaking on to the road so knew the rear impact was quite hard.

The single impact from behind my vehicle was the sole cause of a single impact with the vehicle in front of me.

Upon inspection, I noticed the Taxi has a ComfortDelgro camera which should have recorded the entire incident to confirm the single impact of my car on the car in front.

Driver particulars were exchanged. In order of furthest back in the collision:

SHC3636K	Taxi:	LEE Joo Hak	I/C S1162690D	H/P 96568543
SG18059R	Subaru:	Christopher PATTINSON	I/C S7660391Z	H/P 94236974
SGP942P	Nissan:	LAU Kum Hon George	I/C S0158663G	H/P 96390602
SJR86434E	Honda:	TAN Boon Pin Eric	I/C S8111673C	H/P 96185242

In speaking with the passenger of the Nissan at the scene she confirmed she felt only a single impact on their vehicle from behind.

The driver of the vehicle behind the incident stopped and introduced himself as Bryan Tan, offering himself as an eyewitness account, stating he saw the impact from the taxi on my car as the sole cause of the subsequent forward consecutive impacts. His business card gives his H/P number as 87878755.

My car was in a drivable condition and after confirming with the on-site LTA traffic Marshall I was allowed to do so, moved my car to the hard shoulder then after another road-side visual inspection, proceeded to drive my vehicle home.

Signed:



Chris Pattinson S7660391Z

Accident Sketch Plan

Daniel Jude

From: yvonne tey <yvonne_tey@hotmail.com>
Sent: Monday, May 7, 2018 3:45 PM
To: Daniel Jude
Cc: Chris Pattinson
Subject: SG18059R

I, Tey Cheh Yvonne (I/C number 57342992G) authorise Christopher Pattinson (I/C 57660319Z) to manage all matters in relation to the incident that took place on the ECP on the morning May 7th 2018.

Regards, Yvonne.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0761/2018
DATE : 09-MAY-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : TEY CHEH YVONNE
ADDRESS : 120 TANJONG REU ROAD #04-03
S(436904)
TELEPHONE NO : 96266881

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100464271
VEHICLE NO : SGT8059R
MODEL CODE : SJGKK8
MODEL/YEAR : FORESTER 2.0XT AND CVT
ENGINE NO : FA20A909107
CHASSIS NO : JF1SJGK85GG070757
MILEAGE : 1 KM
DATE IN : 09/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 07/05/2018

Print Date : 10/05/2018
Print Time : 12:57:51

4TORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0761/2018
DATE : 09-MAY-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : TEY CHEH YVONNE
ADDRESS : 120 TANJONG RHU ROAD #04-03

S(436904)
TELEPHONE NO : 96266881

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100464271
VEHICLE NO : SGT8059R
MODEL CODE : S.JGDWXB
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20A909107
CHASSIS NO : JF1SJGR85GG070757
MILEAGE : 1 KM
DATE IN : 09/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 07/05/2018

Print Date : 10/05/2018
Print Time : 12:57:51

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FIRST CAPITAL DATE:07/05/2018 LOCATION:ECP JUNCTION 10 A TIME:0830HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER,HOOD AND PANEL	2240.00	2000 ✓
4	ZZ/003	RESPRAY FRONT BUMPER,HOOD AND PANEL	1680.00	1500 1500/2 ✓
5	ZZ/004	REPAIR/REPLACE REAR BUMPER,TAILGATE,FLOOR PAN AND PANEL	2800.00	2500 ✓
6	ZZ/005	RESPRAY REAR BUMPER,TAIGATE,FLOOR PAN AND PANEL	2100.00	1680 ✓
7	ZZ/006	DISMANTLE/REFIX UNDERCARRIAGE REAR CENTER/LH/RH TO FACILITATE REPAIR	900.00	500? ✓
8	ZZ/007	REMOVE/REFIX EXHAUST	150.00	✓ ✓
9	ZZ/008	TO CONDUCT WATER SEEPAGE TEST	100.00	50 ✓
10	ZZ/009	TRANSFER TAILGATE MECHANISM	150.00	✓ ✓
11	ZZ/011	REMOVE/REFIX CARPET,SEAT TO FACILITATE REPAIRS	400.00	✓ ✓
12	ZZ/012	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	✓ ✓
13	ZZ/013	REMOVE/INSTALL REAR WINDSCREEN	300.00	150 ✓
14	ZZ/014	TO REMOVE/REFIX FUEL TANK	200.00	3 ✓
15	ZZ/015	TO CONDUCT FRONT AND REAR LIGHTING TEST	100.00	✓ ✓
16	ZZ/016	TO CONDUCT FRONT AND REAR PROTECTANT COATING	1000.00	X
17	ZZ/017	TO CONDUCT REAR ANTI RUST COATING	580.00	✓ ✓
18	ZZ/018	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	300 ✓
19	ZZ/019	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	✓ ✓
20	ZZ/020	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	✓ ✓
21	ZZ/021	SUNDRIES	100.00	50 ✓
22	ZZ/10	WHEEL ALIGNMENT	200.00	✓ ✓

Not Auction
PIP Rpn
Before paint job
LKK Auto (MIA)
14 w delays
23/5/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
TOTAL LABOUR CHARGES			13745.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

DAMAGED PARTS & PRICES					
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1 FLOOR PAN R R CP	52129SG0019P DIS ✓	432.00	✓		
2 SKIRT COMPL R END PANEL	52401SG0109P DD ✓	288.00	✓		
3 RAD PNL COMPL RPR	53029SG0009P PD ✓	360.00	✓		
4 HOOD F CPL	57229SG0009P BUC ✓	882.00	✓		
5 HINGE COMPL F HD RH	57260SG0009P NN X	43.20	X		
6 HINGE COMPL F HD LH	57260SG0109P NN X	43.20	X		
7 LOCK ASSY F HOOD RHD	57310SG000 BT ✓	54.00	✓		
8 STRIKER	57311AG010 BT ✓	36.00	✓		
9 BUMPER FACE R	57704SG012 DIS ✓	540.00	✓		
10 BRKT CORNER F RH	57707SG000 BR ✓	36.00	✓		
11 BRKT CORNER F LH	57707SG010 BR ✓	36.00	✓		
12 BRKT SD F RH	57707SG020 BR ✓	12.60	✓		
13 BRKT SD F LH	57707SG030 BR ✓	12.60	✓		
14 BRKT CORNER R RH	57707SG060 FE ✓	18.00	✓		
15 BRKT CORNER R LH	57707SG070 RE ✓	18.00	✓		
16 BRKT SD R RH	57707SG080 RE ✓	14.40	✓		
17 BRKT SD R LH	57707SG090 BR ✓	14.40	✓		
18 BUMPER FACE F (FOR HL/W)	57709SG011 DD ✓	594.00	✓		
19 BACK BEAM CPL F	57711SG0009P BT ✓	288.00	✓		
20 BEAM COMPL R EU	57711SG0219P BT ✓	288.00	✓		
21 ENERGY ABSOR F	57722SG020 NN X	126.00	X		
22 COVER HOOK R	57731SG010NN CUT ✓	12.60	✓		
23 COVER HOOK F SP	57731SG070 NN X	5.40	X		
24 COVER FOG F SP RH	57731SG080 NN X	43.20	X		
25 COVER FOG F SP LH	57731SG090 CUT ✓	43.20	✓		

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 COVER SD F SP RH UPPER	57731SG120 NN	X 12.60	X		
27 COVER SD F SP LH	57731SG130 NN	X 12.60	X		
28 PACKING RAD	57780SG010 NA	X 9.00	X		
29 PACKING RAD	57780SG020 NN	X 9.00	X		
30 PANEL CPL R/G	60809SG0509P BT	X 1072.80			
31 GLASS R/G	63019SG000 BR	X 799.20			
32 RUBBER DAM GLS * 2	63232SG000 CUT	7.20			
33 RUBBER R/G	63232SG010 CUT	12.60			
34 LAMP ASSY HEAD EOF	84002SG220 SCR	2380.00			
35 LAMP ASSY HEAD EOF	84002SG230 NN	X 2380.00	X		
36 REFLEC AY RH	84281SC000 CM	20.40			
37 REFLEX AY LH	84281SC010 SCR	20.40			
38 FOG LAMP ASSY F	84501AJ060 NN	X 544.00	X		
39 LENS & BODY COMPLHL	84912SG111 NN	X 432.00	X		
40 LENS & BODY COMPLRFR	84912SG121 NN	X 432.00	X		
41 NOZZLE COVER ASSYRH	86636SG340Q1 CUT	54.00			
42 NOZZLE COVER ASSYLH	86636SG350V2 CUT	54.00			
43 NOZZLE H L WASHERRH	86636SG361 NN	X 79.20			
44 NOZZLE H L WASHERLH	86636SG371 CUT	79.20			
45 INSULATOR HOOD TRRH	90815SG061 NN	X 36.00	X		
46 INSULATOR HOOD TRLH	90815SG070 NN	X 36.00	X		
47 GARNISH AY RG, B	91111SG000 NN	X 144.00	X		
48 GRILLE ASSY F UPRHG	91121SG210A CR	140.40			
49 GRILLE ASSY F CTRHG	91121SG240A CR	180.00			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
50 GRILLE ASSY F LWRHC	91121SG280A DIS ✓	316.80	✓		
51 BKT GRILLE LWR	91165SG010 DIS ✓	21.60	✓		
52 PROTR R GARNISH	91713SG000 CUT ✓	21.60	✓		
53 PROTECTOR LWR SD	91713SG010 CUT ✓	10.80	✓		
54 ORNAMENT R	93033SG001 SCR ✓	79.20	✓		
55 LETTER MK R XT	93079SG010 NEC ✓	64.80	✓		
56 LETTER MK R SUB	93079SG030 NEC ✓	64.80	✓		
57 CARGO STEP PANEL (RESIN)	E775ESG000 BT ✓	420.00	✓		
58 FRONT NUMBER PLATE	WM001 CRA			45.00	✓

SUB TOTAL	14187.00	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)	2837.40	0.00	0.00	0.00
GRAND TOTAL	11349.60	0.00	45.00	0.00
OVERALL TOTAL	11394.60			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGT8059R

TOTAL LABOUR CHARGES	13745.00	(S) 2709.92
TOTAL SPARE PARTS CHARGES	11394.60	
GRAND TOTAL	25139.60 *	27, 849.52

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

28711432

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



Motor Image Enterprises Pte Ltd
19 Lorong 8 Tua Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SGT-8059-R

Surveyor: _____

DESCRIPTION

PART NO

AMOUNT

1	<u>LINDER COVER FRONT</u>	<u>564405G060</u> <u>NEW</u>	<u>\$288.00</u>
2	<u>DUCT BUMPER</u>	<u>572465G010</u> <u>orig</u>	<u>\$14.40</u>
3	<u>CONDENSER ASSEMBLY</u>	<u>732105G001</u> <u>WA</u>	<u>\$579.40</u>
4	<u>RADIATOR ASSEMBLY</u>	<u>451115G010</u> <u>WA</u>	<u>\$810.00</u>
5	<u>PACKING RADIATOR</u>	<u>451675G010</u> <u>NEW</u>	<u>\$18.00</u>
6	<u>FENDER COMPLETE FRONT LEFT</u>	<u>571205G0309-P</u> <u>WA</u>	<u>\$270.00</u>
7	<u>FRAME COMPLETE RADIATOR LOWER</u>	<u>512315G0009-P</u> <u>WA</u>	<u>\$108.00</u>
8	<u>SHROUD RADIATOR</u>	<u>451225G000</u> <u>WA</u>	<u>\$86.40</u>
9	<u>RESERVE TANK ASSEMBLY</u>	<u>451505G001</u> <u>del</u>	<u>\$61.20</u>
10	_____	_____	_____
11	<u>Muffler LH</u>	<u>44300 54 040</u> <u>WA</u>	<u>601.20</u>
12	<u>Gasket</u>	<u>44011 54 010</u> <u>X2 NEW</u>	<u>7.20^{x2}</u> <u>14.40</u>
13	<u>Exhaust pipe rear</u>	<u>44200 54 031</u> <u>WA</u>	<u>792.00</u>
14	<u>Exhaust cover LH</u>	<u>59024 54 001</u> <u>WA</u>	<u>50.40</u>
15	_____	_____	_____
16	_____	_____	_____
17	_____	_____	_____
18	_____	_____	_____
19	_____	_____	_____
20	_____	_____	_____
21	_____	_____	_____
22	_____	_____	_____
23	_____	_____	_____
24	_____	_____	_____
25	_____	_____	_____

CHK AMOUNT
17/5/2018



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SGT-8059-R

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

1	_____	_____
2	<u>RESPRAY - FRONT LHS - FENDER</u>	<u>\$420.00</u>
3	_____	_____
4	_____	<u>3374.72</u>
5	_____	_____
6	_____	_____
7	_____	_____
8	_____	_____
9	_____	_____
10	_____	_____
11	_____	_____
12	_____	_____

STORIMAGE ENTERPRISES PTE. LTD.
1 LORONG 8, TOA PAJOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGT8059R

ESTAL LABOUR CHARGES	13745.00
ESTAL SPARE PARTS CHARGES	11394.60

RAND TOTAL	25139.60 *

All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

DISCLAIMER : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FIRST CAPITAL DATE:07/05/2018 LOCATION:ECP JUNCTION 10 A TIME:0830HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER,HOOD AND PANEL	2240.00	2000.00
4	ZZ/003	RESPRAY FRONT BUMPER,HOOD AND PANEL	1680.00	1500.00
5	ZZ/004	REPAIR/REPLACE REAR BUMPER,TAILGATE,FLOOR PAN AND PANEL	2800.00	2500.00
6	ZZ/005	RESPRAY REAR BUMPER,TAIGATE,FLOOR PAN AND PANEL	2100.00	1680.00
7	ZZ/006	DISHENTLE/REFIX UNDERCARRIAGE REAR CENTER/LH/RH TO FACILITATE REPAIR	900.00	500.00
8	ZZ/007	REMOVE/REFIX EXHAUST	150.00	150.00
9	ZZ/008	TO CONDUCT WATER SEEPAGE TEST	100.00	50.00
10	ZZ/009	TRANSFER TAILGATE MECHANISM	150.00	150.00
11	ZZ/011	REMOVE/REFIX CARPET,SEAT TO FACILITATE REPAIRS	400.00	400.00
12	ZZ/012	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	150.00
13	ZZ/013	REMOVE/INSTALL REAR WINDSCREEN	300.00	150.00
14	ZZ/014	TO REMOVE/REFIX FUEL TANK	200.00	200.00
15	ZZ/015	TO CONDUCT FRONT AND REAR LIGHTING TEST	100.00	100.00
16	ZZ/016	TO CONDUCT FRONT AND REAR PROTECTANT COATING	1000.00	.00
17	ZZ/017	TO CONDUCT REAR ANTI RUST COATING	580.00	580.00
18	ZZ/018	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	300.00
19	ZZ/019	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	145.00
20	ZZ/020	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	150.00
21	ZZ/021	SUNDRIES	100.00	50.00
22	ZZ/022	REMOVE&REPLACE AIR CON CONDENSER VACUUM/GAS (SIPP)	200.00	200.00 (A)

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
23	ZZ/023	RESFRAY FRONT LHS FENDER (SUPP)	420.00	420.00
24	ZZ/10	WHEEL ALIGNMENT	200.00	200.00
TOTAL LABOUR CHARGES			14365.00	11575.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 GASKET (SUPP) <i>nec</i>	44011SG010	14.40			OK
2 EXH PIPE ASSY R (SUPP) <i>Bt</i>	44200SG031	792.00			OK
3 MUFFLER ASSY LH BLH (SUPP) <i>Bt</i>	44300SG040	601.20			OK
4 RADIATOR ASSY (SUPP) <i>Bt</i>	45111SG010	810.00			OK
5 SERVOUD (SUPP) <i>cr</i>	45122SG000	86.40			OK
6 TANK RESERVE (SUPP) <i>def</i>	45150SG001	61.20			OK
7 FRAME LWR B CP (SUPP) <i>Bt</i>	51231SG0009P	108.00			OK
8 FLOOR PAN R R CP	52129SG0019P	432.00			OK
9 SKIRT COMPL R END PANEL	52401SG0109P	288.00			OK
10 RAD PNL COMPL RFR	53029SG0009P	360.00			OK
11 FRT FENDER LH (SUPP) <i>Bt</i>	57120SG0309P	270.00			OK (A)
12 HOOD F CPL	57229SG0009P	882.00			OK
13 HINGE COMPL F HD RH	57260SG0009P	43.20			X
14 HINGE COMPL F HD LH	57260SG0109P	43.20			X
15 LOCK ASSY F HOOD RH	57310SG000	54.00			OK
16 STRIKER #	57311AG010	36.00			OK
17 BUMPER FACE R	57704SG012	540.00			OK
18 BRKT CORNER F RH	57707SG000	36.00			OK
19 BRKT CORNER F LH	57707SG010	36.00			OK
20 BRKT SD F RH	57707SG020	12.60			OK
21 BRKT SD F LH	57707SG030	12.60			OK
22 BRKT CORNER R RH	57707SG060	18.00			OK
23 BRKT CORNER R LH	57707SG070	18.00			OK
24 BRKT SD R RH	57707SG080	14.40			OK
25 BRKT SD R LH	57707SG090	14.40			OK

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	BUMPER FACE F (FOR EL/W)	57709SG011	594.00			OK
27	BACK BEAM CPL F	57711SG0009P	288.00			OK
28	BEAM COMPL R EU	57711SG0219P	288.00			OK
29	ENERGY ASSOR F	57722SG020	126.00			X
30	COVER HOOK R	57731SG0108N	12.60			OK
31	COVER HOOK F SP	57731SG0070	5.40			X
32	COVER FOG F SP RH	57731SG0080	43.20			X
33	COVER FOG F SP LH	57731SG0090	43.20			OK
34	COVER SD F SP RH UPPER	57731SG0120	12.60			X
35	COVER SD F SP LH	57731SG0130	12.60			X
36	DUCT BUMPER F DIB (SUPP) <i>dist</i>	57746SG010	14.40			OK (A)
37	PACKING RAD	57780SG010	9.00			X
38	PACKING RAD	57780SG020	9.00			X
39	COVER EXH R LH (SUPP) <i>B+</i>	59024SG001	50.40			OK (A)
40	PANEL CPL R/G	60809SG0509P	1072.80			OK
41	GLASS R/G	63019SG000	795.20			OK
42	RUBBER DAM GLS * 2	63232SG000	7.20			OK
43	RUBBER R/G	63232SG010	12.60			OK
44	CONDENSER ASSY (SUPP) <i>B+</i>	73210SG001	579.40			OK (A)
45	LAMP ASSY HEAD EOF	84002SG220	2380.00			OK
46	LAMP ASSY HEAD EOF	84002SG230	2380.00			X
47	REFLEC AY RH	84281SC000	20.40			OK
48	REFLEX AY LH	84281SC010	20.40			OK
49	FOG LAMP ASSY F	84501AJ060	544.00			X

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
50 LENS & BODY COMPLJPL	84912SG111	432.00			X
51 LENS & BODY COMPLJPL	84912SG121	432.00			X
52 NOZZLE COVER ASSYRH	86636SG340Q1	54.00			OK
53 NOZZLE COVER ASSYLH	86636SG350V2	54.00			OK
54 NOZZLE H L WASHERRH	86636SG361	79.20			X
55 NOZZLE H L WASHERLH	86636SG371	79.20			OK
56 INSULATOR HOOD TBRE	90815SG061	36.00			X
57 INSULATOR HOOD TBLH	90815SG070	36.00			X
58 GARNISH AY RG, B	91111SG000	144.00			X
59 GRILLE ASSY F UPRHG	91121SG210A	140.40			OK
60 GRILLE ASSY F CTRHG	91121SG240A	180.00			OK
61 GRILLE ASSY F LWRHG	91121SG280A	316.80			OK
62 BKT GRILLE LMR	91165SG010	21.60			OK
63 PROTR R GARNISH	91713SG000	21.60			OK
64 PROTECTOR LMR SD	91713SG010	10.80			OK
65 ORNAMENT R	93033SG001	79.20			OK
66 LETTER MX R XT	93079SG010	64.80			OK
67 LETTER MX R SUB	93079SG030	64.80			OK
68 CARGO STEP PANEL (RESIN)	E775ESG000	420.00			OK
69 FRONT NUMBER PLATE	WM001			45.00	OK
SUB TOTAL		13187.00	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)		2637.40	0.00	0.00	0.00
GRAND TOTAL		10549.60	0.00	45.00	0.00
OVERALL TOTAL		10594.60			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYAH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGT8059R

NETT ITEM	13187.00
LESS 20 %	-2637.40
NETT AMOUNT	10549.60

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	45.00
---------------------	-------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	11575.00
TOTAL SPARE PARTS CHARGES	10594.60

TOTAL CHARGES	22169.60
ADD 7 % GST	1551.87

GRAND TOTAL	23721.47
-------------	----------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 16 July 2018 5:48 PM
To: 'Daniel Jude'
Cc: David Koh; Dennis Leong; Maggie Wong; Cammy Teo; Jeff Teh; Daniel Lim; Kuan Wei Loong; Sayedinah; SUR
Subject: RE: PENDING FOR FINALIZE-SGT 8059R (DOA: 7/5/2018)

Dear Daniel,

WITHOUT PREJUDICE

Confirmed amount \$22,169.60 before GST @ 14 working days.

Kindly send relevant supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Daniel Jude [mailto:danieljude@motorimage.net]
Sent: Tuesday, 10 July 2018 6:25 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: David Koh <davidkoh@motorimage.net>; Dennis Leong <dennisleong@motorimage.net>; Maggie Wong <maggiewong@motorimage.net>; Cammy Teo <siewchan@motorimage.net>; Jeff Teh <tengchuen@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>; Sayedinah <sayedinah@motorimage.net>
Subject: RE: PENDING FOR FINALIZE
Importance: High

Hi Veron,

Attached for your reference and follow up.

In the near future, if there are such urgent cases

Please contact me at the mentioned number given at the bottom and I will set immediate attention to them.

Best Regards

Daniel A Jude

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, July 10, 2018 5:22 PM
To: Daniel Jude <danieljude@motorimage.net>
Cc: David Koh <davidkoh@motorimage.net>; Dennis Leong <dennisleong@motorimage.net>; Maggie Wong <maggiwong@motorimage.net>; Cammy Teo <siewchan@motorimage.net>; Jeff Teh <tengchuen@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>; Sayedinah <sayedinah@motorimage.net>
Subject: RE: PENDING FOR FINALIZE

Dear Daniel,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us as insurance is chasing.

1.SGT 8059R-DOA: 7/5/2018 (FCIL TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 29 June 2018 4:56 PM
To: 'Daniel Jude' <danieljude@motorimage.net>
Cc: David Koh <davidkoh@motorimage.net>; Dennis Leong <dennisleong@motorimage.net>; Maggie Wong <maggiwong@motorimage.net>; Cammy Teo <siewchan@motorimage.net>; Jeff Teh <tengchuen@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>; Sayedinah <sayedinah@motorimage.net>
Subject: RE: PENDING FOR FINALIZE

Dear Daniel,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1.SGT 8059R-DOA: 7/5/2018 (FCIL TP)
- 2.SCF3278D-DOA:25/5/2018 (AIG OD)
- 3.SJF 4939R-DOA: 27/5/20218 (AIG OD)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Daniel Jude [mailto:danieljude@motorimage.net]

Sent: Tuesday, 19 June 2018 4:29 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: David Koh <davidkoh@motorimage.net>; Dennis Leong <dennisleong@motorimage.net>; Maggie Wong <maggiwong@motorimage.net>; Cammy Teo <siewchan@motorimage.net>; Jeff Teh <tengchuen@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>; Sayedinah <sayedinah@motorimage.net>

Subject: RE: PENDING FOR FINALIZE

Importance: High

Hi Veron,

Vehicle has been repaired and release.

Job has been finalized and will be forwarded to you once confirmed on our end.

Thank you.

Best Regards

Daniel A Jude

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net



LESS SLIP.
MORE GRIP.
SYMMETRICAL AWD

SUBARU
TECHNOLOGY

LEARN MORE

SUBARU



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Sayedinah

Sent: Tuesday, June 19, 2018 4:25 PM

To: 'Veron Chen (LKKAUTO)' <veronchen@lkkauto.com>

Cc: David Koh <davidkoh@motorimage.net>; Dennis Leong <dennisleong@motorimage.net>; Maggie Wong <maggiewong@motorimage.net>; Cammy Teo <siewchan@motorimage.net>; Jeff Teh <tengchuen@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; Daniel Jude <danieljude@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>

Subject: RE: PENDING FOR FINALIZE

Importance: High

Hi Veron,

I will get Mr Daniel Jude & Mr Kuan to follow up on cases @ Toa Payoh.

DJ & Kuan,

Please take note.

Regards

Sayedinah Ali

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP:92992693 DID:67038109 FAX:+65-62535535

Email:sayedinah@motorimage.net

Website:www.tanchong.com :: www.motorimage.net

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]

Sent: Tuesday, 19 June 2018 4:07 PM

To: Sayedinah <sayedinah@motorimage.net>; Daniel Lim <daniellim@motorimage.net>

Cc: David Koh <davidkoh@motorimage.net>; Dennis Leong <dennisleong@motorimage.net>; Maggie Wong <maggiewong@motorimage.net>; Cammy Teo <siewchan@motorimage.net>; Jeff Teh <tengchuen@motorimage.net>

Subject: RE: PENDING FOR FINALIZE

Dear Daniel,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

1. SGT 8059R-DOA: 7/5/2018 (FCIL TP)
2. SCF 3278D-DOA:25/5/2018 (AIG OD)
3. SJF 4939R-DOA: 27/5/20218 (AIG OD)
4. SLJ 7089D-DOA: 10/3/2018 (MSIG TP) (REF :INS/IC/LHI/014/2018)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Friday, 4 May 2018 2:59 PM

To: 'Sayedinah' <sayedinah@motorimage.net>; Daniel Lim <daniellim@motorimage.net>

Cc: David Koh <davidkoh@motorimage.net>; 'dennisleong@motorimage.net' <dennisleong@motorimage.net>; 'maggiewong@motorimage.net' <maggiewong@motorimage.net>; 'siewchan@motorimage.net' <siewchan@motorimage.net>

Subject: RE: PENDING FOR FINALIZE

Dear Sayed,

Check already ?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sayedinah [mailto:sayedinah@motorimage.net]

Sent: Wednesday, 25 April 2018 3:48 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Daniel Lim <daniellim@motorimage.net>

Cc: Sayedinah <sayedinah@motorimage.net>; David Koh <davidkoh@motorimage.net>

Subject: Re: PENDING FOR FINALIZE

Hi Veron,

Will revert tomorrow ya.

Regards

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: "Veron Chen (LKKAuto)" <veronchen@lkkauto.com>

Date: 25/04/2018 15:35 (GMT+08:00)

To: Daniel Lim <daniellim@motorimage.net>

Cc: Sayedinah <sayedinah@motorimage.net>; David Koh <davidkoh@motorimage.net>

Subject: PENDING FOR FINALIZE

Dear Daniel,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

1. SFL 9959R-DOA: 3/12/2017 (MSIG OD)

2. SKS 5045H-DOA: 17/1/2018 (MSIG OD)
3. SLS 9489Y-DOA: 19/12/2017 (ERGO TP)
4. SLT 2968Y-DOA: 25/1/2018 (FCIL TP)
5. SLJ 7089D-DOA: 10/3/2018 (MSIG TP)
6. SFX 4848Y-DOA: 5/3/2018 (CHINA TAIPING TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LESS SLIP.
MORE GRIP.
SYMMETRICAL AWD

SUBARU
TECHNOLOGY

LEARN MORE

SUBARU

f i y

Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0761/2018
DATE : 09-MAY-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073846

OWNER'S NAME : TEY CHEE YVONNE
ADDRESS : 120 TANJONG RHU ROAD #04-03
S(436904)
TELEPHONE NO : 96266881

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100464271
VEHICLE NO : 9GT8059R
MODEL CODE : SJGKE8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20A909107
CHASSIS NO : JF1SJK85G0070757
MILEAGE : 19346 KM
DATE IN : 09/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 07/05/2018

Print Date : 10/07/2018
Print Time : 17:59:55

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FIRST CAPITAL DATE:07/05/2018 LOCATION:ECP JUNCTION 10 A TMA:0830HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER,HOOD AND PANEL	2240.00	2000
4	ZZ/003	RESPRAY FRONT BUMPER,HOOD AND PANEL	1680.00	1500 1500k
5	ZZ/004	REPAIR/REPLACE REAR BUMPER,TAILGATE,FLOOR PAN AND PANEL	2800.00	2500
6	ZZ/005	RESPRAY REAR BUMPER,TAIGATE,FLOOR PAN AND PANEL	2100.00	1680
7	ZZ/006	DISMANTLE/REFIX UNDERCARRIAGE REAR CENTER/LH/RH TO FACILITATE REPAIR	900.00	500?
8	ZZ/007	REMOVE/REFIX EXHAUST	150.00	<
9	ZZ/008	TO CONDUCT WATER SEEPAGE TEST	100.00	50
10	ZZ/009	TRANSFER TAILGATE MECHANISM	150.00	<
11	ZZ/011	REMOVE/REFIX CARPET,SEAT TO FACILITATE REPAIRS	400.00	<
12	ZZ/012	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	<
13	ZZ/013	REMOVE/INSTALL REAR WINDSCREEN	300.00	150
14	ZZ/014	TO REMOVE/REFIX FUEL TANK	200.00	3
15	ZZ/015	TO CONDUCT FRONT AND REAR LIGHTING TEST	100.00	<
16	ZZ/016	TO CONDUCT FRONT AND REAR PROTECTANT COATING	1000.00	X
17	ZZ/017	TO CONDUCT REAR ANTI RUST COATING	580.00	<
18	ZZ/018	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	300.00 ✓
19	ZZ/019	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	✓
20	ZZ/020	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	<
21	ZZ/021	SUNDRIES	100.00	50
22	ZZ/10	WHEEL ALIGNMENT	200.00	<

Not Authorised
PIP Rep
Before paint job
H&K Auto (MIA)
14 w delays
Hp: 84028474

/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION

TOTAL LABOUR CHARGES		13745.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	FLOOR PAN R R CP	52129SG0019P	✓ 432.00			
2	SKIRT COMPL R END PANEL	52401SG0109P	✓ 288.00			
3	RAD PNL COMPL RPR	53029SG0009P	✓ 360.00			
4	HOOD F CPL	57229SG0009P	✓ 882.00			
5	HINGE COMPL F HD RH	57260SG0009P	X 43.20			
6	HINGE COMPL F HD LH	57260SG0109P	X 43.20			
7	LOCK ASSY F HOOD RHD	57310SG000	✓ 54.00			
8	STRIKER	57311AG010	✓ 36.00			
9	BUMPER FACE R	57704SG012	✓ 540.00			
10	BRKT CORNER F RH	57707SG000	✓ 36.00			
11	BRKT CORNER F LH	57707SG010	✓ 36.00			
12	BRKT SD F RH	57707SG020	✓ 12.60			
13	BRKT SD F LH	57707SG030	✓ 12.60			
14	BRKT CORNER R RH	57707SG060	✓ 18.00			
15	BRKT CORNER R LH	57707SG070	✓ 18.00			
16	BRKT SD R RH	57707SG080	✓ 14.40			
17	BRKT SD R LH	57707SG090	✓ 14.40			
18	BUMPER FACE F (FOR HL/W)	57709SG011	✓ 594.00			
19	BACK BEAM CPL F	57711SG0009P	✓ 288.00			
20	BEAM COMPL R EU	57711SG0219P	✓ 288.00			
21	ENERGY ABSOR F	57722SG020	X 126.00			
22	COVER HOOK R	57731SG010NN	✓ 12.60			
23	COVER HOOK F SP	57731SG070	X 5.40			
24	COVER FOG F SP RH	57731SG080	X 43.20			
25	COVER FOG F SP LH	57731SG090	✓ 43.20			

		DAMAGED PARTS & PRICES			
/NO PARTS DESCRIPTION		PARTS NUMBER	NETT	LIST	S/NETT S/LIST REMARKS
26	COVER SD F SP RH UPPER	57731SG120	X 12.60		
27	COVER SD F SP LH	57731SG130	X 12.60		
28	PACKING RAD	57780SG010	X 9.00		
29	PACKING RAD	57780SG020	X 9.00		
30	PANEL CPL R/G	60809SG0509P	X 1072.80		
31	GLASS R/G	63019SG000	X 799.20		
32	RUBBER DAM GLS * 2	63232SG000	/ 7.20		
33	RUBBER R/G	63232SG010	/ 12.60		
34	LAMP ASSY HEAD EOF	84002SG220	/ 2380.00		
35	LAMP ASSY HEAD EOF	84002SG230	X 2380.00		
36	REFLEC AY RH	84281SC000	/ 20.40		
37	REFLEX AY LH	84281SC010	/ 20.40		
38	FOG LAMP ASSY F	84501AJ060	X 544.00		
39	LENS & BODY COMPLJPL	84912SG111	X 432.00		
40	LENS & BODY COMPLRFR	84912SG121	X 432.00		
41	NOZZLE COVER ASSYRH	86636SG340Q1	/ 54.00		mis
42	NOZZLE COVER ASSYLH	86636SG350V2	/ 54.00		mis
43	NOZZLE H L WASHERRH	86636SG361	X 79.20		mc
44	NOZZLE H L WASHERLH	86636SG371	/ 79.20		LH
45	INSULATOR HOOD TBRH	90815SG061	X 36.00		
46	INSULATOR HOOD TBLH	90815SG070	X 36.00		
47	GARNISH AY RG, B	91111SG000	X 144.00		
48	GRILLE ASSY F UPRHG	91121SG210A	/ 140.40		
49	GRILLE ASSY F CTRHG	91121SG240A	/ 180.00		

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

DAMAGED PARTS & PRICES

I/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS
50 GRILLE ASSY F LWRHG	91121SG280A	316.80			
51 BKT GRILLE LWR	91165SG010	21.60			
52 PROTR R GARNISH	91713SG000	21.60			
53 PROTECTOR LWR SD	91713SG010	10.80			
54 ORNAMENT R	93033SG001	79.20			
55 LETTER MK R XT	93079SG010	64.80			
56 LETTER MK R SUB	93079SG030	64.80			
57 CARGO STEP PANEL (RESIN)	E775ESG000	420.00			
58 FRONT NUMBER PLATE	WM001			45.00	
SUB TOTAL		14187.00	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)		2837.40	0.00	0.00	0.00
GRAND TOTAL		11349.60	0.00	45.00	0.00
OVERALL TOTAL		11394.60			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18008714/D1vbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3636K	Veh. Inspected	SGT 8059R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003589MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	10/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JF1SJGK85GG070757	Colour	BLACK	
Odometer	19337	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	225/55 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/55 R18	BRIDGESTONE	7 mm	
L/H Rear Tyre	225/55 R18	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/05/2018	Inspection Date	15/05/2018	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 8059R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FLOOR PAN R R CP (N)	DISTORTED	432.00	432.00
1	SKIRT COMPL R END PANEL (N)	DENTED	288.00	288.00
1	RAD PNL COMPL RPR (N)	DENTED	360.00	360.00
1	HOOD F CPL (N)	BUCKLED	882.00	882.00
1	HINGE COMPL F HD RH (N)	NOT NECESSARY	43.20	-
1	HINGE COMPL F HF LH (N)	NOT NECESSARY	43.20	-
1	LOCK ASSY F HOOD RHD (N)	BENT	54.00	54.00
1	STRIKER (N)	BENT	36.00	36.00
1	BUMPER FACE R (N)	DISTORTED	540.00	540.00
1	BRKT CORNER F RH (N)	BROKEN	36.00	36.00
1	BRKT CORNER F LH (N)	BROKEN	36.00	36.00
1	BRKT SD F RH (N)	BROKEN	12.60	12.60
1	BRKT SD F LH (N)	BROKEN	12.60	12.60
1	BRKT CORNER R RH (N)	BROKEN	18.00	18.00
1	BRKT CORNER R LH (N)	BROKEN	18.00	18.00
1	BRKT SD R RH (N)	BROKEN	14.40	14.40
1	BRKT SD R LH (N)	BROKEN	14.40	14.40
1	BUMPER FACE F (FOR HL/W) (N)	DENTED	594.00	594.00
1	BACK BEAM CPL F (N)	BENT	288.00	288.00
1	BEAM COMPL R EU (N)	BENT	288.00	288.00
1	ENERGY ABSOR F (N)	NOT NECESSARY	126.00	-
1	COVER HOOK R (N)	CUT	12.60	12.60
1	COVER HOOK F SP (N)	NOT NECESSARY	5.40	-
1	COVER FOG F SP RH (N)	NOT NECESSARY	43.20	-
1	COVER FOG F SP LH (N)	CUT	43.20	43.20
1	COVER SD F SP RH UPPER (N)	NOT NECESSARY	12.60	-
1	COVER SD F SP LH (N)	NOT NECESSARY	12.60	-
1	PACKING RAD (N)	NOT NECESSARY	9.00	-
1	PACKING RAD (N)	NOT NECESSARY	9.00	-
1	PANEL CPL R/G (N)	BENT	1,072.80	1,072.80
1	GLASS R/G (N)	BROKEN	799.20	799.20

Report Ref No. CS/FCI18008714/D1vbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RUBBER DAM GLS*2 (N)	CUT	7.20	7.20
1	RUBBER R/G (N)	CUT	12.60	12.60
1	LAMP ASSY HEAD E0F LH (N)	SCRATCHED	2,380.00	2,380.00
1	LAMP ASSY HEAD E0F RH (N)	NOT NECESSARY	2,380.00	-
1	REFLEC AY RH (N)	CRACKED	20.40	20.40
1	REFLEX AY LH (N)	SCRATCHED	20.40	20.40
1	FOG LAMP ASSY F (N)	NOT NECESSARY	544.00	-
1	LENS & BODY COMPLJPL (N)	NOT NECESSARY	432.00	-
1	LENS & BODY COMPLRFR (N)	NOT NECESSARY	432.00	-
1	NOZZLE COVER ASSYRH (N)	CUT	54.00	54.00
1	NOZZLE COVER ASSYLH (N)	CUT	54.00	54.00
1	NOZZLE H L WASHERRH (N)	NOT NECESSARY	79.20	-
1	NOZZLE H L WASHERLH (N)	CUT	79.20	79.20
1	INSULATOR HOOD TBRH (N)	NOT NECESSARY	36.00	-
1	INSULATOR HOOD TBLH (N)	NOT NECESSARY	36.00	-
1	GARNISH AY RG, B (N)	NOT NECESSARY	144.00	-
1	GRILLE ASSY F UPRHG (N)	CRACKED	140.40	140.40
1	GRILLE ASSY F CTRHG (N)	CRACKED	180.00	180.00
1	GRILLE ASSY F LWRHG (N)	DISTORTED	316.80	316.80
1	BKT GRILLE LWR (N)	DISTORTED	21.60	21.60
1	PROTR R GARNISH (N)	CUT	21.60	21.60
1	PROTECTOR LWR AD (N)	CUT	10.80	10.80
1	ORNAMENT R (N)	SCRATCHED	79.20	79.20
1	LETTER MK R XT (N)	NECESSARY	64.80	64.80
1	LETTER MK R SUB (N)	NECESSARY	64.80	64.80
1	CARGO STEP PANEL (RESIN) (N)	BENT	420.00	420.00
1	UNDER COVER FRONT (N) (ADDITIONAL)	SERVICEABLE	288.00	-
1	DUCT BUMPER (N) (ADDITIONAL)	DISTORTED	14.40	14.40
1	CONDENSER ASSEMBLY (N) (ADDITIONAL)	BENT	579.40	579.40
1	RADIATOR ASSEMBLY (N) (ADDITIONAL)	BENT	810.00	810.00
1	PACKING RADIATOR (N) (ADDITIONAL)	SERVICEABLE	18.00	-
1	FENDER COMPLETE FRONT LEFT (N) (ADDITIONAL)	BENT	270.00	270.00
1	FRAME COMPLETE RADIATOR LOWER (N) (ADDITIONAL)	BENT	108.00	108.00

Report Ref No. CS/FCI18008714/D1vbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SHROUD RADIATOR (N) (ADDITIONAL)	CUT	86.40	86.40
1	RESERVE TANK ASSEMBLY (N) (ADDITIONAL)	DEFORMED	61.20	61.20
1	MUFFLER LH (N) (ADDITIONAL)	BENT	601.20	601.20
2	GASKET @\$7.20 (N) (ADDITIONAL)	NECESSARY	14.40	14.40
1	EXHAUST PIPE REAR (N) (ADDITIONAL)	BENT	792.00	792.00
1	EXHAUST COVER LH (N) (ADDITIONAL)	BENT	50.40	50.40
	LESS 20% DISCOUNT		-3,576.08	-2,637.40
			14,304.32	10,549.60
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	FRONT NUMBER PLATE (SN)	CRACKED	45.00	45.00
			145.00	95.00
	<u>LABOUR</u>			
	REPAIR / REPLACE FRONT BUMPER, HOOD AND PANEL		2,240.00	2,000.00
	RESPRAY FRONT BUMPR, HOOD AND PANEL		1,680.00	1,500.00
	REPAIR / REPLACE REAR BUMPER, TAILGATE, FLOOR PAN AND PANEL		2,800.00	2,500.00
	RESPRAY REAR BUMPER, TAILGATE, FLOOR PAN AND PANEL		2,100.00	1,680.00
	DISMENTLE / REFIX UNDERCARRIAGE REAR CENTER / LH / RH TO FACILITATE REPAIR.		900.00	500.00
	REMOVE / REFIX EXHAUST.		150.00	150.00
	TO CONDUCT WATER SEEPAGE TEST.		100.00	50.00
	TRANSFER TAILGATE MECHANISM.		150.00	150.00
	REMOVE / REFIX CARPET, SEAT TO FACILITATE REPAIRS.		400.00	400.00
	REMOVE / REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR.		150.00	150.00
	REMOVE / INSTALL REAR WINDSCREEN.		300.00	150.00
	TO REMOVE / REFIX FUEL TANK.		200.00	200.00
	TO CONDUCT FRONT AND REAR LIGHTING TEST.		100.00	100.00
	TO CONDUCT FRONT AND REAR PROTECTANT COATING.	NOT NECESSARY	1,000.00	-
	TO CONDUCT REAR ANTI RUST COATING.		580.00	580.00

Report Ref No. CS/FCI18008714/D1vbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY / INSTALL REVERSE SENSOR - 2 EYES.		300.00	300.00
	TO SUPPLY / INSTALL REAR TINTED FILM.		145.00	145.00
	REMOVE / REFIX FRONT HEADLAMP WASHER AND PIPING.		150.00	150.00
	WHEEL ALIGNMENT.		200.00	200.00
	RESPRAY FRONT LHS FENDER. (ADDITIONAL)		420.00	420.00
	REMOVE / REPLACE AIR CON CONDENSER VACUUM / GAS. (ADDITIONAL)		200.00	200.00
			14,265.00	11,525.00
GRAND TOTAL			28,714.32	22,169.60
RECOMMENDED COST OF REPAIRS				22,169.60

Report Ref No. CS/FCI18008714/D1vbe2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.