

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0761/2018
DATE : 09-MAY-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : TEY CHEH YVONNE
ADDRESS : 120 TANJONG RHU ROAD #04-03
S(436904)
TELEPHONE NO : 96266881

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100464271
VEHICLE NO : SGT8059R
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20A909107
CHASSIS NO : JF1SJGK85GG070757
MILEAGE : 19346 KM
DATE IN : 09/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 07/05/2018

Print Date : 10/07/2018
Print Time : 17:59:55

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FIRST CAPITAL DATE:07/05/2018 LOCATION:ECP JUNCTION 10 A TMA:0830HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER,HOOD AND PANEL	2240.00	2000.00
4	ZZ/003	RESPRAY FRONT BUMPER,HOOD AND PANEL	1680.00	1500.00
5	ZZ/004	REPAIR/REPLACE REAR BUMPER,TAILGATE,FLOOR PAN AND PANEL	2800.00	2500.00
6	ZZ/005	RESPRAY REAR BUMPER,TAIGATE,FLOOR PAN AND PANEL	2100.00	1680.00
7	ZZ/006	DISMENTLE/REFIX UNDERCARRIAGE REAR CENTER/LH/RH TO FACILITATE REPAIR	900.00	500.00
8	ZZ/007	REMOVE/REFIX EXHAUST	150.00	150.00
9	ZZ/008	TO CONDUCT WATER SEEPAGE TEST	100.00	50.00
10	ZZ/009	TRANSFER TAILGATE MECHANISM	150.00	150.00
11	ZZ/011	REMOVE/REFIX CARPET,SEAT TO FACILITATE REPAIRS	400.00	400.00
12	ZZ/012	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	150.00
13	ZZ/013	REMOVE/INSTALL REAR WINDSCREEN	300.00	150.00
14	ZZ/014	TO REMOVE/REFIX FUEL TANK	200.00	200.00
15	ZZ/015	TO CONDUCT FRONT AND REAR LIGHTING TEST	100.00	100.00
16	ZZ/016	TO CONDUCT FRONT AND REAR PROTECTANT COATING	1000.00	.00
17	ZZ/017	TO CONDUCT REAR ANTI RUST COATING	580.00	580.00
18	ZZ/018	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	300.00
19	ZZ/019	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	145.00
20	ZZ/020	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	150.00
21	ZZ/021	SUNDRIES	100.00	50.00
22	ZZ/022	REMOVE&REPLACE AIR CON CONDENSER VACUUM/GAS (SUPP)	200.00	200.00

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
23	ZZ/023	RESPRAY FRONT LHS FENDER (SUPP)	420.00	420.00
24	ZZ/10	WHEEL ALIGNMENT	200.00	200.00
TOTAL LABOUR CHARGES			14365.00	11575.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 GASKET (SUPP)	44011SG010	14.40			OK
2 EXH PIPE ASSY R (SUPP)	44200SG031	792.00			OK
3 MUFFLER ASSY LH BLH (SUPP)	44300SG040	601.20			OK
4 RADIATOR ASSY (SUPP)	45111SG010	810.00			OK
5 SHROUD (SUPP)	45122SG000	86.40			OK
6 TANK RESERVE (SUPP)	45150SG001	61.20			OK
7 FRAME LWR B CP (SUPP)	51231SG0009P	108.00			OK
8 FLOOR PAN R R CP	52129SG0019P	432.00			OK
9 SKIRT COMPL R END PANEL	52401SG0109P	288.00			OK
10 RAD PNL COMPL RPR	53029SG0009P	360.00			OK
11 FRT FENDER LH (SUPP)	57120SG0309P	270.00			OK
12 HOOD F CPL	57229SG0009P	882.00			OK
13 HINGE COMPL F HD RH	57260SG0009P	43.20			X
14 HINGE COMPL F HD LH	57260SG0109P	43.20			X
15 LOCK ASSY F HOOD RHD	57310SG000	54.00			OK
16 STRIKER	57311AG010	36.00			OK
17 BUMPER FACE R	57704SG012	540.00			OK
18 BRKT CORNER F RH	57707SG000	36.00			OK
19 BRKT CORNER F LH	57707SG010	36.00			OK
20 BRKT SD F RH	57707SG020	12.60			OK
21 BRKT SD F LH	57707SG030	12.60			OK
22 BRKT CORNER R RH	57707SG060	18.00			OK
23 BRKT CORNER R LH	57707SG070	18.00			OK
24 BRKT SD R RH	57707SG080	14.40			OK
25 BRKT SD R LH	57707SG090	14.40			OK

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 BUMPER FACE F (FOR HL/W)	57709SG011	594.00			OK
27 BACK BEAM CPL F	57711SG0009P	288.00			OK
28 BEAM COMPL R EU	57711SG0219P	288.00			OK
29 ENERGY ABSOR F	57722SG020	126.00			X
30 COVER HOOK R	57731SG010NN	12.60			OK
31 COVER HOOK F SP	57731SG070	5.40			X
32 COVER FOG F SP RH	57731SG080	43.20			X
33 COVER FOG F SP LH	57731SG090	43.20			OK
34 COVER SD F SP RH UPPER	57731SG120	12.60			X
35 COVER SD F SP LH	57731SG130	12.60			X
36 DUCT BUMPER F DIB (SUPP)	57746SG010	14.40			OK
37 PACKING RAD	57780SG010	9.00			X
38 PACKING RAD	57780SG020	9.00			X
39 COVER EXH R LH (SUPP)	59024SG001	50.40			OK
40 PANEL CPL R/G	60809SG0509P	1072.80			OK
41 GLASS R/G	63019SG000	799.20			OK
42 RUBBER DAM GLS * 2	63232SG000	7.20			OK
43 RUBBER R/G	63232SG010	12.60			OK
44 CONDENSER ASSY (SUPP)	73210SG001	579.40			OK
45 LAMP ASSY HEAD EOF	84002SG220	2380.00			OK
46 LAMP ASSY HEAD EOF	84002SG230	2380.00			X
47 REFLEC AY RH	84281SC000	20.40			OK
48 REFLEX AY LH	84281SC010	20.40			OK
49 FOG LAMP ASSY F	84501AJ060	544.00			X

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGT8059R

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
50 LENS & BODY COMPLJPL	84912SG111	432.00			X
51 LENS & BODY COMPLRFR	84912SG121	432.00			X
52 NOZZLE COVER ASSYRH	86636SG340Q1	54.00			OK
53 NOZZLE COVER ASSYLH	86636SG350V2	54.00			OK
54 NOZZLE H L WASHERRH	86636SG361	79.20			X
55 NOZZLE H L WASHERLH	86636SG371	79.20			OK
56 INSULATOR HOOD TBRH	90815SG061	36.00			X
57 INSULATOR HOOD TBLH	90815SG070	36.00			X
58 GARNISH AY RG, B	91111SG000	144.00			X
59 GRILLE ASSY F UPRHG	91121SG210A	140.40			OK
60 GRILLE ASSY F CTRHG	91121SG240A	180.00			OK
61 GRILLE ASSY F LWRHG	91121SG280A	316.80			OK
62 BKT GRILLE LWR	91165SG010	21.60			OK
63 PROTR R GARNISH	91713SG000	21.60			OK
64 PROTECTOR LWR SD	91713SG010	10.80			OK
65 ORNAMENT R	93033SG001	79.20			OK
66 LETTER MK R XT	93079SG010	64.80			OK
67 LETTER MK R SUB	93079SG030	64.80			OK
68 CARGO STEP PANEL (RESIN)	E775ESG000	420.00			OK
69 FRONT NUMBER PLATE	WM001			45.00	OK

SUB TOTAL	13187.00	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)	2637.40	0.00	0.00	0.00
GRAND TOTAL	10549.60	0.00	45.00	0.00
OVERALL TOTAL	10594.60			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCT8059R

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
------------------------	--------------	------	------	--------	----------------

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGT8059R

NETT ITEM	13187.00
LESS 20 %	-2637.40
NETT AMOUNT	10549.60

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	45.00
---------------------	-------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	11575.00
TOTAL SPARE PARTS CHARGES	10594.60

TOTAL CHARGES	22169.60
ADD 7 % GST	1551.87

GRAND TOTAL	23721.47
-------------	----------
