



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SGT-8059-R

Surveyor: _____

DESCRIPTION	PART NO	AMOUNT
1 UNDER COVER- FRONT	56440SG060 <i>WV</i>	\$288.00
2 DUCT- BUMPER	57246SG010 <i>WV</i>	\$14.40
3 CONDENSER ASSEMBLY	73210SG001 <i>WV</i>	\$579.40
4 RADIATOR ASSEMBLY	45111SG010 <i>WV</i>	\$810.00
5 PACKING RADIATOR	45167SG010 <i>WV</i>	\$18.00
6 FENDER COMPLETE- FRONT- L&R	57120SG0309-P <i>WV</i>	\$270.00
7 FRAME COMPLETE RADIATOR LOWER	51231SG0009-P <i>WV</i>	\$108.00
8 SHROUD RADIATOR	45122SG000 <i>WV</i>	\$86.40
9 RESERVE TANK ASSEMBLY	45150SG001 <i>WV</i>	\$61.20
10		
11 Muffler LH	44300 SH 040 <i>WV</i>	601.20
12 Gasket	44011 SH 010 <i>X2 WV</i>	7.20 ^{X2} 14.40
13 Exhaust pipe rear	44200 SH 031 <i>WV</i>	792.00
14 Exhaust cover LH	59024 SH 001 <i>WV</i>	50.40
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		

CKC ANA/MD
17/5/2018



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SGT-8059-R

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

1	_____	_____
2	<u>REBSPRAY - FRONT LHS FENDER</u>	<u>\$ 420.00</u>
3	_____	_____
4	_____	<u>3374.72</u>
5	_____	_____
6	_____	_____
7	_____	_____
8	_____	_____
9	_____	_____
10	_____	_____
11	_____	_____
12	_____	_____

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGT8059R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FIRST CAPITAL DATE:07/05/2018 LOCATION:ECP JUNCTION 10 A TIME:0830HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER,HOOD AND PANEL	2240.00	2000.00
4	ZZ/003	RESPRAY FRONT BUMPER,HOOD AND PANEL	1680.00	1500.00
5	ZZ/004	REPAIR/REPLACE REAR BUMPER, TAILGATE, FLOOR PAN AND PANEL	2800.00	2500.00
6	ZZ/005	RESPRAY REAR BUMPER, TAILGATE, FLOOR PAN AND PANEL	2100.00	1680.00
7	ZZ/006	DISMANTLE/REFIX UNDERCARRIAGE REAR CENTER/LH/RH TO FACILITATE REPAIR	900.00	500.00
8	ZZ/007	REMOVE/REFIX EXHAUST	150.00	150.00
9	ZZ/008	TO CONDUCT WATER SEEPAGE TEST	100.00	50.00
10	ZZ/009	TRANSFER TAILGATE MECHANISM	150.00	150.00
11	ZZ/011	REMOVE/REFIX CARPET, SEAT TO FACILITATE REPAIRS	400.00	400.00
12	ZZ/012	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	150.00
13	ZZ/013	REMOVE/INSTALL REAR WINDSCREEN	300.00	150.00
14	ZZ/014	TO REMOVE/REFIX FUEL TANK	200.00	200.00
15	ZZ/015	TO CONDUCT FRONT AND REAR LIGHTING TEST	100.00	100.00
16	ZZ/016	TO CONDUCT FRONT AND REAR PROTECTANT COATING	1000.00	.00
17	ZZ/017	TO CONDUCT REAR ANTI RUST COATING	580.00	580.00
18	ZZ/018	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	300.00
19	ZZ/019	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	145.00
20	ZZ/020	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	150.00
21	ZZ/021	SUNDRIES	100.00	50.00
22	ZZ/022	REMOVE&REPLACE AIR CON CONDENSER VACUUM/GAS (SUPP)	200.00	200.00 (A)

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255