

PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

30/4/18 occ. dnt. bph

not Authorized

14/5/18

1/5 * 3680/r

2018 photo After rep.

14/5-confirmed

Tel :

Fax :

to Marcus 14/5/18 @ 1040

Quotation No : QO18/05-1122	Quotation Date : 10/05/2018	Terms : 30 DAYS
Vehicle No : SLL1839K	Chassis No : JM6BN22A8H0140543	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: FWD, INSURED'S VEHICLE NO: SLZ845A, DATE OF ACCIDENT: 10.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000	538.00
3	REAR BUMPER REFLECTOR	2	51.0000	102.00
4	REAR BUMPER SIDE RETAINER	2	37.0000	74.00
5	REAR BUMPER SIDE GUIDE	2	55.1000	110.20
6	REAR BUMPER SIDE GUIDE RIVETS	4	9.1000	36.40
7	REAR BUMPER CLIP	10	5.0000	50.00
8	REAR BUMPER SCREW SPACER	2	10.0000	20.00
9	REAR BUMPER SPACE SCREW	2	15.0000	30.00
10	REAR BUMPER TOW COVER	1	17.0000	17.00
11	REAR END PANEL	1	190.0000	190.00
12	REAR END PANEL INNER TRIM	1	45.0000	45.00
13	REAR END PANEL INNER TRIM CLIPS	4	5.0000	20.00
14	BOOTLID	1	958.0000	958.00
15	BOOTLID LOCK	1	153.0000	153.00
16	BOOTLID HINGE	1	146.0000	146.00
17	BOOTLID SKYACTIV BADGE	1	64.0000	64.00
18	BOOTLID CENTRE LOGO BADGE	1	75.0000	75.00
19	BOOTLID MAZDA 3 BADGE	1	54.0000	54.00
20	BOOTLID PULLER	1		
21	REAR LAMP CLIPS HOLDERS	6	5.0000	30.00
22	LESS 20% ITEM (1-21)	1	1.0000	1.00
23	REAR BUMPER PARKING SENSOR	1 set	450.0000	450.00

C/F 0.00

Page 1 of 2

P-3293
26344

PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/05-1122	Quotation Date : 10/05/2018	Terms : 30 DAYS
Vehicle No : SLL1839K	Chassis No : JM6BN22A8H0140543	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: FWD, INSURED'S VEHICLE NO: SLZ845A, DATE OF ACCIDENT: 10.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00
25	TO RUST-PROOFING OF THE AFFECTED AREAS	1	100.0000	100.00
26	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	120.0000	120.00
27	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,000.0000	1,000.00
28	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,200.0000	1,200.00

4604.4

LKK Auto Consultants hence **notify** the Repairer of the following:

- To resurvey before/after **spray** painting
- To display **damaged part(s)** during survey
- Parts prices are **subject** to survey
- Third party survey on "no prejudice" basis
- No **illegal modification** allowed
- Supplemental work to be resurveyed and is subject to approval from Insurance Company

Approved by repairer

Sub Total	6,778.60
GST(7.00%)	474.50
Total (SGD)	7,253.10

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216