



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : GBB8921EMake & Model : FIAT DOBLO 1.3MJTDYear of Manufacture : 2010Chassis No. : ZFA22300005727117Ins Company : OAC VS AXAEngine No. : 199A20003660817Excess : -Policy No. : -Date of Accident : 08.05.2018Time of Accident : 08:30Suggested Days of Repair : -In-house Vehicle Assessor**Repair Estimate**Case Owner : WILLIAM

Signature : _____

Parts (a) Cost / List Price Items \$ 17,870.05Plus/Less 10% \$ 1,787.01Total of Cost / List \$ 16,083.05(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 705.00Total Parts Cost (Appendix A) \$ 16,788.05Labour (Appendix B) \$ 4,140.00Total Repair Cost \$ 20,928.05

The above total will be subjected to 7% G.S.T.

Contact No

Frt Counter Operation

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell_cr@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Name of Surveyor : BryanCompany : LKK AutoSurvey conducted on : 14/05/2018 at 1145hrs.

Acknowledged by Repairer

Signature: _____

Date: _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 9 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____

Date: _____

Spare Parts

Vehicle No : GBB8921E Case Owner : WILLIAM
 Make & Model : FIAT DOBLO 1.3MJTD Year Manufacture : 2010
 Chassis No : ZFA22300005727117 Engine No : 199A20003660817
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front number plate with casing ✓	1				\$ 35.00	SVL
2	Front bumper ✓	1		\$ 755.66			distorted
3	Front bumper fog lamp cover LH ?	1		\$ 121.33			?
4	Front bumper fog lamp cover RH ✓	1		\$ 121.33			SVL
5	Front bumper reinforcement ?	1		\$ 1,112.10			?
6	Front grille ?	1		\$ 375.88			?
7	Front grille badge logo X	1		\$ 142.26			SVL
8	Headlamp LH ?	1		\$ 288.00			?
9	Headlamp RH ?	1		\$ 288.00			?
10	Headlamp lower garnish LH ?	1		\$ 184.34			?
11	Headlamp lower garnish RH ✓	1		\$ 184.34			?
12	Rear number plate with casing ✓	1				\$ 35.00	SVL
13	Rear bumper ✓	1		\$ 295.60			Bnc
14	Rear bumper LH ✓	1		\$ 405.00			Distorted
15	Rear bumper RH X	1		\$ 405.00			SVL
16	Rear bumper reflector LH X	1		\$ 35.72			SVL
17	Rear bumper reflector RH X	1		\$ 35.72			SVL
18	Reverse sensors ✓	2				\$ 200.00	Damn
19	Taillamp LH ?	1		\$ 332.72			broken
20	Taillamp RH ✓	1		\$ 346.51			?
21	Taillamp covering LH ✓	1		\$ 337.50			Cut
22	Taillamp covering RH ✓	1		\$ 337.50			Cut
23	Back door LH ✓	1		\$ 2,008.80			Bnc
24	Back door LH badge logo ?	1		\$ 30.00			Neu
25	Back door LH upper hinge ?	1		\$ 120.70			?
26	Back door LH lower hinge ?	1		\$ 120.70			?
27	Back door LH check ?	1		\$ 66.53			?
28	Back door LH glass ✓	1		\$ 165.00			Shattered
29	Back door LH glass sealant ✓	1				\$ 40.00	Neu
30	Back door LH glass inner seal ✓	1				\$ 30.00	Neu

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

Page 2

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBB8921E

Case Owner : WILLIAM

Make & Model : FIAT DOBLO 1.3MJTD

Year Manufacture : 2010

Chassis No : ZFA22300005727117

Engine No : 199A20003660817

Sales Order : 0

Supplier : 0

Order By : 0

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Back door LH wiper arm ✓	1		\$ 74.00			10f
32	Back door LH wiper arm blade ✗	1		\$ 27.00			SVL
33	Back door LH wiper motor ?	1		\$ 547.68			?
34	Back door LH wiper arm cover ✗	1		\$ 20.25			SVL
35	Back door LH trim board ?	1		\$ 268.14			?
36	speed limit sticker - 70 km/h ✓	1				\$ 15.00	hlc
37	Rear number plate lamp LH ?	1		\$ 56.44			?
38	Rear number plate lamp RH ?	1		\$ 56.44			?
39	Back door LH upper lock ?	1		\$ 166.36			?
40	Back door LH upper lock cover ?	1		\$ 11.64			?
41	Back door LH upper lock striker ?	1		\$ 42.45			?
42	Back door LH lower lock ?	1		\$ 163.30			?
43	Back door LH lower lock cover ?	1		\$ 11.64			?
44	Back door LH lower lock striker ?	1		\$ 42.45			?
45	Back door RH ✓	1		\$ 1,888.19			Bnc
46	Back door RH emblem - Mutijet ✓	1		\$ 76.73			hlc
47	Back door RH sticker - singtel ✓	1				\$ 100.00	hlc
48	Back door RH upper hinge ?	1		\$ 120.70			?
49	Back door RH lower hinge ?	1		\$ 120.70			?
50	Back door RH check ?	1		\$ 66.53			?
51	Back door RH glass ✓	1		\$ 195.00			Shamond
52	Back door RH glass sealant ✓	1				\$ 40.00	hlc
53	Back door RH glass inner seal ✓	1				\$ 30.00	hlc
54	Back door RH trim board ?	1		\$ 268.14			?
55	Back door RH upper lock ?	1		\$ 166.36			?
56	Back door RH upper lock cover ?	1		\$ 11.64			?
57	Back door RH upper lock striker ?	1		\$ 42.45			?
58	Back door RH lower lock ?	1		\$ 162.00			?
59	Back door RH lower lock cover ?	1		\$ 11.64			?
60	Back door RH lower lock striker ?	1		\$ 42.45			?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

15/05/2018

11:02 AM

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBB8921E Case Owner : WILLIAM

Make & Model : FIAT DOBLO 1.3MJTD Year Manufacture : 2010

Chassis No : ZFA22300005727117 Engine No : 199A20003660817

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
61	Back door opening weatherstrip ✓	1		\$ 321.36			deformed
62	Back door top weatherstrip ✓	1		\$ 140.46			deformed
63	Back door weatherstrip ✓	1		\$ 292.38			deformed
64	Rear bumper reinforcement ✓	1		\$ 297.00			✓
65	Rear end panel ?	1		\$ 651.43			?
66	Rear end panel top garnish ?	1		\$ 337.50			?
67	LH rear body panel (fender) X	1		\$ 2,217.73			repa
68	LH rear body panel sticker - Singtel ✓	1				\$ 180.00	hko
69	LH rear body panel inner shield X	1		\$ 128.60			HN
70	Back door lock RH X	1		\$ 207.03			HN
71	0	0					
72	0	0					
73	0	0					
74	0	0					
75	0	0					
76	0	0					
77	0	0					
78	0	0					
79	0	0					
80	0	0					
81	0	0					
82	0	0					
83	0	0					
84	0	0					
85	0	0					
86	0	0					
87	0	0					
88		0					
89		0					
90		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **GBB8921E**

Case Owner

: **WILLIAM**

Make & Model : **FIAT DOBLO 1.3MJTD**

Year of Manufacture

: **2010**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To transfer back door LH parts and mechanisms to new door.	\$60.00	40/-
2	To transfer back door RH parts and mechanisms to new door.	\$60.00	40/-
3	To remove/replace back door LH glass.	\$60.00	40/-
4	To remove/replace back door RH glass.	\$60.00	40/-
5	To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure.	\$250.00	180/-
6	To remove/refit fuel tank to facilitate repairs.		~44
7	To remove/refit cargo compartment trims and garnish to facilitate repairs.	\$50.00	40/-
8	To remove/refit aircond parts, vacuum & recharge gas.	\$100.00	~44
9	Labour charges to repair and panel beat the frt support panel and replace damaged parts.	\$500.00	400/-
10	Labour charges to repair and panel beat the LH rear body inner structure, RH taillamp panel, rear floor board panel, cutting/welding and replacing damaged parts.	\$1,400.00	1200/-
11	To check wiring functions and focus headlamps.	\$20.00	✓
12	To remove/replace reverse sensor to new rear bumper and check wiring functions.	\$80.00	40/-

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

photo

ComfortDelGro Engineering Pte Ltd

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

: WILLIAM
: 2010

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.