

22/03/2018

ACC REC BY:

REP:

CS/AWA18008728/200302

Special Instruction:

ASSIGNMENT (Office)

From (Person): Pan Kah Leong

of AWA

Date/Time: 14/5/2018

Estimated Cost: \$19,470.40

Bill to:

OD / TP / WL / IT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 9884 X

Insured:

at Workshop m/s Comfort Delgro Engineering

Tel: 68676919 Dong

of 45 Pandan Rd.

Policy No: AVCP8B0091021700

Claim No:

NSV1800284 / KW

Sum Insured:

Excess:

\$3800

Make of Veh:

D.O.A.

29/4/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Dennis 9180 1800

H.O.D. Endorsement:

Date/Time: 14/5

Person Contacted:

Dong

Vehicle IN / OUT

Date/Time	Action/Instruction () Estimate
	<u>GBG 9884 X - X</u>
	<u>Revert thm email</u>
<u>24/5/18</u>	<u>Authorise repair ; Inform Dennis & Wong authorise repair</u> <u>Repairer advise repair vehicle estimate within 3 month (refer email)</u>
	<u>* Submit Prelim report.</u>
	<u>exclude check repairs \$ 10549.07</u>

** REMARKS: "2" due to no photos support.

No photo upload 24/5

Janice Lee (LKKAuto)

From: Hew, LeeFong <LeeFong.Hew@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Thursday, May 17, 2018 10:40 AM
To: Janice Lee (LKKAuto)
Cc: SUR
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Janice

Please also check with the manufacturer's workshop if they can repair the vehicle and estimated repair period required.

Regards
Hew Lee Fong
Senior Claims Analyst
Motor Claims

*Borro
Toyota*

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0533
F: +65 6423 0864
E: leefong.hew@awac.com
W: www.awac.com

From: Hew, LeeFong On Behalf Of Motorsurvey
Sent: May 17, 2018 10:33 AM
To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Janice

CDGE had informed our insured that due to parts unavailable, the repair works will take about 5 months.

Insured is not willing to wait for so long, please assist to put vehicle up for repair tender with our other Q+ workshops. Please revert with their estimated repair period required.

Regards
Hew Lee Fong
Senior Claims Analyst
Motor Claims

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0533
F: +65 6423 0864
E: leefong.hew@awac.com
W: www.awac.com

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Sent: May 16, 2018 5:29 PM

To: Motorsurvey <Motorsurvey@awac.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Kah Leong,

Enclosed preliminary revised for GBG 9884X.

Repair day : 14 Days

We have not authorize repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, KahLeong [<mailto:KahLeong.Tan@awac.com>] **On Behalf Of** Motorsurvey

Sent: Monday, May 14, 2018 9:15 AM

To: assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: FW: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Importance: High

Dear Sirs,

Please assists on the OD survey assignment below.

Sorry for the omission.

Regards

Tan Kah Leong

Claims Group

Global Markets

Allied World Assurance Company, Ltd

60 Anson Road #08-01 MapleTree Anson Singapore 079914

T: +65 6423 0867

F: +65 6423 0864

E: kahleong.tan@awac.com

W: www.awac.com

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>

Sent: Friday, 11 May, 2018 4:18 PM

To: Motorsurvey <Motorsurvey@awac.com>

Cc: Hew, LeeFong <LeeFong.Hew@awac.com>

Subject: Re: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Importance: High

Dear Sir,

May I know when your side arrange conduct survey our client vehicle no.GBG9884X

Best Regards,

Wong Chee Wei
Crash Repair Pandan
DID 68676919
HP 97239882

From: Motorsurvey <Motorsurvey@awac.com>
To: 'CDGE Pandan Private Cars Crash Repair Counter' <pandan_cr@sparkcarcare.com>
Date: 05/09/2018 04:54 PM
Subject: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW
Sent by: "Hew, LeeFong" <LeeFong.Hew@awac.com>

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	: GBG 9884 X		
Policy Number	: AVCPSB0091021700	Account Code:	A458SD3
Policy Excess	: \$ 3,800		
Voluntary Excess	: NA		
Sum Insured	: Market Value with COE & PARF / 2017		
Make / Model	: TOYOTA DYNA 150 5MT		
Name of Workshop	: COMFORTDELGRO ENGINEERING		
Contact Number	: 6867 6919 / 9723 9882		
Person to Contact	: Mr Wong Chee Wei		
Estimated Cost of repairs	: \$ 19,470.40		
(x)	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)		
(x)	Please revert with your preliminary survey report with photographs		
Remarks			

Regards,

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Catherine Chong (LKK Auto)

From: Tan, KahLeong <KahLeong.Tan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Monday, 14 May, 2018 9:15 AM
To: 'assignments'
Cc: 'SUR'
Subject: FW: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW
Importance: High

Dear Sirs,

Please assists on the OD survey assignment below.

Sorry for the omission.

Regards
Tan Kah Leong
Claims Group
Global Markets

Allied World Assurance Company, Ltd
60 Anson Road #08-01 MapleTree Anson Singapore 079914
T: +65 6423 0867
F: +65 6423 0864
E: kahleong.tan@awac.com
W: www.awac.com

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Sent: Friday, 11 May, 2018 4:18 PM
To: Motorsurvey <Motorsurvey@awac.com>
Cc: Hew, LeeFong <LeeFong.Hew@awac.com>
Subject: Re: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW
Importance: High

Dear Sir ,

May i known when your side arrange conduct survey our client vehicle no.GBG9884X

Best Regards,

Wong Chee Wei
Crash Repair Pandan
DID 68676919
HP 97239882

From: Motorsurvey <Motorsurvey@awac.com>
To: 'CDGE Pandan Private Cars Crash Repair Counter' <pandan_cr@sparkcarcare.com>
Date: 05/09/2018 04:54 PM
Subject: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW
Sent by: "Hew, LeeFong" <LeeFong.Hew@awac.com>

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	: GBG 9884 X	Account Code:	A458SD3
Policy Number	: AVCPSB0091021700		
Policy Excess	: \$ 3,800		
Voluntary Excess	: NA		
Sum Insured	: Market Value with COE & PARF / 2017		
Make / Model	: TOYOTA DYNA 150 5MT		
Name of Workshop	: COMFORTDELGRO ENGINEERING		
Contact Number	: 6867 6919 / 9723 9882		
Person to Contact	: Mr Wong Chee Wei		
Estimated Cost of repairs	: \$ 19,470.40		
(x)	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)		
(x)	Please revert with your preliminary survey report with photographs		
Remarks			

Regards,

Claims Division

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: NSV1800284/kw

Date: 16 May 2018

Our Ref: CS/AWA18008727/M1rb

The Motor Claims Department
ALLIED WORLD ASSURANCE COMPANY LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. GBG 9884X

We thank you for the instruction on 14/05/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle 14/5/2018 at the premises of m/s: COMFORTDELGRO ENGINEERING and have the following to report:-

Repairer's Estimate (Gross)	: <u>S\$ 19,470.00</u>
Revised Estimate Amount	: <u>S\$ 9,416.60</u>
"Check" Items (Estimated)	: <u>S\$ 6,403.10</u>
Total Repair	: <u>S\$ 15,819.70</u>
Pre-Accident Value	: <u>S\$ 69,000.00</u>
COE/PARF value	: <u>S\$ 33,391.00</u>
Nett Value	: <u>S\$ 35,609.00</u>

Description of Damage:
The vehicle sustained damages at the front portion.



Comments/Present Status:
Damages consistent.
Repair cost economical.
Repair Day: 14 days

Yours faithfully
MA CHIN FOOK
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4831M
Vehicle Details	
Vehicle No.:	GBG9884X
Vehicle to be Exported:	No
Intended De-registration Date:	16 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2764780
Chassis No.:	JTFAT35YX0K209513
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	21 Dec 2017
First Registration Date:	21 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,804.00
COE Rebate Amount:	\$33,391.00
Total Rebate Amount:	\$33,391.00

The information contained herein is correct as at 16 May 2018.

OK

Janice Lee (LKKAuto)

From: Denis Teo Chin Chye <denisteo@sparkcarcare.com>
Sent: Wednesday, May 23, 2018 4:52 PM
To: Janice Lee (LKKAuto)
Cc: SUR; Ng Zong Xiong
Subject: Re: GBG 9884X AWA

Dear janice,

I have spoken to Mr Yu (Insured) as we will try to complete the repair within 3 month.

Currently one of our stockist able to bring in within 6-8week and is subjected manufacture(Toyota japan) have stock.

Please contact me if you need any further clarification.

Thanks & Rgds

Denis Teo,Manager,Crash Repair, CDGE,TEL:6383 7168,FAX:6284 4284

From: "Janice Lee (LKKAuto)" <JaniceLee@lkkauto.com>
To: Denis Teo Chin Chye <denisteo@sparkcarcare.com>
Cc: SUR <sur@lkkauto.com>
Date: 23/05/2018 16:25
Subject: GBG 9884X AWA

Dear Dennis,

Kindly confirm whether the vehicle can be repair within 3 months ?

Thank you.

Best Regards,
Jannice Lee (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Janice Lee (LKKAuto)

From: Wong, Kin <Kin.Wong@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Wednesday, May 23, 2018 5:19 PM
To: Janice Lee (LKKAuto); Motorsurvey
Cc: SUR
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Hi Janice

As mentioned in our earlier email, please proceed.

Thank you.

Regards,

Kin Wong

Allied World Assurance Company, Ltd.
60 Anson Road #08-01
Singapore 079914
T: +65 6423 0894
F: +65 6423 0864
E: kin.wong@awac.com
W: www.awac.com

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Sent: Wednesday, 23 May 2018 5:00 PM
To: Motorsurvey <Motorsurvey@awac.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Kin,

Enclosed reply from Dennis. Can we proceed to inform the authorize repair?

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Kin [mailto:Kin.Wong@awac.com] **On Behalf Of** Motorsurvey
Sent: Wednesday, May 23, 2018 4:10 PM
To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Hi Janice

As spoken, CDGE has confirmed that they can most likely repair the vehicle within 3 months.

So if they can email to confirm this to you, please proceed to authorize \$9,416.60, checked item of \$6,403.10 to be confirmed after dismantling.

Thank you.

Regards,

Kin Wong

Allied World Assurance Company, Ltd.
60 Anson Road #08-01
Singapore 079914
T: +65 6423 0894
F: +65 6423 0864
E: kin.wong@awac.com
W: www.awac.com

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Sent: Tuesday, 22 May 2018 3:27 PM
To: Wong, Kin <Kin.Wong@awac.com>
Cc: SUR <sur@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Hi Kin,

1. Wah Hong – bid for P/P \$23,201.70 (estimated) , Repair day: 28 days (including some item need air freight for 5-6 days)(estimate)
2. Hua Hong – bid for L/S \$29,500.00/- , Repair day : 6 weeks (estimate)

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAuto)
Sent: Monday, May 21, 2018 5:32 PM
To: Wong, Kin <Kin.Wong@awac.com>
Cc: SUR <sur@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Kin,

Please refer to below reply:

1. Hua Hong – pending reply
2. Lai Huat – unable to undertake offer
3. Yew Hock Motor – unable to undertake offer
4. Wah Hong – pending reply (will reply by today because they still checking for parts)
5. Accord Auto (Bukit Merah) – unable to undertake offer
6. Accord Auto (Ang Mo Kio) – unable to undertake offer

According Borneo Motor(manufacture's workshop), the repair takes around 3 weeks (estimated). Freight parts from overseas takes 3-4 weeks. Total repair takes around 2-3 months(estimate).

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Kin [<mailto:Kin.Wong@awac.com>]
Sent: Monday, May 21, 2018 8:42 AM
To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Hi Janice

Please give us an update so we can inform insured accordingly too.

Thank you.

Regards,

Kin Wong

Allied World Assurance Company, Ltd.

60 Anson Road #08-01

Singapore 079914

T: +65 6423 0894

F: +65 6423 0864

E: kin.wong@awac.com

W: www.awac.com

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Sent: Friday, 18 May 2018 2:45 PM

To: Wong, Kin <Kin.Wong@awac.com>

Cc: SUR <sur@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>

Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Kin,

Noted.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Kin [<mailto:Kin.Wong@awac.com>]

Sent: Friday, May 18, 2018 2:37 PM

To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Motorsurvey <Motorsurvey@awac.com>

Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Hi Janice

Please send chaser and update again.

Thank you.

Regards,

Kin Wong

Allied World Assurance Company, Ltd.

60 Anson Road #08-01

Singapore 079914

T: +65 6423 0894

F: +65 6423 0864

E: kin.wong@awac.com

W: www.awac.com

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Sent: Friday, 18 May 2018 2:36 PM

To: Wong, Kin <Kin.Wong@awac.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Kin,

As spoken, we are still pending reply from others repairer regarding the tender.

We have sent tender to :

1. Hua Hong – pending reply
2. Lai Huat – pending reply
3. Yew Hock Motor – unable to undertake offer
4. Wah Hong – pending reply
5. Accord Auto (Bukit Merah) – pending reply
6. Accord Auto (Ang Mo Kio) – pending reply

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Kin [<mailto:Kin.Wong@awac.com>]

Sent: Friday, May 18, 2018 1:16 PM

To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Hi Janice

Any updates?

Thank you.

Regards,

Kin Wong

Allied World Assurance Company, Ltd.

60 Anson Road #08-01

Singapore 079914

T: +65 6423 0894

F: +65 6423 0864

E: kin.wong@awac.com

W: www.awac.com

From: Hew, LeeFong **On Behalf Of** Motorsurvey

Sent: Thursday, 17 May 2018 10:40 AM

To: 'Janice Lee (LKKAuto)' <JaniceLee@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Janice

Please also check with the manufacturer's workshop if they can repair the vehicle and estimated repair period required.

Regards
Hew Lee Fong
Senior Claims Analyst
Motor Claims

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0533
F: +65 6423 0864
E: leefong.hew@awac.com
W: www.awac.com

From: Hew, LeeFong On Behalf Of Motorsurvey
Sent: May 17, 2018 10:33 AM
To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Janice

CDGE had informed our insured that due to parts unavailable, the repair works will take about 5 months.

Insured is not willing to wait for so long, please assist to put vehicle up for repair tender with our other Q+ workshops.
Please revert with their estimated repair period required.

Regards
Hew Lee Fong
Senior Claims Analyst
Motor Claims

Allied World Assurance Company, Ltd
60 Anson Road #08-01 Mapletree Anson Singapore 079914
T: +65 6423 0533
F: +65 6423 0864
E: leefong.hew@awac.com
W: www.awac.com

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Sent: May 16, 2018 5:29 PM
To: Motorsurvey <Motorsurvey@awac.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Dear Kah Leong,

Enclosed preliminary revised for GBG 9884X.
Repair day : 14 Days

We have not authorize repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, KahLeong [<mailto:KahLeong.Tan@awac.com>] **On Behalf Of** Motorsurvey

Sent: Monday, May 14, 2018 9:15 AM

To: assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: FW: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Importance: High

Dear Sirs,

Please assists on the OD survey assignment below.

Sorry for the omission.

Regards

Tan Kah Leong

Claims Group

Global Markets

Allied World Assurance Company, Ltd

60 Anson Road #08-01 MapleTree Anson Singapore 079914

T: +65 6423 0867

F: +65 6423 0864

E: kahleong.tan@awac.com

W: www.awac.com

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>

Sent: Friday, 11 May, 2018 4:18 PM

To: Motorsurvey <Motorsurvey@awac.com>

Cc: Hew, LeeFong <LeeFong.Hew@awac.com>

Subject: Re: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW

Importance: High

Dear Sir ,

May i known when your side arrange conduct survey our client vehicle no.GBG9884X

Best Regards,

Wong Chee Wei
 Crash Repair Pandan
 DID 68676919
 HP 97239882

From: Motorsurvey <Motorsurvey@awac.com>
 To: 'CDGE Pandan Private Cars Crash Repair Counter' <pandan_cr@sparkcarcare.com>
 Date: 05/09/2018 04:54 PM
 Subject: OD survey assignment for GBG 9884 X - DOA : 29.04.2018 Our Ref: NSV1800284/KW
 Sent by: "Hew. LeeFong" <LeeFong.Hew@awac.com>

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	: GBG 9884 X		
Policy Number	: AVCPSB0091021700	Account Code:	A458SD3
Policy Excess	: \$ 3,800		
Voluntary Excess	: NA		
Sum Insured	: Market Value with COE & PARF / 2017		
Make / Model	: TOYOTA DYNA 150 5MT		
Name of Workshop	: COMFORTDELGRO ENGINEERING		
Contact Number	: 6867 6919 / 9723 9882		
Person to Contact	: Mr Wong Chee Wei		
Estimated Cost of repairs	: \$ 19,470.40		
(x)	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)		
(x)	Please revert with your preliminary survey report with photographs		
Remarks			

Regards,

Claims Division

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error,

please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, May 23, 2018 5:32 PM
To: 'Denis Teo Chin Chye'; 'pandan_cr@sparkcarcare.com'
Cc: SUR; Ng Zong Xiong
Subject: RE: GBG 9884X AWA

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBG 9884XJ (excess \$3,800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denis Teo Chin Chye [mailto:denisteo@sparkcarcare.com]
Sent: Wednesday, May 23, 2018 4:52 PM
To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Ng Zong Xiong <ngzx@cdge.com.sg>
Subject: Re: GBG 9884X AWA

Dear Janice,

I have spoken to Mr Yu (Insured) as we will try to complete the repair within 3 months.

Currently one of our stockists able to bring in within 6-8 weeks and is subjected to manufacture (Toyota Japan) have stock.

Please contact me if you need any further clarification.

Thanks & Rgds

Denis Teo, Manager, Crash Repair, CDGE, TEL: 6383 7168, FAX: 6284 4284

From: "Janice Lee (LKKAuto)" <JaniceLee@lkkauto.com>

To: Denis Teo Chin Chye <denisteo@sparkcarcare.com>
Cc: SUR <sur@lkkauto.com>
Date: 23/05/2018 16:25
Subject: GBG 9884X AWA

Dear Dennis,

Kindly confirm whether the vehicle can be repair within 3 months ?

Thank you.

Best Regards,
Jannice Lee (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2018 11:33
Date Of Accident	29/04/2018 18:00
Exact Location Of Accident	JUNCTION OF JALAN BUROH AND JURONG PORT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG9884X
Insured/Policyholder	
Name Of Registered Owner	SONOMA ENTERPRISE PTE LTD
Co Reg No	199504831M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84502635
Alternative Phone No	OFFICE-62652528
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA-3.0 D 1.5T (M)
Exact Purpose for which vehicle was being used at time of accident	TRANSPORTATION
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	AVCPSB0091021700
Cover Note Number	
Driver	
Name of Driver	LI CHUNBO
Passport No/FIN	G2942605N
Date Of Birth	27/07/1982
Occupation	OUTDOOR
Date Of Driving Pass	21/09/2017
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92463119
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 15 JALAN TEPONG #05-09 SINGAPORE
 Postcode 619336
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBS3346J
 Vehicle Make/Model/Colour VOLVO / GREEN
 Details Of Properties FRONT RIGHT HANS SIDE PORTION
 Vehicle Category BUS
 Name of Driver HARY PADLI MANURUNG BIN RAMLAN
 NRIC/Passport Number G2107639U
 Contact Number UNKNOWN
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

3 weeks
 3-4 week - freight

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **reudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 30 Apr 2018
 11:30 AM


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

COMPONENTS ENGINEERING PTE LTD
 EXERCISE BUSINESS ON PARKWAY ROAD
 NAME & SIGNATURE: 
 DESIGNATION: _____ DATE: 20/04/18
 Reporting Centre Personnel's Signature
 Name: GONG CHEE WEI
 NRIC/TIN No. 872180994

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25 Apr 2018 18:00 I drove B86-9834 X On Jln Puch, Was turning to Jurong Port Road. I thought the SBS bus was left turning, but the Bus was going ~~left~~ Straight, then the accident happened.


DECLARATION

I/We declare the foregoing particulars are true in every respect.



 Policyholder's Signature
 Date & Time: 30 Apr 2018
 11:30 am


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: 
 NRIC/IN No: 677180991

COMMERCIAL VEHICLE (ION 1)

92330/C

CERTIFICATE OF INSURANCE

I 38

A45100

Corr. Type : C

330200

THE MOTOR VEHICLES LIABILITY RISKS AND COMPANIES (REGULATORY) ACT 1991 OF THE REPUBLIC OF SINGAPORE
THE ROAD TRAFFIC ACT 1960 OF MALAYSIA

THE AGREEMENT BETWEEN THE MINISTER FOR TRANSPORT (SINGAPORE) AND THE MOTOR INSURERS BUREAU OF SINGAPORE DATED 12 FEBRUARY 1975
THE AGREEMENT BETWEEN THE MINISTER OF TRANSPORT (MALAYSIA) AND THE MOTOR INSURERS BUREAU OF WEST MALAYSIA DATED 15 JANUARY 1988
ANY SUBSEQUENT AMENDMENTS TO THE ABOVE ACTS AND AGREEMENTS

CERTIFICATE No. **AVCP9802R1031700** **Challr: J79AT15YK3209512**

1. Index Mark and Registration Number of Vehicle **QSC 8884 T**

2. Name of Policyholder **SOMORA ENTERPRISE PTE LTD**

3. Effective Date of Commencement of Insurance **21 December 2017**
for the purposes of the Ordinance

4. Date of Expiry of Insurance **20 December 2018**

5. Persons or Classes of Persons entitled to drive* (For certificate references MX1 and MX4, see overleaf)
ANY PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the provisions of other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use* (For certificate reference MX1, see overleaf)

- A. USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
 - B. USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
 - C. USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES.
- THE POLICY DOES NOT COVER:
- 1. USE FOR HIRE OR REWARD OR FOR RACING, RACE-MAKING, RELIABILITY TRIAL OR SPEED-TESTING.
 - 2. USE WHILE DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

Estimated Value : **MARKET VALUE WITH COE/PAFF**
 Hire Purchase Owner :
 Type of Cover : **Comprehensive**

Limitations required inoperative by Section 77 of the Road Traffic Ordinance (1960 (Malaysia) or Section 7 of the Motor Vehicle (Third-Party) and Compensation Ordinance (1960 (Republic of Singapore)) are not to be included under the headings.

WE HEREBY CERTIFY that the policy to which this certificate refers is issued in accordance with the provisions of Part IV of the Road Transport Act (1987 (Malaysia) and The Motor Vehicle (Third-Party) and Compensation Act (Chapter 107) (Republic of Singapore)



[Handwritten signature]

Spare Parts

Vehicle No. : GBG9884X
 Make & Model : TOYOTA DYNA 150 5MT
 Chassis No. : JTFAT35YX0K209513

Submit By : Wong Chee Wei
 Year Manufacture : 2017
 Engine No. : 1KD2764780

Pages 2

S/No	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price	Disposition By Surveyor
31	FRONT BUMPER <i>ok</i>	1	\$300.00	270			
32	FRONT BUMPER BRACKET <i>lth ok</i>	1	\$240.00	165			
33	FR NUMBER PLATE <i>was</i>	1				\$45.00	
34	FRONT DOOR LH <i>ok</i>	1	\$580.00	600			
35	FRONT DOOR LH HINGE <i>ok</i>	1	\$45.00	50			
36	FRONT LOWER DOOR SEAL LH <i>new</i>	1	\$48.00	75			
37	WEATHERSTRIP <i>new</i>	1	\$75.00	75			
38	FRONT TRIM COVER LH <i>dis</i>	1	\$300.00	390			
39	DASHBOARD <i>dis</i>	1	\$600.00	550			
40	LOWER DASHBOARD COVER LH <i>dis</i>	1	\$95.00	X	ND		
41	LOWER DASHBOARD COVER RH <i>one x</i>	1	\$120.00				
42	LOWER DASHBOARD COVER CENTRE <i>? 705+195</i>	1	\$95.00	400	✓ CRA		
43	UPPER DASHBOARD COVER LH <i>?</i>	1	\$38.00	100	✓ CRA		
44	UPPER DASHBOARD COVER RH <i>?</i>	1	\$38.00	X	ND		
45	UPPER DASHBOARD COVER CENTRE <i>?</i>	1	\$180.00	240	✓ CRA		
46	METER COVER <i>X</i>	1	\$125.00	X	ND		
47	FRONT AIRBAG COVER LH <i>?</i>	1	\$1,200.00	2750	✓		No photo ?
48	A/C BLOWER UNIT <i>?</i>	1	\$110.00	X	ND		
49	A/C HEATER & EVAPORATOR UNIT ASSY <i>?</i>	1	\$2,500.00	1740	✓		No photo ?
50	A/C TUBE <i>?</i>	1	\$160.00	fx	SIC		
51	HEATER HOSE INLET OULET <i>?</i>	2	\$420.00				
52	CONDENSER <i>?</i>	1	\$150.00	650	✓		} No photo ?
53	CONDENSER BRACKET <i>?</i>	1	\$250.00	240	✓		
54	LIQUID PIPE OULET <i>?</i>	1	\$350.00	510	✓		
55	DISCHARGE HOSE <i>?</i>	1	\$210.00	300	✓		
56	FRONT MUDGUARD LH <i>new X</i>	1	\$80.00				
57	FRONT MUDGUARD BRACKET LH <i>new X</i>	1	\$90.00				
58	BODY SEALANT <i>new</i>					\$120.00	
59							
60							
61							
62							
63							
64							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : Own Damage
 3rd Party
 Windscreen

Vehicle No. : **GBG9884X**
 Make & Model : TOYOTA / DYNA 150 5MT
 Year of Manufacture : 2017
 Chassis No. : JTFAT35YX0K209513
 Engine No. : 1KD2764780
 Policy No. : AVCPSB0091021700
 Time of Accident : 15.20 P.M

Ins Company : AWAC
 Excess : _____
 Date of Accident : 29.04.2018
 Suggested Days of Repair : 20 DAY

In-house Vehicle Assessor

Repair Estimates

Name : Wong Chee Wei
 Signature : _____
 Contact No : 68676919
 HP : 97239882

Parts (a) Cost / List Price Items	\$12,927.00	12,927.00
Plus/Less 10 %	\$1,292.70	
(b) Nett Price Items		
Less _____ %		12,029.369
(c) Special Nett Items	\$191.00	191
Total Parts Cost (Appendix A)	\$14,410.70	
Labour (Appendix B)	\$5,060.00	
Total Repair Cost	\$19,470.70	19,470.70

The above total will be subjected to 7% G.S.T. 20782.441

Name of Surveyor : _____
 Company : _____
 Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.
 (b) Recommended Days of Repair : _____ day(s)
 (c) Resurvey : Required / Not Required
 (d) Excess : \$ _____
 (e) Signature of surveyor : _____ Date: _____

COMFORTDELGRO ENGINEERING PTE LTD

Appendix B

45 Pandan Road S (609386)

Tel: 68676919 Fax: 62626950,68676903

Labour

Vehicle No. : GBG9884X Submit By : Wong Chee Wei
 Make & Model : TOYOTA Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO REMOVE/ REPLACE/RE FIT / STRIAGHTEN/PANEL BEAT / CUT / WELD / RE ALIGN :FRONT PANEL,FR CROSS PANEL DOOR LH & RH , A PILLE RH & LH ,FLOOR PANEL / FRONT BUMPER AND DAMAGED AREA	\$1,600.00	1200.
2	TO PUTTY,RESPRAY :FRONT PANEL,FR CROSS PANEL, DOOR RH & LH ,A - PILLE RH & LH ,FLOOR PANEL , FRONT BUMPER AND DAMAGED AREA	\$2,400.00	1000
3	TO CHECK WIRE	\$60.00	30.
4	TO REMOVE / REPLACE A/C BLOWER UNIT ,HEATER & EVAPORATOR UNIT,CONDENSER .	\$250.00	/
5	TO VACCUM AND RE FILL A/C GAS AND OIL	\$160.00	120.
6	TO REMOVE / REPLACE DASH BOARDS	\$200.00	/
7	TO REMOVE / REPLACE FRONT WINDSCREEN	\$100.00	/
8	TO REMOVE / TRANSFER DOOR FITTING AND MACHANISM TO NEW DOOR / FACILITATE REPAIR RH & LH	\$300.00	60.
Report - *S \$3800- P/P Repair - Before Paint Photo Let Also MB 14 wdays			

[Handwritten Signature]
8/11/18

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Spare Parts

Vehicle No: GBG9884X Submit By: Wong Chee Wei
 Make & Model: TOYOTA DYNA 150 5MT Year Manufacture: 2017
 Chassis No: JTFAT35YXOK2D9513 Engine No: 1KD2764780

OD

S/Order

S/No	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price	Disposition By
✓	FRONT WINDSCREEN <i>cvh</i>	1	\$480.00	480			
✓	FRONT WINDSCREEN RUBBER <i>w/r</i>	1	\$120.00	95			
3	IU BRACKET <i>w/r</i>	1				\$26.00	
✓	WIPER PANEL <i>br</i>	1	\$120.00	32.5			
✓	WIPER PANEL SEAL <i>w/r</i>	1	\$45.00	55			
✓	WIPER NOZZLE <i>tan</i>	12	\$20.00	20			
✓	WIPER ARM LH <i>br</i>	1	\$75.00	60			
✓	WIPER ARM RH <i>br</i>	1	\$75.00	60			
✓	WIPER BLADE LH <i>br</i>	1	\$55.00	55			
✓	WIPER BLADE RH <i>br</i>	1	\$45.00	55			
✓	WIPER MOTOR LINKAGE <i>gbr</i>	1	\$120.00	125			
✓	CORNER PANEL LH <i>br</i>	1	\$125.00	95			
✓	CORNER PANEL CLIP <i>w/r</i>	2	\$7.50	15			
✓	CORNER PANEL BRACKET SIDE <i>br</i>	1	\$40.00	35			
✓	CORNER PANEL BRACKET UPPER <i>br</i>	1	\$25.00	40.25			
✓	CORNER PANEL TOP COVER <i>w/r</i>	1	\$45.00	98.83			
✓	SIDE MIRROR LH <i>cut</i>	1	\$100.00	220			
✓	ROUND MIRROR LH <i>w/r</i>	1	\$420.00	-			
✓	ROUND MIRROR BRACKET LH <i>br</i>	1	\$120.00	-			
✓	SIDE MIRROR BRACKET CAP LH <i>w/r</i>	1	\$35.00	-			
✓	FRONT PANEL <i>abt</i>	1	\$450.00	400			
✓	EMBLEM - DYNA <i>w/r</i>	1	\$85.00	40			
✓	FRONT GRILLE <i>w/r</i>	1	\$230.00	230			
✓	FRONT GRILLE CLIP MALE <i>w/r</i>	6	\$3.50	29			
✓	FRONT GRILLE CLIP FEMALE <i>w/r</i>	4	\$4.25	17			
✓	LOGO - TOYOTA <i>w/r</i>	1	\$40.00	40			
✓	LOWER FRONT CROSS PANEL <i>R x</i>	1	\$240.00	-			
✓	A PILLAR PANEL <i>R x</i>	1	\$190.00	-			
✓	HEADLAMP LH <i>w/r</i>	1	\$470.00	470			
✓	HEADLAMP RH <i>w/r</i>	1	\$470.00	470			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

~~FRONT GRILLE~~ *Acc*
 FRONT PANEL CLIP *2 nos - R/L*
~~FRONT GRILLE~~
 FRONT SUPPORT PANEL
 LWS SUPPORT BAR

Vehicle Part

Vehicle No. : **GBG9884X**
 Make & Model : **TOYOTA DYNA 150 SMT**
 Chassis No. : **JTFAT35YXDK209513**

Submit By : **Wong Chee Wei**
 Year Manufacture : **2017**
 Engine No. : **1KD2764780**

S/No	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price	Disposition By Surveyor
31	FRONT BUMPER <i>del</i>	1	\$300.00	290			
32	FRONT BUMPER BRACKET <i>LH. del</i>	1	\$240.00	125			
33	FR NUMBER PLATE <i>del</i>	1				\$45.00	
34	FRONT DOOR LH <i>del</i>	1	\$850.00	652			
35	FRONT DOOR LH <i>Hinge. del</i>	2	\$45.00	50			
36	FRONT LOWER DOOR SEAL LH <i>del</i>	1	\$48.00	25			
37	WEATHERSTRIP <i>del</i>	1	\$75.00	75			
38	FRONT TRIM COVER LH <i>del</i>	1	\$300.00	390	<i>del</i>		
39	DASHBOARD <i>del</i>	1	\$600.00	550			
40	LOWER DASHBOARD COVER LH <i>del</i>	1	\$95.00	-			
41	LOWER DASHBOARD COVER RH <i>del</i>	1	\$120.00	-			
42	LOWER DASHBOARD COVER CENTRE <i>del</i>	1	\$95.00	400			
43	UPPER DASHBOARD COVER LH <i>del</i>	1	\$38.00	100			
44	UPPER DASHBOARD COVER RH <i>del</i>	1	\$38.00	-			
45	UPPER DASHBOARD COVER CENTRE <i>del</i>	1	\$160.00	340			
46	METER COVER <i>del</i>	1	\$125.00	-			
47	FRONT AIRBAG COVER LH <i>del</i>	1	\$4,200.00	2750			
48	A/C BLOWER UNIT <i>del</i>	1	\$140.00	-			
49	A/C HEATER & EVAPORATOR UNIT ASSY <i>del</i>	1	\$2,900.00	1,740			
50	A/C TUBE <i>del</i>	1	\$180.00	-			
51	HEATER HOSE INLET OULET <i>del</i>	2	\$420.00	-			
52	CONDENSER <i>del</i>	1	\$480.00	650			
53	CONDENSER BRACKET <i>del</i>	1	\$269.00	290			
54	LIQUID PIPE OULET <i>del</i>	1	\$360.00	550			
55	DISCHARGE HOSE <i>del</i>	1	\$240.00	340			
56	FRONT MUDGUARD LH <i>del</i>	1	\$90.00	-			
57	FRONT MUDGUARD BRACKET LH <i>del</i>	1	\$90.00	-			
58	BODY SEALANT <i>del</i>					\$120.00	
59							
60							
61							
62							
63							
64							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

LHF door glass door maldy

LHF Door Hinge - 2

Air con Motor - 1

Chewing - 1

LHF Door Power Window Regulator + Motor

LOWER Air Con + Ass Clowm + Fan + Pipe
 Air Con + BRACKET.

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609386)
Tel: 68676919 Fax: 62626950,68676903

Appendix B

Labour

Vehicle No. : GBG9884X
Make & Model : TOYOTA

Submit By : Wong Chee Wei
Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO REMOVE/ REPLACE/RE FIT / STRIAGHTEN/PANEL BEAT / CUT / WELD / RE ALIGN :FRONT PANEL,FR CROSS PANEL DOOR LH & RH , A PILLE RH & LH ,FLOOR PANEL / FRONT BUMPER AND DAMAGED AREA	\$1,800.00	1200.
2	TO PUTTY,RESPRAY :FRONT PANEL,FR CROSS PANEL, DOOR RH & LH ,A - PILLE RH & LH ,FLOOR PANEL , FRONT BUMPER AND DAMAGED AREA	\$2,400.00	1500
3	TO CHECK WIRE	\$80.00	30.
4	TO REMOVE / REPLACE A/C BLOWER UNIT ,HEATER & EVAPORATOR UNIT,CONDENSER .	\$250.00	/
5	TO VACCUM AND RE FILL A/C GAS AND OIL	\$160.00	120.
6	TO REMOVE / REPLACE DASH BOARDS	\$200.00	/
7	TO REMOVE / REPLACE FRONT WINDSCREEN	\$100.00	/
8	TO REMOVE / TRANSFER DOOR FITTING AND MACHANISM TO NEW DOOR / FACILITATE REPAIR RH & LH	\$380.00	60.
	Devort -		
	XS \$23800		
	P/P Repair -		
	Before Paint Photo		
	Let Auto M/B		
	14 W/acc/s		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

VEHICLE NO.: **GBG9884X**
 MAKE: **GYNA 150 5MT**
 MODEL:
 YEAR OF MAKE: **2017**
 CHASSIS NO.: **JTFAT35YXOK209513**

++ put all as "2"

S/N	Parts Description	PART NUMBER	Qty	Rem COST
1	LH FRT DOOR TOP HINGE / bent			X
2	LH FRT DOOR BOTTOM HINGE / bent			X
3	LH FRT DOOR GLASS REGULATOR WITH MOTOR / crack		1	120
4	AIRCON FAN MOTOR ASSY / crack	88590		X
5	AIRCON SUCTION PIPE			X
6	AIRCON RETURN PIPE / bent		1	115
7	AIRCON CONDENSOR BRACKET / bent	88462A		
8	AIRCON FAN MOTOR WIRE HARNESS / broken	87138S	2	915
9	AIRCON PIPE FROM COMPRESSOR TO COIL / bent	88712B	1	120
10	AIRCON PIPE FROM DRIER TO CONDENSOR / bent	88716A		
11	AIRCON PIPE FROM CONDENSOR TO COMPRESSOR / bent	88711		
12	AIRCON FAN MOTOR BRACKET / bent	88463	1	115
13	WIPER PANEL OUTER / bent	55078		
14	WIPER TOP STRIP / bent	55378B		
15	FRT PANEL SIDE CLIPS / missing		2	
16	DASHBORAD REINFORCEMENT BAR / bent		1	480
17	AIRCON BLOWER CASING / crack	87010	1	950
18	AIRCON COIL CASING / crack	87210F		
19	DASHBORAD LH SHELF / crack	55451C	1	160.65
20	DASHBORAD CENTER SHELF / crack	55452A	1	125.78
21	AIRCON CASING AIR DUCT / crack			
22	AIRCON DRAINAGE / bent Washer tank		1	65
23	Dashborad LH Bracket	55322C		
24	Air fan pipe 3mt	88710A		
25	LHF door glass inner moulding	68172A		
26	LH door 1st company address sticker		SN	\$15
27				
28				
29				
30				

3166.43
 x 1.1
 3483.073
 15
 3498.073



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1888 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

MS. COMFORTDELORO ENGINEERING PTE LTD
(DELORO)
50 BRADFIELD ROAD
EXTENSION 1 BRIDGEVIEW
SINGAPORE 259601
6749884X
09%

NO: 0110203874
DATE: 15/06/2018
AMOUNT: 110,000.00
TAX: 10,000.00
TOTAL: 120,000.00

AMOUNT: 120,000.00

QTY	Description	Part No	Unit	Price	Amount
1	GRIP WIPER RH/RH	DUS	1	400.00	400.00
2	WIPER BLADE FR	DUH20-3	2	25.00	50.00
1	WIPER NOZZLE R/L/H	DUH59	1	30.00	30.00
1	WIPER ARM LH 2013	DDICT41	1	200.00	200.00
1	WIPER BLADE FR RH	DDICT10	1	30.00	30.00
1	WIPER WASHFR LH	DDICT39	1	50.00	50.00
1	GRIP	DDIAD10	1	50.00	50.00
8	FR FLOOR BRKT	DUS	8	50.00	400.00
9	FR PANEL	DDI2015	1	600.00	600.00
10	LOCK NEW	DDIAG2-22	1	40.00	40.00
11	RAD GRILLE	GRIES-1	1	240.00	240.00
12	RAD GRILLE R/L	DUS	1	4.00	4.00
12	GRIP	DUS	1	3.00	3.00
14	FRONT LAMP	DDIAG3-9	1	40.00	40.00
15	HEADLAMP UNIT RH	DST211	1	480.00	480.00
16	HEADLAMP UNIT	DST211	1	480.00	480.00
17	FR BUMPER	DST211	1	280.00	280.00
18	FR BUMPER BRACKET LH	DST211	1	125.00	125.00
19	DOOR FR LH	DUS	1	652.00	652.00
20	DOOR W/STRIP FR LH	DUS	1	75.00	75.00
21	DOOR W/STRIP FR LH	DUS	1	75.00	75.00

Handwritten numbers 1 through 21, corresponding to the line items in the table.

Printed: SAT 15/06/2018 3:30:51 PM

COMFORTDELORO ENGINEERING PTE LTD

SCM, MAIN OFFICE (BRADFIELD)

NAME & SIGNATURE: *[Signature]*

DESIGNATION: *[Signature]* DATE: 15/06/18

6.6.18





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
 TEL: 6291 2827 FAX: 6296 4390
 A/C: 6291 1886 FAX: 6291 7717
 Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

TO: COMFORTDELORO ENGINEERING PTE LTD
 (DELORO)

NO: 011923R074
 DATE: 7

TOTAL EX GST	SGD 3,767.56
DELORO 27%	1,017.74
RECEIVED FROM	SGD 3,967.56

QTY	W
DESCRIPTION	
UNIT PRICE	
TOTAL	
AMOUNT	
TAX	
TOTAL	

3708

DATE TIME: 08/06/2018 0:30:53 PM
 SERIAL: 001
 THIS DOCUMENT IS COMPUTER GENERATED. No signature required.

COMFORTDELORO ENGINEERING PTE LTD
 SCM MAIN OFFICE (BRADGELL)
 NAME & SIGNATURE: *[Signature]*
 DESIGNATION: *[Signature]* DATE: 15/6/18
 6.6.18





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

MS: COMFOITDELGRO ENGINEERING PTE LTD
 (DELEGRO)
 15 WILMINGTON ROAD #01-01
 SUTHERLAND SQUARE
 SINGAPORE 231510
 TEL: 6296 4390
 FAX: 6291 7717

NO: 0119203889
 DATE: 11/08/2008
 TAX: 100.00
 TOTAL: 100.00

DATE: 11/08/2008

Code	Description	Quantity	Unit Price	Total Price	Tax
✓ 39	DAS (BRAND)	1	39.00	39.00	0.00
		TOTAL QUANTITY	TOTAL	39.00	0.00
			TOTAL	39.00	0.00

Handwritten: 39
 6/8
 15/08/08
 COMFOITDELGRO ENGINEERING PTE LTD
 SCM, MAIN OFFICE (BRADDELL)
 NAME & SIGNATURE: _____
 DESIGNATION: _____ DATE: _____

550

Printed on 11/08/2008 11:55:20 AM

SALESMAN: AT

This document is computer generated. No signature required.

Copyright © 2008 HE XING AUTO PARTS PTE LTD



HE XING AUTO PARTS PTE LTD





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
 TEL: 6291 2827 FAX: 6296 4390
 A/C: 6291 1888 FAX: 6291 7717
 Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: COMFORTDELGRO ENGINEERING PTE LTD
 (DELGRO)
 205 BRADDELL ROAD/BLK C
 EXTENSION 4 3RD FLOOR
 SINGAPORE 570201
 68698845
 HELIOS

NO: DL19205142
 PAGE: 1
 DATE: 06.07.2018
 A/C CODE: 1113100
 TERMS: 1/30
 PO No: 450029395

Part No	Description	Location	Qty	Unit Price	Amount
1 ✓ 188461-25050	CONDENSER	DDS (52)	1	650.00	650.00
2 ✓ 188590-25080	AIR CON FAN MOTOR	DDS 38	1	250.00	250.00
3 ✓ 188463-25041	AIR CON CONDENSER BRACKET	DDS (53)	1	200.00	200.00
4 ✓ 188462-25020	AIR CON CONDENSER BRACKET SMALL	DDS 512	1	115.00	115.00
5 ✓ 187148-25070	AIR CON FAN MOTOR WITH HARNESS	DDS 58	1	65.00	65.00
6 ✓ 155008-37110	WIPER PANEL NEW	DB1FS0 (4)	1	325.00	325.00
7 ✓ 155748-37080	WIPER PANEL TOP SEAL	DDS (5)	1	35.00	35.00
TOTAL QUANTITY				TOTAL	2,350.00
				ADJUST @ 7%	164.50
				GRAND TOTAL	SIN 2,514.50

Verified By	Helen Seet Senior Logistics Supervisor Logistics Management
GL A/C Code	
Business Area	
Cost Center	
Approved for payment	Raymond Fong
Posted By	

0606 GMT 05:07:00 18 0 28:35 AM

SALESMAN MI

This document is computer generated. No signature required.

FOR USE ONLY AND NOT RETURNABLE

COMFORTDELGRO ENGINEERING PTE LTD

SCM MAIN OFFICE (BRADDELL)

NAME & SIGNATURE: *[Signature]* 5/7/18 10:50h

DESIGNATION: _____ DATE: _____

GOODS RECEIVED BY: _____





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: **COMFORTDELGRO ENGINEERING PTE LTD**
(DELGRO)
 205 BRADDELL ROAD BJKC
 EXTENSION 1, 3RD LEVEL
 SINGAPORE 579701
 GBC9884X
 HELEN

NO: **DL19205145**
 PAGE: **1**
 DATE: **13/07/2018**
 A/C CODE: **LDDE100**
 TERMS: **CR**
 P/O NO: **4500793395**

Toyota Dyna

Part No	Description	Location	Qty	Unit Price	Amount	
1	T73970-37021-C0 AIRBAG LH	DDS #	47	2,750.00	2,750.00	
2	T69802-37061 REGULATOR FR LH -P/W	DUID75-1 #	3	120.00	120.00	
3	T68730-37010 DOOR HINGE FR TOP LH	DDS #	3	50.00	50.00	
4	T85211-37250 WIPER ARM RH 2013	DDS #	8	60.00	60.00	
5	T85150-37150 WIPER LINK 2013	DUIF20-1 #	1	125.00	125.00	
6	T87010-37230 A/C ON COOLING UNIT ASSY	DDS #	1	1,790.00	1,790.00	
TOTAL QUANTITY:				6	TOTAL	SIN 4,895.00
					ADD GST @ 7%	342.65
					GRAND TOTAL	SIN 5,237.65

Verified By	Helen Seet Senior Logistics Supervisor Logistics Management
GL A/C Code	
Business Area	
Cost Center	
Approved for payment	Raymond Fong
Posted By	

AL
 13/7/18
 11:55

Print / MT / 13/07/2018 9:44:04 AM

SALESMAN MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

COMFORTDELGRO ENGINEERING PTE LTD

SCM, MAIN OFFICE (BRADDELL)

NAME & SIGNATURE: _____

SIGNATURE: _____ DATE: _____

GOODS RECEIVED BY _____

F & O E



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
 TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
 DAIHATSU / KIA / SUZUKI / HONDA
 TEL: 6291 2827 FAX: 6295 4390
 A/C: 6291 1895 FAX: 6291 7717
 Co. Reg. No: 200310923R GST Reg No: 20-0310923-R

TAX INVOICE

TO: COMFORTDELGRO ENGINEERING PTE LTD
 (DELGRO)
 205 BR. MARYMOUNT ROAD BLK C
 EXTENSION 11 3RD FLOOR
 SINGAPORE 379794
 GRU9884X
 HELIX

NO: 0149106087
 DATE: 31.07.2018
 QUANTITY: 1118.000
 TAXES: 0.00
 TOTAL: 4000704495

Part No	Description	Quantity	Unit Price	Amount
1 15534637210	DASHBOARD REINFORCE	316	1.50	480.00
2 1534053720001	UPPER DASHBOARD COVER RTK	43	40.00	1720.00
3 1553463700001	UPPER DASHBOARD COVER RL	43	40.00	1720.00
4 15230637511	AC COIL FLOWER CASING	317	2.00	634.00
5 18871125491	AC PIPE FROM CONDENSER TO COMPRESSOR	317	1.50	480.00
6 18871125821	AC PIPE FROM COMPRESSOR TO COIL	317	1.50	480.00
18871125461	AC PIPE FROM DRIER TO CONDENSER	316	1.50	480.00

TOTAL QUANTITY: 2015.000
 TOTAL AMOUNT: 204.00
 GRAND TOTAL: SIN 3,119.00

Verified By	Helen Seet Senior Logistics Supervisor Logistics Management
GL A/C Code	
Business Area	
Cost Center	
Approved for payment	Raymond Fong
Posted By	

31.7.18
 2:15 pm

Report Date: 31/07/2018 12:01 PM
 SALESMAN: MI
 This document is computer generated. No signature required.

THIS DOCUMENT IS NOT VALID UNLESS IT IS RETURNABLE



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
 TEL: 6291 2827 FAX: 6296 4390
 A/C: 6291 1886 FAX: 6291 7717
 Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

TO: COMFORTDELGRO ENGINEERING PTE LTD
 (DELGRO)
 205 BRADDON ROAD (BLOCK D)
 LINTAS BUILDING 4TH FLOOR,
 SINGAPORE 119076
 TEL: 62988442

NO: DL19208691
 DATE: 5/10/18
 AMOUNT: 1200.00
 TAXES: 0.00
 PAYMENT: 450000780
 VENDOR: 461100040000

Part No	Description	UNIT	QTY	Unit Price	Amount
1	FR DOOR TRIM BOARD LH	PCS	1	400.00	400.00
2	MIRROR LH	PCS	1	220.00	220.00
3	AIR COND PIPE JOINT	PCS	1	120.00	120.00
4	FR SIDE PANEL LH	DUPLICATE	1	95.00	95.00
5	WASHER TANK	PCS	1	65.00	65.00
6	FR FRONT PANEL	DUPLICATE	1	200.00	200.00

TOTAL QUANTITY: 6
 TOTAL: 1200.00
 TAX TOTAL: 0.00
 GRAND TOTAL: 1200.00

COMFORTDELGRO ENGINEERING PTE LTD
 205 Braddell Road (Block D) Singapore 119076
 Tel: (65) 6285 7323 Fax: (65) 6285 9142

PROVISIONAL ACCEPTANCE

Date: 5/10/18

Received By: [Signature] (Name)

Quantity and delivered as: (Goods) (Tick)

From: Mr. [Name] [Address]

Goods are delivered as shown on invoice. No signature required.

Goods are delivered as shown on invoice. No signature required.



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 78 DUNLOP STREET, SINGAPORE 209403
 TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
 DAIHATSU / KIA / SUZUKI / HONDA
 TEL: 6291 2827 FAX: 6296 4390
 A/C: 6291 1806 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: COMFORTDELGRO ENGINEERING PTE LTD
 (DELGRO)
 205 BRADDELL ROAD BLK C
 EXTENSION 1, 3RD LEVEL
 SINGAPORE 579701
 GBG9884K
 HELEN

NO: DL19209430
 PAGE: 1
 DATE: 22/10/2018
 A/C CODE: LDDE100
 TERMS: CR
 P/O NO: 4500798750

Part No	Description	Location	Qty	Unit Price	Amount
1	T55312-37011-B0	PANEL INSTRUMENT	DDS	42 1 205.00	SIN 205.00
2	T55320-37060-B0	PANEL ASSY	DDS	42 1 195.00	SIN 195.00
TOTAL QUANTITY			2	TOTAL	SIN 400.00
ADD GST @ 7%					28.00
GRAND TOTAL					<u>SIN 428.00</u>

COMFORTDELGRO ENGINEERING PTE LTD
 205 Braddell Road (Block C) Singapore 579701
 Tel: (65) 6291 2827 Fax: (65) 6296 4390

PROVISIONAL ACCEPTANCE

Date: _____

Received By: _____ (Name)

Quantity and quality of goods delivered are checked (Tick)

Print / MT / 22/10/2018 2:35:55 PM
 SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

0.1/1/15 22/10/18 15.2
 GOODS RECEIVED BY



Borneo Motors

CO Reg No : 196700086Z
GST Reg No: MR-8500000-9
21 Pandan Avenue, #07-01 Serkeo Logistics Hub
Singapore 609388 Tel: 6631 1111



TAX INVOICE

Customer Details/Remarks ComfortDelGro Engineering Pte Ltd West Wing 4th Floor 205 Braddell Road Singapore 579701 Attn: Chloe (A/C Dept) APX8020 63838837		Accounts Details ComfortDelGro Engineering Pte Ltd West Wing 4th Floor 205 Braddell Road Singapore 579701 Attn: Chloe (A/C Dept) Attn: Angie/Steve		Invoice No: 50030324 WIP No: 40496 Sale Type: R Account No: P1000003 / CDGE Credit Term: 30 Dept: C			
Operator	Salesman	Customer P.O. No.		Date	Time	Page	
bpsH003	Kenneth Chua	4500799326		19/10/2018	12:57	1	
Item	Location	Part Number	Description	Qty	Unit Price	Disc%	Total Price
1	ZL	A53898-37010	PLATE, FR PILLAR TO	1.00	8.55	0.00	8.55
2	ZL	A55045-37010 B0	PANEL SUB-ASSY.	1.00	85.28	0.00	85.28
3	ZL	A55429-37020	STAY, INSTRUMENT	1.00	40.05	0.00	40.05
4	ZL	A55451-37011 B0	BOX, INSTRUMENT	1.00	160.65	0.00	160.65
5	ZL	A55452-37010 B0	BOX, INSTRUMENT	1.00	125.78	0.00	125.78
			319 520				
<p style="text-align: center;">CERTIFIED TRUE COPY</p>							
For & on behalf of Borneo Motors			Certified Goods Received		Total Amount		420.31
Signature			Signature, Company Stamp and Date		GST 7%		29.42
					Please Pay		449.73

Goods sold are non-refundable

All Cheque must be crossed and made payable to
"BORNEO MOTORS (SINGAPORE) PTE LTD"

E. & O.E.

CUSTOMER COPY



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD Ref : CS/AWA18008728/Dcd3e2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 04-12-2019



Code : AWA

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBG 9884X
Policy No.	AVCPSB0091021700	Coverage (\$)	0.00
Claim No.	NSV1800284/KW	Excess (\$)	3,800.00
Assign From	TAN KAH LEONG	Assign Date	14/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFAT35YX0K209513	Colour	WHITE
Odometer	19572	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	BRIDGESTONE	8 mm
L/H Front Tyre	195/75 R15	BRIDGESTONE	8 mm
R/H Rear Tyre	155 R12	BRIDGESTONE	8 mm
L/H Rear Tyre	155 R12	BRIDGESTONE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/04/2018	Inspection Date	14/05/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 609286		

5a. Remarks

A) THE MARKET VALUE IS S\$69,000.00 (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **14 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 9884X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT WINDSCREEN (WCP)	CRACKED	490.00	480.00
1	FRONT WINDSCREEN RUBBER (WCP)	NECESSARY	120.00	95.00
1	WIPER PANEL (WCP)	BENT	325.00	325.00
1	WIPER PANEL SEAL (WCP)	NECESSARY	55.00	55.00
2	WIPER NOZZLE (WCP)	TORN (1PC ONLY)	40.00	20.00
1	WIPER ARM LH (WCP)	BENT	75.00	60.00
1	WIPER ARM RH (WCP)	BENT	65.00	60.00
1	WIPER BLADE LH (WCP)	BENT	55.00	55.00
1	WIPER BLADE RH (WCP)	BENT	55.00	55.00
1	WIPER MOTOR LINKAGE (WCP)	BENT	125.00	125.00
1	CORNER PANEL LH (WCP)	BENT	125.00	95.00
3	CORNER PANEL CLIP (WCP)	NECESSARY	15.00	15.00
1	CORNER PANEL BRACKET SIDE (WCP)	BENT	40.00	35.00
1	CORNER PANEL BRACKET UPPER (WCP)	BENT	40.05	40.05
1	CORNER PANEL TOP COVER (WCP)	MISSING	93.83	93.83
1	SIDE MIRROR LH (WCP)	CUT	220.00	220.00
1	ROUND MIRROR LH (WCP)	NOT DAMAGED	120.00	-
1	ROUND MIRROR BRACKET LH (WCP)	NOT DAMAGED	190.00	-
1	SIDE MIRROR BRACKET CAP LH (WCP)	NOT DAMAGED	35.00	-
1	FRONT PANEL (WCP)	DENTED	450.00	400.00
1	EMBLEM - DYNA (WCP)	NECESSARY	40.00	40.00
1	FRONT GRILLE (WCP)	MISSING	250.00	230.00
6	FRONT GRILLE CLIP MALE (WCP)	NECESSARY	29.00	29.00
9	FRONT GRILLE CLIP FEMALE (WCP)	NECESSARY (4PCS ONLY)	27.00	17.00
1	LOGO - TOYOTA (WCP)	NECESSARY	85.00	40.00
1	LOWER FRONT CROSS PANEL (WCP)	TO REPAIR SEE LABOUR	210.00	-
1	A PILLAR PANEL (WCP)	TO REPAIR SEE LABOUR	190.00	-
1	HEADLAMP LH (WCP)	CRACKED	650.00	480.00
1	HEADLAMP RH (WCP)	CRACKED	650.00	480.00
1	FRONT BUMPER (WCP)	DEFORMED	300.00	290.00
1	FRONT BUMPER BRACKET LH (WCP)	BENT	240.00	125.00
1	FRONT DOOR LH (WCP)	BENT	652.00	652.00

Report Ref No. CS/AWA18008728/Dcd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR LH HINGE (WCP)	BENT	50.00	50.00
1	FRONT LOWER DOOR SEAL LH (WCP)	NECESSARY	75.00	75.00
1	WEATHERSTRIP (WCP)	NECESSARY	75.00	75.00
1	FRONT TRIM COVER LH (WCP)	DISTORTED	390.00	390.00
1	DASHBOARD (WCP)	DISTORTED	600.00	550.00
1	LOWER DASHBOARD COVER LH (WCP)	NOT DAMAGED	95.00	-
1	LOWER DASHBOARD COVER RH (WCP)	SERVICEABLE	120.00	-
1	LOWER DASHBOARD COVER CENTRE (WCP)	CRACKED	400.00	400.00
1	UPPER DASHBOARD COVER LH (WCP)	CRACKED	100.00	100.00
1	UPPER DASHBOARD COVER RH (WCP)	NOT DAMAGED	38.00	-
1	UPPER DASHBOARD COVER CENTRE (WCP)	CRACKED	340.00	340.00
1	METER COVER (WCP)	NOT DAMAGED	125.00	-
1	FRONT AIRBAG LH (WCP)	* CHECK	2,750.00	-
1	A/C BLOWER UNIT (WCP)	NOT DAMAGED	110.00	-
1	A/C HEATER & EVAPORATOR UNIT ASSY (WCP)	* CHECK	2,500.00	-
1	A/C TUBE (WCP)	SERVICEABLE	160.00	-
2	HEATER HOSE INLET OULET (WCP)	SERVICEABLE	420.00	-
1	CONDENSER (WCP)	* CHECK	650.00	-
1	CONDENSER BRACKET (WCP)	* CHECK	290.00	-
1	LIQUID PIPE OUTLET (WCP)	* CHECK	550.00	-
1	DISCHARGE HOSE (WCP)	* CHECK	380.00	-
1	FRONT MUDGUARD LH (WCP)	SERVICEABLE	80.00	-
1	FRONT MUDGUARD BRACKET LH (WCP)	SERVICEABLE	90.00	-
1	LH FRT DOOR TOP HINGE (NPA) (ADDITIONAL)	* CHECK	-	-
1	LH FRT DOOR BOTTOM HINGE (NPA) (ADDITIONAL)	* CHECK	-	-
1	LH FRT DOOR GLASS REGULATOR WITH MOTOR (WCP) (ADDITIONAL)	* CHECK	120.00	-
1	AIRCON FAN MOTOR ASSY (NPA) (ADDITIONAL)	* CHECK	-	-
1	AIRCON SUCTION PIPE (NPA) (ADDITIONAL)	* CHECK	-	-
1	AIRCON RETURN PIPE (WCP) (ADDITIONAL)	* CHECK	115.00	-
1	AIRCON CONDENSOR BRACKET (NPA) (ADDITIONAL)	* CHECK	-	-
1	AIRCON FAN MOTOR WIRE HARNESS (WCP) (ADDITIONAL)	* CHECK	915.00	-
1	AIRCON PIPE FROM COMPRESSOR TO COIL (WCP) (ADDITIONAL)	* CHECK	120.00	-
1	AIRCON PIPE FROM DRIER TO CONDENSOR (NPA) (ADDITIONAL)	* CHECK	-	-

Report Ref No. CS/AWA18008728/Dcd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON PIPE FROM CONDENSOR TO COMPRESSOR (NPA) (ADDITIONAL)	* CHECK	-	-
1	AIRCON FAN MOTOR BRACKET (WCP) (ADDITIONAL)	* CHECK	115.00	-
1	WIPER PANEL OUTER (NPA) (ADDITIONAL)	* CHECK	-	-
1	WIPER TOP STRIP (NPA) (ADDITIONAL)	* CHECK	-	-
2	FRT PANEL SIDE CLIPS (NPA) (ADDITIONAL)	* CHECK	-	-
1	DASHBOARD REINFORCEMENT BAR (WCP) (ADDITIONAL)	* CHECK	480.00	-
1	AIRCON BLOWER CASING (WCP) (ADDITIONAL)	* CHECK	950.00	-
1	AIRCON COIL CASING (NPA) (ADDITIONAL)	* CHECK	-	-
1	DASHBOARD LH SHELF (WCP) (ADDITIONAL)	* CHECK	160.65	-
1	DASHBOARD CENTER SHELF (WCP) (ADDITIONAL)	* CHECK	125.78	-
1	AIRCON CASING AIR DUCT (NPA) (ADDITIONAL)	* CHECK	-	-
1	WASHER TANK (WCP) (ADDITIONAL)	* CHECK	65.00	-
1	DASHBOARD LH BRACKET (NPA) (ADDITIONAL)	* CHECK	-	-
1	AIR CON PIPE JOINT (NPA) (ADDITIONAL)	* CHECK	-	-
1	LHF DOOR GLASS INNER MOULDING (NPA) (ADDITIONAL)	* CHECK	-	-
	COST PLUS 10%		1,961.13	659.19
			21,572.44	7,251.07
	SPECIAL NETT ITEMS			
1	IU BRACKET (SN)	NECESSARY	26.00	26.00
1	FR NUMBER PLATE (SN)	MISSING	45.00	45.00
1	BODY SEALANT (SN)	NECESSARY	120.00	120.00
1	LH DOOR COMPANY ADDRESS STICKER (SN) (ADDITIONAL)	* CHECK	15.00	-
			206.00	191.00
	LABOUR			
	TO REMOVE / REPLACE / REFIT / STRAIGHTEN / PANEL BEAT / CUT / WELD / RE-ALIGN : FRONT PANEL, FR CROSS PANEL DOOR LH & RH, A PILLE RH & LH, FLOOR PANEL / FRONT BUMPER AND DAMAGED AREA. INCLUSIVE OF THE REPAIR OF LOWER FRONT CROSS PANEL AND A PILLAR PANEL.		1,600.00	1,200.00
	TO PUTTY, RESPRAY:FRONT PANEL, FR CROSS PANEL, DOOR RH & LH, A-PILLE RH & LH, FLOOR PANEL, FRONT BUMPER AND DAMAGED AREA.		2,400.00	1,000.00
	TO CHECK WIRE.		60.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REPLACE A/C BLOWER UNIT, HEATER & EVAPORATOR UNIT, CONDENSER.		250.00	250.00
	TO VACUUM AND RE FILL A/C GAS AND OIL.		150.00	120.00
	TO REMOVE / REPLACE DASH BOARDS.		200.00	200.00
	TO REMOVE / REPLACE FRONT WINDSCREEN.		100.00	100.00
	TO REMOVE / TRANSFER DOOR FITTING AND MECHANISM TO NEW DOOR / FACILITATE REPAIR RH & LH.		300.00	60.00
			5,060.00	2,960.00
GRAND TOTAL			26,838.44	10,402.07
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$10,549.07 NETT)				10,402.07
LESS EXCESS				-3,800.00
NETT LIABILITY				6,602.07

Report Ref No. CS/AWA18008728/Dcd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.