

12/03/2018

ASS. BY:

REF: CS/CTI18008732/Tlr b n2

Special Instruction:

Surveyor:

Taufik.

ASSIGNMENT (Office)

From (Person):

Mufin

Irene Tay

of CTI

Date/Time:

14/5/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLK 8267U

Insured:

GBD 9936X

at Workshop m/s:

Performance (Alexandra)

Tel:

of

302 Alexandra Road Singapore

159941

Policy No.:

DMCVSN3060611700

Claim No.:

SNM18062395102

Sum Insured:

Excess:

Make of Veh.:

D.O.A. 12/5/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp:

05062018 @ 4pm

H.O.D. Endorsement:

Date/Time:

11052018

Person Contacted:

Gary

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 8267U - X

GBD 9936X - X

Confirm \$10,664.15 @ 6 days

Red: \$6201.10, 371.

Page No. *Tanjin*

REF: *C7*

ASSIGNMENT

From: *05062018* Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLK 8267U*
at Workshop n/s: *Performance*
of: *303 Alexandra Rd*

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: *Grey*

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

4-430
owner waiting
Vehicle: IN / OUT

Date: Person Contacted:

Veh No: *SLK 82674* Yr Regn: *2017 Jan.*

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *BMW 730LI* CC: *1978*

Colour: *Grey* A/C: Insured / Std / NI / NA

Sp. Reading: *40882* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *WB A7E 020X 09.24 5275*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD / Rm / STD A/Rm or

Tyre Size: F: *205/60R16* 245/50R18

R:

BS / DUN / EXNOVA / GV / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: *6* mm R/Bal: *6* mm

L/Bal: *6* mm L/Bal: *6* mm

D.O.A.

D.O.I. *6/6/18 R1840*

Survey held at *PML*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report

typist

☒ : Final Report

Date/Time, File Return to?

Days Of Repair: *6*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation

15-RE-51

2 Photos

2 Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Weekend (\$

Report Format: *7P*

Lump Sum / L.B. / (\$ *10,664.15*

220

LAIM SUBFOLDER...(New Assignment)

Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
14 May 2018 14:19 Assign				New Assignment Cancel Case

[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

DETAILS

[Created by insurer]

Claimant:	CHIN CHEE HEUN		
Vehicle Reg. No.:	SLK8267U	Date of Loss:	12/05/2018 00:00 - :59
Claim Type:	TP / SNM18D02395C02	Policy/Cover Note No.:	DMCVSN3060611700
Vehicle Reg. No. (Insured):	GBD9936X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/05/2018]		
Adj Asg. Remarks:	EST \$18,045.82, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Janice Lee (LKKAUTO)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Tuesday, July 10, 2018 6:21 PM
To: Taufikh (LKKAUTO); SUR
Subject: FINAL REPORT / SLK8267U
Attachments: Final Report SLK8267U.pdf

Dear Taufikh

We refer to the above and the attached Final Report.

Please confirm COR as follows:

Total Labour : 5,078.00

Total Parts : 5,586.15

Total Labour & Parts : 10,664.15

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2018 09:00
Date Of Accident	12/05/2018 08:15
Exact Location Of Accident	WOODLANDS AVE 4 MOVING OUT TO ADMIRALTY RD WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8267U
Insured/Policyholder	
Name Of Registered Owner	CHIN CHEE HEUN
NRIC No	S1471134A
Email Address	MIKECHIN@SIAC.COM.SG
Mobile Phone No	(LOCAL) +65-97535177
Alternative Phone No	OFFICE-97535177

Vehicle Particulars

Manufacturer	BMW
Model	730LIA
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18V01003/VPC/R01
Cover Note Number	

Driver

Name of Driver	CHIN CHEE HEUN
NRIC No	S1471134A
Date Of Birth	18/07/1961
Occupation	INDOOR
Date Of Driving Pass	08/11/1983
Driving Experience	34 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97535177
Fax Number	
Contact Number	OFFICE-97535177
Email Address	MIKECHIN@SIAC.COM.SG

Address	8 CASUARINA WALK
Postcode	574066
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9936X
Vehicle Make/Model/Colour	TOYOTA DYNA SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MALASISAMY PRABAKARAN
NRIC/Passport Number	
Contact Number	97531100/90050003 CHEONG
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature: *[Signature]*
 Date & Time: 11/05/2018

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

GBD. 9936X.

while driving along the road. woodland Ave 4,
 gas, out from the side road. to Admiralty Rd
 went. Lorry vehicle. GBD 9936X, hit onto my
 car my vehicle. SLK 8267 U

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: *[Signature]* - 12/05/2018

Date & Time: 1140 hrs

Driver's Signature:
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/PIK No.:

[Signature]
 12/5/18

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

14 MAY 2018

Estimate No. : b1 46906
Date Estimated : 12/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Chin Chee Heun
8 Casuarina Walk

Singapore 574066

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK8267U	G245275	26/01/2017	730Li	0

DESCRIPTION

To replace rear bumper, bootlid & attachment include knocking cause by the accident

2125 2,975.00

Painting rear bumper, bootlid, tail panel

2102 2,819.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To carry out body cavity preservation. (Per panel).

100 118.00

To replace front seat crash-active head restraint air bags including reset and conduct check for function.

451 531.00

To replace both front seat belts and tensioners including reset and checks for proper function.

nn x 7.451 531.00

Sundries.

new 7. 150.00

Total Labour 1: 7,301.00

DESCRIPTION

TAILGATE ALUMINIUM
REAR BUMPER ADAPTER
REAR BUMPER ADAPTER
REAR BUMPER CARRIER
REAR BUMPER CENTRE GUIDE
REAR LH MOUNT LATERAL
REAR RH MOUNT LATERAL
LH TRIM EXHAUST TAILPIPE
RH TRIM EXHAUST TAILPIPE
REAR BUMPER CENTRE GUARD
BUMPER GUARD REAR
RUBBER STRIP LH
RUBBER STRIP RH

QTY	PRIC
1	2,107.20
1	77.65
1	77.65
1	898.50
1	51.50
1	142.55
1	142.55
1	247.20
1	247.20
1	84.20
1	102.95
1	85.05
1	85.05

bt 2,107.20
ne 77.65
nn x 77.65
bt 898.50
? 51.50
nn x 142.55
? 142.55
? 247.20
x 247.20
de 84.20
de 102.95
ne 85.05
new 85.05



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46906
Date Estimated : 12/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK8267U	G245275	26/01/2017	730Li	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER COVER	1	107.05	107.05
Protection f	2	8.65	17.30
TRIM REAR PRIMED	1	216.45	216.45
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,586.85	1,586.85
REAR BUMPER TOWING EYE COVER PRIMED	1	55.70	55.70
BOOTLID CHROME TRIM STRIP	1	176.10	176.10
EMBLEM GROMMET	2	0.80	1.60
LETTERING 730Li	1	62.55	62.55
REAR PLAQUE 82MM	1	69.50	69.50
TRUNK LID GASKET (RFK)	1	100.60	100.60
Drip rail	1	111.40	111.40
(DG) REPAIR KIT CRASH ACTIVE HEAD R	2	159.80	319.60
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
ULTRASONIC SENSOR ARKTIKGRAU (WC27)	4	380.65	1,522.60
FRT SEAT BELT LOWER STRAP (SCHWARZ)	2	423.75	847.50

Total Parts : 9,564.25

Car No. 01 / 30 / 15 / 15 / 15 / 15 / 15 / 15 / 15 / 15

Reg No. 01 / 18 / 640

Description: Tarifu

Engine No. 9749 5749

Date of Birth: 12/05/2018

Signature: [Signature]

Signature: [Signature]

Signature: [Signature]

Signature: [Signature]

Signature: [Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	: 16,865.25	7,301.00
Parts	: 9,564.25	
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,180.57
Grand Total	:	18,045.82

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401550W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46906
Date Estimated : 12/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Chin Chee Heun
8 Casuarina Walk

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 574066

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLK8267U	G245275	26/01/2017	730Li	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid include knocking out dents caused by the accident	2125.00		2,125.00	
To spray painting rear bumper and boot lid	2102.00		2,102.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
To replace front seat crash-active head restraint air bags including reset and conduct check for function.	451.00		451.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TAILGATE ALUMINIUM	2,107.20	1.00		2,107.20
REAR BUMPER ADAPTER	77.65	1.00		77.65
REAR BUMPER CARRIER	898.50	1.00		898.50
REAR BUMPER CENTRE GUARD	84.20	1.00		84.20
BUMPER GUARD REAR	102.95	1.00		102.95
RUBBER STRIP LH	85.05	1.00		85.05
RUBBER STRIP RH	85.05	1.00		85.05
REAR BUMPER COVER	107.05	1.00		107.05
REAR BUMPER PANEL PRIMED (PDG/PMA)	1,586.85	1.00		1,586.85
LETTERING 730Li	62.55	1.00		62.55
REAR PLAQUE 82MM	69.50	1.00		69.50
(DG) REPAIR KIT CRASH ACTIVE HEAD R	159.80	2.00		319.60

SUPPLEMENTARY ITEMS

Total Labour :	5,078.00
Total Parts :	5,586.15
Total Labour & Parts :	10,664.15
Deduction for Excess :	
Total Repair Costs less Excess:	10,664.15
GST @7%:	746.49
Grand Total :	11,410.64

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18008732/T1RBN2

Date: 19/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3060611700
Claimant Vehicle No :	SLK8267U	Insured Vehicle No :	GBD9936X
Date of Loss:	12/05/2018	Nature of Claim:	TP
		Claim No:	SNM18D02395C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8267U	Engine No:	16139771B48B20B
Make & Model:	BMW 730LI, 2.0 LED NAV HUD SR (A)	Chassis No:	WBA7E020X0G245275
Reg. Date:	26/01/2017 (Man. Year: 2016)	Odometer:	40882 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50R18	Rear Tyre Size:	245/50R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,714.25	5,736.15	3,978.10	40.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,151.00	4,928.00	2,223.00	31.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,865.25	10,664.15	6,201.10	36.77
+ GST 7.00/7.00% (S\$)	1,180.57	746.49	434.08	36.77
Nett Amount (S\$)	18,045.82	11,410.64	6,635.18	36.77

INSPECTION

Date of Assignment:	14/05/2018	
Date Inspected:	06/06/2018	Inspected At:
		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2018)
Parts: 143	BMW 730LI 2.0 LED NAV HUD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLK8267U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE ALUMINIUM	Bent	2,107.20 FS	*2,107.20 FS
2	1	*REAR BUMPER ADAPTER	Necessary	77.65 FS	*77.65 FS
3	1	*REAR BUMPER ADAPTER	Not Necessary	77.65 FS	*- FS
4	1	*REAR BUMPER CARRIER	Bent	898.50 FS	*898.50 FS
5	1	*REAR BUMPER CENTRE GUIDE	Not Necessary	51.50 FS	*- FS
6	1	*REAR LH MOUNT LATERAL	Not Necessary	142.55 FS	*- FS
7	1	*REAR RH MOUNT LATERAL	Not Necessary	142.55 FS	*- FS
8	1	*LH TRIM EXHAUST TAILPIPE	Not Necessary	247.20 FS	*- FS
9	1	*RH TRIM EXHAUST TAILPIPE	Not Necessary	247.20 FS	*- FS
10	1	*REAR BUMPER CENTRE GUARD	Deformed	84.20 FS	*84.20 FS
11	1	*BUMPER GUARD REAR	Deformed	102.95 FS	*102.95 FS
12	1	*RUBBER STRIP LH	Necessary	85.05 FS	*85.05 FS
13	1	*RUBBER STRIP RH	Necessary	85.05 FS	*85.05 FS
14	1	*REAR BUMPER COVER	Deformed	107.05 FS	*107.05 FS
15	2	*PROTECTION F	Not Necessary	17.30 FS	*- FS
16	1	*TRIM REAR PRIMED	Not Necessary	216.45 FS	*- FS
17	1	*REAR BUMPER PANEL PRIMED (PDC/PMA)	Deformed	1,586.85 FS	*1,586.85 FS
18	1	*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	55.70 FS	*- FS
19	1	*BOOTLID CHROME TRIM STRIP	Not Necessary	176.10 FS	*- FS
20	2	*EMBLEM GROMMET	Not Necessary	1.60 FS	*- FS
21	1	*LETTERING 730LI	Necessary	62.55 FS	*62.55 FS
22	1	*REAR PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
23	1	*TRUNK LID GASKET (RFK)	Not Necessary	100.60 FS	*- FS
24	1	*DRIP RAIL	Not Necessary	111.40 FS	*- FS
25	2	*(DG) REPAIR KIT CRASH ACTIVE HEAD R	Cut	319.60 FS	*319.60 FS
26	4	*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
27	4	*ULTRASONIC SENSOR ARKTIKGRAU (WC27)	Not Necessary	1,522.60 FS	*- FS
28	2	*FRT SEAT BELT LOWER STRAP (SCHWARZ)	Not Necessary	847.50 FS	*- FS
29	1	*SUNDRIES	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,714.25	5,736.15
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER,BOOTLID & ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	2,975.00	2,125.00
2	PAINTING REAR BUMPER,BOOTLID,TAIL PANEL	New	2,819.00	2,102.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
5	TO REPLACE FRONT SEAT CRASH-ACTIVE HEAD RESTRAINT AIR BAGS INCLUDING RESET AND CONDUCT CHECK FOR FUNCTION	New	531.00	451.00
6	TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION	New	531.00	-
Gross Labour Cost (S\$)			7,151.00	4,928.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >