

**Trans-cab Auto Services Pte Ltd**

AAD1805-098

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 693Z**

*Not Authorized  
L1 Lmp @ 5850. 8050*

Vehicle No.:	<b>SHF 693Z</b>
Chassis No.:	VF1ABL15AUC281172
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	10.5.2018
Third Party Insurer :	<b>AIG</b>

<b>PART</b>		<b>LIST</b>	
1	1 BUMPER COVER REAR	\$	<i>Br</i> 1,108.46 —
2	1 BUMPER LOWER REAR	\$	<i>DISP</i> 768.84 —
3	1 BUMPER BRACKET CTR REAR	\$	<i>D.Y</i> 113.47 —
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sm</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>CR</i> 43.61 —
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sm</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Br</i> 777.52 —
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>D.Y</i> 225.95 —
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Br</i> 225.95 —
13	1 BOOT REAR	\$	<i>Br</i> 2,872.68 —
14	1 BOOT FINISHER	\$	<i>Sm</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05 X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Br</i> 225.36 —
19	1 BOOT BADGE	\$	<i>Br</i> 225.36 —
20	1 BOOT STRUT LH	\$	<i>Sm</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sm</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84 } X
24	1 BOOT INNER TRIM	\$	<i>Sm</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sm</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81

**Trans-cab Auto Services Pte Ltd**

**AAD1805-098**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 693Z**

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	}
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sm	671.45	
32	1 FENDER PANEL REAR LH	\$	R	3,299.13	
33	1 WHEELARCH REAR LH	\$	Sm	543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	
35	1 FENDER PANEL REAR RH	\$	R	3,299.13	
36	1 WHEELARCH REAR RH	\$	Sm	543.47	
37	1 TAILLAMP RH	\$	Sm	552.55	
38	1 TAILLAMP PANEL RH	\$	R	986.70	
39	1 TAILLAMP LH	\$	Sm	552.55	
40	1 TAILLAMP PANEL LH	\$	R	986.70	}
41	1 OUTER PANEL REAR (End Panel)	\$	B	1,471.77	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	nd	404.56	✓
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
44	1 SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
45	1 EXHAUST REAR	\$	R	7,489.05	X
46	1 EXHAUST CAP REAR	\$	R	230.49	X
47	1 FUEL FLAP L70Y	\$	Sm	343.57	X
<b>TOTAL</b>		<b>\$</b>		<b>39,057.17</b>	
10%		<b>\$</b>		<b>3,905.72</b>	
		<b>\$</b>		<b>35,151.45</b>	

**Specical Nett**

1	1SET PARKING AID	\$	Short	700.00	✓
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1805-098

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 693Z**

16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	}
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
19	1 TAILLAMP CLIP RH	\$	na	5.00	
20	1 TAILLAMP CLIP LH	\$	na	5.00	
21	2 REAR WINDSCREEN SELANT	\$	na	80.00	
22	1 WINDSCREEN MOULDING	\$	na	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sm	385.00	
25	1 SPARE TYRE	\$	Sm	330.00	

**TOTAL \$ 2,225.02**

**TOTAL PARTS \$ 37,376.47**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,500.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601

**Trans-cab Auto Services Pte Ltd**

**AAD1805-098**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 693Z**

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nr</i> 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nr</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nr</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nr</i> 380.00 X

**TOTAL \$ 10,340.00**

**Over All Total \$ 47,716.47**

**(LUMP SUM)**

**Repair Days**

**15 DAYS**

*5 days*

**LKK Auto Consultants hence notify**

**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: