

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 616Y

AAD1805-082

*Not Authorised
L1 Sup @ ?*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 616Y

VF1ABL15AUC278497

RENAULT

LATITUDE

9.5.2018

EQ INSURANCE

PART			LIST	
1	1 BUMPER COVER REAR	\$	B ₁ 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	Dis/CM 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	CM 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	S ₂ 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	S ₂ 44.99	X
6	1 BUMPER REFLECTOR RH	\$	CM 43.61	✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	S ₂ 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	Dis 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	CM 43.61	✓
10	1 BUMPER BEAM REAR	\$	B ₁ 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	B ₁ 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	B ₁ 225.95	✓
13	1 BOOT REAR	\$	B ₁ 2,872.68	✓
14	1 BOOT FINISHER	\$	B ₂ 470.06	✓
15	1 BOOT WHEATERSTRIP	\$	nd/L ₁ 323.05	✓
16	1 BOOT REFLECTOR LAMP LH	\$	CM 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	CM 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	M ₂ 225.36	✓
19	1 BOOT BADGE	\$	M ₂ 225.36	✓
20	1 BOOT STRUT LH	\$	S ₂ 276.08	} X
21	1 BOOT STRUT RH	\$	S ₂ 276.08	
22	1 BOOT HINGE LH	\$	R 367.84	
23	1 BOOT HINGE RH	\$	R 367.84	
24	1 BOOT INNER TRIM	\$	S ₂ 586.45	
25	1 BOOT SWITCH	\$	S ₂ 168.13	
26	1 BOOT LOCK	\$	R 202.67	
27	1 BOOT LOCK CATCH	\$	R 74.40	
28	2 LICENCE PLATE LAMP	\$	S ₂ 50.52	}
29	2 BOOT RUBBER PLUG	\$	S ₂ 221.81	

Trans-cab Auto Services Pte Ltd

AAD1805-082

No. 2 Arig Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 616Y

30	1 DOOR PANEL REAR LH	\$	R 2,844.66	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sm 671.45	X
32	1 FENDER PANEL REAR LH	\$	Bu 3,299.13	✓
33	1 WHEELARCH REAR LH	\$	Sm 543.47	X
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm 671.45	X
35	1 FENDER PANEL REAR RH	\$	R 3,299.13	X
36	1 WHEELARCH REAR RH	\$	Sm 543.47	X
37	1 TAILLAMP RH	\$	CR 552.55	✓
38	1 TAILLAMP PANEL RH	\$	R 986.70	✓
39	1 TAILLAMP LH	\$	CR 552.55	✓
40	1 TAILLAMP PANEL LH	\$	R 986.70	✓
41	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77	✓
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM 404.56	✓
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu R 2,189.88	✓
44	1 SPARE WHEEL PANEL TRIM	\$	Sm 612.21	X
45	1 EXHAUST REAR	\$	R 7,489.05	✓
46	1 EXHAUST CAP REAR	\$	R 230.49	✓
47	1 FUEL FLAP L70Y	\$	Sm 343.57	X
TOTAL		\$	39,057.17	
10%		\$	3,905.72	
		\$	35,151.45	

Special Nett

1	1SET PARKING AID	\$	Shan 700.00	✓
2	1SET REAR BUMPER CLIP	\$	na 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sm 17.82	X
11	1SET BOOT FINISHER CLIP	\$	nei 24.20	✓
12	1 BOOT STICKER "Trans-cab"	\$	na 30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na 30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na 45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00	X

Trans-cab Auto Services Pte Ltd

AAD1805-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 616Y

16 1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00 X
17 1 FENDER INNER TRIM CLIP LH	\$	na 28.00 X
18 1 FENDER INNER TRIM CLIP LH	\$	na 28.00 X
19 1 TAILLAMP CLIP RH	\$	na 5.00 ✓
20 1 TAILLAMP CLIP LH	\$	na 5.00 ✓
21 2 REAR WINDSCREEN SELANT	\$	na 80.00 40sn
22 1 WINDSCREEN MOULDING	\$	na 100.00 ✓
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 30sn
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn 385.00 X
25 1 SPARE TYRE	\$	sn 330.00 X
TOTAL \$		2,225.02
TOTAL PARTS \$		37,376.47

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 13201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 20001
To Rust-Proofing Of The Affected Areas.	\$	170.00 1201
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 601
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 } 601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1805-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 616Y

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	100/
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	80/
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	NA X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120/
To check steering geometry and computer wheel alignment	\$	220.00	NA X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	NA X

TOTAL \$ 12,540.00

Over All Total \$ 49,916.47

(LUMP SUM)

Repair Days

20 DAYS

14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: