

22/03/2002

ASS. REC. BY:

REF: CS/MSG18008783/Aqd302

Special Instruction:

Surveyor:
Menimen

Adrian

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSIG

Date/Time:

15/5/18 @ 9:39am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FY 4136M

Insured:

FS 5001T

at Workshop m/s

MS Car Auto

Tel:

6385 1838

of

8 Kaki Bukit Ave 4 # 01-07 Premier

Policy No:

MSD/VMT/17-363097-CA

Claim No:

MSC/V/18-000667

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/05/2018

CA / REV / REP. 7 REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

9:50am @ 15/5/18

Person Contacted:

Desmond

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FY 4136M - NA / MSG18008783/h4 DOA: 10/5/18
	FS 5001T - NA / MSG18008783/h4 DOA: 10/5/18
16/5/18 @ 4:20pm	Informed Lionel Tan, we are pending estimate from vapairrev.
01/8/18 @ 10:11am	revised to Lionel Tan via Menimen.
	LS \$1200, 4 days (Red \$ 4795.60, 80%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18008783/Aqd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-05-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FS 5001T	Veh. Inspected	FY 4136M
Policy No.	MSD/MT/17-363097-CA	Coverage (\$)	0.00
Claim No.	MSCV/18-000667	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/05/2018	Inspection Date	15/05/2018
Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 May 2018		15 May 2018 09:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	SHAWAR FAROUK BA'ARRFFAN BIN MOHAMAD A , ID: S9342674F								
Main Claimant:	TAN CHENG MUN , ID: S7586346B								
Vehicle Reg. No.:	FY4136M	Date of Loss:	10/05/2018 00:00 - :59 [163 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/17-363097-CA (Third Party Only) Coverage: 17/04/2017 - 19/08/2018						
Vehicle Reg. No. (Insured):	FS5001T	Policy No. (Claimant):							
		Excess:							
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/05/2018]								
Adj Asg. Remarks:	Third Party Pre-repair Survey. TP nominated LKK to be SJE Insured - Non-reporting .								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 01 Aug 2018

Preliminary Advice

Insured Vehicle No	: FS5001T	Accident Date	: 10/05/2018
TP Vehicle No	: FY4136M	Assignment Date	: 15/05/2018
Make	: HONDA WAVE 125-R	Est. Duration of Repair	: 4.00
Date of Inspection	: 15/05/2018		
Inspection At	: MS CAR AUTO PTE LTD (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,995.60
Revised Amount	:S\$	2,504.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,504.95
Lump Sum Repair	:S\$	1,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 16 May 2018 4:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE FY 4136M (YOUR REF: MSC/V/18-000667)

This mail is associated with :
***FY4136M (MSC/V/18-000667)**
[FS5001T]

TP
TAN CHENG MUN
May 10 2018 12:00AM
[SHAWAR FAROUK BA'ARRFFAN BIN MOHAMAD A]
Ms Car Auto Pte Ltd

Dear Lionel,

Please be informed that we have inspected the motorbike FY 4136M on 15/05/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6346B
Vehicle Details	
Vehicle No.:	FY4136M
Vehicle to be Exported:	Yes
Intended De-registration Date:	15 May 2018
Vehicle Make:	HONDA
Vehicle Model:	WAVE 125R A
Primary Colour:	Red
Manufacturing Year:	2004
Engine No.:	NF125MPE0012543
Chassis No.:	NF125MP0012543
Maximum Power Output:	-
Open Market Value:	\$1,660.00
Original Registration Date:	14 Sep 2004
First Registration Date:	14 Sep 2004
Transfer Count:	5
Actual ARF Paid:	\$249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2019
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$2,020.00
COE Rebate Amount:	\$522.00
Total Rebate Amount:	\$522.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/05/2018 13:52
Date Of Accident	10/05/2018 07:30
Exact Location Of Accident	UPP EAST COAST RD INFRONT ESSO PETROL KIOSK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FY4136M
Insured/Policyholder	
Name Of Registered Owner	TAN CHENG MUN
NRIC No	S7586346B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90222751
Alternative Phone No	OFFICE-90222751

Vehicle Particulars

Manufacturer	HONDA
Model	WAVE 125R A
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	-
Cover Note Number	72070840

Driver

Name of Driver	TAN CHENG MUN
NRIC No	S7586346B
Date Of Birth	14/01/1975
Occupation	OUTDOOR
Date Of Driving Pass	04/07/2016
Driving Experience	1 YEAR AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90222751
Fax Number	
Contact Number	OFFICE-90222751
EMail Address	NOEMAIL

No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name	TAN CHENG MUN
Approximate Age	
Injuries Sustain	HAND, LEGS, BACK, CHEST, NECK
Injured person in which vehicle?	FY4136M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

Exit entrance of Esso petrol kiosk

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10/05/2018, I was riding along lane 1 of Upper East coast rd. When I ride passed the junction of Bedok South Ave 1 and upper east coast rd, and was passing the ESSO petrol kiosk. There was a car stopped at the exit of petrol kiosk. When I passed the said car, FS5001T suddenly came out from the side of the car and collided into my motorcycle.

[Handwritten signature]

Refer to police report

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180510/2190

2 of 3

Report No. T/20180510/2190

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FY4136M	MSIG INSURANCE (SINGAPORE) PTE. LTD.	72070840	12/02/2018	11/02/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider				
Name	SHAWAR FAROUK BA'ARRFFAN BIN MOHAMED ARRFFAN		ID No.	S9342674F
Related Vehicle	FS5001T (Motorcycle)		Contact No.	85113051
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Rider				
Name	TAN CHENG MUN		ID No.	S7586346B
Related Vehicle	FY4136M (Motorcycle)		Contact No.	90222751
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	10/05/2018		Date Discharge	10/05/2018
No. of Days granted Medical Leave	07		Degree of Injury	NIL

Brief Details.

On 10/05/2018, I was riding my motorcycle (FY4136M), along lane 1 of Upper East Coast road. When I ride passed the junction of Bedok South ave 1 and Upper East Coast road, and was passing the ESSO petrol kiosk. There was a car stopped at the exit of ESSO petrol kiosk. when I was passing the said car, a motorcycle (FS5001T) suddenly came out from the side of the said car and collided into my motorcycle. After the accident, the rider of FS5001T and myself took a rest at the road side. After which, we took photos of the damages on our motorcycle, we then ride off.
I proceed to seek treatment as I was not feeling well after the accident and was subsequently given 7 days of medical certificate by the doctor. I suffered injuries on my both my hands and legs, my back, my chest area and the back of my neck.

TPMS16.
Xiao Chen

SJE : _____
 Date of Survey : _____
 Contacts : _____

Vehicle Nos : FY 4136M
 Model : Honda wave 125
 Year : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Headlamp <i>Cut.</i>	1	\$ 285.00	\$ 285.00
2	Headlamp cowling <i>Repair</i>	1	\$ 85.00	\$ 85.00
3	Front fender <i>Cut</i>	1	\$ 135.00	\$ 135.00
4	Fork stem <i>new</i>	1	\$ 185.00	\$ 185.00
5	Fork wheel bearing <i>new</i>	1	\$ 75.00	\$ 75.00
6	Fork assy <i>new</i>	1	\$ 575.00	\$ 575.00
7	Front fairing <i>Cut</i>	1	\$ 85.00	\$ 85.00
8	Front center cover <i>Cut</i>	1	\$ 85.00	\$ 85.00
9	Handlebar <i>new</i>	1	\$ 175.50	\$ 175.50
10	Handlebar grip (set) <i>new</i>	1	\$ 75.00	\$ 75.00
11	Handle bar balancer (set) <i>new</i>	1	\$ 75.00	\$ 75.00
12	Signal light <i>Cut RH, Lit Rwd</i>	2	\$ 70.00	\$ 140.00
13	Radiator <i>new</i>	1	\$ 375.60	\$ 375.60
14	Condensor <i>new</i>	1	\$ 350.00	\$ 350.00
15	Front left fairing <i>Cut</i>	1	\$ 125.00	\$ 125.00
16	Rear left fairing <i>Cut</i>	1	\$ 125.00	\$ 125.00
17	Pillion bracket LH <i>new Cut</i>	1	\$ 105.00	\$ 105.00
18	Front right fairing <i>Cut</i>	1	\$ 125.00	\$ 125.00
19	Rear right fairing <i>new</i>	1	\$ 125.00	\$ 125.00
20	Footrest RH <i>Cut</i>	1	\$ 95.00	\$ 95.00
21	Exhaust <i>new</i>	1	\$ 615.90	\$ 615.90
22	Exhaust guard <i>Cut</i>	1	\$ 125.00	\$ 125.00

1535.50
1381.55

Parts Sub Total : \$ 3,772.00
 Discount 10% : \$ 377.20
PARTS TOTAL : \$ 3,394.80

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	License plate F+B <i>Best</i>	2	\$ 30.00	\$ 60.00
2	Handphone <i>Handphone Holder NL</i>	1	\$ 180.80 40	\$ 180.80 40
3	Front rims <i>new</i>	1	\$ 175.00	\$ 175.00
4	Side mirrors <i>Cut</i>	1	\$ 85.00	\$ 85.00
5	Tailbox <i>Cut</i>	1	\$ 300.00	\$ 300.00
6	Tailbox bracket <i>new</i>	1	\$ 105.00	\$ 105.00
7	Helmet <i>Rwd</i>	1	\$ 275.00	\$ 600.00

560

SPECIAL NETT TOTAL : \$ 1,505.80

Nos.	LABOUR	S\$
1	To R&R accident damage parts, to cut/weld knock and realign accident affected area	\$ 600.00
2	To putty and respray accident affected area	\$ 350.00
4	To check wheel alignment	\$ 60.00
5	To check chassis alignment	\$ 85.00

500

LABOUR TOTAL : \$ 1,095.00

PARTS TOTAL : \$ 3,394.80
 SPECIAL NETT TOTAL : \$ 1,505.80

LABOUR TOTAL :	\$	1,095.00	
TOTAL :	\$	5,995.60	6322 6
Deduct 20% :	\$	1,199.12	
GRAND TOTAL :	\$	4,796.48	

Adrian King -
 r/s 15/05/18.
 04 days

total: 2441.55

r/s: 1.2K (Nett Value).

1.2K

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 May 2018		15 May 2018 09:39 Edit Adj Rpt	S\$1,200.00 Edit Estimates	S\$1,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SHAWAR FAROUK BA'ARRFFAN BIN MOHAMAD A , ID: S9342674F								
Main Claimant:	TAN CHENG MUN , ID: S7586346B								
Vehicle Reg. No.:	FY4136M	Date of Loss:	10/05/2018 00:00 - :59 [163 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000667	Policy/Cover Note No.:	MSD/VMT/17-363097-CA (Third Party Only) Coverage: 17/04/2017 - 19/08/2018						
Vehicle Reg. No. (Insured):	F55001T	Policy No. (Claimant):							
		Excess:							
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/06/2018]								
Adj Asg. Remarks:	Third Party Pre-repair Survey. TP nominated LKK to be SJE Insured - Non-reporting .								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (13/08/2018): Re: Alert: Im. Report (FY4136M)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FY4136M (MSC/V/18-000667)
[FS5001T]**

TP

TAN CHENG MUN

May 10 2018 12:00AM

[SHAWAR FAROUK BA'ARRFFAN BIN MOHAMAD A]

Ms Car Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="checkbox"/>
Assessment Reports			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 10:11	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
2	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
3	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
4	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
5	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
6	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
7	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
8	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
9	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
10	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
11	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	31/07/18 15:57	General View	 Load JPG	<input checked="" type="checkbox"/>
34	31/07/18 15:57	General View	 Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
36	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
37	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
38	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
39	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
40	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
41	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
42	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
43	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
44	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>
45	31/07/18 15:57	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/05/18 17:39	TP PRI	Load PDF	
2	14/05/18 17:42	TP PRI LETTER & ACCDT REPORT	Load PDF	
3	14/05/18 18:08	TP REPLY & NOMINATED LKK TO BE OUR COMMON SJE	Load PDF	
4	14/05/18 18:24	E-FILE REPORT (SY4136M)	Load PDF	
5	16/08/18 08:44	TPD FY4136M - POLICE REPORT & LTA SEARCH	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008783/AQD3E2

Date: 16/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-363097-CA
Claimant Vehicle No :	FY4136M	Insured Vehicle No :	FS5001T
Date of Loss:	10/05/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000667

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FY4136M	Engine No:	NF125MPE0012543
Make & Model:	HONDA WAVE 125-R, 125cc (M)	Chassis No:	NF125MP0012543
Reg. Date:	14/09/2004 (Man. Year: 2004)	Odometer:	62842 km
Colour:	Orange		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	Wings 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,233.60	2,004.95	3,228.65	61.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,095.00	500.00	595.00	54.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,328.60	2,504.95	3,823.65	60.42
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	6,328.60	1,200.00	5,128.60	81.04

INSPECTION

Date of Assignment:	15/05/2018	
Date Inspected:	15/05/2018 Inspected At:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 16 Aug 2018)
Parts:	N/A HONDA WAVE 125-R 125cc (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FY4136M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Cut	285.00 FL	*285.00 FL
2	1		*HEADLAMP COWLING	Repair	85.00 FL	*- FL
3	1		*FRONT FENDER	Cracked	135.00 FL	*135.00 FL
4	1		*FORK STEM	Not Necessary	185.00 FL	*- FL
5	1		*FORK WHEEL BEARING	Not Necessary	75.00 FL	*- FL
6	1		*FORK ASSY	Not Necessary	575.00 FL	*- FL
7	1		*FRONT FAIRING	Cracked	85.00 FL	*85.00 FL
8	1		*FRONT CENTER COVER	Cracked	85.00 FL	*85.00 FL
9	1		*HANDLEBAR	Necessary	175.50 FL	*175.50 FL
10	1		*SET HANDLEBAR GRIP	Not Necessary	75.00 FL	*- FL
11	1		*SET HANDLE BAR BALANCER	Not Necessary	75.00 FL	*- FL
12	2		*SIGNAL LIGHT	O/S Cut / N/S Damaged	140.00 FL	*140.00 FL
13	1		*RADIATOR	Not Necessary	375.60 FL	*- FL
14	1		*CONDENSOR	Not Necessary	350.00 FL	*- FL
15	1		*FRONT LEFT FAIRING	Cracked	125.00 FL	*125.00 FL
16	1		*REAR LEFT FAIRING	Cut	125.00 FL	*125.00 FL
17	1		*PILLION BRACKET LH	Cracked	105.00 FL	*105.00 FL
18	1		*FRONT RIGHT FAIRING	Cracked	125.00 FL	*125.00 FL
19	1		*REAR RIGHT FAIRING	Not Necessary	125.00 FL	*- FL
20	1		*FOOTREST RH	Cut	95.00 FL	*95.00 FL
21	1		*EXHAUST	Not Necessary	615.90 FL	*- FL
22	1		*EXHAUST GUARD	Cut	125.00 FL	*125.00 FL
23	2		*LICENSE PLATE F+B	Bent	60.00 FS	*20.00 FS
24	1		*HANDPHONE HOLDER	Necessary	180.80 FS	*40.00 FS
25	1		*FRONT RIMS	Not Necessary	175.00 FS	*- FS
26	1		*SIDE MIRRORS	Cut	85.00 FS	*50.00 FS
27	1		*TAILBOX	Cut	300.00 FS	*200.00 FS
28	1		*TAILBOX BRACKET	Not Necessary	105.00 FS	*- FS
29	1		*HELMET	Damaged	600.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,647.80	2,165.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	414.20	160.55
Total Parts (\$\$)	5,233.60	2,004.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT DAMAGE PARTS, TO CUT / WELD KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	600.00	250.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	350.00	200.00
3	TO CHECK WHEEL ALIGNMENT	New	60.00	50.00
4	TO CHECK CHASSIS ALIGNMENT	New	85.00	0.00
Gross Labour Cost (\$\$)			1,095.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >