

ASS. REC. BY:

REF: CS/FCI18008787/

Uqd3/m2

Special Instruction:

Surveyor
CWS

March

ASSIGNMENT (Office)

From (Person):

May chua

of

FCI

Date/Time:

15/5/18 @ 8:45am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLN 9176 B

Insured:

SHA 4790B

at Workshop m/s

Trans Eurokars

Tel:

63958685

of

12 Sungai Kadut Ave

Policy No:

Claim No:

D18003544MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A

04/05/18

(Client's Record)

16/05/18 @ 4pm

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

9:02am @ 15/5/18

Person Contacted:

ERIC

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 9176 B - X

SHA 4790B - CS/FCI15015934/gb XX

DOA: 6/9/15

18/5/18 @ 2:25pm revised to May chua by email.

REF: FCI

ASSIGNMENT

From:

Date:

7/5/2018

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SLN 9176 B

at Workshop m/s

Trans Eurokars

of

5 Upi Close.

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

1:30pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$100k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

17A64962

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLN 9176 B

Yr Regn:

5-17

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

made

C.C.

1998

Colour:

blue

A/C:

Insured / Std / NI / NA

Sp. Reading

15838

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6CW107140125472

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

4/5/18

D.O.I.

17/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

trailing cracked u/c neg 10k.

14/6/18 Informal cotherine final by 1670.22 trailing & bulbs not consistent. already informed Jess not given and we will stand our side to insurance (paid \$4741.24%)

RECEIVED 14 JUN 2018

Date/Time. File Pass to?



Preli. Report

1) 14/6/18



Final Report

Date/Time. File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

\$ S + RS \$ SI

Photos

Others

TOTAL

145
50
16
211

Report Format :

TP

Lump Sum / I.B.I. (\$)

1670.22



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18008787/Uqd3

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 15-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4790B	Veh. Inspected	SLN 9176B
Policy No.		Coverage (\$)	0.00
Claim No.	D18003544MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/05/2018	Inspection Date	
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003544MFSH

Date: 18 May 2018

Our Ref: CS/FCI18008787/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 9176B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/05/2018 at the premises of M/s TRANS EUROKARS. and have the following to report:-

Workshop Estimate Amount	: S\$ 5,886.16 .
Revised Estimate Amount	: S\$ 1,670.22 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	07-05-2018	Our Ref No. D18003544MFSH
Accident Date	04-05-2018	Claim Type. Third Party
Insured Vehicle	SHA4790B	Third Party Vehicle. SLN9176B
Survey Location	EUROKARS CENTRE 12 SUNGEI KADUT AVE	
Contact Person.	ERIC PAU	
Contact No.	63958685/ 96185991	Fax No. 00
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

9.02 am
Eric
VNI
1pm @ 16/5

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/239792)



PRI Documents



Close



PRI Header Details

Claim No	D18003544MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS EL
Workshop Name	TRANS EUOKARS PTE LTD (Contact Person : ERIC PAU)	Survey Location & Contact Details	EUOKARS CENTRE 12 SUNGEI KADUT AVE Mobile: 96185991 , Phone: 63958685 , Fax: 00 EmailId: ERIC.PAU@EUOKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA4790B	TP Vehicle No	SLN9176B
PRI Recieved Date	10-05-2018 09:18:01 PM	Surveyor Appointed Date	15-05-2018 08:44:08 AM	Surveyor Accept Date	15-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	15-05-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 18 May 2018 2:25 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003544MFSH/1
Attachments: CSFC18008787Uqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SLN 9176B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 15 May 2018 9:05 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003544MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 15 May 2018 8:44 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003544MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Up to 64% off Car Insurance
with SG's No. 1 Motor Insurer

Receive **\$150**
shopping vouchers*

FIND OUT MORE

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)

[Advertiser Login](#)

[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd

Browse by Category ▼

Sort by

1 vehicles

Mazda 5

Advanced

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	Mazda 5		Any	Any	2017	Any	
		Mazda 5 2.0A Sunroof	\$100,200	\$10,340 /yr	16-Feb-2017	1,998 cc	28
A Well Maintained Car. I Service It Regularly. Selling Because Upgrading. Good Buy And Genuine Seller.							
Posted: 29-Apr-2018 Tags: 2017 Mazda 5, Mazda 5, Mazda, 5, Used Mazda							

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage

For old advertisements, view [Expired ads](#)

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [For](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, buy used Mazda 5, Mazda 5 Singapore, used Mazda 5 Singapore, used Mazda 5, used vehicles Singapore or even buy used Mazda 5 Singapore importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle le

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or wa

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 6486F

Vehicle Details

Vehicle No.: SLN9176B

Vehicle to be Exported: No

Intended De-registration Date: 17 May 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA5 5-DOOR WAGON 2.0L SP.6EAT
SUNROOF

Primary Colour: Blue

Manufacturing Year: 2017

Engine No.: PE10470317

Chassis No.: JM6CW1071H0125472

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$20,028.00

Original Registration Date: 22 May 2017

First Registration Date: 22 May 2017

Transfer Count: 0

Actual ARF Paid: \$20,040.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 May 2027

PARF Rebate Amount: \$15,030.00

Intended COE Rebate Details

COE Expiry Date: 21 May 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$55,414.00

COE Rebate Amount: \$49,932.00

Total Rebate Amount: \$64,962.00

The information contained herein is correct as at 17 May 2018

OK



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

Not Affected
Haha

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Liu Siyu ADDRESS : Blk 6 Lorong 4 Reality Park Singapore 536905 TEL : 94554025BRYAN	WIP : 17938 EXCESS : DATE: 10-May-18 JESS 6395 7874
VEH NO :	SLN9176B	DATE IN :	CONTACT PERSON :
CHASSIS NO :	JM6CW1071H0125472	MILEAGE :	TYPE OF CLAIM :
MODEL :	MAZDA5	DATE REG.:	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB	\$ 915.40
2	RETAINER(LHS), REAR BUMPER	1	MC513-50-2J1C	\$ 45.30
3	RETAINER(RHS), REAR BUMPER	1	MC513-50-2H1B	\$ 45.30
4	BRACKET(LHS), REAR BUMPER	1	MC513-51-077A	\$ 5.40
5	BRACKET(RHS), REAR BUMPER	1	MC513-51-067A	\$ 5.40
6	GUARD(LHS), REFLECTOR	1	MC513-50-371	\$ 20.50
7	REFLECTOR LHS	1	MD350-51-5L0E	\$ 50.40
8	GUARD(RHS), REFLECTOR	1	MC513-50-361	\$ 20.50
9	REFLECTOR RHS	1	MD350-51-5M0E	\$ 50.40
10	REAR REINFORCEMENT	1	MC235-56-B9XC	\$ 148.00
11	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	\$ - 6.00
12	RIVET, REAR BUMPER	4	MBN8F-50-355	\$ - 21.60
13	GROMMET, REAR BUMPER	1	M9991-00-501	\$ - 2.80
14	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ - 10.00
15	GROMMET, REAR BUMPER	2	MC235-50-ES1	\$ - 8.80
16	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	\$ - 6.60
TOTAL PARTS			17.80	\$ 1,362.40
LESS 10%			16.02	\$ 136.24
TOTAL PARTS COST				\$ 1,226.16

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630	\$ 1,500.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	11X	\$ 660.00

4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00
			1130	
TOTAL LABOUR			\$ -	\$ 4,660.00
TOTAL PARTS			\$ -	\$ 1,226.16
TOTAL			\$ -	\$ 5,886.16
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	
GST 7%			\$ -	\$ -
GRAND TOTAL			\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To supply damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9/181670.22

6411.72



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD		NAME : Ms Liu Siyu		WIP : 17938	
36 ROBINSON ROAD		ADDRESS : Blk 6 Lorong 4 Reality Park		EXCESS :	
#16-01 CITY HOUSE		Singapore 536905		DATE: 10-May-18	
SINGAPORE 068877					
ATTN. : MOTOR CLAIMS		TEL : 945540258BRYAN			
FAX :					
VEH NO :	SLN9176B	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6CW1071H0125472	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	22-May-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB		\$ 915.40
2	RETAINER(LHS), REAR BUMPER	1	MC513-50-2J1C		\$ 45.30
3	RETAINER(RHS), REAR BUMPER	1	MC513-50-2H1B		\$ 45.30
4	BRACKET(LHS), REAR BUMPER	1	MC513-51-077A		\$ 5.40
5	BRACKET(RHS), REAR BUMPER	1	MC513-51-067A		\$ 5.40
6	GUARD(LHS), REFLECTOR	1	MC513-50-371		\$ 20.50
7	REFLECTOR LHS	1	MD350-51-5L0E		\$ 50.40
8	GUARD(RHS), REFLECTOR	1	MC513-50-361		\$ 20.50
9	REFLECTOR RHS	1	MD350-51-5M0E		\$ 50.40
10	REAR REINFORCEMENT	1	MC235-56-B9XC		\$ 148.00
11	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	\$ 6.00	\$ 6.00
12	RIVET, REAR BUMPER	4	MBN8F-50-355	\$ 21.60	\$ 21.60
13	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80	\$ 2.80
14	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.00	\$ 10.00
15	GROMMET, REAR BUMPER	2	MC235-50-ES1	\$ 8.80	\$ 8.80
16	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	\$ 6.60	\$ 6.60
SUPPLEMENTARY ITEM					
1	LAMP LHS, REAR COMB	1	MC513-51-160D	\$ 573.00	\$ 573.00
2	BULBS	2	M9970-08-215	\$ 10.40	\$ 10.40
TOTAL PARTS				\$ 639.20	\$ 1,945.80
LESS 10%				\$ 63.92	\$ 194.58
TOTAL PARTS COST				\$ 575.28	\$ 1,751.22
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 660.00	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.		\$ 630.00	\$ 1,500.00

3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.		\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 1,620.00 \$ 4,660.00
			TOTAL PARTS	\$ 575.28 \$ 1,751.22
			TOTAL	\$ 2,195.28 \$ 6,411.22
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 2,195.28
			GST 7%	\$ 153.67 \$ -
			GRAND TOTAL	\$ 2,348.95 \$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18008787/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4790B	Veh. Inspected	SLN 9176B	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18003544MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	15/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071H0125472	Colour	BLUE	
Odometer	15839	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TOYO	7 mm	
L/H Front Tyre	205/55 R16	TOYO	7 mm	
R/H Rear Tyre	205/55 R16	TOYO	7 mm	
L/H Rear Tyre	205/55 R16	TOYO	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/05/2018	Inspection Date	17/05/2018	
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER REVERSE SENSORS.	NOT NECESSARY	660.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			4,560.00	1,590.00
GRAND TOTAL			6,411.22	1,670.22
RECOMMENDED COST OF REPAIRS				1,670.22

Report Ref No. CS/FCI18008787/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.