ASS. REC. BY:	REF: CS 401 1800	8794/Ktd	3n2 Special	Instruction:	
Surveyor Kennuth		ENT (Office)			
From (Person): Jenny	Hew of	UOI	Dat	e/Time: _	15/5/18@ 10.51am
Estimated Cost:		Bill to:			
	DD RES/EVA/INV/MV/				
To Inspect Vehicle No:	SFE 1380Z		Insured;	SKB	83479
of No· 10, MK	reng Hoe Motor Ind Park 2A # 0	11-04	Tel:	648	1 2001
Policy No:		Claim No:			M12D08051805
Sum Insured:		Excess:			
Make of Veh: (Client's Record)	2		D.C).A J	3/05/2018
CA / REV / REP. / RE	V 24 HRS wp) DISIS 18 Person Contacted:	Donlyn		LO.D. Endo	DUT
	nction () Estimate	00			*
SFEI	380Z-x		na more		
	3479-006/AIG	11022642	Msq3y)	DOA: 8/10/2011
8/11 8196	93.20 Confirm	N Efic	19 (RE	ed. 20	578, 990)
-					



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interr	nationale Des Experts En Auton	nobile
UNI	TED OVERSEAS I	NSURANCE LTD	Ref : CS/UOI180087	794/Ktd3
	NSON ROAD #28-0 RINGLEAF TOWER	01 R SINGAPORE 079909	Date: 15-05-2018 Code: UOI2	
١.		Policy Particula	ars :- THIRD PARTY CLA	IM
	Insured Veh.	SKB 8347G	Veh. Inspected	SFE 1380Z
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	JENNY LEW	Assign Date	15/05/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	259)	Steering	
	Brakes		Modification	
	General			
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
		Descri	ption of Damages	
j.	Engina No.	Gen	eral Information	
	Accident Date	13/05/2018	Inspection Date	15/05/2018
	Survey held at	CHENG HOE MOTOR SERV	/ICE	
		10 ANG MO KIO IND PARK : #01-04 ANG MO KIO AUTOR	[[[[[[[] [[] [] [] [] [] [] [] [] [] []	
ia.			Remarks	
	A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS , WE HAVE NOT AUTHORIS	IS. ED REPAIRS.

Nivitha (LKK Auto)

From:

LEW JENNY < jennylew@uoi.com.sg>

Sent:

Tuesday, 15 May 2018 10:51 AM

To:

CHENG HOE MOTOR PTE LTD (AMK); assignments; SUR

Subject:

RE: Repair Survey (Single Joint Expert) - SFE1380Z, doa 13/05/18 (Yr insured

SKB8347G)

Attachments:

SFE1380 GIA.zip

Dear Dorlyn,

We will appoint LKK as SJE as per requested.

Dear Shiau Chan,

Please arrange to survey the vehicle at Cheng Hoe Motor Pte Ltd.

Thank You.

Warmest Regards

Jenny Lew

Claims Department

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: CHENG HOE MOTOR PTE LTD (AMK) [mailto:chmamk@singnet.com]

Sent: Monday, 14 May, 2018 5:36 PM To: LEW JENNY < jennylew@uoi.com.sg>

Subject: Fw: Repair Survey (Single Joint Expert) - SFE1380Z, doa 13/05/18 (Yr insured SKB8347G)

Hi Jenny,

Please assist to arrange.

Thank you.

Rgds,

Dorlyn Li (Ms)

CHENG HOE MOTOR PTE LTD (AMK)

No. 10 Ang Mo Kio Ind Park 2A

#01-04

Ang Mo Kio Autopoint Singapore 568047

Tel: 6481 2001 Fax: 6482 1296

Email: chmamk@singnet.com

From: CHENG HOE MOTOR PTE LTD (AMK)
Sent: Monday, May 14, 2018 2:41 PM

To: <u>UOI (CLAIMS DEPT)</u>; <u>CHENG HOE MOTOR PTE LTD (HQ)</u>
Subject: Repair Survey (Single Joint Expert) - SFE1380Z, doa 13/05/18 (Yr insured SKB8347G)

Dear Sir,

OUR CLIENT - SFE1380Z

DOA:

13/05/2018 @ 1940HRS

YR INSURED: SKB8347G (LOOI YEW KIAT)

- (A) KIndly provide us of your surveyor listing for the selection on the survey.
- (B) Also, please advise as below :-
- 1) Has your insured reported the accident to you?
- 2) Pls advise if he admitted fault?
- 3) Are you agree on **DIRECT SETTLEMENT**?
- 4) if possible, pls email a copy of your insured's report to us.

Thank you.

Rgds,

Dorlyn

CHENG HOE MOTOR PTE LTD

Tel: 664812001 Fax: 64821296

Used Mercedes-Benz C180 Car for Sale in Singapore, Igua ... Page 1 of 2

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products


Insurance

Articles

Forum

Resources

OX



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	4312H	
Vehicle No.:	SFE1380Z	
Vehicle to be Exported:	No	
Intended De-registration Date:	14 May 2018	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	C 180 BLUEEFFICIENCY	
Primary Colour:	Black	
Manufacturing Year:	2012	
Engine No.:	27491030025172	
Chassis No.:	WDD2040312A792300	
Maximum Power Output:	115.0 kW (154 bhp)	
Open Market Value:	\$30,160.00	
Original Registration Date:	16 Nov 2012	
First Registration Date:	16 Nov 2012	
Transfer Count:	2	
Actual ARF Paid: Intended PARF Rebate Details	\$30,160.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	15 Nov 2022	
PARF Rebate Amount:	\$21,112.00	
Intended COE Rebate Details		
COE Expiry Date:	15 Nov 2022	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$58,001.00	
COE Rebate Amount:	\$26,116.00	
Total Rebate Amount:	\$47,228.00	

The information contained herein is correct as at 14 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

*	\sim 1	חבו	V 4	STA	4-1.5	1-136	г
AU	u	DEI	ш	SIA	- 17		۰

Date Of Report

14/05/2018 12:51

Date Of Accident

13/05/2018 19:40

Exact Location Of Accident

OUTSIDE 5 THOMSON HEIGHTS

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SFE1380Z

Insured/Policyholder

Name Of Registered Owner

CHEW CHUI SHIANG LINDA

NRIC No.

S1654312H

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-96213327

Alternative Phone No

OTHERS-97893757

Vehicle Particulars

Manufacturer

MERCEDES-BENZ

Model

C180-1.6 (A)

Exact Purpose for which vehicle was being used at

time of accident

ON THE WAY HOME

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5078403563-02

Cover Note Number

16/05/2018 - 15/05/2019

Driver

Name of Driver

M SUNTHARALINGAM

NRIC No

S1597434F

Date Of Birth

26/09/1963

Occupation Date Of Driving Pass INDOOR

11/03/1981

Driving Experience

37 YEARS AND 2 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-97893757

Fax Number

Contact Number EMail Address

MSUNDRAM@DBS.COM

Page 1 of 11

5 THOMSON HEIGHTS Address

574834 Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - CHANGE/CROSS LANE Type Of Accident

CLEAR Weather Conditions DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 3 NO Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

YES Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NAME:

NO

NO

2

NO

NO

: KISHEN M SUNTHARALINGAM

: MALE GENDER:

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

AS I SAW MOTOR CAE SKB8347G ON THE OPPOSITE DIRECTION, I SLOWED DOWN, PREPARING TO STEER INWARD TO GIVE WAY, HOWEVER, MOTOR CAR SKB8347G SPED UP AND HIT ONTO MY VEHICLE REAR RH PORTION, RIGHT AFTER THE IMPACT, HIS VEHICLE LOST CONTROL AND HIT ONTO ANOTHER PARKED VEHICLE C (SJT1923G) BEFORE HIS VEHICLE MOUNTED THE SIDE KERB. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

SKB8347G Vehicle Registration Number VOLVO Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR Vehicle Category LOOI YEW KIAT Name of Driver S1255479F NRIC/Passport Number

90232614 Contact Number

17 MUNSHI ABDULLAH WALK Address

788597 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJT1923G

Vehicle Make/Model/Colour

METALLIC SILVER BMW

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

VEHICLE NO .:

DATE & TIME:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Re Sun Hun 1

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.

Thomasin B: SKB 83476 DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Vehicle No: SFE 13807 (NTUC) Date & Time: 13/05/2018 (N 1940 (deav) div) As i saw motor car SKB 83476 on the opposite direction, i slowed down, prepaging to Steer inword to give way However, in car SKB 83476 speed up and hit onto my vehicle may However, in car SKB 83476 speed up and hit onto my vehicle may Right after the impact, his vehicle lost control and hit onto my vehicle war RH por Right after the impact, his vehicle lost control and hit onto my vehicle way However, in some state of the side kerb. No was injured.		AC FEIZENZ
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Vehicle No: SFE 13802 (NTUC) Date & Time: 13/05/2018 (N 1940 (dear) day) As i saw motor car SKB 83476 on the opposite direction is slowed down, prepaying to steer inward to give way. However, in car SKB 83476 speed up and hit onto may vehicle year RH por Right after the impact, his vehicle lost control and hit orto anotoparked vehicle (before his vehicle mounted the side kerb. No		AS SFE 13802 W I DASSEMBER
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Vehicle No: SFE 1380Z (NTUC) Date & Time: 13/05/2018 (N 1940 (dear dw) As i Saw motor Car SKB 83476 on the opposite direction, I slowed down, propaging to Steer inward to give way However, n Car SKB 83476 Specify and hit unto my vehicle year RH pur Right after the impact, his reficle lost control and hit unto anoto parked vehicle C before his reficle mounted the side kerb. No		
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Vehicle No: SFE 1380Z (NTUC) Date & Time: 13/05/2018 (N. 1940 (dear) day) As i saw motor car SKB 83476 on the opposite direction, i slowed down, prepaging to steer inward to give way. However, in car SKB 83476 speed up and hit onto may vehicle year RH por Right after the impact, his rehicle lost control and hit orto and parked vehicle Chefore his rehicle mounted the side kerb. N	Thomson	
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Vehicle No: SFE 1380Z (NTUC) Date & Time: 13/05/2018 (No. 1940) As I saw motor car SKB 83476 on the opposite direction of slewed down, prepaging to steer inward to give way. However, in car SKB 83476 speed up and hit onto my vehicle year RM por Right after the impact, his rehicle lost control and hit outo anotoparked vehicle C before his rehicle mounted the side kerb. No.	Hight A	(157719)26
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Vehicle No: SFE 1380Z (NTUC) Date & Time: 13/05/2018 (No. 1940) As I saw motor car SKB 83476 on the opposite direction of slewed down, prepaging to steer inward to give way. However, in car SKB 83476 speed up and hit onto my vehicle year RM por Right after the impact, his rehicle lost control and hit outo anotoparked vehicle C before his rehicle mounted the side kerb. No.		Metallic Silve
Describe circumstances of the accident Vehicle No: SFE 13807 (NTUC) Date & Time: 13/05/2018 (N 1940 (dear) day) As i Saw motor Car SKB 83476 on the opposite direction, i slowed down, preparing to Steer inward to give way. However, n Car SKB 83476 Spead up and hit onto may vehicle rear RH por Right after the impact, his vehicle lost control and hit onto another parked vehicle C before his vehicle mounted the side kerb. No		
Vehicle No: SFE 13807 (NTUC) Date & Time: 13/05/2018 (N 1940 (dear) day) As I saw motor car SKB 83476 on the opposite direction of slowed down, prepaging to steer inward to give way. However, no car SKB 83476 speakup and hit onto my vehicle may RH por Right after the impact, his vehicle lost control and hit onto another parked vehicle Chefore his vehicle mounted the side kerb. No		
Vehicle No: SFE 13807 (NTUC) Date & Time: 13/05/2018 (N 1940 (dear) day) As i saw motor car SKB 83476 on the opposite direction, i slowed down, preparing to steer inward to give way However, in car SKB 83476 speck up and hit onto my vehicle year RM por Right after the impact, his vehicle lost control and hit onto another parked vehicle C before his vehicle mounted the side kerb. No	M. J.	
Date & Time: 13/05/2018 (2) 1940 (dear/dy) As i saw motor car SKB 83476 on the opposite direction, i slowed down, prepaging to steer inward to give way. However, in car SKB 83476 specify and hit onto my vehicle near RH por Right after the impact, his vehicle lost control and hit onto ano parked vehicle Chefore his rehicle mounted the side kerb. N	DESCRIBE CIRCUMSTANCES	20 A (200)
As i saw motor car SKB 83476 on the opposite direction, i slowed down, prepaging to steer inward to give way. However, in car SKB 83476 speakup and hit unto mod vehicle near Ry por Right after the impact, his vehicle lost control and hit unto anot parked vehicle C before his rehicle mounted the side kerb. N	VANCIA NO SFE	
Slowed down, propaging to Steer inward to give way. However, in Car SKB 83476 Specify and hit onto my vehicle near Ry por Right after the impact, his vehicle lost control and hit onto ano parked vehicle Chefore his rehicle mounted the side kerb. N	DULK LINNE 12/0	STAVIA (" 1740 GEAN GUY)
	Car SKB 83476 Right after the in parked vehicle	spanne to steer inward to give way. However, of specific and hit anto my vehicle rear RH pormition, his vehicle lost control and hit anto and
	Car SKB 83476 Right after the in parked vehicle was injured.	speadup and hit onto my vehicle rear RH pos whact, his vehicle lost control and hit unto and Chefore his vehicle mounted the side kerb. N
under your own comprehensive policy. Please check with your policy for more information.	Car SKB 83476 Right after the in parked vehicle was injured.	epangg to Steer inward to give way. However, to speed up and hit onto my vehicle way RH pure what, his vehicle lost control and hit onto and C before his vehicle mounted the side kerb. No our insurer may have 14 days Time Frame for you to submit an Own Damage C
under your own comprehensive policy. Please check with your policy for more information. DECLARATION	Note: Please note that you under your own co	epaging to Steer inward to give way. However, the special up and hit onto more vehicle way RH powerful, his vehicle lost control and hit onto and before his vehicle mounted the side kerb. No before his vehicle mounted the side kerb. No our insurer may have 14days Time Frame for you to submit an Own Damage Comprehensive policy. Please check with your policy for more information.
under your own comprehensive policy. Please check with your policy for more information.	Note: Please note that you under your own co	epaging to Steer inward to give way. However, " Specify up and hit onto my vehicle way RH por Minact, his vehicle lost control and hit outo and Chefere his vehicle mounted the side kerb. N our insurer may have 14days Time Frame for you to submit an Own Damage Comprehensive policy. Please check with your policy for more information.

Attn. MR. Cenneth

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

UNITED OVERSEAS INSURANCE LTD

3 ANSON ROAD

#28-01 SPRINGLEAF TOWER

SINGAPORE 079909

62227733 TEL:

FAX: 63273869 NOT Northains

ATTN: Motor Claim Department

WS Ref: Claim Type: TP/UOI/AMK

Third Party

Accident Date: TP Veh Reg No: 13/05/2018

SKB8347G

CHSm 87

Resorry After Pains

Estimate No: ES1890534/AMK

Date: 14 May 2018

5078403563-02 Policy No:

Veh Reg No: SFE1380Z

Make/Model: MERCEDES BENZ C180K

Chassis No: WDD2040312A792300

Engine No: 27491030025172 Reg. Date:

16/11/2012

Estimate Repair Cost to Vehicle No :SFE1380Z

	Description	U/Price	Quantity	List Price	Amount
	Net Price			<u>SS</u>	<u>SS</u>
I	FRONT RH DOOR	*****	0902020	By 174600	
2	FRONT RH DOOR SEAL	1,746.00	1 PC	1,740.00	
3	FRONT RH DOOR SEAL FRONT RH DOOR CHROME MOULDING	282.00	1 PC	NA 282.00	
4	FRONT RH DOOR CHROME MOULDING FRONT RH DOOR INNER LOWER RUBBER	92.00	1 PC	92.00	-
5	FRONT RH DOOR INNER LOCK	→ 55.00	——— PC	33.00	*×
6		310.00	1 PC	0 / 310.00	
7	FRONT RH INNER DOOR FRAME STEP GARNISH REAR RH DOOR	V 115.00	1 PC	n 113.00	1
33		2,088.00	1 PC	2,000.00	
8	REAR RH DOOR SEAL	282.00	1 PC	na 282.00	
9	REAR RH DOOR CHROME MOULDING	90.00	1 PC	90.00	_
0	REAR RH DOOR INNER LOWER RUBBER	45.00	1 PC	45.00	X
11	REAR RH DOOR HINGE (2 PCS)	295.00	1 SET	The St.	<u> </u>
12	REAR RH DOOR WINDOW OUTER CHROME MOULDING	135.00	1 PC	Na 135.00	75
3	REAR RH DOOR INNER LOCK	288.00	1 PC	nd 288.00	10
4	REAR RH DOOR POWER WINDOW MOTOR	625.00	1 PC	"In 625.00	_
5	REAR RH DOOR REGULATOR	670.00	1 PC	670.00	_
6	REAR RH DOOR QUARTER GLASS -	× 120.00	- 1 PC	120.00	X
7	REAR RH DOOR WINDOW INNER TOP GUIDE RAIL		1 PC	211 145.00	2
8	REAR RH DOOR INNER DOOR FRAME STEP GARNISH	√ 83.00	1 PC	83.00	7-
9	RH SIDE SKIRT	525.00	1 PC	525.00	_
0	RH SIDE SKIRT CLIPS	9.00	10 PC	Me 90.00	_
1	REAR RH FENDER	2,030.00	1 PC	Ry 2,030.00	-
2	REAR RH FENDER INNER SHIELD CHIE	-170.00	1 PC	CM 170.00	2
3	RH ROCKER PANEL	540.00	1 PC	Ry 540.00	_
4	RH B PILLAR	360.00	1 PC	2 560.00	
5	REAR RH RIM 17"	590.00	1 PC	nu 590.00	
6	REAR SEAT BELT	375.00	2 PC	7n 750.00	
7	AIR BAG ECU	1,095.00	1 PC	na 1,095.00	
8	FRONT RH SEAT AIRBAG	640.00		Burn 640.00	
9	RH WINDOW AIRBAG	795.00		Bry 795.00	_
0	RH WINDOW AIRBAG ROOF LINING Re Form	1,215.00	1 PC		
1	FRONT RH WINDSCREEN PILLAR INNER GARNISH	112.00		Mgc 1,215.00	12
2	RH FLOOR BOARD UNDER COVER	290.00		112.00	in _
	The state of the s	290.00			
			166		
	2001000		Less 10%	1,686.80	15,181.20
	Special Net		106	68.4	14683.
3	CHASSIS FRAME STICKER	150.00	1 PCS	Ma 150.00	_
4	REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	1

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL. 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

M/S: UNITED OVERSEAS INSURANCE LTD

3 ANSON ROAD

#28-01 SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 62227733

ATTN: Motor Claim Department

WS Ref:

TP/UOI/AMK

Claim Type:

Third Party

Accident Date:

13/05/2018

TP Veh Reg No: SKB8347G

Estimate No:

ES1890534/AMK

Date:

14 May 2018

Policy No:

5078403563-02

Veh Reg No:

SFE1380Z

Make/Model: Chassis No:

MERCEDES BENZ C180K

4540 /

Engine No:

WDD2040312A792300 27491030025172

Reg. Date:

16/11/2012

Estimate Repair Cost to Vehicle No :SFE1380Z

FAX: 63273869

	Description	U/Price	Quantity	List Price	Amount
35	REAR RH DOOR QUARTER GLASS SEALANT	20.00	1 PC	M 20.00	<u>ss</u>
	Labour			210.00	210.00
36	TOWING (BY KING DOLLY)	120.00	14.414	222700	./
37	REMOVE AND REFIX REAR WINDSCREEN GLASS —	120.00	1 LA	120.00	-
38	REMOVE AND REFIX REAR RH DOOR WINDOW GLASS	120.00	1LA	120.00	×
39		60.00	1 LA	60.00	
27	REMOVE & REFIX REAR BUMPER, BOTH RH DOORS, RH SIDE SKIRT; TO CUT, WELD & RENEW RH ROCKER PANEL, RH	3,200.00	1 LA	3,200.00	25001
	CENTRE DOOR PILLAR, REAR RH FENDER: KNOCKING &			200	0
	REPAIR RH FLOORBOARD & REALIGN THE SAME				
40	PUTTY & RESPRAY BOTH RH DOORS, RH ROCKER PANEL, RH SIDE SKIRT, RH CENTRE DOOR PILLAR, REAR RH FENDER, FLOORBOARD & ALL AFFECTED AREAS	1,200.00	1 LA	1,200.00	11001
41	REMOVE & REFIX REAR SEAT, FRT SEAT, GARNISH, ROOF LINING TO FACILITATE REPAIR	350.00	1 LA	350.00	1801
42	REMOVE & REFIX FRT SEAT, AIRBAG, BOTH REAR SEAT BELTS, AIRBAG ECU & REALIGN THE SAME	300.00	1 LA	300.00	2201
43	TO CLEAR FAULT CODE & REPROGRAMME THE SAME	300.00	1 LA	300.00	2501
44	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 PC	80.00	- '
45	TO MOUNT ON CAR-O-LINER, JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	2
46	REMOVE & REFIX BOTH RH DOOR WINDOW GLASSES & RESET CENTRAL LOCKING	200.00	1 LA	200.00	1601
47	RUSTPROOFING	180.00	1 LA	180.00	1201
				6,360.00	6,360.00

PARU: 14983-20 SN: 210 L: 4540 19733.20

ac. EEFP1: 1919

PLS CHELK & CONFIRM

LKK Auto Consultants hence notify

- the Repairer of the following:

 To resurvey before and spray painting

 To display damaged part(s) during resurvey
- · Parta prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

M/S: UNITED OVERSEAS INSURANCE LTD

3 ANSON ROAD

#28-01 SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 62227733

ATTN: Motor Claim Department

WS Ref:

TP/UOI/AMK

Claim Type:

Third Party

Accident Date:

13/05/2018

TP Veh Reg No: SKB8347G

Estimate No:

ES1890534/AMK

Date:

14 May 2018

Policy No:

5078403563-02

Veh Reg No:

SFE1380Z

Make/Model:

MERCEDES BENZ C180K

Chassis No: WDD2040312A792300

Engine No: 27491030025172

Reg. Date:

16/11/2012

Estimate Repair Cost to Vehicle No :SFE1380Z

FAX: 63273869

Description	U/Price	Quantity	List Price	Amoun
			SS	SS
			Total	S\$ 21,751.20
		Add G	ST @ 7%	1,522.58
		Total Amoun	it Payable	S\$ 23,273.78

VEHICLE LYING AT: NO.10 ANG MO KIO INDUSTRIAL PARK 2A #01-04 AMK AUTOPOINT SINGAPORE 568047

TEL: 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITE	OVERSEAS IN	SURANCE LTD	Ref : CS/UOI18008794	4/Ktd3n2
	ON ROAD #28-0 GLEAF TOWER	1 SINGAPORE 079909	Date: 15-11-2018 Code: UOI2	
. 888		Policy Particula	rs :- THIRD PARTY CLAIN	
I	nsured Veh.	SKB 8347G	Veh. Inspected	SFE 1380Z
F	Policy No.		Coverage (\$)	0.00
-	Claim No.	M12D08051805	Excess (\$)	0.00
-	Assign From	JENNY LEW	Assign Date	15/05/2018
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	MERCEDES C180 (A)	c.c	1595
E	Engine No.	HIDDEN	Year of Reg.	2012
-	Chassis No.	WDD2040312A792300	Colour	METALLIC BLACK
	Odometer	93301	Steering	IN ORDER
E	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
(General	GOOD		
3.		Cond	ditions of Tyres	
		Size	Make	Balance
F	R/H Front Tyre	225/45 R17	CONTINENTAL	8 mm
ı	_/H Front Tyre	225/45 R17	CONTINENTAL	8 mm
F	R/H Rear Tyre	225/45 R17	CONTINENTAL	8 mm
ı	_/H Rear Tyre	225/45 R17	CONTINENTAL	8 mm
4.		Descri	ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	O/S BODY.	
1	DAMAGES SEE D	ETAILS.		
5.		Gene	eral Information	
1	Accident Date	13/05/2018	Inspection Date	15/05/2018
	Survey held at	CHENG HOE MOTOR SERV	ICE	
		10 ANG MO KIO IND PARK 2 #01-04 ANG MO KIO AUTOF	2A POINT . SINGAPORE 568047	
5a.			Remarks	
	A)THE INSPECTION B)IN ACCORDAN	ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS , WE HAVE NOT AUTHORIS	IS. ED REPAIRS.
5b.		Estima	ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	16 Working Da	ys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFE 1380Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT RH DOOR (N)	BENT	1,746.00	1,746.00
1	FRONT RH DOOR SEAL (N)	NECESSARY	282.00	282.00
	FRONT RH DOOR CHROME MOULDING (N)	DENTED	92.00	92.00
	FRONT RH DOOR INNER LOWER RUBBER (N)	SERVICEABLE	55.00	
	FRONT RH DOOR INNER LOCK (N)	DENTED	310.00	310.00
	FRONT RH INNER DOORFRAME STEP GARNISH (N)	DENTED	115.00	115.00
1	REAR RH DOOR (N)	BENT	2,088.00	2,088.00
1	REAR RH DOOR SEAL (N)	NECESSARY	282.00	282.00
1	REAR RH DOOR CHROME MOULDING (N)	MISSING	90.00	90.00
1	REAR RH DOOR INNER LOWER RUBBER (N)	SERVICEABLE	45.00	
1	SET REAR RH DOOR HINGE (2 PCS)(N)	BENT	295.00	295.00
1	REAR RH DOOR WINDOW OUTER CHROME MOULDING (N)	NECESSARY	135.00	135.00
1	REAR RH DOOR INNER LOCK (N)	DENTED	288.00	288.00
1	REAR RH DOOR POWER WINDOW MOTOR (N)	JAMMED	625.00	625.00
1	REAR RH DOOR REGULATOR (N)	BENT	670.00	670.00
1	REAR RH DOOR QUARTER GLASS (N)	SERVICEABLE	120.00	
1	REAR RH DOOR WINDOW INNER TOP GUIDE RAIL (N)	DISTORTED	145.00	145.00
1	REAR RH DOOR INNER DOOR FRAME STEP GARNISH (N)	DENTED	83.00	83.00
1	RH SIDE SKIRT (N)	MISSING	525.00	525.00
10	RH SIDE SKIRT CLIPS @\$9.00 (N)	NECESSARY	90.00	90.00
1	REAR RH FENDER (N)	BENT	2,030.00	2,030.00
1	REAR RH FENDER INNER SHIELD (N)	CRACKED	170.00	170.00
1	RH ROCKER PANEL (N)	BENT	540.00	540.00
1	RH B PILLAR (N)	BENT	560.00	560.00
1	REAR RH RIM 17" (N)	DENTED	590.00	590.00
2	REAR SEAT BELT @\$375.00 (N)	JAMMED	750.00	750.00
1	AIR BAG ECU (N)	NECESSARY	1,095.00	1,095.00
1	FRONT RH SEAT AIRBAG (N)	BURST	640.00	640.00
1	RH WINDOW AIRBAG (N)	BURST	795.00	795.00
1	ROOF LINING (N)	DEFORMED	1,215.00	1,215.00
1	FRONT RH WINDSCREEN PILLAR INNER GARNISH (N)	MTG CRACKED	112.00	112.00
1	RH FLOOR BOARD UNDER COVER (N)	CRACKED	290.00	290.00

Report Ref No. CS/UOI18008794/Ktd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

19,693.20

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,686.80	-1,664.80
			15,181.20	14,983.20
	SPECIAL NETT ITEMS			
1	CHASSIS FRAME STICKER (SN)	NECESSARY	150.00	150.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	40.00	100
1	REAR RH DOOR QUARTER GLASS SEALANT (SN)	NECESSARY	20.00	20.00
			210.00	170.00
	LABOUR			
	TOWING (BY KING DOLLY).		Workshop (\$) -1,686.80 15,181.20 150.00 40.00 20.00	120.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY		
	REMOVE AND REFIX REAR RH DOOR WINDOW GLASS.	A CONTRACTOR OF	60.00	60.00
	REMOVE & REFIX REAR BUMPER,BOTH RH DOORS,RH SIDE SKIRT;TO CUT & WELD & RENEW RH ROCKER PANEL,RH CENTRE DOOR PILLAR,REAR RH FENDER;KNOCKING & REPAIR RH FLOORBOARD & REALIGN THE SAME.		3,200.00	2,000.00
	PUTTY & RESPRAY BOTH RH DOORS,RH ROCKER PANEL,RH SIDE SKIRT,RH CENTRE DOOR PILLAR,REAR RH FENDER,FLOORBOARD & ALL AFFECTED AREAS.		1,200.00	1,100.00
	REMOVE & REFIX REAR SEAT, FRT SEAT, GARNISH ROOF LINING TO FACILITATE REPAIR.		350.00	180.00
	REMOVE & REFIX FRT SEAT, AIRBAG, BOTH REAR SEAT BELTS, AIRBAG ECU & REALIGN THE SAME.		300.00	220.00
	TO CLEAR FAULT CODE & REPROGRAMME THE SAME.		300.00	250.00
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.		350.00 300.00 300.00 80.00	80.00
	TO MOUNT ON CAR-O-LINER, JACK & STRAIGHTEN CHASSIS.		250.00	250.00
	REMOVE & REFIX BOTH RH DOOR WINDOW GLASSES & RESET CENTRAL LOCKING.		120.00 60.00 3,200.00 1,200.00 350.00 300.00 80.00 250.00 200.00 180.00 6,360.00	1
	RUSTPROOFING.		10 4000000	V 1
			6,360.00	4,540.00
	GRAND TOTAL		150.00 15,181.20 150.00 40.00 20.00 210.00 120.00 3,200.00 3,200.00 300.00 300.00 250.00 180.00 6,360.00	19,693.20

Report Ref No. CS/UOI18008794/Ktd3n2

KONG SENG CHEONG

RECOMMENDED COST OF REPAIRS

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.