

Surveyor

MA

ASSIGNMENT (Office)

From (Person)

Peter wang

of ASM (AXA)

Date/Time 14/5/18

Estimated Cost

Bill to

(O) / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SGR 866R

Insured

Y56 3637

at Workshop to/

Ah Lim Motor

Tel:

64831244

of 10 AMK Ind Parle 2 A #01-09

Policy No.

Claim No.

S8M00G79

Sum Insured

Excess

\$ 3000.00

Make of Veh.

(Client's Record)

D.O.A. 5/5/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

9:32am @ 15/5/18

Person Contacted

Zila

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGR 866R - CCA/ASM1800620/Apr 13

D.O.A. 5/5/2018

16/5/18 @

3:42pm revert to Peter Wang via Smart Claim.

16/5/18 @

6pm Peter Wang informed 1/15 EX: \$3000 via Smart Claim.

17/5/18 @

1:34pm Informed Eileen C/A 15 EX: \$3000 by email.

30/5/18 @

7:48pm Informed Peter that we have received supplementary \$1240 via Smart Claim.

13/6/18 @

12:10pm Peter informed can proceed supplementary via Smart Claim.

21/8/18 @

5:38pm Informed 1/2nd revert to Peter Wang via Smart Claim (2nd supplementary).

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record) _____

Make of Veh: _____

(Policy Condition) _____

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$184K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: -

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFR 866R Yr Regn: GET 2016
 Type: M.Carr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: NISSAN Qashqai 1197Colour: Black A/C: Insured / Std / NI / NASp. Reading: 26912 T/Radio: Insured / Std / NI / NA

Eng. No: _____

C/Vo: SJNFEAJ11U1-699139Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60/R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CON

Front

Rear

R/Bal: 7 mm R/Bal: 7 mmL/Bal: 7 mm L/Bal: 7 mmD.O.A. _____ D.O.I. 15/5/2018

Survey held at _____

Des. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time: 06/11/18 @ 12.03pm Action / Instruction: Lynn Kheng informed proceed to settle via Smart Claim
02/11/18 confirmed with Nuri Hong Asset Ag to 19873
(Ref 3 6134, 24%)

- RECEIVED 14 NOV 2018

Date/Time: File Pass to: ☐ : Prel. Report11/14/18 transfer ☐ : Final Report

Date/Time: File Return to: _____

Days Of Repair: 15Resurvey No. of Trip: 1

Survey Fee

Transportation

1. E-P. 1st

2. Other

3. Other

4. Other

5. Other

Add Fee: ☐ Site Insp 15☐ Interview 15☐ Test. fees 15☐ Workshop 15Report Format: Smart ClaimLum. Sum: 19873

300

300



Service Request Details

Claim

S8M00G79

Reference

None 

Loss Date

May 5, 2018

Request Date

May 14, 2018

Due Date

May 21, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGR866R

Make

NISSAN

Service Address

10 Ang Mo Kio Ind. Park 2A, , , 568047

Primary Contact/Insured

WINEBERRY PTE LTD
22 INGGU ROAD, 757364, Singapore
68420766
SHIRLEY@INSMART.SG

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Wkshop: Ah Lim @ AMK Excess: \$3000 Pending wkshop's estimate To survey WP

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Model
QASHQAI 1.2

Service Address

10 Ang Mo Kio Ind. Park 2A, . , 568047

Primary Contact/Insured

WINEBERRY PTE LTD
22 INGGU ROAD, 757364, Singapore
68420766
SHIRLEY@INSMART.SG

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

Wkshop: Ah Lim @ AMK Excess: \$3000 Pending wkshop's estimate To survey WP

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE



SENT

11/6/18 12:03 PM

FROM

KHONG Lynn

SUBJECT

Re:RE: Adjustment to offer - Proceed to settle

BODY

Thanks



TYPE



SENT

11/1/18 2:36 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT RE: Adjustment to offer

BODY Dear Victor, any updates? - Shiau Chan



TYPE 

SENT 10/18/18 12:08 PM

FROM LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT RE: Adjustment to offer

BODY Dear Vincent, as spoken with you earlier. Refer to...



TYPE 

SENT 10/16/18 8:36 AM

FROM KHONG Lynn

SUBJECT Adjustment to offer

BODY Recommended adjustment on labour: Front portion o...



TYPE 

SENT 10/12/18 5:42 PM

FROM LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT RE: Re:RE: Revised estiamte not consistent - Kindly advise repair status

BODY Dear Lynn, there were a total of 2 supplementary L...



RE: Adjustment to offer

Type

🔗 Question

Message

Dear Vincent, as spoken with you earlier. Refer to the message dated 16/10/2018. We have negotiating with repairer on the repair cost. They are only unable accept the offer of labour no. 131 and supplementary labour. They insist the labour cost of labour no. 131 at \$800.00 instead of \$600.00 & supplementary labour cost \$400.00. (see receipt invoice uploaded) Hope the above clarify. - Shiau Chan

Reply



Auto
Consultants
Pte Ltd

81 UBI AVE L, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564318

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/10/18

Survey Details:

Date of loss	5-May-18
Date of appointment	14-May-18
Date of survey	15-May-18
Location of survey	AH LIM MOTOR

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SGR 866R
Make and Model	NISSAN QASHQAI
Date of registration	31/10/2016
Excess	\$ 3,000.00
Market Value	\$ 84,000.00
Parf Rebate	\$ 51,058.00
Nett Loss	\$ 32,942.00

Repair details:

Initial Estimate	\$ 26,007.00	(EST \$24,267.00 + SUPP 1 \$1,340.00 + SUPP 2 \$400.00)
------------------	--------------	---

Proposed/Revised repair cost:

Parts	\$ 15,883.00
Check items (estimate)	\$ -
Labour	\$ 3,990.00
Total	\$ 19,873.00
Lump Sum(if applicable)	\$

Number of days for repair	<u>15</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.
KINDLY APPROVE ON 2ND SUPPLEMENTARY.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

◀ Adjustment to offer

Type

🔔 Question

Message

Recommended adjustment on labour: Front portion on no: 116) Recommend \$20, instead of \$\$30/- 118) Recommend \$50, instead of \$120/- 119) Not given. 120) Recommend \$100 if the items are affected. Kindly advise photo. If no photos will be cancelled. 121) Recommend \$100 if the items are affected. Kindly advise photo. If no photos will be cancelled. 123) Recommend \$150 to \$200, instead of \$250. Rear portion on no: 126) Recommend \$20, instead of \$30/- 128) If end panel need to be replace, than \$60 will be given. Kindly advise photo. If no photos will be cancelled. 129) Recommend \$40, instead of \$60/- 130) End panel repair back will recommend \$500. If replaced will be at \$600/-. Kindly advise photo. 131) end panel repair back will recommend at \$450. If replaced end panel will be at \$600/-. Supplementary labour: 1) To transfer data to new automatic transmission control module unit, to ask for repair invoice, Thank you.

Reply

68804349

Vincent AXA.



RE: Re:RE: Revised estiamte not consistent - Kindly advise repair status

Type

🔗 Question

Message

Dear Lynn, there were a total of 2 supplementary list. One dated 28/05/2018 for \$1,340.00 which we had informed your side on 30/05/2018. The second supplementary list was dated 16/08/2018, which is the labour cost for some work done for the 1st supplementary list. The 2nd supplementary amount to \$400.00, which we have adjusted to \$150.00. In general, the supplementary was surveyed and adjusted during the repair process. The 1st supplementary list submitted to us during the repair process while the 2nd supplementary list submitted to us together with final bill after repair. - Shiau Chan

Reply

Re:RE: Revised estimate not consistent - Kindly advise repair status

Type

Question

Message

Dear Shiau Chan, is the repair done before this supplementary is submitted? If so, kindly advise whether it was surveyed and adjusted before repair / replacement. Thanks

There ~~was~~^{were} a total of 2 supp list. one dated 28/05/2018 for 1340.00 which ~~was~~ we had informed your side on 30/05/2018. The ^{supp list} 2nd ~~list~~ was dated 16/06/18, which is ~~the~~ the below cost for some work ~~done~~ done for the 1st supp list. The 2nd supp amount to \$4001-, which we have adjusted to \$150.00.

In general, the supp was surveyed and adjusted ~~before~~ ~~the completion of~~ during the repair process. the 1st supp list submitted to us during the repair process while the 2nd supp list submitted to us together with final bill of material.

⏪ Re:RE: Revised estimate not consistent - Kindly advise repair status

Type

🔗 Question

Message

Dear Shiau Chan, is the repair done before this supplementary is submitted? If so, kindly advise whether it was surveyed and adjusted before repair / replacement. Thanks

Reply



RE: Revised estiamte note consistent

Type

🔔 Question

Message

Dear Lynn, kindly approve on supplementary. - Shiau Chan

Reply



RE: Revised estiamte note consistent

Type

🔔 Question

Message

Dear Peter, the latest IA had mentioned \$20,093.00 are including the supplementary cost \$1,340.00 (approved), and recently 2nd supplementary \$400.00 (pending for approval) and some parts previously prices not available. Hope the above clarify. - Shiau Chan

Reply



Revised estiamte note consistent

SFR 2662

Type

🔔 Question

Message

Hi Shiau Chan, I noted that the revised IA figures is inconsistent with your message: Based on your first IA, adjusted repair cost is \$16714. You have subsequently requested for supplementary cost of \$1340 (approved), and recently another \$400 (pending for approval). However, that only gives to a total of \$18454, which is different from \$20093 in your new IA. Please clarify. Thank you!

Reply

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/08/18

Survey Details:

Date of loss	5-May-18
Date of appointment	14-May-18
Date of survey	15-May-18
Location of survey	AH LIM MOTOR

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SGR 866R
Make and Model	NISSAN QASHQAI
Date of registration	31/10/2016
Excess	\$ 3,000.00
Market Value	\$ 84,000.00
Part Rebate	\$ 51,058.00
Nett Loss	\$ 32,942.00

Repair details:

Initial Estimate	\$ 23,699.00	(EST \$21,959.00 + SUPP 1 \$1,340.00 + SUPP 2 \$400.00)
------------------	--------------	---

Proposed/Revised repair cost:

Parts	\$ 15,883.00
Check items (estimate)	\$ -
Labour	\$ 4,210.00
Total	\$ 20,093.00
Lump Sum(if applicable)	\$

Number of days for repair	<u>15</u>
---------------------------	-----------



Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.
KINDLY APPROVE ON SUPPLEMENTARY.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Supplementary items authorized

Type

🔗 Question

Message

Supplementary items authorized, In future, Pls ask for mandate first for supplementary items

Reply



SUPPLEMENTARY LIST OF VEHICLE SGR 866R UPLOADED

Type

🔗 Question

Message

Dear Peter, we have received supplementary of \$1,340.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. - Shiau Chan

Reply

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 17 May 2018 1:34 PM
To: ahlimmc@singnet.com.sg
Cc: SUR
Subject: VEHICLE SGR 866R (DOA: 05/05/2018)

Dear Eileen,

As instructed by our client, please proceed to repair the insured vehicle **SGR 866R (Excess \$3,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Authorized

Type

🔔 Question

Message

Pls proceed to authorize repair. Excess: \$3000 (\$500 basic + \$2500 young unnamed)

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564318

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/05/18

Survey Details:

Date of loss	5-May-18
Date of appointment	14-May-18
Date of survey	15-May-18
Location of survey	AH LIM MOTOR

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SGR 866R
Make and Model	NISSAN QASHQAI
Date of registration	31/10/2016
Excess	\$ 3,000.00
Market Value	\$ 84,000.00
Parf Rebate	\$ 51,058.00
Nett Loss	\$ 32,942.00

Repair details:

Initial Estimate	\$ 21,959.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 10,038.00
Check items (estimate)	\$ 2,866.00
Labour	\$ 3,810.00
Total	\$ 16,714.00
Lump Sum(if applicable)	\$

Number of days for repair	<u>15</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

PENDING FOR PARTS PRICES.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	2421E

Vehicle Details

Vehicle No.:	SGR866R
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Purple
Manufacturing Year:	2016
Engine No.:	HRA2296944A
Chassis No.:	SJNFEAJ11U1699139
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,689.00
Original Registration Date:	31 Oct 2016
First Registration Date:	31 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$13,689.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2026
PARF Rebate Amount:	\$10,266.00

Intended COE Rebate Details

COE Expiry Date:	30 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$40,792.00
Total Rebate Amount:	\$51,058.00

The information contained herein is correct as at 07 May 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9335381A



LEOW ZHEN HUI, WESLEY

廖振輝

Name

CHINESE

Date of birth

28-09-1993

Sex

M

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Vehicle Number S9335381A

Name

LEOW ZHEN HUI, WESLEY

Birth Date: 28 Sep 1993

Issue Date: 28 Jan 2013




002146140F

Hp: 9438 4428 / 9765 7087

Email: May.⁸⁰⁰ @ wineberry.com.sg



NRIC No: S9335381A



Date of issue

15-10-2008

22 INSUR AD
SINGAPORE 57384

NRIC No: S9335381A

Date: 28/03/2016

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS/ES

EFFECTIVE DATE

Class 3: Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 28 Jan 2013

MP 425A



Licence No: S9335381A

Ang Leck Mien (F)

Li YongHong Adiel (M)

Ong Jia Jing Nichol (F)

Teo MIN HUI (F).

any
inf: No
Car: No
Tsh: 5

Certificate of Insurance

Account Number
 11618

Motor Vehicle Third Party Risk Insurance Policyholder: WINEBERRY PTE LTD (Company Reg. Number: 2017000010, 1181, Singapore)
 Motor Vehicle Third Party Risk (Rule: 1994) (Malaysia)

Policy details

Policyholder name	WINEBERRY PTE LTD	Certificate number	GA283092 / 1
Cover	Comprehensive	Chassis number	514FEA11U1699119
Plan name	Flexi	Engine number	1RA223E644
NCD applicable	20%		
Vehicle registration number	SGR866R		
Period of Insurance	From 31/10/2017 to 30/10/2018 (Auto policy renewal)		
Finance loan company	HL BANK		

Persons or classes of persons entitled to drive*

- Any Named Driver as stated in the Policy
1. HOE WAN YONG
- Any person who is driving on the Policyholder's order or with their permission

Provided that the person or class of persons is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation or that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover: use for hire or reward, racing, speed trials, speed testing, the carrying of goods or other articles in connection with any trade or business, or use for any purpose in connection with motor racing or in the Motor Car, whether stationary or in use or otherwise, or whilst driving, racing, speed trials, or use for any other purpose or whilst the vehicle is being used for racing, speed trials or whilst the vehicle is being used for any other purpose.

1. The policy does not cover any use of the Motor Vehicle for any purpose other than those stated in the policy.

EXCESS	Basic Own Damage Excess	SGD 500.00
	Accident Excess	SGD 100.00

Additional excess is applicable as follows:

- \$5500 for Unlicensed/Unauthorized Driver
- \$5500 for Licensed/Young and Inexperienced Driver
- \$55000 for Licensed/Young and Inexperienced Drivers. This additional excess is reduced to \$52,500 if the driver is a member of AXA Young Drivers Club.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy is issued on the basis of the information provided in accordance with the provisions of the Motor Vehicle Third Party Risk Insurance Act, Chapter 288, and Part 1 of the Road Transport Act, 1987, (Singapore).

AXA Insurance Pte Ltd



Authorized signatory

Important note

Policyholder and insured must read the policy and accompanying documents carefully to understand the terms, conditions, coverages, exclusions, and limitations of the policy. The policyholder and insured must also read the policy and accompanying documents carefully to understand the terms, conditions, coverages, exclusions, and limitations of the policy. The policyholder and insured must also read the policy and accompanying documents carefully to understand the terms, conditions, coverages, exclusions, and limitations of the policy.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/05/2018 16:46
Date Of Accident	05/05/2018 13:30
Exact Location Of Accident	PIE TOWARDS THOMSON RD AFTER STEVENS RD EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGR866R
Insured/Policyholder	
Name Of Registered Owner	WINEBERRY PTE LTD
Co Reg No	199402421E
Email Address	MAY.SOO@WINEBERRY.COM.SG
Mobile Phone No	(LOCAL) +65-97657087
Alternative Phone No	OFFICE-94384458
Vehicle Particulars	
Manufacturer	NISSAN
Model	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA283092
Cover Note Number	31/10/2017 - 30/10/2018
Driver	
Name of Driver	LEOW ZHEN HUI, WESLEY
NRIC No	S9335381A
Date Of Birth	28/09/1993
Occupation	INDOOR
Date Of Driving Pass	28/01/2013
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94384458
Fax Number	
Contact Number	
Email Address	MAY.SOO@WINEBERRY.COM.SG

Address 22 INGGU ROAD
 Postcode 757364
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
 Foreign Vehicle Registration Number WWH9682 (PRIVATE CAR)
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5
 Passenger 1
 NAME: : ANG LECK MIEN
 GENDER: : FEMALE
 Passenger 2
 NAME: : LI YONGHENG ADRIEL
 GENDER: : MALE
 Passenger 3
 NAME: : ONG JIA JING NICHOL
 GENDER: : FEMALE
 Passenger 4
 NAME: : TEO MIN HUI
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] BISHAN N.P.C
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKU8231G
 Vehicle Make/Model/Colour
 Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	WWH9682
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SKK5089Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

Date of accident: 5/5/2018 Time: 13:30 Location: P I E towards Thompson
 My Vehicle A: SGR866R Vehicle B: SK118231G Vehicle C: WVH 9682
 Vehicle D: SLK 5089Z

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the Police Report No. T/2018 0305/201

type. Own Damage claim

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my file accident report to:

Name and signature of workshop personnel including company stamp

My workshop:

Email address:

& myself:

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

We declare the foregoing particulars are true in every respect:

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time




Driver's Signature
(If driver is not the policyholder)
Date & Time



Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:





**SINGAPORE
POLICE FORCE**



T/20180505/2101

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

1 of 3

Report No. T/20180505/2101

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/05/2018 15:51		Vide Report No.:		Station Diary No.: 119	
Informant's Particulars					
Name of Informant: LEOW ZHEN HUI, WESLEY			Address: 22 INGGU ROAD SINGAPORE 757364		
ID Type / ID No.: NRIC NO / S9335381A			Contact No.: Home/Office: Mobile: 94384458		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 24	Date of Birth: 28/09/1993	Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name: SIM	
Occupation: Student			Driving Licence Information: Class: 3 Date of Expiry:		

General information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 05/05/2018 13:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 PAN ISLAND EXPRESSWAY THOMSON ROAD After Stevens Road Exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 80 Km/h	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SGR866R	Car	NISSAN		Brown		4
SKK5089Z	Car	TOYOTA		White		0
SKU8231G	Car	MAZDA		Red		0
VWH9682	Car	TOYOTA		Black		0



**SINGAPORE
POLICE FORCE**



T/20180505/2101

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5528999

2 of 3

Report No. T/20180505/2101

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LEOW ZHEN HUI, WESLEY	ID No.	S9335381A
Related Vehicle	SGR866R (Car)	Contact No.	94384458
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 05/05/2018 at about 1.30pm, I was driving my vehicle SGR866R along PIE towards the direction of Thomson Road at the 1st lane. Just after Stevens Road exit, I noticed that the vehicle in front of mine brake and I follow suit. While my vehicle was slowed down, I felt an impact. Subsequently, I alighted to make a check and I realized that it was a chain collision involving 3 other vehicles and my vehicle was the third one. I am still in shock and could not remember the details exactly. I do have a in car recording but the memory card was not inserted.

After the accident, LTA road marshal attended to the scene and I was advised to lodge a police report as it involves a Malaysia registered vehicle. I am able to sketch the accident scene and attached as Annex A in this report.

CON
215/60/17

Sketch Plan Pg. 5



SINGAPORE
POLICE FORCE



T/20180505/2101

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

3 of 3

Report No. T/20180505/2101

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Refer to Annex A WA

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Staff Sgt ONG KIAN KENG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SI DZUL HAIRIE BIN RAMLI

Contact No.: 65476220



SINGAPORE
POLICE FORCE

Signature Of Informant:

Date/Time:

05/05/2018 15:51

Classification Of Case:

SN 061

Authentication Stamp
NP168

SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST: M9-0009639-E RCB NO: 06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No: 58M00679

Claim Type: Own Damage

Accident Date: 05/05/2018

car at
workshop

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
SPARE PARTS				
1 FRONT BONNET		1 PC	600.00	
2 FRONT BONNET HINGE LH		1 PC	45.00	
3 FRONT BONNET HINGE RH		1 PC	45.00	
4 FRONT BONNET INSULATOR		1 PC	130.00	
5 FRONT BONNET INSULATOR CLIPS X 12		12 PC	18.00	
6 FRONT BONNET RUBBER FRONT		1 PC	70.00	
7 FRONT BONNET RUBBER CENTER		1 PC	55.00	
8 FRONT BONNET INNER LOCK		1 PC	55.00	
9 FRONT BONNET LOCK LEVER		1 PC	80.00	
10 FRONT BONNET LOCK CABLE		1 PC	55.00	
11 FRONT BONNET STAND CLIP		1 PC	8.00	
12 FRONT BONNET RUBBER STOPPER LH		1 PC	10.00	
13 FRONT BONNET RUBBER STOPPER RH		1 PC	10.00	
14 FRONT GRILLE WITH CHROME MOULDING		1 PC	340.00	
15 FRONT GRILLE EMBLEM		1 PC	58.00	
16 FRONT GRILLE CLIPS X 8		8 PC	32.00	
17 HEADLAMP LH		1 PC	350.00	
18 HEADLAMP LOWER BRACKET LH		1 PC	20.00	
19 HEADLAMP RH		1 PC	350.00	
20 HEADLAMP LOWER BRACKET RH		1 PC	20.00	
21 FRONT BUMPER		1 PC	380.00	
22 FRONT BUMPER SIDE RETAINER LH		1 PC	20.00	
23 FRONT BUMPER SIDE RETAINER RH		1 PC	20.00	
24 FRONT BUMPER CLIPS X 15		15 PC	30.00	
25 FRONT BUMPER REINFORCEMENT		1 PC	280.00	
26 FRONT BUMPER REINFORCEMENT BRACKET LH		1 PC	80.00	
27 FRONT BUMPER REINFORCEMENT BRACKET RH		1 PC	80.00	
28 FRONT BUMPER SPONGE		1 PC	145.00	
29 FOGLAMP LH		1 PC	330.00	
30 FOGLAMP RH		1 PC	330.00	
31 FOGLAMP COVER LH		1 PC	65.00	
32 FOGLAMP COVER RH		1 PC	65.00	
33 FRONT FENDER RH		1 PC	380.00	
34 FRONT FENDER WHEEL ARCH RH		1 PC	280.00	
35 FRONT FENDER COWLING RH		1 PC	75.00	
36 FRONT FENDER COWLING CLIPS		8 PC	16.00	
37 FRONT FENDER LH		1 PC	380.00	
38 FRONT FENDER WHEEL ARCH LH		1 PC	280.00	
39 FRONT FENDER COWLING LH		1 PC	75.00	

Front
Bumper

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

garage

3

12



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
 DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			SS	SS
40 FRONT FENDER COWLING CLIPS		8 PC	X 16.00 X nm	
41 RADIATOR SUPPORT PANEL TOP		1 PC	550.00 = dm	
42 RADIATOR SUPPORT PANEL SIDE LH		1 PC 65	70.00 = dm	
43 RADIATOR SUPPORT PANEL SIDE RH		1 PC 65	X 70.00 = dm	
44 RADIATOR SUPPORT PANEL LOWER -CHECK PRICE		1 PC	X 0.0000 X nm	
45 AIR CON CONDENSER		1 PC	X 650.00 = dm	
46 AIR CON CONDENSER PIPE (FROM COND TO COMP) -CHECK PRICE		1 PC 125	0.0000	
47 AIR CON CONDENSER PIPE (FROM COND TO VALVE) -CHECK PRICE		1 PC 120	0.0000	
48 AIR CON CONDENSER PIPE (FROM COMP TO VALVE) -CHECK PRICE		1 PC 175	0.0000	
49 RADIATOR ASSY		1 PC	520.00	
50 RADIATOR FAN MOTOR ASSY		1 PC 64	500.00	
51 RADIATOR TOP BUSH LH & RH		2 PC	30.00	
52 RADIATOR TOP AIR GUIDE		1 PC	65.00 = dm	
53 RADIATOR SIDE AIR GUIDE LH		1 PC	40.00	
54 RADIATOR SIDE AIR GUIDE RH		1 PC	40.00	
55 RADIATOR TOP HOSE		1 PC	75.00 X	
56 RADIATOR BOTTOM HOSE -CHECK PRICE		1 PC	0.0000 X	
57 RADIATOR BOTTOM HOSE CONNECTING PIPE -CHECK PRICE		1 PC	0.0000 X	
58 RADIATOR BOTTOM HOSE (TO ENGINE) -CHECK PRICE		1 PC	0.0000 X	
59 RADIATOR BOTTOM BUSH LH & RH		2 PC	X 30.00 X	
60 RADIATOR SPARE TANK		1 PC	X 125.00 X	
61 RADIATOR SPARE TANK HOSE NO. 1 -CHECK PRICE		1 PC 78	X 0.0000	
62 RADIATOR SPARE TANK HOSE NO. 2 -CHECK PRICE		1 PC	X 0.0000 X nm	
63 INTERCOOLER ASSY		1 PC	1,500.00 = dm	
64 INTERCOOLER TOP HOSE (RH)		1 PC 175	165.00	
65 INTERCOOLER SIDE HOSE (LH)		1 PC 94	240.00	
66 INTERCOOLER SIDE AIR GUIDE RH -CHECK PRICE		1 PC	0.0000 X	
67 INTERCOOLER TOP BRACKET RH -CHECK PRICE		1 PC	0.0000 X	
68 INTERCOOLER TOP BUSH RH		1 PC	15.00 X	
69 INTERCOOLER TOP BRACKET LH -CHECK PRICE		1 PC	0.0000 X	
70 INTERCOOLER TOP BUSH LH		1 PC	15.00 X	
71 OIL COOLER		1 PC 67	X 450.00	
72 HORN X 2		12 PC 85	170.00 = dm	
73 WIPER WASHER TANK		1 PC	X 135.00 X nm	
74 WIPER WASHER TANK NECK		1 PC	25.00 = dm	
75 ALTERNATOR -CHECK PRICE		1 PC	0.0000	
76 ALTERNATOR BELT		1 PC	55.00	
77 AIR CON CONDENSER -CHECK PRICE		1 PC	0.0000	
78 INTAKE MANIFOLD -CHECK PRICE		1 PC	0.0000	
79 ENGINE ECU -CHECK PRICE		1 PC	0.0000	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
 DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
80 AIR DUCT		1 PC	115.00	DM
81 AIR DUCT CLIPS X 2		2 PC	4.00	NCC
82 ENGINE MOUNTING RH		1 PC	280.00	X
83 ENGINE MOUNTING FRONT		1 PC	80.00	X
84 ENGINE MOUNTING REAR		1 PC	75.00	X
85 GEARBOX MOUNTING LH		1 PC	80.00	X
86 REAR W/S MOULDING (COMES WITH W/S)		1 PC	650.00	DM
87 TAILGATE -CHECK PRICE		1 PC	0.0000	DM
88 TAILGATE HINGE LH		1 PC	30.00	X
89 TAILGATE HINGE RH		1 PC	30.00	X
90 TAILGATE EMBLEM		1 PC	45.00	DM
91 TAILGATE LAMP LH		1 PC	160.00	X
92 TAILGATE NO. PLATE GARNISH		1 PC	175.00	X
93 TAILGATE INNER LOCK		1 PC	105.00	X
94 TAILGATE RUBBER		1 PC	85.00	X
95 TAILGATE QASHQAI LOGO		1 PC	65.00	X
96 TAILAMP LH		1 PC	185.00	X
97 REAR BUMPER		1 PC	450.00	X
98 REAR BUMPER SIDE RETAINER LH		1 PC	28.00	X
99 REAR BUMPER SIDE RETAINER RH		1 PC	28.00	X
100 REAR BUMPER CLIPS		15 PC	30.00	DM
101 REAR BUMPER REFLECTOR LH		1 PC	36.00	X
102 REAR BUMPER LOWER SPOILER (SILVER) -CHECK PRICE		1 PC	0.0000	X
103 REAR BUMPER REINFORCEMENT		1 PC	350.00	X
104 REAR BUMPER REINFORCEMENT BRACKET LH		1 PC	75.00	X
105 REAR BUMPER REINFORCEMENT BRACKET RH		1 PC	75.00	X
106 REAR BUMPER SPONGE		1 PC	95.00	X
107 END PANEL		1 PC	300.00	X
108 END PANEL GARNISH		1 PC	55.00	X
109 REAR FENDER WHEEL ARCH LH		1 PC	280.00	DM
				15,179.00

Special Nett

110 NUMBER PLATE (FRONT & REAR)

111 COOLANT

112 ATF OIL

113 INNER SEAL

114 SEALANT

115 REAR BUMPER REVERSE SENSOR

2 PC 1 PC 20.00 35 DM
 1 PC 30.00 DM
 1 PC 160.00 80 NCC
 1 PC 20.00 NCC
 1 PC 40.00 NCC
 2 SET 400.00 350 DM



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmco@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
 DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
				720.00
LABOUR				
116 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00 30	
117 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS		1 PC	100.00	
118 TO REMOVE AND REPLACE INTERCOOLER ASSY, OIL COOLER		1 PC	180.00 120	
119 TO REMOVE AND REPLACE ENGINE ECU		1 PC	150.00 60	
120 TO REMOVE AND REPLACE INTAKE MANIFOLD & ALTERNATOR		1 PC	180.00 120	
121 TO REMOVE & REPLACE ENGINE MOUNTING & GEARBOX MOUNTING		1 PC	120.00	
122 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	80.00 60	
123 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	350.00 250	
124 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, HEADLAMP SUPPORT PANEL TO KNOCK & REPAIR FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH, FRONT DOOR RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1,500.00 800	
125 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH		1 PC	1,200.00 800	
126 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00 30	
127 TO REMOVE & REFIT REAR WINDSCREEN		1 EA	120.00 100	
128 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	120.00 60	
129 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.		1 PC	80.00 60	
130 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR REAR FENDER LH, SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	900.00 600	
131 TO SPRAY TAILGATE, REAR BUMPER, END PANEL, REAR FENDER LH, SPARE TYRE PANEL		1 PC	900.00 800	

6,060.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Amount Before Excess	S\$ 21,959.00
Add GST @ 7%	1,537.13
Total Amount payable	S\$ 23,496.13

TOTAL: SINGAPORE DOLLAR TWENTY THREE THOUSAND FOUR HUNDRED NINETY SIX AND CENTS THIRTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



Repair
EXCESS \$3000
PIP Repair
Before paint job
Lte Auto (M/A)
5.50pm

[Signature]
8/6/18

71954
2302 parts w/o prices
1940
400
2607



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G79

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate No: MC0913074

Date: 28 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
SPARE PARTS				
1 TRANSMISSION CONTROL BOX Dem		1 PC	1,080.00	
2 HEADLAMP TOP PANEL L/R St		2 PC	140.00	
3 AIRCON DISCHARGE PIPE NO.2 St		1 PC	55.00	
4 BONNET STAND HOLDER hbc		1 PC	5.00	
5 REAR BUMPER CLIP hbc		3 PC	24.00	
6 REAR BOOT WIPER MOTOR NUT hbc		3 PC	36.00	
				1,340.00

Amount Before Excess S\$ 1,340.00
GST Amount S\$ 93.80

Total Amount payable S\$ 1,433.80

The above vehicle was surveyed by LKK - MR MA on 15/05/2018

28/05/2018 e 12am
NLM Andrus
Ryau
LKK Andrus

For AH LIM MOTOR COMPANY
AH LIM MOTOR CO.
TEL: 10, ANG MO KIO INDUSTRIAL PARK 2A
#01-09, AMK AUTOPOINT
SINGAPORE 568047
AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlilmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 16 Aug 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No: S8M00G79

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
LABOUR				
1 TO PROGRAMME AND TRANSFER DATA TO NEW AUTOMATIC TRANSMISSION CONTROL MODULE UNIT		1 PC	400.00 1501-	400.00
Amount Before Excess				S\$ 400.00
GST Amount				S\$ 28.00
Total Amount payable				S\$ 428.00

The above vehicle was surveyed by LKK - MR MA on 15/05/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint, Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
AUTHORIZED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
 DIG-T CVT ABS 2WD

Your Ref No: 58M00679

Claim Type: Own Damage

Accident Date: 05/05/2018

car at workshop

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
SPARE PARTS				
1 FRONT BONNET		1 PC	600.00	
2 FRONT BONNET HINGE LH		1 PC	45.00	
3 FRONT BONNET HINGE RH		1 PC	45.00	
4 FRONT BONNET INSULATOR		1 PC	130.00	
5 FRONT BONNET INSULATOR CLIPS X 12		12 PC	18.00	
6 FRONT BONNET RUBBER FRONT		1 PC	70.00	
7 FRONT BONNET RUBBER CENTER		1 PC	55.00	
8 FRONT BONNET INNER LOCK		1 PC	55.00	
9 FRONT BONNET LOCK LEVER		1 PC	80.00	
10 FRONT BONNET LOCK CABLE		1 PC	55.00	
11 FRONT BONNET STAND CLIP		1 PC	8.00	
12 FRONT BONNET RUBBER STOPPER LH		1 PC	X 10.00	
13 FRONT BONNET RUBBER STOPPER RH		1 PC	X 10.00	
14 FRONT GRILLE WITH CHROME MOULDING		1 PC	340.00	
15 FRONT GRILLE EMBLEM		1 PC	58.00	
16 FRONT GRILLE CLIPS X 8		8 PC	32.00	
17 HEADLAMP LH		1 PC	350.00	
18 HEADLAMP LOWER BRACKET LH		1 PC	20.00	
19 HEADLAMP RH		1 PC	350.00	
20 HEADLAMP LOWER BRACKET RH		1 PC	20.00	
21 FRONT BUMPER		1 PC	380.00	
22 FRONT BUMPER SIDE RETAINER LH		1 PC	20.00	
23 FRONT BUMPER SIDE RETAINER RH		1 PC	20.00	
24 FRONT BUMPER CLIPS X 15		15 PC	30.00	
25 FRONT BUMPER REINFORCEMENT		1 PC	X 280.00	
26 FRONT BUMPER REINFORCEMENT BRACKET LH		1 PC	X 80.00	
27 FRONT BUMPER REINFORCEMENT BRACKET RH		1 PC	X 80.00	
28 FRONT BUMPER SPONGE		1 PC	145.00	
29 FOGLAMP LH		1 PC	X 330.00	
30 FOGLAMP RH		1 PC	X 330.00	
31 FOGLAMP COVER LH		1 PC	X 65.00	
32 FOGLAMP COVER RH		1 PC	X 65.00	
33 FRONT FENDER RH		1 PC	380.00	
34 FRONT FENDER WHEEL ARCH RH		1 PC	280.00	
35 FRONT FENDER COWLING RH		1 PC	X 75.00	
36 FRONT FENDER COWLING CLIPS		3 PC x 14.00	X 16.00	photo
37 FRONT FENDER LH		1 PC	380.00	
38 FRONT FENDER WHEEL ARCH LH		1 PC	X 280.00	
39 FRONT FENDER COWLING LH		1 PC	X 75.00	

Front Damage

garage

3 PC x 14.00 X 16.00 photo



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
 DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
40 FRONT FENDER COWLING CLIPS		8 PC	X 16.00	
41 RADIATOR SUPPORT PANEL TOP		1 PC	550.00	
42 RADIATOR SUPPORT PANEL SIDE LH		1 PC	65.00	
43 RADIATOR SUPPORT PANEL SIDE RH		1 PC	65.00	Photo
44 RADIATOR SUPPORT PANEL LOWER -CHECK PRICE		1 PC	X 0.0000	
45 AIR CON CONDENSER		1 PC	650.00	
46 AIR CON CONDENSER PIPE (FROM COND TO COMP) -CHECK PRICE		1 PC	125 0.0000	
47 AIR CON CONDENSER PIPE (FROM COND TO VALVE) -CHECK PRICE		1 PC	120 0.0000	
48 AIR CON CONDENSER PIPE (FROM COMP TO VALVE) -CHECK PRICE		1 PC	175 0.0000	
49 RADIATOR ASSY		1 PC	520.00	
50 RADIATOR FAN MOTOR ASSY		1 PC	500.00	Photo broken
51 RADIATOR TOP BUSH LH & RH		2 PC	30.00	
52 RADIATOR TOP AIR GUIDE		1 PC	65.00	
53 RADIATOR SIDE AIR GUIDE LH		1 PC	40.00	
54 RADIATOR SIDE AIR GUIDE RH		1 PC	40.00	
55 RADIATOR TOP HOSE		1 PC	75.00	
56 RADIATOR BOTTOM HOSE -CHECK PRICE		1 PC	0.0000	
57 RADIATOR BOTTOM HOSE CONNECTING PIPE -CHECK PRICE		1 PC	0.0000	
58 RADIATOR BOTTOM HOSE (TO ENGINE) -CHECK PRICE		1 PC	0.0000	
59 RADIATOR BOTTOM BUSH LH & RH		2 PC	X 30.00	
60 RADIATOR SPARE TANK		1 PC	X 125.00	
61 RADIATOR SPARE TANK HOSE NO. 1 -CHECK PRICE		1 PC	180 0.0000	Photo broken
62 RADIATOR SPARE TANK HOSE NO. 2 -CHECK PRICE		1 PC	X 0.0000	
63 INTERCOOLER ASSY		1 PC	1,500.00	
64 INTERCOOLER TOP HOSE (RH)		1 PC	75.00	Photo broken
65 INTERCOOLER SIDE HOSE (LH)		1 PC	240.00	Photo broken
66 INTERCOOLER SIDE AIR GUIDE RH -CHECK PRICE		1 PC	0.0000	
67 INTERCOOLER TOP BRACKET RH -CHECK PRICE		1 PC	0.0000	
68 INTERCOOLER TOP BUSH RH		1 PC	15.00	
69 INTERCOOLER TOP BRACKET LH -CHECK PRICE		1 PC	0.0000	
70 INTERCOOLER TOP BUSH LH		1 PC	15.00	
71 OIL COOLER		1 PC	X 450.00	Photo broken
72 HORN X 2		2 PC	85 170.00	
73 WIPER WASHER TANK		1 PC	X 135.00	
74 WIPER WASHER TANK NECK		1 PC	25.00	
75 ALTERNATOR -CHECK PRICE		1 PC	0.0000	
76 ALTERNATOR BELT		1 PC	55.00	
77 AIR CON CONDENSER -CHECK PRICE		1 PC	0.0000	
78 INTAKE MANIFOLD -CHECK PRICE		1 PC	0.0000	
79 ENGINE ECU -CHECK PRICE		1 PC	0.0000	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S: AXA INSURANCE PTE LTD

8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
 DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
80 AIR DUCT		1 PC	115.00	
81 AIR DUCT CLIPS X 2		2 PC	4.00	
82 ENGINE MOUNTING RH		1 PC	280.00	
83 ENGINE MOUNTING FRONT		1 PC	80.00	
84 ENGINE MOUNTING REAR		1 PC	75.00	
85 GEARBOX MOUNTING LH		1 PC	80.00	
86 REAR W/S MOULDING (COMES WITH W/S)		1 PC	650.00	
87 TAILGATE -CHECK PRICE		1 PC	0.0000	1850.00
88 TAILGATE HINGE LH		1 PC	30.00	
89 TAILGATE HINGE RH		1 PC	30.00	
90 TAILGATE EMBLEM		1 PC	45.00	
91 TAILGATE LAMP LH		1 PC	160.00	
92 TAILGATE NO. PLATE GARNISH		1 PC	175.00	
93 TAILGATE INNER LOCK		1 PC	105.00	
94 TAILGATE RUBBER		1 PC	85.00	
95 TAILGATE QASHQAI LOGO		1 PC	65.00	
96 TAILAMP LH		1 PC	185.00	
97 REAR BUMPER		1 PC	450.00	
98 REAR BUMPER SIDE RETAINER LH		1 PC	28.00	
99 REAR BUMPER SIDE RETAINER RH		1 PC	28.00	
100 REAR BUMPER CLIPS		15 PC	30.00	
101 REAR BUMPER REFLECTOR LH		1 PC	36.00	
102 REAR BUMPER LOWER SPOILER (SILVER) -CHECK PRICE		1 PC	0.0000	
103 REAR BUMPER REINFORCEMENT <i>1st</i>		1 PC	350.00	<i>Photo</i> ✓
104 REAR BUMPER REINFORCEMENT BRACKET LH <i>1st</i>		1 PC	75.00	<i>Photo</i> ✓
105 REAR BUMPER REINFORCEMENT BRACKET RH <i>1st</i>		1 PC	75.00	<i>Photo</i> ✓
106 REAR BUMPER SPONGE <i>1st</i>		1 PC	95.00	<i>Photo</i> ✓
107 END PANEL <i>1st</i>		1 PC	300.00	<i>Photo</i> ✓
108 END PANEL GARNISH		1 PC	55.00	
109 REAR FENDER WHEEL ARCH LH		1 PC	280.00	
				15,179.00

Special Nett

- 110 NUMBER PLATE (FRONT & REAR)
 111 COOLANT
 112 ATF OIL
 113 INNER SEAL
 114 SEALANT
 115 REAR BUMPER REVERSE SENSOR

Front only

2 PC 1st 30.00 35
 1 PC 30.00
 1 PC 160.00 80
 1 PC 20.00
 1 PC 40.00
 2 SET 400.00 750



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@simgnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
 DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
				720.00

LABOUR

116	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 30	
117	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	
118	TO REMOVE AND REPLACE INTERCOOLER ASSY, OIL COOLER	1 PC	180.00 120	
119	TO REMOVE AND REPLACE ENGINE ECU	1 PC	150.00 60 x	
120	TO REMOVE AND REPLACE INTAKE MANIFOLD & ALTERNATOR	1 PC	180.00 120 x	
121	TO REMOVE & REPLACE ENGINE MOUNTING & GEARBOX MOUNTING	1 PC	120.00 ? x	
122	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00 60	
123	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	250.00 250	
124	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, HEADLAMP SUPPORT PANEL, TO KNOCK & REPAIR FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH, FRONT DOOR RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,500.00 800	
125	TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH	1 PC	1,200.00 800	
126	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 30	
127	TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00 120	
128	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	120.00 60	
129	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	80.00 60	
130	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, TO KNOCK & REPAIR REAR FENDER LH, SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	900.00 600	
131	TO SPRAY TAILGATE, REAR BUMPER, END PANEL, REAR FENDER LH, SPARE TYRE PANEL	1 PC	900.00 800	

6,060.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@sngnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Amount Before Excess	S\$ 21,959.00
Add GST @ 7%	1,537.13
Total Amount payable	S\$ 23,496.13

TOTAL: SINGAPORE DOLLAR TWENTY THREE THOUSAND FOUR HUNDRED NINETY SIX AND CENTS THIRTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORIZED SIGNATURE



2nd
Excess \$3000
PIP Repair
Before paint flow
LKK Auto (MIA)

ab 5.5pm

Resurvey taken
by T. Ryan
LKK Auto



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0913074

Ref No: MF0911229

Date: 07 Aug 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No: S8M00G79

Claim Type: Own Damage

Accident Date: 05/05/2018

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SGR866R

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET		1 PC	600.00	
2 FRONT BONNET HINGE LH		1 PC	45.00	
3 FRONT BONNET HINGE RH		1 PC	45.00	
4 FRONT BONNET INSULATOR		1 PC	130.00	
5 FRONT BONNET INSULATOR CLIPS X 12		12 PC	18.00	
6 FRONT BONNET RUBBER FRONT		1 PC	70.00	
7 FRONT BONNET RUBBER CENTER		1 PC	55.00	
8 FRONT BONNET INNER LOCK		1 PC	55.00	
9 FRONT BONNET LOCK LEVER		1 PC	80.00	
10 FRONT BONNET LOCK CABLE		1 PC	55.00	
11 FRONT BONNET STAND CLIP		1 PC	8.00	
12 FRONT GRILLE WITH CHROME MOULDING		1 PC	340.00	
13 FRONT GRILLE EMBLEM		1 PC	58.00	
14 FRONT GRILLE CLIPS X 8		8 PC	32.00	
15 HEADLAMP LH		1 PC	350.00	
16 HEADLAMP RH		1 PC	350.00	
17 FRONT BUMPER		1 PC	380.00	
18 FRONT BUMPER SIDE RETAINER LH		1 PC	20.00	
19 FRONT BUMPER SIDE RETAINER RH		1 PC	20.00	
20 FRONT BUMPER CLIPS X 15		15 PC	30.00	
21 FRONT BUMPER SPONGE		1 PC	145.00	
22 FRONT FENDER RH		1 PC	380.00	
23 FRONT FENDER WHEEL ARCH RH		1 PC	280.00	
24 FRONT FENDER COWLING CLIPS		3 PC	12.00	
25 FRONT FENDER LH		1 PC	380.00	
26 RADIATOR SUPPORT PANEL TOP		1 PC	550.00	
27 RADIATOR SUPPORT PANEL SIDE LH		1 PC	65.00	
28 RADIATOR SUPPORT PANEL SIDE RH		1 PC	65.00	
29 AIR CON CONDENSER		1 PC	650.00	
30 AIR CON CONDENSER PIPE (FROM COND TO COMP)		1 PC	125.00	
31 AIR CON CONDENSER PIPE (FROM COND TO VALVE)		1 PC	120.00	
32 AIR CON CONDENSER PIPE (FROM COMP TO VALVE)		1 PC	175.00	
33 RADIATOR ASSY		1 PC	520.00	
34 RADIATOR FAN MOTOR ASSY		1 PC	500.00	
35 RADIATOR TOP BUSH LH & RH		2 PC	30.00	
36 RADIATOR TOP AIR GUIDE		1 PC	65.00	
37 RADIATOR SIDE AIR GUIDE LH		1 PC	40.00	
38 RADIATOR SIDE AIR GUIDE RH		1 PC	40.00	
39 RADIATOR SPARE TANK HOSE NO. 1		1 PC	28.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2
#01-09 AMK Autopoint Singapore
Tel: 6483 1244



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0913074

Ref No: MF0911229

Date: 07 Aug 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2

DIG-T CVT ABS 2WD

Your Ref No: S8M00G79

Claim Type: Own Damage

Accident Date: 05/05/2018

1ST FINALISATION

Repair Cost to Vehicle No (For Finalization):SGR866R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
40 INTERCOOLER ASSY		1 PC	1,500.00	
41 INTERCOOLER TOP HOSE (RH)		1 PC	175.00	
42 INTERCOOLER SIDE HOSE (LH)		1 PC	240.00	
43 OIL COOLER		1 PC	450.00	
44 HORN		1 PC	85.00	
45 WIPER WASHER TANK NECK		1 PC	25.00	
46 AIR DUCT		1 PC	115.00	
47 AIR DUCT CLIPS X 2		2 PC	4.00	
48 REAR W/S MOULDING (COMES WITH W/S)		1 PC	650.00	
49 TAILGATE		1 PC	1,850.00	
50 TAILGATE EMBLEM		1 PC	45.00	
51 TAILGATE INNER LOCK		1 PC	105.00	
52 TAILGATE RUBBER		1 PC	85.00	
53 TAILGATE QASHQAI LOGO		1 PC	65.00	
54 REAR BUMPER		1 PC	450.00	
55 REAR BUMPER SIDE RETAINER LH		1 PC	28.00	
56 REAR BUMPER CLIPS		15 PC	30.00	
57 REAR BUMPER REINFORCEMENT		1 PC	350.00	
58 REAR BUMPER REINFORCEMENT BRACKET LH		1 PC	75.00	
59 REAR BUMPER REINFORCEMENT BRACKET RH		1 PC	75.00	
60 REAR BUMPER SPONGE		1 PC	95.00	
61 END PANEL		1 PC	300.00	
62 REAR FENDER WHEEL ARCH LH		1 PC	280.00	
63 TRANSMISSION CONTROL BOX		1 PC	1,080.00	
64 HEADLAMP TOP PANEL L/R		2 PC	140.00	
65 AIRCON DISCHARGE PIPE NO.2		1 PC	55.00	
66 BONNET STAND HOLDER		1 PC	5.00	
67 REAR BUMPER CLIP		3 PC	24.00	
68 REAR BOOT WIPER MOTOR NUT		3 PC	36.00	
				15,328.00

Special Nett

69 NUMBER PLATE (FRONT)	1 PC	35.00
70 COOLANT	1 PC	30.00
71 ATF OIL	1 PC	80.00
72 INNER SEAL	1 PC	20.00
73 SEALANT	1 PC	40.00
74 REAR BUMPER REVERSE SENSOR	2 SET	350.00

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore
 Tel: 6483 1244 Fax: 6483 6170

AN LIM FACTOR COMPANY
No. 10 Ang Mo Kio Industrial Estate
#01-00 Telok Ayer St. Singapore 560010
Tel: 6352 2444 Fax: 6352 2445



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0913074

Ref No: MF0911229

Date: 07 Aug 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No: S8M00G79

Claim Type: Own Damage

Accident Date: 05/05/2018

Repair Cost to Vehicle No (For Finalization):SGR866R

Amount Before Excess	S\$ 20,093.00
Less Excess	S\$ 3,000.00
Amount Before GST	S\$ 17,093.00
Add GST @ 7%	1,196.51
Total Amount payable	S\$ 18,289.51

TOTAL: SINGAPORE DOLLAR EIGHTEEN THOUSAND TWO HUNDRED EIGHTY NINE AND CENTS FIFTY ONE ONLY

The above vehicle was surveyed by LKK - MR MA on 15/05/2018

For AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore
Tel: 6483 1244
AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlumc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No:

58M00679

car and
workshop

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 FRONT BONNET		1 PC	600.00	
2 FRONT BONNET HINGE LH		1 PC	45.00	
3 FRONT BONNET HINGE RH		1 PC	45.00	
4 FRONT BONNET INSULATOR		1 PC	130.00	
5 FRONT BONNET INSULATOR CLIPS X 12		12 PC	18.00	
6 FRONT BONNET RUBBER FRONT		1 PC	70.00	
7 FRONT BONNET RUBBER CENTER		1 PC	55.00	
8 FRONT BONNET INNER LOCK		1 PC	55.00	
9 FRONT BONNET LOCK LEVER		1 PC	80.00	
10 FRONT BONNET LOCK CABLE		1 PC	55.00	
11 FRONT BONNET STAND CLIP		1 PC	8.00	
12 FRONT BONNET RUBBER STOPPER-LH		1 PC	10.00	
13 FRONT BONNET RUBBER STOPPER RH		1 PC	10.00	
14 FRONT GRILLE WITH CHROME MOULDING		1 PC	340.00	
15 FRONT GRILLE EMBLEM		1 PC	58.00	
16 FRONT GRILLE CLIPS X 8		8 PC	32.00	
17 HEADLAMP LH		1 PC	350.00	
18 HEADLAMP LOWER BRACKET LH		1 PC	20.00	
19 HEADLAMP RH		1 PC	350.00	
20 HEADLAMP LOWER BRACKET RH		1 PC	20.00	
21 FRONT BUMPER		1 PC	380.00	
22 FRONT BUMPER SIDE RETAINER LH		1 PC	20.00	
23 FRONT BUMPER SIDE RETAINER RH		1 PC	20.00	
24 FRONT BUMPER CLIPS X 15		15 PC	30.00	
25 FRONT BUMPER REINFORCEMENT		1 PC	280.00	
26 FRONT BUMPER REINFORCEMENT-BRACKET LH		1 PC	80.00	
27 FRONT BUMPER REINFORCEMENT-BRACKET RH		1 PC	80.00	
28 FRONT BUMPER SPONGE		1 PC	145.00	
29 FOGLAMP LH		1 PC	330.00	
30 FOGLAMP RH		1 PC	330.00	
31 FOGLAMP COVER LH		1 PC	65.00	
32 FOGLAMP COVER RH		1 PC	65.00	
33 FRONT FENDER RH		1 PC	380.00	
34 FRONT FENDER WHEEL ARCH RH		1 PC	280.00	
35 FRONT FENDER COWLING RH		1 PC	75.00	
36 FRONT FENDER COWLING CLIPS		3 8 PC x 14.00	16.00	photo
37 FRONT FENDER LH		1 PC	380.00	
38 FRONT FENDER WHEEL ARCH LH		1 PC	280.00	
39 FRONT FENDER COWLING LH		1 PC	75.00	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			SS	SS
40 FRONT FENDER COWLING CLIPS		8 PC	16.00	
41 RADIATOR SUPPORT PANEL TOP		1 PC	550.00	
42 RADIATOR SUPPORT PANEL SIDE LH		1 PC	70.00	
43 RADIATOR SUPPORT PANEL SIDE RH	bt	1 PC	70.00	Photo
44 RADIATOR SUPPORT PANEL LOWER -CHECK PRICE		1 PC	0.0000	
45 AIR CON CONDENSER		1 PC	650.00	
46 AIR CON CONDENSER PIPE (FROM COND TO COMP) -CHECK PRICE		1 PC	0.0000	
47 AIR CON CONDENSER PIPE (FROM COND TO VALVE) -CHECK PRICE		1 PC	0.0000	
48 AIR CON CONDENSER PIPE (FROM COMP TO VALVE) -CHECK PRICE		1 PC	0.0000	
49 RADIATOR ASSY		1 PC	520.00	
50 RADIATOR FAN MOTOR ASSY		1 PC	500.00	Photo broken
51 RADIATOR TOP BUSH LH & RH		2 PC	30.00	
52 RADIATOR TOP AIR GUIDE		1 PC	65.00	
53 RADIATOR SIDE AIR GUIDE LH		1 PC	40.00	
54 RADIATOR SIDE AIR GUIDE RH		1 PC	40.00	
55 RADIATOR TOP HOSE		1 PC	75.00	
56 RADIATOR BOTTOM HOSE -CHECK PRICE		1 PC	0.0000	
57 RADIATOR BOTTOM HOSE-CONNECTING PIPE -CHECK PRICE		1 PC	0.0000	
58 RADIATOR BOTTOM HOSE (TO ENGINE) -CHECK PRICE		1 PC	0.0000	
59 RADIATOR BOTTOM BUSH LH & RH		2 PC	30.00	
60 RADIATOR SPARE TANK		1 PC	125.00	
61 RADIATOR SPARE TANK HOSE NO. 1 -CHECK PRICE		1 PC	0.0000	Photo bt
62 RADIATOR SPARE TANK HOSE NO. 2 -CHECK PRICE		1 PC	0.0000	
63 INTERCOOLER ASSY		1 PC	1500.00	
64 INTERCOOLER TOP HOSE (RH)		1 PC	165.00	Photo bt
65 INTERCOOLER SIDE HOSE (LH)		1 PC	240.00	Photo bt
66 INTERCOOLER SIDE AIR GUIDE RH -CHECK PRICE		1 PC	0.0000	
67 INTERCOOLER TOP BRACKET RH -CHECK PRICE		1 PC	0.0000	
68 INTERCOOLER TOP BUSH RH		1 PC	15.00	
69 INTERCOOLER TOP BRACKET LH -CHECK PRICE		1 PC	0.0000	
70 INTERCOOLER TOP BUSH LH		1 PC	15.00	
71 OIL COOLER		1 PC	450.00	Photo bt
72 HORN X 2		12 PC	720.00	
73 WIPER WASHER TANK		1 PC	135.00	
74 WIPER WASHER TANK NECK		1 PC	25.00	
75 ALTERNATOR -CHECK PRICE		1 PC	0.0000	
76 ALTERNATOR BELT		1 PC	55.00	
77 AIR CON CONDENSER -CHECK PRICE		1 PC	0.0000	
78 INTAKE MANIFOLD -CHECK PRICE		1 PC	0.0000	
79 ENGINE ECU -CHECK PRICE		1 PC	0.0000	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1344 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 63382522
 ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
 DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost	Amount
			SS	SS
80 AIR DUCT		1 PC	115.00	
81 AIR DUCT CLIPS X 2		2 PC	4.00	
82 ENGINE MOUNTING RH		1 PC	280.00	
83 ENGINE MOUNTING FRONT		1 PC	80.00	
84 ENGINE MOUNTING REAR		1 PC	75.00	
85 GEARBOX MOUNTING LH		1 PC	80.00	
86 REAR W/S MOULDING (COMES WITH W/S)		1 PC	650.00	
87 TAILGATE -CHECK PRICE		1 PC	0.0000	1850.00
88 TAILGATE HINGE LH		1 PC	30.00	
89 TAILGATE HINGE RH		1 PC	30.00	
90 TAILGATE EMBLEM		1 PC	45.00	
91 TAILGATE LAMP LH		1 PC	160.00	
92 TAILGATE NO. PLATE GARNISH		1 PC	175.00	
93 TAILGATE INNER LOCK		1 PC	105.00	
94 TAILGATE RUBBER		1 PC	85.00	
95 TAILGATE QASHQAI LOGO		1 PC	65.00	
96 TAILAMP LH		1 PC	185.00	
97 REAR BUMPER		1 PC	150.00	
98 REAR BUMPER SIDE RETAINER LH		1 PC	28.00	
99 REAR BUMPER SIDE RETAINER RH		1 PC	28.00	
100 REAR BUMPER CLIPS		15 PC	30.00	
101 REAR BUMPER REFLECTOR LH		1 PC	36.00	
102 REAR BUMPER LOWER SPOILER (SILVER) -CHECK PRICE		1 PC	0.0000	
103 REAR BUMPER REINFORCEMENT <i>st</i>		1 PC	350.00	<i>Photo</i>
104 REAR BUMPER REINFORCEMENT BRACKET LH <i>st</i>		1 PC	75.00	<i>Photo</i>
105 REAR BUMPER REINFORCEMENT BRACKET RH <i>st</i>		1 PC	75.00	<i>Photo</i>
106 REAR BUMPER SPONGE <i>for</i>		1 PC	95.00	<i>Photo</i>
107 END PANEL <i>Rein</i>		1 PC	300.00	<i>Photo</i>
108 END PANEL GARNISH		1 PC	55.00	
109 REAR FENDER WHEEL ARCH LH		1 PC	280.00	
				15,179.00

Special Nett

- 110 NUMBER PLATE (FRONT & REAR)
 111 COOLANT
 112 ATF OIL
 113 INNER SEAL
 114 SEALANT
 115 REAR BUMPER REVERSE SENSOR

front only

2 PC 1PC 20.00 35
 1 PC 30.00
 1 PC 160.00 80
 1 PC 20.00
 1 PC 40.00
 2 SET 400.00 350



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
 DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Description	U/Price	Quantity	Cost S\$	Amount S\$
LABOUR				
front labour 116 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00 30	
117 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
118 TO REMOVE AND REPLACE INTERCOOLER ASSY, OIL COOLER		1 PC	150.00 120	
119 TO REMOVE AND REPLACE ENGINE ECU		1 PC	150.00 60	
120 TO REMOVE AND REPLACE INTAKE MANIFOLD & ALTERNATOR		1 PC	180.00 120?	
121 TO REMOVE & REPLACE ENGINE MOUNTING & GEARBOX MOUNTING		1 PC	120.00 ?	
122 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	X 80.00 60	
123 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	350.00 250	
124 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, HEADLAMP SUPPORT PANEL, TO KNOCK & REPAIR FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH, FRONT DOOR RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1500.00 800.	
125 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH		1 PC	1200.00 800.	
rear labour 126 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00 30	
127 TO REMOVE & REFIT REAR WINDSCREEN		1 EA	120.00 120	
128 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	120.00 60	
129 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.		1 PC	30.00 60	
130 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, TO KNOCK & REPAIR REAR FENDER LH, SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	900.00 600	
131 TO SPRAY TAILGATE, REAR BUMPER, END PANEL, REAR FENDER LH, SPARE TYRE PANEL		1 PC	900.00 800	
				6,060.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 08 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No: -

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R

Amount Before Excess S\$ 21,959.00

Add GST @ 7% 1,537.13

Total Amount payable S\$ 23,496.13

TOTAL: SINGAPORE DOLLAR TWENTY THREE THOUSAND FOUR HUNDRED NINETY SIX AND CENTS THIRTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

Repair
Excess \$3000
PIP Repair
Before point flow
LKK Auto (MA)

Q. S. M.

Resurvey taken
by Ryan
LKK Auto

[Signature]



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahliminc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913074

Date: 28 May 2018

Policy No: GA283092

Veh Reg No: SGR866R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Your Ref No: S8M00G79

Claim Type: Own Damage

Accident Date: 05/05/2018

Estimate Repair Cost to Vehicle No :SGR866R


Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
SPARE PARTS				
1 TRANSMISSION CONTROL BOX Dam		1 PC	1,080.00	✓
2 HEADLAMP TOP PANEL L/R Ist		2 PC	140.00	✓
3 AIRCON DISCHARGE PIPE NO.2 Ist		1 PC	55.00	✓
4 BONNET STAND HOLDER New		1 PC	5.00	✓
5 REAR BUMPER CLIP New		3 PC	24.00	✓
6 REAR BOOT WIPER MOTOR NUT New		3 PC	36.00	✓
				1,340.00

Amount Before Excess S\$ 1,340.00

GST Amount S\$ 93.80

Total Amount payable S\$ 1,433.80

The above vehicle was surveyed by LKK - MR MA on 15/05/2018

28/05/2018 e 12am
NLM Andrus
Ryan
LKK Andrus


For AH LIM MOTOR COMPANY
AH LIM MOTOR CO.
BLV 10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09, AMK AUTOPOINT
SINGAPORE 56804
AUTHORISED SIGNATURE


RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT
#04-07/16 SINGAPORE 568047

Tel: 6481 2025/ 6481 5797 Fax No: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co. Reg.:200800062E GST Reg. No.:200800062E

AH LIM MOTOR COMPANY
10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT
S 568047

Alex
92397610

Tax Invoice: RA182206

Invoice Date: 18/07/2018

Vehicle Num: SGR 866 R

Make/Model: NISSAN QASHQAI

Mileage (Km): 26,915

Advisor: SOO FONG

Technical Person: YANG / SOO FONG

Ref./Remark: 01.06.18 ~ 18.07.18

Terms: CASH

Currency: SGD

No. Particular	Quantity	Unit Price	Amount \$
1 LABOUR CHARGES :- TO PROGRAMME AND TRANSFER DATA TO NEW AUTOMATIC TRANSMISSION CONTROL MODULE UNIT TO REPLACE SELF SUPPLIED AUTOMATIC TRANSMISSION CONTROL MODULE UNIT			400.00

Dollars: Four Hundred Twenty-Eight Only

Customer's Signature/Co. Stamp



for RIVERVIEW AUTO SERVICES PTE LTD

E. & O.E.

Total \$	400.00
GST @ 7% \$	28.00
Amount Due \$	428.00

ADVISOR'S SIGNATURE

Remarks : Dear customers, please ensure that your invoice is stamped PAID after making payment.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CS/ASM18008795/Dqd3e2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN : PETER WANG			Date : 15-11-2018	
			Code : ASM	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SGR 866R
Policy No.	GA283092	Coverage (\$)	0.00	
Claim No.	S8M00G79	Excess (\$)	3,000.00	
Assign From	PETER WANG	Assign Date	14/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SJNFEAJ11U1699139	Colour	BLACK	
Odometer	26912	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R17	CONTINENTAL	7 mm	
L/H Front Tyre	205/60 R17	CONTINENTAL	7 mm	
R/H Rear Tyre	205/60 R17	CONTINENTAL	7 mm	
L/H Rear Tyre	205/60 R17	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/05/2018	Inspection Date	15/05/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE MARKET VALUE IS S\$184,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR.		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 866R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET (CONSISTENT)	DAMAGED	600.00	600.00
1	FRONT BONNET HINGE LH (CONSISTENT)	DAMAGED	45.00	45.00
1	FRONT BONNET HINGE RH (CONSISTENT)	DAMAGED	45.00	45.00
1	FRONT BONNET INSULATOR (CONSISTENT)	DAMAGED	130.00	130.00
12	FRONT BONNET INSULATOR CLIPS (CONSISTENT)	NECESSARY	18.00	18.00
1	FRONT BONNET RUBBER FRONT (CONSISTENT)	DAMAGED	70.00	70.00
1	FRONT BONNET RUBBER CENTER (CONSISTENT)	DAMAGED	55.00	55.00
1	FRONT BONNET INNER LOCK (CONSISTENT)	DAMAGED	55.00	55.00
1	FRONT BONNET LOCK LEVER (CONSISTENT)	DAMAGED	80.00	80.00
1	FRONT BONNET LOCK CABLE (CONSISTENT)	DAMAGED	55.00	55.00
1	FRONT BONNET STAND CLIP (CONSISTENT)	NECESSARY	8.00	8.00
1	FRONT BONNET RUBBER STOPPER LH (CONSISTENT)	NOT NECESSARY	10.00	-
1	FRONT BONNET RUBBER STOPPER RH (CONSISTENT)	NOT NECESSARY	10.00	-
1	FRONT GRILLE WITH CHROME MOULDING (CONSISTENT)	DAMAGED	340.00	340.00
1	FRONT GRILLE EMBLEM (CONSISTENT)	DAMAGED	58.00	58.00
8	FRONT GRILLE CLIPS (CONSISTENT)	NECESSARY	32.00	32.00
1	HEADLAMP LH (CONSISTENT)	DAMAGED	350.00	350.00
1	HEADLAMP LOWER BRACKET LH (CONSISTENT)	NOT NECESSARY	20.00	-
1	HEADLAMP RH (CONSISTENT)	DAMAGED	350.00	350.00
1	HEADLAMP LOWER BRACKET RH (CONSISTENT)	NOT NECESSARY	20.00	-
1	FRONT BUMPER (CONSISTENT)	DAMAGED	380.00	380.00
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	DAMAGED	20.00	20.00
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	DAMAGED	20.00	20.00
15	FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT BUMPER REINFORCEMENT BRACKET LH (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT BUMPER REINFORCEMENT BRACKET RH (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	DAMAGED	145.00	145.00
1	FOGLAMP LH (CONSISTENT)	NOT NECESSARY	330.00	-

Report Ref No. CS/ASM18008795/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FOGLAMP RH (CONSISTENT)	NOT NECESSARY	330.00	-
1	FOGLAMP COVER LH (CONSISTENT)	NOT NECESSARY	65.00	-
1	FOGLAMP COVER RH (CONSISTENT)	NOT NECESSARY	65.00	-
1	FRONT FENDER RH (CONSISTENT)	DAMAGED	380.00	380.00
1	FRONT FENDER WHEEL ARCH RH GARNISH (CONSISTENT)	DAMAGED	280.00	280.00
1	FRONT FENDER COWLING RH (CONSISTENT)	NOT NECESSARY	75.00	-
8	FRONT FENDER COWLING CLIPS (CONSISTENT)	NECESSARY-3PCS ONLY	16.00	12.00
1	FRONT FENDER LH (CONSISTENT)	DAMAGED	380.00	380.00
1	FRONT FENDER WHEEL ARCH LH (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT FENDER COWLING LH (CONSISTENT)	NOT NECESSARY	75.00	-
8	FRONT FENDER COWLING CLIPS (CONSISTENT)	NOT NECESSARY	16.00	-
1	RADIATOR SUPPORT PANEL TOP (CONSISTENT)	DAMAGED	550.00	550.00
1	RADIATOR SUPPORT PANEL SIDE LH (CONSISTENT)	DAMAGED	70.00	65.00
1	RADIATOR SUPPORT PANEL SIDE RH (CONSISTENT)	DAMAGED	70.00	65.00
1	RADIATOR SUPPORT PANEL LOWER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	AIR CON CONDENSER (CONSISTENT)	DAMAGED	650.00	650.00
1	AIR CON CONDENSER PIPE (FROM COND TO COMP) (CONSISTENT)	DAMAGED	125.00	125.00
1	AIR CON CONDENSER PIPE (FROM COND TO VALVE)	DAMAGED	120.00	120.00
1	AIR CON CONDENSER PIPE (FROM COMP TO VALVE) (CONSISTENT)	DAMAGED	175.00	175.00
1	RADIATOR ASSY (CONSISTENT)	DAMAGED	520.00	520.00
1	RADIATOR FAN MOTOR ASSY (CONSISTENT)	BROKEN	500.00	500.00
2	RADIATOR TOP BUSH LH & RH (CONSISTENT)	DAMAGED	30.00	30.00
1	RADIATOR TOP AIR GUIDE (CONSISTENT)	DAMAGED	65.00	65.00
1	RADIATOR SIDE AIR GUIDE LH (CONSISTENT)	DAMAGED	40.00	40.00
1	RADIATOR SIDE AIR GUIDE RH (CONSISTENT)	DAMAGED	40.00	40.00
1	RADIATOR TOP HOSE (CONSISTENT)	NOT NECESSARY	75.00	-
1	RADIATOR BOTTOM HOSE (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	RADIATOR BOTTOM HOSE CONNECTING PIPE (NPA) (CONSISTENT)	NOT NECESSARY	-	-

Report Ref No. CS/ASM18008795/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR BOTTOM HOSE (TO ENGINE) (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	RADIATOR BOTTOM BUSH LH & RH (CONSISTENT)	NOT NECESSARY	30.00	-
1	RADIATOR SPARE TANK (CONSISTENT)	NOT NECESSARY	125.00	-
1	RADIATOR SPARE TANK HOSE NO. 1 (CONSISTENT)	BENT	28.00	28.00
1	RADIATOR SPARE TANK HOSE NO. 2 (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	INTERCOOLER ASSY (CONSISTENT)	DAMAGED	1,500.00	1,500.00
1	INTERCOOLER TOP HOSE (RH) (CONSISTENT)	BENT	175.00	175.00
1	INTERCOOLER SIDE HOSE (LH) (CONSISTENT)	BENT	240.00	240.00
1	INTERCOOLER SIDE AIR GUIDE RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	INTERCOOLER TOP BRACKET RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	INTERCOOLER TOP BUSH RH (CONSISTENT)	NOT NECESSARY	15.00	-
1	INTERCOOLER TOP BRACKET LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	INTERCOOLER TOP BUSH LH (CONSISTENT)	NOT NECESSARY	15.00	-
1	OIL COOLER (CONSISTENT)	BENT	450.00	450.00
2	HORN (CONSISTENT)	DAMAGED-1PC ONLY	170.00	85.00
1	WIPER WASHER TANK (CONSISTENT)	NOT NECESSARY	135.00	-
1	WIPER WASHER TANK NECK (CONSISTENT)	DAMAGED	25.00	25.00
1	ALTERNATOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	ALTERNATOR BELT (CONSISTENT)	NOT NECESSARY	55.00	-
1	AIR CON CONDENSER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	INTAKE MANIFOLD (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	ENGINE ECU (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	AIR DUCT (CONSISTENT)	DAMAGED	115.00	115.00
2	AIR DUCT CLIPS (CONSISTENT)	NECESSARY	4.00	4.00
1	ENGINE MOUNTING RH (CONSISTENT)	NOT NECESSARY	280.00	-
1	ENGINE MOUNTING FRONT (CONSISTENT)	NOT NECESSARY	80.00	-
1	ENGINE MOUNTING REAR (CONSISTENT)	NOT NECESSARY	75.00	-
1	GEARBOX MOUNTING LH (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR W/S MOULDING (COMES WITH W/S) (CONSISTENT)	DAMAGED	650.00	650.00
1	TAILGATE (CONSISTENT)	DAMAGED	1,850.00	1,850.00

Report Ref No. CS/ASM18008795/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE HINGE LH (CONSISTENT)	NOT NECESSARY	30.00	-
1	TAILGATE HINGE RH (CONSISTENT)	NOT NECESSARY	30.00	-
1	TAILGATE EMBLEM (CONSISTENT)	DAMAGED	45.00	45.00
1	TAILGATE LAMP LH (CONSISTENT)	NOT NECESSARY	160.00	-
1	TAILGATE NO. PLATE GARNISH (CONSISTENT)	NOT NECESSARY	175.00	-
1	TAILGATE INNER LOCK (CONSISTENT)	DAMAGED	105.00	105.00
1	TAILGATE RUBBER (CONSISTENT)	DAMAGED	85.00	85.00
1	TAILGATE QASHQAI LOGO (CONSISTENT)	DAMAGED	65.00	65.00
1	TAILLAMP LH (CONSISTENT)	NOT NECESSARY	185.00	-
1	REAR BUMPER (CONSISTENT)	DAMAGED	450.00	450.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	DAMAGED	28.00	28.00
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	NOT NECESSARY	28.00	-
15	REAR BUMPER CLIPS (CONSISTENT)	DAMAGED	30.00	30.00
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	NOT NECESSARY	36.00	-
1	REAR BUMPER LOWER SPOILER (SILVER) (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	350.00	350.00
1	REAR BUMPER REINFORCEMENT BRACKET LH (CONSISTENT)	BENT	75.00	75.00
1	REAR BUMPER REINFORCEMENT BRACKET RH (CONSISTENT)	BENT	75.00	75.00
1	REAR BUMPER SPONGE (CONSISTENT)	TORN	95.00	95.00
1	END PANEL (CONSISTENT)	DENTED	300.00	300.00
1	END PANEL GARNISH (CONSISTENT)	NOT NECESSARY	55.00	-
1	REAR FENDER WHEEL ARCH LH (CONSISTENT)	DAMAGED	280.00	280.00
1	TRANSMISSION CONTROL BOX (ADDITIONAL) (CONSISTENT)	DAMAGED	1,080.00	1,080.00
2	HEADLAMP TOP PANEL L/R (ADDITIONAL) (CONSISTENT)	BENT	140.00	140.00
1	AIRCON DISCHARGE PIPE NO.2 (ADDITIONAL) (CONSISTENT)	BENT	55.00	55.00
1	BONNET STAND HOLDER (ADDITIONAL) (CONSISTENT)	NECESSARY	5.00	5.00
3	REAR BUMPER CLIP (ADDITIONAL) (CONSISTENT)	NECESSARY	24.00	24.00

Report Ref No. CS/ASM18008795/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
3	REAR BOOT WIPER MOTOR NUT (ADDITIONAL) (CONSISTENT)	NECESSARY	36.00	36.00
			18,827.00	15,328.00
	<u>SPECIAL NETT ITEMS</u>			
2	NUMBER PLATE (FRONT & REAR) (SN) (CONSISTENT)	DAMAGED-1PC ONLY	70.00	35.00
1	COOLANT (SN) (CONSISTENT)	DAMAGED	30.00	30.00
1	ATF OIL (SN) (CONSISTENT)	NECESSARY	160.00	80.00
1	INNER SEAL (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
2	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	400.00	350.00
			720.00	555.00
	<u>LABOUR</u>			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		100.00	100.00
	TO REMOVE AND REPLACE INTERCOOLER ASSY, OIL COOLER.		180.00	50.00
	TO REMOVE AND REPLACE ENGINE ECU.	NOT NECESSARY	150.00	-
	TO REMOVE AND REPLACE INTAKE MANIFOLD & ALTERNATOR.	NOT NECESSARY	180.00	-
	TO REMOVE & REPLACE ENGINE MOUNTING & GEARBOX MOUNTING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR BUMPER SENSORS.	NOT NECESSARY	80.00	-
	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT.		350.00	200.00
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, HEADLAMP SUPPORT PANEL. TO KNOCK & REPAIR FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH, FRONT DOOR RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1,500.00	800.00

Report Ref No. CS/ASM18008795/Dqd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH.		1,200.00	800.00
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	100.00
	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		120.00	60.00
	TO REMOVE AND REINSTALL / REPLACE REAR BUMPER SENSORS.		80.00	40.00
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR REAR FENDER LH, SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		900.00	600.00
	TO SPRAY TAILGATE, REAR BUMPER, END PANEL, REAR FENDER LH, SPARE TYRE PANEL.		900.00	800.00
	TO PROGRAMME AND TRANSFER DATA TO NEW AUTOMATIC TRANSMISSION CONTROL MODULE UNIT. (ADDITIONAL)		400.00	400.00
			6,460.00	3,990.00
GRAND TOTAL			26,007.00	19,873.00
RECOMMENDED COST OF REPAIRS				19,873.00
LESS EXCESS				-3,000.00
NETT LIABILITY				16,873.00

Report Ref No. CS/ASM18008795/Dqd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.