


ICC | CC 4, Asm 1800 8800, URA352 | LKK: 45127
 Marnus | DOI: 15/5/18 | Date/Time: 14/5/2018
 Registered in Merimen: —

Pre-assign / CCU / FTE



Insured Vehicle No.: SPE 4586
 Name of Insured: GWA Yik Pang.
 Insured Tel No.: HP: 82013904
 Excess Sec II :SS D.O.A: 13/5/18
 Is driver the owner? (YES / NO) Nature of Accident:

Claim No.: SPm 001407
 Policy No.: GA 298279/1
 Make / Model: M-Benz
 Place of Accident: Orchard Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SLB 63995



INSRS:
 WSP: KAH MOTOR
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:

Date/Time

14/5

SLB 63995 - X

SPE 4586 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 4/9/18 Confirm with: 2milin

Email ☐ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 15

If NO or B 28, Ass. Lia:

Repair Cost: S\$ 5957.84

Loss of Rental (LOR): S\$ (days)

Loss of Use (LOU): S\$ 300.00 (\$ 50 x 6 days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$

Medical: S\$

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost S\$

Total: S\$ 6257.84 Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

"ave. 1 S\$ 6257.84

Name: KAH MOTOR CO. SDN. BHD

Payee 2: (Strike if N.A.) S\$

Name 2:

Payee 3: (Strike if N.A.) S\$

Name 3:

Signature

Marcus

REF:

AXA

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLE 6399S

at Workshop m/s:

Kah Motor

of

15 Ubi Rd 4

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

15/5/2018 9.30am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

746.

IDAC Accident Rpt:

Consistent? : Yes or No

IA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

PIP

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLE 6399S

Yr Regn:

7 / 16

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda Jazz

O.C.

1498

Colour:

Gold

A/C

Insured / Std / NI / NA

Sp. Reading

022938

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMAK5850H X200208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

13/5/18

D.O.I.

15/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 54462

\$ 5568.07

(Red: \$ 1897.13 / 25%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S+PT \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008800/Uma3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 15-05-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKE 458G	Veh. Inspected	SLE 6399S	
Policy No.		Coverage (\$)	0.00	
Claim No.	SBM00HOT	Excess (\$)	0.00	
Assign From		Assign Date	15/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/05/2018	Inspection Date		
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor To Survey this
vehicle thanks

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLE6399S
Chassis No : JHMGK5850HX200208
Model : JAZZ 1.5VTIR CVT 17YM
Owner's Name : CHEAH PEI CHING
Ins Policy No. :
Date of Accident : 13/5/2018

Document No. : SQT18001965 Page 1
Date : 14. May 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B31190101
Date | Time : 14. May 2018 12:26:47 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO):						
	OWNER: CHEAH PEI CHING						
	OWNER INSURER: AXA INSURANCE S'PORE PTE LTD						
	ACC DATE: 13/5/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SKE458G						
67010-T5A-N10ZZ	PANEL COMP.R.FR.DOOR <i>Bo 1500/serf</i>	1	757.20	25	567.90 ✓	39.75	607.65 ✓
67324-T5A-003	TAPE SET.R.FR.DOOR <i>rec</i>	1	32.90	25	24.67 ✓	1.73	26.40 ✓
72326-T5A-003	SEALFR.DOOR LOWER <i>nn</i>	1	5.30	25	3.97 <i>X</i>	0.28	4.25
67510-T5A-N10ZZ	PANEL COMPR.RR.DOOR <i>Bo 1500/serf</i>	1	703.40	25	527.55 ✓	36.93	564.48 ✓
67825-T5A-003	TAPER.RR.DOOR SASH <i>rec</i>	1	15.40	25	11.55 ✓	0.81	12.36 ✓
72824-T5A-J01	SUB SEALR.RR.DOOR <i>nn</i>	1	6.30	25	4.72 <i>X</i>	0.33	5.05
72826-T5A-003	SEALRR.DOOR LOWER <i>rec</i>	1	3.20	25	2.40 <i>X</i>	0.17	2.57
71800-T5B-003ZF	GARNISH ASSYR.SIDE SILL <i>dis</i>	1	363.60	25	272.70 ✓	19.09	291.79 ✓
91505-TM8-003	CLIPBUMPER <i>rec</i>	6	2.00	25	9.00 ✓	0.63	9.63 ✓
91514-TF0-003	CLIPSIDE SILL GARNISH <i>nn</i>	2	5.10	25	7.65 <i>X</i>	0.54	8.19
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J <i>cu</i>	1	819.60	25	614.70 ✓	43.03	657.73 ✓
Sum Item					<u>2046.81</u>	<u>143.29</u>	<u>2,190.10</u>
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00 ✓	12.60	192.60 ✓
Sum Ext. Service					<u>180.00</u>	<u>12.60</u>	<u>192.60</u>

BOSUN	SUNDRIES <i>rec</i>	1	30.00 <i>10</i>		30.00	2.10	32.10
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1	1	320.00 <i>250</i>		320.00	22.40	342.40
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	350.00 ✓		350.00	24.50	374.50
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	350.00 ✓		350.00	24.50	374.50



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLE6399S
Chassis No : JHMGK5850HX200208
Model : JAZZ 1.5VTIR CVT 17YM
Owner's Name : CHEAH PEI CHING
Ins Policy No. :
Date of Accident : 13/5/2018

Document No. : SQT18001965 Page 2
Date : 14. May 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B31190101
Date | Time : 14. May 2018 12:26:47 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKFE22K	REPLACE R SIDE STILL PANEL GARNISH, REPAIR R SIDE <i>450</i>	1	1400.00	<i>900</i>	1400.00	98.00	1498.00
BP06R	SPRAY PAINTING ON R SIDE STILL PANEL GARNISH, R <i>350</i>	1	2300.00	<i>1500</i>	2300.00	161.00	2461.00
Sum Labor					4750.00	332.50	5,082.50

Survey By *Marcus Lee* *C Slim*
Date & Time *15/5/18* *81006303 (HR)*
Excess
Status *Not Insured*
Signature *Take photo before repair.*
5-6 day

Total Amount 6,976.81 488.39 7,465.20
Total (Inclusive of GST) **7,465.20**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 14/5/2018 1:11:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/5/2018

Survey Details:

Date of loss	13-May-18
Date of appointment	14-May-18
Date of survey	15-May-18
Location of survey	Kah Motor Co Sdn Bhd (Ubi)

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLE 6399S
Make and Model	HONDA JAZZ 1.5
Date of registration	28-Jul-16
Excess	
Market Value	\$ 74,000.00
Parf Rebate	\$ 54,462.00
Nett Loss	\$ 19,538.00

Repair details:

Initial Estimate	\$ 6,976.81
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,215.72
Check items (estimate)	\$ 11.09
Labour	\$ 3,010.00
Total	\$ 5,236.81
Lump Sum(if applicable)	\$ -

Number of days for repair	5-6 days
---------------------------	----------



Service Request Details

Claim

S8M00H0T

Reference

None

Loss Date

May 13, 2018

Request Date

May 14, 2018

Due Date

May 14, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

~~NO~~ YES Marcus
15/5/2018
930am
owner
waiting

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Actions

Next Step

Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #

SLE6399S

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

GOH YIK PANG

BLK 21 BEDOK SOUTH ROAD, #14-43, 460021, Singapore

JASPERGOHYP@GMAIL.COM

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Nivitha (LKK Auto)

From: Lim Chou Siong <cslim@honda.com.sg>
Sent: Monday, 14 May 2018 1:24 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: DIRECT SETTLEMENT OF VEHICLE NO. SLE6399S AGAINST SKE458G
Attachments: 1495_001.pdf

Categories: Mateen

To Officer In Charge,

The Above Attachment For Your Reference,

Kindly Help To Arrange Surveyor To Survey This Vehicle SLE6399S,

Your Insure Vehicle Number SKE458G, Accident Date 13/05/18,

Thank for your help.

Best Regards,

Lim Chou Siong
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4
Singapore 408610
E-mail : cslim@honda.com.sg
Fax : 67480770 DID : 68465671 H/P : 81006303

From: Printer Service
Sent: Monday, 14 May, 2018 1:17 PM
To: Lim Chou Siong <cslim@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKE 458G (Insd veh)	Model:	HONDA
	SLE 6399S (TP veh)		JAZZ 1.5 VTIR CVT ABS
Date of Accident:	13/05/2018		D/AIRBAG 2WD

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	7,465.19
Final Repair Cost	:	\$	5,957.84
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	6 days at \$50.00 per day
LTA / GIA Search Fee	:	\$	days

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 6,257.84

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____15____

BOLA Liability: _____100____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	KAH MOTOR CO. SDN. BHD.	:	\$ 6,257.84

NUR SHAQILAH BTE ABDOL
WAHAB

20/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

SERVICE REQUESTSMESSAGESCLAIMS

<< Service Request Details

Claim

S8M00CH0T

Reference

CC4/ASM18006800/Uuat3s2

Loss Date

May 13, 2018

Request Date

May 14, 2018

Due Date

May 14, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Work

More

Document Type

Document Sub Type

Upload Documents

Vehicle Information

Incident Vehicle Registration #

SLE6399S

Make

TPVD HONDA

Model

JAZZ-1.5 VTIR CVT (A)

Primary Contact/Insured

GOH YIK PANG

BLK 21 BEDOK SOUTH ROAD, #14-43, 460021, Singapore

JASPERGOHYIP@GMAIL.COM

Service Address

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

NAME

TYPE

SUB-TYPE

AUTHOR

DATE UPLOADED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Accident Statement

Reports & Statement

Meritman

SERVICE REQUESTS MESSAGES CLAIMS

Service Request Details

Claim

S8MD0H0T

Reference

CC4/ASM18006800/Uua3s2

Loss Date

May 13, 2018

Request Date

May 14, 2018

Due Date

May 14, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Task

More

Apply

Vehicle Information

Incident Vehicle Registration #

SLE6399S

Make

Service Address

TPVD HONDA

Model

JAZZ-1.5 VTIR CVT (A)

Primary Contact/Insured

GOH YIK PANG

BLK 21 BEDOK SOUTH ROAD, #14-43, 460021, Singapore

JASPERGOHYP@GMAIL.COM

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

CREATED USER

VERSION DATE

ESTIMATED AMOUNT

APPROVED AMOUNT

STATUS

SHARE

CLONE

Messages

Invoices

History

Documents

Assessment

Metrics

Notes



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration# SLE6399S

Purchase Date mm/dd/yyyy

Registration State SINGAPORE

Registration Date * 07/28/2016

Mileage 22938

Age of Vehicle 1

Driver Details

CATEGORY

POLICY INFORMATION

ASSESSMENT INFORMATION

Manufacturing Year

2016

Year

Make

TPVD HONDA

HONDA

Model

JAZZ-1.5 VTIR CVT (A)

JAZZ 1.5 VTIR CVT ABS D//

Type

Type of Paint

Chassis No

JHMGK5850HX200208

Engine No

L15B31190101

Engine Capacity

1498 cc

CATEGORY

FNOL INFORMATION

POST SURVEY INFORMATION

Driver Name

CHEAH PEI CHING

Date of Birth

January 27, 1983

Age

35

Occupation

Unknown

Education Qualification

Other

Driving Experience

0

Driver License #

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	05/15/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	YesNo
Towing Charges	0		Footbrake (Serviceable)	YesNo
Voluntary Excess	0		Handbrake (Serviceable)	YesNo
Compulsory Excess	0		Engine Modification	YesNo
Young/Inexperienced/Unlicensed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	185/55R16	Rear Tyre Size	185/55R16
Front left side	DUNLOP 8mm	Rear left side	DUNLOP 8mm
Front right side	DUNLOP 8mm	Rear right side	DUNLOP 8mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

Labour

EDIT	S/N	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/L BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1				REMOVE & INSTALL REAR COMPARTMENT LININGS, RR		250		0		0	Reviewing			
		2				REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST.		350		0		0	Reviewing			
		3				REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST.		350		0		0	Reviewing			
		4				REPLACE R SIDE STILL PANEL GARNISH. REPAIR R SIDE.		900		0		0	Reviewing			
		5				SPRAY PAINTING ON R SIDE STILL PANEL GARNISH, R		1500		0		0	Reviewing			
		6				WHEEL ALIGNMENT		180		0		0	Reviewing			

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Add

Approve

Deny

Submit/42

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		6	
	2	PANEL COMPR.FR.DOOR	Reviewing	567.9	BADLY DENTED / BENT	
	3	TAPE STEP.FR.DOOR	Reviewing	24.67	NECESSARY	
	4	SEAL.FR.DOOR LOWER	Reviewing	0	NOT NECESSARY	
	5	PANEL COMPR.RR.DOOR	Reviewing	527.55	BADLY DENTED / BENT	
	6	TAPER.RR.DOOR SASH	Reviewing	11.55	NECESSARY	
	7	SUB SEAL.RR.DOOR	Reviewing	0	NOT NECESSARY	
	8	SEAL.RR.DOOR LOWER	Reviewing	0	NOT NECESSARY	
	9	GARNISH ASSYR.SIDE SILL	Reviewing	272.7	DISTORTED	
	10	CLIPBUMPER	Reviewing	9	NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$5,568.07

Claim Amount \$5,568.07

CATEGORY ESTIMATE REVISED AMOUNT

Labour \$3,530.00 \$3,530.00

Miscellaneous \$2,038.07 \$2,038.07

Submit for Review