

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to Survey this
vehicle thanks

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT18001965	Page	1
	8 SHENTON WAY	Date	: 14. May 2018		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SLE6399S	Engine No	: L15B31190101		
Chassis No	: JHMGK5850HX200208	Date Time	: 14. May 2018 12:26:47 PM		
Model	: JAZZ 1.5VTIR CVT 17YM	Surveyor Name	:		
Owner's Name	: CHEAH PEI CHING	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 13/5/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHEAH PEI CHING						
	OWNER INSURER: AXA INSURANCE S'PORE PTE LTD						
	ACC DATE: 13/5/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SKE458G						
67010-T5A-N10ZZ	PANEL COMP.R.FR.DOOR <i>Body rd/sent</i>	1	757.20	25	567.90 ✓	39.75	607.65
67324-T5A-003	TAPE SETR.FR.DOOR <i>nee</i>	1	32.90	25	24.67 ✓	1.73	26.40
72326-T5A-003	SEALFR.DOOR LOWER	1	5.30	25	3.97 ?	0.28	4.25
67510-T5A-N10ZZ	PANEL COMPR.RR.DOOR <i>Body rd/sent</i>	1	703.40	25	527.55 ✓	36.93	564.48
67825-T5A-003	TAPER.RR.DOOR SASH <i>nee</i>	1	15.40	25	11.55 ✓	0.81	12.36
72824-T5A-J01	SUB SEALR.RR.DOOR	1	6.30	25	4.72 ?	0.33	5.05
72826-T5A-003	SEALRR.DOOR LOWER	1	3.20	25	2.40 ?	0.17	2.57
71800-T5B-003ZF	GARNISH ASSYR.SIDE SILL <i>D.S</i>	1	363.60	25	272.70 ✓	19.09	291.79
91505-TM8-003	CLIPBUMPER <i>nee</i>	6	2.00	25	9.00 ✓	0.63	9.63
91514-TF0-003	CLIPSIDE SILL GARNISH <i>nee</i>	2	5.10	25	7.65 ✓	0.54	8.19
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J <i>cut</i>	1	819.60	25	614.70 ✓	43.03	657.73
Sum Item					2046.81	143.29	2,190.10
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00 ✓	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60
BOSUN	SUNDRIES	<i>nee</i> 1	30.00 <i>10</i>		30.00	2.10	32.10
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1		320.00 <i>250</i>		320.00	22.40	342.40
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	350.00 ✓		350.00	24.50	374.50
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	350.00 ✓		350.00	24.50	374.50

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLE6399S

Chassis No : JHMGK5850HX200208

Model : JAZZ 1.5VTIR CVT 17YM

Owner's Name : CHEAH PEI CHING

Ins Policy No. :

Date of Accident : 13/5/2018

Document No. : SQT18001965 **Page** 2

Date : 14. May 2018

Customer No. : WZA006

Svc Advisor : LIM CHOU SIONG

Engine No : L15B31190101

Date | Time : 14. May 2018 12:26:47 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKFE22K	REPLACE R SIDE STILL PANEL GARNISH, REPAIR R SIDE <i>450</i>	1	1400.00	<i>90%</i>	1400.00	98.00	1498.00
BP06R	SPRAY PAINTING ON R SIDE STILL PANEL GARNISH, R <i>350</i>	1	2300.00	<i>1150</i>	2300.00	161.00	2461.00
Sum Labor					4750.00	332.50	5,082.50

Survey By

Date & Time

Excess

Status

Signature

Marcus Khek *C Slim*
15/5/18 *81006303 (H)*
Not defect
Take photo before repair.
5-6 day

Total Amount 6,976.81 488.39 7,465.20**Total (Inclusive of GST)** 7,465.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 14/5/2018 1:11:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)