LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. From: LKK Auto Consultants Pte Ltd 6 Temasek Boulevard 51 Ubi Ave 1 #01-25 #18-01 Suntec Tower 4 Paya Ubi Industrial Park Singapore 038986 Singapore 408933

Attn: Josey Loh Date: 03 Jul 2018

Preliminary Advice

Vehicle No : SKP7565B Accident Date : 12/05/2018

Make : NISSAN NOTE Policy No. : PNPV2017-00007269

Assignment Date : 14/05/2018 Excess : \$\$500.00 Date of Inspection : 17/05/2018 Est. Duration of Repair : 6.00

Inspection At : ETHOZ PROTECT PTE LTD (BUKIT BATOK)

30 BUKIT BATOK CRESCENT

SINGAPORE 658075

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,461.00
Revised Amount	:S\$	8,411.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,411.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage Kindly let us have your authorisation.	
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.	
()	Other comments:	