

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Josey Loh

Date: 18 May 2018

## Preliminary Advice

Vehicle No	: SKP7565B	Accident Date	: 12/05/2018
Make	: NISSAN NOTE	Policy No.	: PNPF2017-00007269
Assignment Date	: 14/05/2018	Excess	: S\$500.00
Date of Inspection	: 17/05/2018	Est. Duration of Repair	: 6 days
Inspection At	: ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,046.00
Revised Amount	:S\$	4,736.00
Check Items (Estimated)	:S\$	2,315.00
Total	:S\$	7,051.00
Lump Sum Repair		:S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	45,036.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,964.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :