



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLL7370E

Date of Accident : 14 May 2018

Mr Nurdiana Binte Sayang

Date : 15 May 2018

Estimate To Repair SGG1816L - Toyota Corolla 1.6 Auto

Chassis No : MR053ZEC107118688

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	Rear fender (LHS) <i>DD/surf</i>	\$ 590.00
02	1 pc	Rear fender inner shield (LHS) <i>11</i>	\$ 40.00
03	1 pc	Rear fender inner trim (LHS) <i>11</i>	\$ 75.00
04	1 pc	Rear fender inner trim clips <i>11</i>	\$ 4.30
05	1 pc	Left rear fender air vent <i>11</i>	\$ 25.00
06	1 pc	Left rear fender lower panel <i>D.S</i>	\$ 95.00
07	1 pc	Left rear fender inner liner <i>11</i>	\$ 125.80
08	1 pc	Rear lamp (LHS) <i>310</i>	\$ 300.00
09	1 pc	Rear lamp panels (LHS) <i>30.5.10</i>	\$ 496.00
10	4 pcs	Rear lamp clip holder @ \$4.30 <i>11</i>	\$ 17.20
11	1 pc	Rear bumper assy <i>D.S</i>	\$ 395.00
12	2 pcs	Rear bumper brackets @ \$20.00 <i>n/s m</i>	\$ 40.00
13	2 pcs	Rear bumper side retainers @ \$70.00 <i>m/s surf</i>	\$ 140.00
14	1 pc	Rear bootlid <i>n</i>	\$ 735.00
15	2 pcs	Rear bootlid hinges @ \$85.00 <i>n</i>	\$ 170.00
16	1 pc	Rear bootlid reflector (LHS) <i>cm</i>	\$ 85.00
17	1 pc	Rear boot 1.6E emblem <i>nu</i>	\$ 80.00
18	1 pc	Rear bootlid VVT-I emblem <i>nu</i>	\$ 40.00
19	1 pc	Bootlid altis emblem <i>nu</i>	\$ 34.00
20	1 pc	Bootlid centre emblem badge <i>nu</i>	\$ 68.00
21	1 pc	Bootlid outer chrome garnish <i>11</i>	\$ 175.00
22	1 pc	Bootlid weather strip <i>11</i>	\$ 175.00
23	4 pc	Bootlid lock cable clips @ \$4.50 <i>11</i>	\$ 18.00
24	1 pc	Bootlid inner trim cover <i>11</i>	\$ 85.00
25	5 pcs	Bootlid inner trim cover clips @ \$4.50 <i>11</i>	\$ 22.50
26	2 pcs	Bootlid rubber stoppers @ \$12.00 <i>11</i>	\$ 24.00
27	1 pc	Bootlid lock <i>11</i>	\$ 60.00
28	1 pc	Bootlid lock sticker <i>11</i>	\$ 56.00
29	1 pc	Bootlid lock sticker garnish <i>11</i>	\$ 55.00
30	1 pc	Rear end panel <i>n</i>	\$ 685.00
31	1 pc	Rear end panel inner trim <i>11</i>	\$ 210.00
			\$ 5,120.80
Less 25 %			\$ 1,280.20
			\$ 3,840.60
<u>SPECIAL NETT ITEMS</u>			
32	1 pc	Rear licence plate <i>11</i>	\$ 60.00
33	1 pc	Rear bumper parking sensor <i>11</i>	\$ 280.00
34	1 pc	Rear luggage floor panel insulation padding <i>11</i>	\$ 250.00
35	1 pc	Rear windscreen glass sealant <i>nu</i>	\$ 20.00

confirm with Maray.

15.05.2018
@1635

N.f. Author
1/5/18
15/5/18
take photo After repair
5 day.

2333
1749.25



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLL7370E
Date of Accident : 14 May 2018

Mr Nurdiana Binte Sayang

Date : 15 May 2018

Estimate To Repair SGG1816L - Toyota Corolla 1.6 Auto
Chassis No : MR053ZEC107118688

S/No	Quantity	Description	Amount
36	1 pc	<u>SPECIAL NETT ITEMS</u> Rear windscreen glass inner sponge seal <i>au</i>	\$ 80.00 \$ 690.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 80.00
02		To remove and refit rear windscreen glass.	\$ 200.00
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
04		To rust-proofing of the affected areas.	\$ 350.00
05		To drop petrol tank, hoses to facilitate bodywork repair, final checking amd testing.	\$ 180.00
06		To transfer of door fittings and perform water seepage test.	\$ 17 180.00
07		To reinstall of rear bumper parking sensor.	\$ 150.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,400.00
09		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 3,890.00
		Total	\$ 8,420.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2333
1749.75

4079.75
3263.80

30

20

120

80

50

60

x

50

1000

900

4079.75