

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2905/05/18

Like Auto Consultants hence notify
Your Ref: [blank] following:

Date: 15th May 2018

MR CHEW YEOW YONG
BLK 245, #02-85
PASIR RIS STREET 21
SINGAPORE 510245

- To resurvey before later spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*N. + A. [signature]
4d. [signature]
17/5/18 Tel: 62883861
Take photo before painting.*

Estimate cost of repair to NISSAN QASHQAI 1.2 (A) 5door - SLS 6948 J

Acknowledged by Repairer

1 pc tail gate door 'QASHQAI' emblem		\$ 87.00	Nett	✓
1 pc tail gate door 'NISSAN' emblem		59.70	"	X
16 pcs tail gate door inner trim board clips @ \$ 5.00 N		80.00	"	X
1 pc tail gate door inner lock		116.70	"	X
1 pc tail gate door lock stricker		31.70	"	X
1 pc tail gate door		2,936.80	"	X
1 pc rear bumper		747.00	"	✓
1 pc rear bumper reinforcement		619.20	"	?
1 pc rear bumper sponge damper		126.40	"	?
5 pcs rear bumper top clips & holder @ \$ 7.40 N		14.80	"	✓
2 pcs rear bumper o/s & n/s stay bracket @ \$ 126.00 N		252.00	"	?
2 pcs rear bumper o/s & n/s side retainer @ \$ 35.90 N		71.80	"	?
1 pc rear bumper tow bar cover		18.80	"	?
8 pcs rear bumper low clips @ \$ 5.00 N		40.00	"	✓
4 pcs rear bumper o/s & n/s reverse sensor @ \$ 210.00 N		840.00	"	2805.0
2 pcs rear bumper o/s & n/s reflector @ \$ 55.00 N		110.00	"	X
4 pcs rear bumper o/s & n/s top screw & stopper @ \$ 8.00 N		32.00	"	X
2 pcs rear bumper o/s & n/s side lower bracket @ \$ 23.80 N		47.60	"	?
2 pcs rear bumper o/s & n/s side lower bracket clips @ \$ 5.00 N		10.00	"	?
1 pc rear end panel		482.60	"	?
1 pc rear end panel top garnish		63.50	"	X
5 pcs rear end panel top garnish clips @ \$ 5.00 N		25.00	"	X
1 pc rear number plate & frame		60.00	"	X

\$ 6,888.60 Nett

Less 10% \$ 688.86

\$ 6,199.74

To wiring check up & transfer affected wiring system. 50.00 20

To remove & refix tail gate inner trim board cover, lock, garnish & necessary parts, to enable repair tail gate door. 150.00 X

To remove & refix rear cushion seat, carpet, floor mat, garnish & necessary parts. 120.00 60

To jack, straighten & knocking out rear exhaust muffler, tail pipe & necessary parts. 120.00 X

To respray Tuff-Kote on all affected accident parts. 90.00 ?

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out tail gate door, rear end panel & necessary parts, to weld, renew & align above parts. 1,200.00 520

To putty & respray painting on all affected accident parts. 1,500.00 600

HUP MOTOR TRADING & SERVICE

\$ 9,429.74