

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Cheong

Date: 24 Aug 2018

## Preliminary Advice

Vehicle No	: SLW405C	Accident Date	: 11/05/2018
Make	: MERCEDES-BENZ 200	Policy No.	: DMPCSN1803561800
Assignment Date	: 15/05/2018	Excess	: S\$1,100.00
Date of Inspection	: 16/05/2018	Est. Duration of Repair	: 7 days
Inspection At	: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	: \$	14,542.28 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	: \$	14,378.03 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	: \$	0.00
Total	: \$	14,378.03
Lump Sum Repair		: \$

### **Total Loss Consideration**

New for Old Value	: \$	
Pre-Accident Value	: \$	165,000.00
COE / PARF Rebate	: \$	73,456.00
Salvage Value	: \$	
Margin for Repair	: \$	91,544.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : SUPPLEMENTARY AMOUNT IS \$ 671.11