

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 28 Aug 2018

Preliminary Advice

Vehicle No	: SLW405C	Accident Date	: 11/05/2018
Make	: MERCEDES-BENZ 200	Policy No.	: DMPCSN1803561800
Assignment Date	: 15/05/2018	Excess	: S\$1,100.00
Date of Inspection	: 16/05/2018	Est. Duration of Repair	: 7 days
Inspection At	: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,682.28 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	14,378.03 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,378.03
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	165,000.00
COE / PARF Rebate	:S\$	73,456.00
Salvage Value	:S\$	
Margin for Repair	:S\$	91,544.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :