



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW405C

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **23566**
Reg No/Reg Date **SLW405C / 26/01/2018**
Date In/Mileage **22/05/2018/ 5561**
Chassis No **WDD1760432J698369**
Engine No **27091031475857**
Make/Model **MB/MB A 200 (W176) "STYLE"**
Colour/Trim **028 890 Cavansite B/ 044 471 ARTICO/Fabr**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	30/05/2018/ 17:43		301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X FRONT STIFFENING	1.00	622.03	00.00	622.03
X RH FRONT FENDER BRACKET	1.00	11.76	00.00	11.76
X AIR DUCT	1.00	37.32	00.00	37.32

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 671.11**
671.11 46.98
Total Payable 718.09

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany


Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address				Owner Name & Vehicle Info			
CHINA TAIPING INSURANCE (S) PTE LTD ATTN: MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909				Cust No/Name	WCV33796/Mr Goh Zheng Hui (Wu Zhenghui)		
Contact No 62222366				Reg No/Reg Date	SLW405C / 26/01/2018		
				Date In/Mileage	22/05/2018/ 5561		
				Chassis No	WDD1760432J698369		
				Engine No	27091031475857		
				Make/Model	MB/MB A 200 (W176) "STYLE"		
				Colour/Trim	028 890 Cavansite B/ 044 471 ARTICO/Fabr		
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No.	
WC000668	Credit	23/08/2018/ 15:05	K0	301 / Kerlyn Ong	23566	28145406	
Description of Goods / Services					Qty	Unit Price S\$	Amount S\$
M BPNSUN							F.O.C.
POLICY NO/ACC DATE : DMPCSN1803561800 // 11/05/2018							
DRIVE IN/EXCESS : 11/05/2018 // \$1100							
DATE IN/DATE SURVEY: 16/05/2018 1400 // LKK - RASUL							
BY/AUTHORIZED ON : 18/05/2018 1753 // LKK - SHIRLEY							
A BPILAB							3360.00
STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT							
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.							1950.00
A BPIRES							
RESPRAY BONNET, FRONT BUMPER, RH/ FRONT FENDER & RH/ WING MIRROR							
A BPILAB					0.10		380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO							
IDENTIFICATION STANDARD. NETT							120.00
A BPILAB							
TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT							540.00
A BPILAB							
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT							140.00 A
S BPNTOW							
ACCIDENT TOWING FROM U CHANGI RD NORTH TO PLSC							
USING KING DOLLEY							
WO: 147974							
X BPNEXC							-1100.00
INSURANCE EXCESS							
M BPNSUN							980.00
RH/ FRONT DISK WHEEL							60.00
A BPILAB							
TRANSFER RIM AND BALANCING TYRE. NETT							
X FRONT BUMPER					1.00	1146.15	1146.15
X FRONT BUMPER COMPANY SIGN					1.00	57.73	57.73
X GROMMET					2.00	2.23	4.46
X FRONT BUMPER LOWER CHROME					1.00	122.51	122.51
X FRONT BUMPER LOWER COVER					1.00	315.08	315.08
X FRONT DISTANCE SENSOR					1.00	172.07	172.07

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg