

ASS. REC. BY: Richard REF: CS/AU/17010385/1106-1 Special Instructions: PAS
 Surveyor: Richard ASSIGNMENT (Office)
 From (Person): Angie Gun of AU Date/Time 15052018
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No. GX7834 E Insured: SP67700E
 at Workshop m/s Sheng Li Lai Tel: 91119222
 of 2 koki Bukit Aie 2 #01-36
 Policy No: 2100492332 Claim No: 2469512186SG 005.
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 8/5/2017
 (Client's Record)
 CA / REV / REP. / REV 24 HRS 30/5/2017 R.O.D. Endorsement: _____
 Date/Time 29/5/2017 5:07pm Person Contacted Mr. Low Vehicle IN/OUT

Date/Time	Action/Instruction (*) Estimate
	<u>GX7834 E</u>
	<u>Survey: 30/5/2017; dismantle: 31/5/2017; after repair: 2/6/2017</u>
	<u>L/S 2500 & ch. Rep: \$7000, 73%.</u>

Submit paper survey

RECEIVED 21 MAY 2018

Catherine Chong (LKK Auto)

From: Gan, Angiegeokling <Angiegeokling.Gan@aig.com>
Sent: Tuesday, 15 May, 2018 4:45 PM
To: 'SUR'; 'Admin A'; assignments@lkkauto.com
Subject: [Paper Resurvey] AIG ref: 2469512186SG005 ; LKK ref: CS3/AIG17010385/JH3S2 // OIV - SFG700E ; TPV - GX7834E
Attachments: 2469512186SG_11_05_2018_RULINGS_JUDGMENTS_SENTENCES_B28397 -001.pdf

Dear All,

We refer above matter for which you had conducted PRI on 30/5/2017.

Kindly assist on paper resurvey and let us have surveyor's adjustments as soon as possible.

Attached TPPD LOD for your reference.

Looking forward to hearing from you.

Thank you.

Best Regards,

Angie Gan
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +(65) 6419 1013 | Fax +(65) 6835 7416
Angiegeokling.Gan@aig.com | www.aig.com.sg

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



ACRA Reg. No.
200309625D

EAST ASIA LAW CORPORATION

Advocates & Solicitors


496498

133 New Bridge Road #10-02
Chinatown Point Singapore 059413
Tel: 65 6323 2565 Fax: 65 6323 2373
E-mail: law@ealc.com.sg
Website: www.ealc.com.sg

Kasturibai Manickam
Jocinda Wong Jia Heng

(Service of Court documents by way of fax is not accepted)

Team
ADJ



Our Ref: 2017.4938.EA.MK.YA
Your Ref: SFG700E(2ND)

9-May-2018

WITHOUT PREJUDICE

PDX#8181
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

CERTIFICATE OF POSTING
CHOO CHIN KIAT
30 Taneh Merah Kechil Road
#13-01 Singapore 465558

PDX Intercompany Exchange Pte Ltd



010808370271

FROM EAST ASIA LAW CORP.
PDX Box No. 8080

Dear Sir,

CLAIMANT: ALUMNI CONSTRUCTION & TRADING PTE LTD
ACCIDENT INVOLVING GX7834E(1ST) & SFG700E(2ND) & PA7001G(3RD) ON 08 MAY 2017 ALONG ANG MO KIO AVE 5 (OPPOSITE ITE) AT ABOUT 0845 HOURS

We act for ALUMNI CONSTRUCTION & TRADING PTE LTD, the owner of vehicle no. GX7834E(1ST), whose vehicle was damaged as a result of the abovementioned accident by vehicle no. SFG700E(2ND) and our search reveals that you were the insurers of motor vehicle no. SFG700E(2ND)

We are instructed that the accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1) Costs of repair	\$ 9,500.00
2) Loss of Use (PRI 2+7)	\$ 900.00
3) Survey report fee	\$ 695.00
4) LTA search fee	\$ 16.00
5) Costs + GST	\$ 963.00
6) Incidentals + GST	\$ 53.50
Total:	\$ 12,127.50

We enclose copies of the following documents supporting our client's claim for your attention:-

- 1) GIA accident report of our client's report GX7834E(1ST)
- 2) LTA search for SFG700E(2ND)
- 3) Final repair bill for GX7834E(1ST)
- 4) Original Survey report enclosing original color copies of photographs depicting damages to vehicle no. GX7834E(1ST)
Enclosed document may be photocopied on both sides to save paper and be environment friendly

Please note that if you are insured and you wish to claim your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days from the receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on the supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

Kasturibai Manickam
East Asia Law Corporation

Enc.
cc:

Ref. GX7834E(1ST)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/05/2017 14:14
Date Of Accident	08/05/2017 08:45
Exact Location Of Accident	ANG MO KIO AVE 5 (OPPOSITE ITE)
Country/State Of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GX7834E
Insured/Policyholder	
Name Of Registered Owner	ALUMNI CONSTRUCTION & TRADING PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96365798
Alternative Phone No	OFFICE-96365798
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 150 M
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	A 28604491 MKC
Cover Note Number	15/09/2016 TO 14/09/2017
Driver	
Name of Driver	KOH HSIEN-CHIN, WILLIE (GAO XIANJIN, WILLIE)
NRIC No	S8242364H
Date Of Birth	15/12/1982
Occupation	OUTDOOR
Date Of Driving Pass	21/06/2004
Driving Experience	12 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96365798
Fax Number	
Contact Number	
EEmail Address	WILLKHC@GMAIL.COM

Address APT BLK 544 ANG MO KIO AVE 10 #06-2280 (S) 560544

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION- CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFG700E

Vehicle Make/Model/Colour VOLVO

Details Of Properties

Name of Driver CHOO CHIN KIAT

NRIC/Passport Number S1348457J

Contact Number 96621428

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number PA7001G

Vehicle Make/Model/Colour TOYOTA BUS

Details Of Properties

Name of Driver

WAGIMAN BIN IBRAHIM

NRIC/Passport Number

S1715842B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Accident Sketch Plan Pg. 1

09-05-17 14:14 : Alumni Construction & Trading

105 6482 9556

W 1/ 1

Fax: 6748 1006

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Please Sign & Return

Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

09/05/17 1340



Witnessed by Reporting Centre Personnel

Sketch Plan

Sketch Plan grid with handwritten notes:

- Top right: red light
- Point A: GF 7B 34E
- Point B: SFG 700E
- Point C: PA 700 KG
- Vertical labels on the left: A, B, C

Accident Sketch Plan Pg. 1

09-05-17:14:15 :Alumni Construction & Trading

:+65 8482 9556

* 1/ 1

Describe Circumstances of the Accident

I was using of traffic light and about 10m off I felt impact from the back. After that I get down from my truck, I realise there is three vehicles involved in the accident.

MSIC
GAP 2017
08 May 2017
☐ Reporting Only
☐ Own Damage Claim
☒ Third Party Claim
☒ Other Workshop
Sheng Li Lin

Declaration

We declare that the above particulars are true in every respect.



[Signature]



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Enquire Vehicle & Owner Information (Vehicle No. SFG700E As At 08 May 2017 / 08:45:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: SHENG LI LAI-GX7834E

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S1348457J
Owner Name: CHOO CHIN KIAT
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 30
Registered Street Name: TANAH MERAH KECHIL ROAD
Registered Unit No.: # 13 - 01
Registered Building Name: -
Registered Postal Code: 465558

Current Vehicle Details

Vehicle No.: SFG700E
Make Description/Model: VOLVO / XC60 T5
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Enquire Vehicle & Owner Information (Vehicle No. PA7001G As At 08 May 2017 / 08:45:00)**Law Firm Search Details****Search Reason:** Insurance claim in relation to traffic accident**Law Firm Case No.:** 2017-4938**Current Owner Details****Owner ID Type:** Business**Owner ID:** 53243496W**Owner Name:** SHREE MAJU ENTERPRISES**Registered Address Type:** HDB / HUDC**Registered Block/House No.:** 336**Registered Street Name:** TAH CHING ROAD**Registered Unit No.:** # 03 - 181**Registered Building Name:** -**Registered Postal Code:** 610336**Current Vehicle Details****Vehicle No.:** PA7001G**Make Description/Model:** TOYOTA / HIACE 2.5 A**Insurance Company Name:** NTUC INCOME INS CO-OP LTD

Text size: -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 2451M

Vehicle Details

Vehicle No: GX7834E

Vehicle to be Exported: No

Intended De-registration Date: 29 May 2017

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 D

Primary Colour: Blue

Manufacturing Year: 2004

Engine No.: 5L5460224

Chassis No.: JTFUF34Y303002686

Maximum Power Output:

Open Market Value: \$23,715.00

Original Registration Date: 15 Sep 2004

First Registration Date: 15 Sep 2004

Transfer Count: 0

Actual ARF Paid: \$1,186.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date:

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 14 Sep 2019

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$23,901.00

COE Rebate Amount: \$10,967.00

Total Rebate Amount: \$10,967.00**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 29 May 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution.

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 28 May 2017 at 12:54 AM

Vehicle No: 11111111
 (1) Item (2) Description (3) Quantity (4) Unit (5) Remarks
 (6) Defect (7) Date (8) By (9) Status (10) Date (11) Status
 (12) Date (13) Status (14) Status (15) Status

VAN / LORRY (Rear)

Vehicle No: 11111111
 (1) Item (2) Description (3) Quantity (4) Unit (5) Remarks
 (6) Defect (7) Date (8) By (9) Status (10) Date (11) Status
 (12) Date (13) Status (14) Status (15) Status

Vehicle No: 11111111

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BT	✓	1
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket	BT	✓	1
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993106	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	DD R		
1160	993851	Rear LH Taillamp	SCR	✓	1
1161	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	SCR	✓	1
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1189	995156	Rear LH Door			
1190	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1191	995194	Rear LH Door Hinge			
1192	995307	Rear RH Door Hinge			
1193	993261	Rear LH Door Lock			
1194	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1195	994729	Third Brake Light			
1181	994543	Tailgate	BUK	✓	1
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem	STICKERS	✓	3
1183	994543	Tailgate Outer Handle			
1184	994545	Tailgate Garnish Side bracket	BT	✓	2
1196	994602	Tailgate Glass			
1197	994606	Tailgate Glass Rubber			
1198	994604	Tailgate Glass Moulding			
1199	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1192	994629	Tailgate Lock	Lock	✓	1
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge	BT	✓	4
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993622	Rear RH Mudflap			
1229	993934	Rear RH Wheel Rim			
1230	994025	Rear RH Rim Cover			
1231	995065	Rear RH Tyre			
1232	992179	Fuel Tank			
1233	992184	Fuel Tank Bracket			
1234	990247	Sticker			

No of Items: 11

Assessor: Richard

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2017 Edit Reg		29 May 2017 00:00 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

CHOO CHIN KIAT, ID: S1348457J

Main Claimant:

ALUMNI CONSTRUCTION & TRADING PTE. LTD., Co. Reg. No.: 198802451M

Vehicle Reg. No.:

GX7834E

Date of Loss:

08/05/2017 08:00 - :59

Claim Type:

TP / 2469512186SG

Policy/Cover Note No.:

2100492332 (Comprehensive)

Vehicle Reg. No. (Insured):

SFG700E

Policy No. (Claimant):

Excess:

Repairer:

Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]
Norsiah.MdNoor@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjanto] ... [Final Rpt due 07/06/2017]

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS








































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GX7834E (2469512186SG)
[SFG700E]

TP
ALUMNI CONSTRUCTION & TRADING PTE. LTD.
May 8 2017 8:40AM
[CHOO CHIN KIAT]
Sheng Li Lai

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer	
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	30/05/17 15:00	Accident Statement From: SC - Reg. No: SFG700E, Claimant: CHOO CHEN KIAT						 Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
2	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
3	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
4	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
5	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
6	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
7	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
8	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
9	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
10	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
11	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
12	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
13	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
14	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
15	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
16	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
17	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
18	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
19	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
20	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
21	31/05/17 08:40	General View						 Load JPG	<input checked="" type="checkbox"/>		
22	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
23	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
24	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
25	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
26	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
27	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
28	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
29	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
30	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
31	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
32	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
33	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
34	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
35	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
36	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
37	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		
38	05/06/17 10:18	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>		

39	05/06/17 10:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	05/06/17 10:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	05/06/17 10:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	05/06/17 10:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	05/06/17 10:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	05/06/17 10:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	05/06/17 10:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	05/06/17 10:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	05/06/17 10:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
49	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
50	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
51	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
52	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
53	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
54	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
55	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
56	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
57	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
58	05/06/17 10:18	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/05/17 17:40	TP GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17010385/JH3S2
Date: 06/06/2017

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100492332
Claimant: GX7834E Insured Vehicle No: SFG700E
Vehicle No: Date of Loss: 08/05/2017 Nature of Claim: TP Claim No: 2469512186SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GX7834E
Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 5L5460224
Reg. Date: 15/09/2004 (Man. Year: 2004) Chassis No: JTFUF34Y303002686
Colour: Blue Odometer: 309904 km
Engine Capacity: 2986 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14 Rear Tyre Size: 155X R12 (D)
Front Left Side: Bridgestone 5 mm Rear Left Side: Yokohama 5/5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/05/2017
Date Inspected: 30/05/2017 Inspected At: Sheng Li Lai (KAKI BUKIT)
NO. 2 KAKI BUKIT AVE 2, # 01-36
AUTOHUB KAKI BUKIT
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: Richard Harjanto

Manager: Ashley Chong Chin Yan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BRACKET	Bent	0.00 F	*- F
3	1		*REAR END PANEL	Repair	0.00 F	*- F
4	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F
5	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
6	1		*TAILGATE	Buckled	0.00 F	*- F
7	3		*TAILGATE STICKERS	Torn	0.00 F	*- F
8	2		*TAILGATE SIDE BRACKET	Bent	0.00 F	*- F
9	1		*TAILGATE LOCK LATCH RH	Distorted	0.00 F	*- F
10	4		*TAILGATE HINGE	Bent	0.00 F	*- F
11	1		*SPARE TYRE BRACKET	*Check	0.00 F	*- F
F=Franchise part						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

SHENG LI LAI

No. 2 Kaki Bukit Avenue 2, #01-36 Kaki Bukit Autohub, Singapore 417921
Tel: 68420302 Fax: 67460295

Date : 15 February 2018
Name : ALUMNI CONSTRUCTION & TRADING PTE LTD
Address : C/O 2 KAKI BUKIT AVENUE 2
#01-36 KAKI BUKIT AUTOHUB
SINGAPORE 417921
Vehicle No. : GX7834E
Model : TOYOTA DYNA
Accident date : 8 May 2017

Final Repair Bill for Vehicle no. GX7834E

To supply labour and replaced parts, labour charges for
repairing, knocking-panel beating, welding and respray
(Lump Sum Repair)

\$ 9,500.00

Singapore Dollars: **NINE THOUSAND AND FIVE HUNDRED ONLY**

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: ALUMNI CONSTRUCTION & TRADING PTE LTD
c/o Sheng li Lai
2 Kaki Bukit Ave 2
01 - 36
Kaki Bukit Autohub
Singapore 417921

Invoice no.: TP17050011

Date: 13 FEB 2018

Vehicle no: GX 7834 E

Model : TOYOTA DYNA 150 D

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 30 May 2017 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 695.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
TOTAL :		\$ 695.00

Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.

Official Stamp

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the Rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : GX 7834 E

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

List Items

1pc	Tailboard with hinges	Bent/deformed	\$ 926.00	\$ <i>red</i> 926.00 ✓
1 pc	Tailboard lower member	Bent/distorted	\$ 289.90	\$ <i>red</i> 289.90 X
2 pcs	Tailboard lock	Damaged	\$ 228.00	\$ <i>red</i> 228.00 ✓
4 pcs	Tailboard rubber stopper	Warped/deformed	\$ 120.00	\$ <i>To. 1</i> 120.00 ✓
1pc	Sticker 'TOYOTA'	Essential	\$ 84.00	\$ <i>red</i> 84.00 ✓
1pc	Sticker 'DYNA'	Essential	\$ 27.70	\$ <i>red</i> 27.70 ✓
2 pcs	Side board	Damaged	\$ 2,500.00	\$ <i>red</i> 2,500.00 X
2 pcs	Side board lower member	Bent/distorted	\$ 850.00	\$ <i>red</i> 850.00 X
2 pcs	Taillamp	Base cracked	\$ 380.00	\$ <i>red</i> 380.00 ✓
2 pcs	Taillamp bracket	Dent/distorted	\$ 180.00	\$ <i>red</i> 180.00 ✓
1pc	Rear end cross member	Bent/distorted	\$ 458.00	\$ <i>red</i> 458.00 X
1 pc	Chassis frame	Bent	\$ 850.00	\$ <i>red</i> 850.00 X
1 pc	Spare tyre carrier	bent	\$ 563.10	\$ <i>red</i> 563.10 X
1 pc	Exhaust tail pipe	bent	\$ 691.80	\$ <i>red</i> 691.80 X
1 pc	Rear cross member tow hook	deformed	\$ 146.00	\$ <i>red</i> 146.00 X

	Parts Sub-Total	\$ 8,294.50	\$ 8,294.50
Discount	25.00%	\$ 2,073.63	\$ 2,073.63
		\$ 6,220.88	\$ 6,220.88

1945.7
1459.27

Vehicle Number : GX 7834 E

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

Special Nett Items

1pc	Sticker '10PAX'	Essential	\$ 35.00	\$ <i>red</i> 35.00 / 0
1pc	Sticker '60KM/H'	Essential	\$ 35.00	\$ <i>red</i> 35.00 / 0
1 pc	Number plate	damaged	\$ 45.00	\$ <i>red</i> 45.00 / 5
1 pc	Number plate base	necessary	\$ 65.00	\$ <i>red</i> 65.00 ✓
2 pcs	Rear number plate light	Essential	\$ 50.00	\$ <i>red</i> 50.00 ✓

Special Nett Sub-Total \$ 230.00 \$ 230.00

Spare Parts Total \$ 6,450.88 \$ 6,450.88

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
------	------------------	---------------------------	------------------------------

	Spare Parts	Total c/f	\$ 6,450.88	\$ 6,450.88	
1	Towing fees.	\$ 150.00	\$ 11	150.00	X
2	To mount vehicle on jig bench to assist chassis alignment.	\$ 350.00	\$ 11	350.00	X
3	To remove/supply aluminium casing for cargo deck assy.	\$ 2,000.00	\$ NA	2,000.00	X
4	To check wiring functions & conduct water leakage test.	\$ 150.00	\$	120.00	30
5	Labour charges to repair and panel beat the tailboard lower support, rear cargo deck and replace the above mentioned parts.	\$ 1,600.00	\$	1,400.00	800
6	To remove/ ^{refix} replace exhaust silencer.	\$ 120.00	\$	100.00	60
7	To putty, apply primer & spray-paint the affected areas.	\$ 1,400.00	\$	1,200.00	600
8	To apply rust-proofing on repaired/replaced panels.	\$ 180.00	\$	150.00	60
		Total	\$ 12,400.88	\$ 11,920.88	

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 9,500.00


Fong Kok Heng
Qualified Appraiser





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17010385/Urbs2-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 24-05-2018



ATTN: ANGIE GAN

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFG 700E	Veh. Inspected	GX 7834E
Policy No.	2100492332	Coverage (\$)	0.00
Claim No.	2469512186SG	Excess (\$)	0.00
Assign From	ANGIE GAN	Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA 150	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	JTFUF34Y303002686	Colour	BLUE
Odometer	309904	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14	BRIDGESTONE	5 mm
L/H Front Tyre	185 R14	BRIDGESTONE	5 mm
R/H Rear Tyre	155X R12 (D)	YOKOHAMA	5/5 mm
L/H Rear Tyre	155X R12 (D)	YOKOHAMA	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/05/2017	Inspection Date	30/05/2017
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 7834E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILBOARD WITH HINGES	BENT	926.00	926.00
1	TAILBOARD LOWER MEMBER	TO REPAIR SEE LABOUR	289.90	-
2	TAILBOARD LOCK	BENT	228.00	228.00
4	TAILBOARD RUBBER STOPPER	TORN	120.00	120.00
1	STICKER 'TOYOTA'	NECESSARY	84.00	84.00
1	STICKER 'DYNA'	NECESSARY	27.70	27.70
2	SIDE BOARD	TO REPAIR SEE LABOUR	2,500.00	-
2	SIDE BOARD LOWER MEMBER	TO REPAIR SEE LABOUR	850.00	-
2	TAILLAMP	CRACKED	380.00	380.00
2	TAILLAMP BRACKET	BENT	180.00	180.00
1	REAR END CROSS MEMBER	TO REPAIR SEE LABOUR	458.00	-
1	CHASSIS FRAME	TO REPAIR SEE LABOUR	850.00	-
1	SPARE TYRE CARRIER	TO REPAIR SEE LABOUR	563.10	-
1	EXHAUST TAIL PIPE	TO REPAIR SEE LABOUR	691.80	-
1	REAR CROSS MEMBER TOW HOOK	TO REPAIR SEE LABOUR	146.00	-
LESS 25% DISCOUNT			-2,073.62	-486.42
			6,220.88	1,459.28
<u>SPECIAL NETT ITEMS</u>				
1	STICKER '10PAX' (SN)	NECESSARY	35.00	10.00
1	STICKER '60KM/H' (SN)	NECESSARY	35.00	10.00
1	NUMBER PLATE (SN)	BENT	45.00	15.00
1	NUMBER PLATE BASE (SN)	BENT	65.00	65.00
2	REAR NUMBER PLATE LIGHT (SN)	NECESSARY	50.00	50.00
			230.00	150.00

Report Ref No. CS3/AIG17010385/Urbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOWING FEES.	NOT NECESSARY	150.00	-
	TO MOUNT VEHICLE ON JIG BENCH TO ASSIST CHASSIS ALIGNMENT.	NOT NECESSARY	350.00	-
	TO REMOVE / SUPPLY ALUMINIUM CASING FR CARGO DECK ASSY.	NOT NECESSARY	2,000.00	-
	TO CHECK WIRING FUNCTIONS & CONDUCT WATER LEAKAGE TEST.		150.00	30.00
	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE TAILBOARD LOWER SUPPORT, REAR CARGO DECK AND REPLACE THE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF TAILBOARD LOWER MEMBER, SIDE BOARD, SIDE BOARD LOWER MEMBER, REAR END CROSS MEMBER, CHASSIS FRAME, SPARE TYRE CARRIER, EXHAUST TAIL PIPE AND REAR CROSS MEMBER TOW HOOK.		1,600.00	800.00
	TO REMOVE / REFIX EXHAUST SILENCER.		120.00	60.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS.		1,400.00	600.00
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.		180.00	60.00
			5,950.00	1,550.00
	GRAND TOTAL		12,400.88	3,159.28
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00

Report Ref No. CS3/AIG17010385/Urb2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.