# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

From: LKK Auto Consultants Pte Ltd

Attn: Josey Loh Date: 07 Jun 2018

# **Preliminary Advice**

Insured Vehicle No : SJC3932G

TP Vehicle No : SLX1928Z Accident Date : 09/05/2018

Make : TOYOTA COROLLA ALTIS Assignment Date : 15/05/2018

Date of Inspection : 14/05/2018 Est. Duration of Repair : 30 days

Inspection At : Hwa Seng Spray Painting Co (160 SIN MING)

160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY

Singapore 575722

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages ....front and rear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	62,090.45
Revised Amount	:S\$	32,795.93
Check Items (Estimated)	:S\$	25,224.15
Total	:S\$	58,020.08

Lump Sum Repair :S\$

### **Total Loss Consideration**

(X) Other comments: We have not authorized repairs.

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.