

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 00361

Vehicle Details

Vehicle No.: SLX1928Z
Vehicle to be Exported: Yes
Intended De-registration Date: 14 May 2018
Vehicle Make: TOYOTA
Vehicle Model: TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour: Black
Manufacturing Year: 2015
Engine No.: 1ZR532561
Chassis No.: MR053REH104539371
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,589.00
Original Registration Date: 10 Mar 2016
First Registration Date: 10 Mar 2016
Transfer Count: 1
Actual ARF Paid: \$19,589.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 09 Mar 2026
PARF Rebate Amount: \$14,691.00

Intended COE Rebate Details

COE Expiry Date: 09 Mar 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$43,000.00
COE Rebate Amount: \$33,608.00
Total Rebate Amount: \$48,299.00

The information contained herein is correct as at 09 May 2018

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CC4/FWD18008831/Kea3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 15-05-2018



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJC 3932G	Veh. Inspected	SLX 1928Z
Policy No.		Coverage (\$)	0.00
Claim No.	1201800005723	Excess (\$)	0.00
Assign From		Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/05/2018	Inspection Date	14/05/2018
Survey held at	HWA SENG SPRAY PAINTING COMPANY 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

ke

21

HWA SENG SPRAY PAINTING CO

1 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

DATE OF

ACCIDENT: 09/05/2018

YOUR INSURED

VEHICLE NO: SJC 39 32 G

Not Notified
Cl Long 831,800/-
Assessing After Repair

32 days

Estimate repair cost to TOYOTA ALTIS reg no: SLX 1928 Z

- 1pc bootlid SS
- 2pcs bootlid hinges (SS60.20/pc)
- 1pc bootlid rubber
- 1pc bootlid upper lock
- 1pc bootlid lower lock
- 1pc bootlid chrome
- 2pcs bootlid reflector (SS325.10/pc)
- 1pc bootlid lock cable
- 1pc logo emblem
- 1pc emblem 'corolla'
- 1pc emblem 'Altis'
- 2pcs rear number plate lamp (SS62.90/pc)
- 2pcs taillamp assy (SS281.90/pc)
- 1pc end panel
- 1pc spare tyre panel
- 1pc rear rear floor panel
- 2pcs taillamp panel (SS168.20/pc)
- 1pc rear bumper
- 2pcs rear bumper retainer (SS104.40/pc)
- 2pcs rear bumper bracket (SS41.70/pc)
- 2pcs taillamp lower bracket (SS62.70/pc)
- 2pcs rear panel side (SS1029.70/pc)
- 2pcs rear panel corner (SS111.60/pc)
- 1pc rear bumper reinforcement
- 2pcs rear absorber (SS187.10/pc)
- 1pc rear axle beam
- 2pcs rear bearing hub (SS637.40/pc)
- 1pc speaker board
- 1pc end panel garnish
- 1pc spare tyre board
- 2pcs rear bumper reflector (SS36.70/pc)
- 1pc o/s/r panel inner trim
- 1pc n/s/r panel inner trim
- 1pc n/s/r panel ducting
- 2pcs rear panel inner shield (SS49.80/pc)
- 1pc o/s/r pillar inner trim
- 1pc n/s/r pillar inner trim
- 2pcs rear door striker (SS64.30/pc)
- 1pc exhaust pipe
- 1pc exhaust pipe mounting
- 1pc exhaust pipe bush

Ry	655.50	✓
R RT	120.40	X
D1/T1	166.40	✓
Rd	382.10	✓
D1/T1	24.40	✓
Ways	248.30	✓
CRT	650.20	✓
Sn	53.10	X
Rn	52.20	✓
Rn	42.40	✓
Rn	44.10	✓
Rn	125.80	X
CRT	563.80	✓
Ry	581.20	✓
Rt/Rn	802.90	✓
Ry	845.00	✓
Ry	336.40	✓
Ry	482.00	✓
CRT	208.80	✓
Ry	83.40	✓
CRT	125.40	✓
Rn	2059.40	✓
Rn	223.20	✓
Ry	361.60	✓
Ry	374.20	✓
Sn	2347.10	X
Sn	1274.80	X
Rn	692.80	X
Rd	229.40	✓
CRT	349.30	✓
Sn	73.40	X
Reloun	415.20	✓
7	415.20	✓
CRT	124.70	✓
Sn	99.60	X
Rn	353.50	X
Rn	353.50	X
Rn	128.60	✓
Ry	865.70	X
Sn	37.10	X
Rn	18.10	X
17390.20		

HWA SENG SPRAY PAINTING CO

2 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

c/f		17390.20	
1pc bonnet		R ₂ 1028.10	✓
2pcs bonnet hinges (S\$50.10/pc)		R ₂ 100.20	✓
1pc bonnet lock		R ₂ 128.90	✓
1pc bonnet cable		T _m 59.50	✓
2pcs headlamp (S\$2009.60/pc)		R ₂ 4019.20	✓
1pc front grille		R ₂ 559.60	✓
1pc front grille emblem		R ₂ 43.10	✓
1pc support panel		R ₂ 977.60	✓
1pc bridge panel		R ₂ 103.10	✓
1pc front cross member		R ₂ 1925.30	X
1pc front bumper		C _M 458.10	✓
1pc front bumper reinforcement		R ₂ 379.20	✓
1pc front bumper sponge		R ₂ 91.10	X
2pcs front bumper fog lamp (S\$ 256.90/pc)		c/s C _M 513.80	✓
2pcs front bumper fog lamp cover (S\$88.90/pc)		ol ₁ 177.80	✓
1pc front bumper lower grille		R ₂ 139.30	X
2pcs front fender (S\$716.60/pc)		R ₂ 1433.20	✓
2pcs front fender inner shield (S\$163.40/pc)		c/s ? R ₂ 326.80	X
2pc front fender emblem (S\$ 41.70/pc)		R ₂ 83.40	✓
2pcs front wheel house (S\$423.30/pc)		c/s R ₂ 846.60	✓
3pcs horn (S\$110.90/pc)		R ₂ 332.70	✓
1pc radiator assy		R ₂ 1764.00	✓
1pc radiator motor		T _m 439.30	✓
1pc radiator cowl		R ₂ 246.90	✓
1pc radiator fan blade		C _M 149.10	✓
1pc air con condenser		R ₂ 1404.40	✓
1pc alternator		R ₂ 2628.10	✓
1pc wiper tank		R ₂ 121.60	✓
1pc wiper tank motor		R ₂ 228.80	X
1pc air con discharge pipe		R ₂ 365.10	✓
1pc air con inlet pipe		R ₂ 663.80	✓
1pc coolant tank		R ₂ 168.90	✓
1pc radiator cap		R ₂ 37.60	✓
1pc bonnet stand		R ₂ 53.30	✓
1pc engine mounting front		C _M 188.80	✓
1pc engine mounting left		C _M 268.90	✓
1pc engine mounting right		C _M 423.90	✓
1pc engine mounting rear		C _M 254.80	✓
		40524.10	

HWA SENG SPRAY PAINTING CO

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

3 of 4

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

c/i

40524.1

1pc ABS pump	SS
1pc air cleaner box	
1pc air cleaner chamber	
1pc air flow sensor	
1pc air intake hose	
1pc ECU unit	
1pc fuse box	
1pc ABS pipe	
1pc intake manifold	
1pc exhaust manifold	
1pc air cleaner house mounting	
1pc engine wire hardness	
1pc front engine mounting bracket	
1pc rear engine mounting bracket	
1pc right engine mounting bracket	
1pc left engine mounting bracket	
1pc brake master pump	
1pc brake booster	
1pc engine valve cover	
1pc engine top cover	
4pcs engine top cover mounting (S\$18.40/pc)	
1pc water pump	
1pc manifold gasket	
4pcs engine injector (S\$266.70/pc)	
1pc engine injector fuel rail pressure pipe	
1pc throttle body	
1pc air reservoir intake pipe	
1pc water hose top	
1pc water hose lower	
1pc water adaptor	
1pc thermostat housing	
2pcs air bag sensor (S\$284.80/pc)	

Less 25%

CM	5245.70	✓
CM	888.20	✓
2.1	133.10	✓
1m	537.60	X
5m	1087.00	X
10	2981.60	✓
CM	528.70	✓
DIY 10	728.70	✓
CM	833.90	✓
1m	923.70	X
1m	248.90	X
1m	3672.20	X
0.1	182.80	✓
0.1	76.40	✓
DIY	192.80	✓
1m	120.80	✓
1m	567.70	X
1m	1898.80	X
1m	541.30	X
CM	328.70	✓
1m	73.60	X
1m	326.30	X
1m	49.80	X
5m	1066.80	X
5m	388.20	X
5m	1835.90	X
5m	128.70	X
1m	46.80	✓
5m	61.70	X
5m	54.90	X
10	115.60	✓
CM	569.60	✓
	66960.6	
	16740.15	
	50220.45	

HWA SENG SPRAY PAINTING CO

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 095744008)

TEL: 64533100

FAX: 62669932

4 of 4

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

c/f


50220.45

Labour & misc charges

Labour to remove and install rear windscreen
Sealant & clip
Inner seal
Labour to remove and install upholstery and roof lining
Vaccum and top up air con gas
Panel knocking
Spray painting
Tuff kote
Wire checkin front and rear
Labour to remove and install engine to facilitate
repair and rear undercarriage
Reprogramme the air bag sensor
Refix exhaust pipe
Towing service (King Dolly)
1pc reverse camera
2 set of number plate and casing (\$555.00/pc)
Labour to remove and install petrol tank
1 set reverse sensor

	160.00	1201
Me	80.00	401a
Me	60.00	301a
	550.00	1201
	160.00	1001
	4300.00	36001
	3500.00	28001
	450.00	3001
	200.00	801
	800.00	2401
	280.00	1501
	160.00	801
(Bill)	160.00	1201
Me	380.00	801
Me	110.00	901a
	160.00	801
Tr	360.00	2001a
	62090.45	

HWA SENG SPRAY PAINTING CO



14/05/2018



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey belowwater spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SELL YOUR CAR BY BIDDING

HIGHEST SELLING PRICE GUARANTEED!

OR GET \$100 CASH!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coo Renewal Toyota Yios 1.5A



10000 Downpayment Monthly
From \$1000 onwards, 1 year
3.8% KAMBA Car Financing
GV Credit Pte Ltd



Think One Automobile



Browse by Category

« Back (1 2 3) Next »

Sort by Date Posted

20 results/page

49 vehicles

Toyota altis

Advanced Search



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota altis	Any	Any	2016	Any	Any	Any	Available

**Toyota Corolla Altis 1.6A****\$75,800**

\$8,640 /yr

16-Feb-2016

1,598 cc

-

Sedan

Available

Guaranteed Good Condition! Can Send To Borneo Or STA For Checking! \$0 Down Payment Available! We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Cost! In House Loan Or Bank Loan Available...

88 Motor Trading

Posted: 14-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

**Toyota Corolla Altis 1.6A****\$80,800**

\$9,200 /yr

04-Mar-2016

1,598 cc

25,000 km

Sedan

Available

1 Owner, Very Low Mileage Done At 25,000km Only! Accident Free, Solely Service By Borneo Motor, 5 Years Borneo Warranty, Road Tax Till March 2019, Like New Condition! Buy With Confidence! In House Fina...

Horizon Motoring

Posted: 14-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

**Toyota Corolla Altis 1.6A Elegance****\$82,800**

\$9,300 /yr

21-Mar-2016

1,598 cc

35,000 km

Sedan

Available

Accredited Company! As Good As New, 1 Owner, Full Agent Serviced With Receipt And Borneo Motor 5 Years Warranty, Accident Free. Low Mileage And Taken Care By Careful Owner, Buy And Drive With Peace Of...

Fu Yip Motor Trading

Posted: 14-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

**Toyota Corolla Altis 1.6A Elegance****\$81,800**

\$9,150 /yr

28-Mar-2016

1,598 cc

36,000 km

Sedan

Available

1 & Only Owner, Non Uber/Grab/Rental Car! Low Mileage! Excellent Condition! Like Brand New! High Specs Model Comes With Full GPS, Bluetooth, DVD Touch Screen, Reverse Camera! Original Sports Rims! Key...

Ka-Hup Vehicles Trading

Posted: 13-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

Car Buying


Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

**Toyota Corolla Altis 1.6A****\$75,800**

\$8,270 /yr

07-Jul-2016

1,598 cc

13,284 km

Sedan

Available

\$0 Down Payment Drive Away! Still Under Warranty By Borneo Motors! Like Brand New Car Condition With No Repair Needed! Low Fuel Consumption, Low Maintenance! High Trade In For Your Car! Kindly Call Our...

Benefit Auto Enterprise Pte Ltd

Posted: 13-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

**Toyota Corolla Altis 1.6A Elegance****\$76,800**

\$8,590 /yr

03-Mar-2016

1,598 cc

57,375 km

Sedan

Available

Promotional 1.99% Interest Rate! Elegance Model! Comes With Driver Side Electric Seats And Push Start! One Owner Only! Still Under Warranty! 1.99% Bank Interest Rate Available! Call For A Viewing Appo...

Mayfair Motoring

Posted: 12-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

Toyota Corolla Altis 1.6A Elegance**\$80,000**

\$8,810 /yr

03-May-2016

1,598 cc

30,500 km

Sedan

Available

age For Home Use Only, Maintained By Borneo Motors Only, Never Been Overseas To Malaysia, Grey Metallic Colour, Good Condition,

Compare



Posted: 12-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$87,800

\$9,020 /yr

28-Dec-2016

1,598 cc

25,879 km

Sedan

Available

Graded **A** by **STP**

One Owner. Definitely Not A Rental Car. Genuine Mileage. Excellent Condition. Fully Agent Service Records. 5 Years Warranty From Borneo Motors. Buy With A Peace Of Mind From Award Accredited Company. ...

Autolink Holdings Pte Ltd

Posted: 12-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$76,800

\$8,390 /yr

08-Jul-2016

1,598 cc

63,148 km

Sedan

Available

Full Agent Serviced With Receipt And Borneo Motor 3 Years Warranty, Accident Free. Taken Care By Careful Owner, Trade In Welcomed, Bank Loan Available With Flexible Interest Rates, 0-10% Deposit Drive...

Posted: 12-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$77,800

\$8,290 /yr

26-Sep-2016

1,598 cc

14,120 km

Sedan

Available

In House Loan To 95% Available! Serviced At Borneo With Valid Warranty, Last On Feb 18. Low Mileage Done 14120km! Tip Top Condition, View To Believe. 100% Accident Free. Price Negotiable. Call Now!

Lake View Credit Pte Ltd

Posted: 12-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Let's help you 2888 K7

Many auspicious and rare car plates for sale at a good price! Get lucky today with our Bidded car plate numbers for sale!

Find out more!



Toyota Corolla Altis 1.6A Elegance

\$78,800

\$8,550 /yr

01-Jun-2016

1,598 cc

47,000 km

Sedan

Available

1 Owner, High PARF Value Of \$9,995, Bank Loan Available, Please Call For Viewing, Price Negotible, Don't Miss, Good Condition, Well Maintenance.

Posted: 12-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$78,800

\$8,710 /yr

14-Jun-2016

1,598 cc

13,166 km

Sedan

Available

\$0 Down Payment Drive Away! New Arrival Superb Conditions Inside Out. Smooth And Reliable For Point To Point Driving. Spacious And Luxury With Lots Of Leg Space And Large Boot Space.

Benefit Auto Enterprise Pte Ltd

Posted: 12-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$81,800

\$9,190 /yr

16-Mar-2016

1,598 cc

34,000 km

Sedan

Available

1 Owner Unit! Fully Agent Service By Borneo With Warranty, No Gimmicks! Price Negotiable, Low Mileage Done, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Buy From Us ...

Hue Yang Credit Pte Ltd

Posted: 11-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$79,999

\$8,940 /yr

21-Mar-2016

1,598 cc

19,959 km

Sedan

Available

No Gimmicks! Price Negotiable, Low Mileage 19959Km, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call Now For Viewing.

Posted: 11-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$79,800

\$8,530 /yr

26-Sep-2016

1,598 cc

20,158 km

Sedan

Available

\$0 Drive Away, 100% Loan Inclusive Of Insurance. Excellent Fuel Economy And Easy Handling, Flexible Loan Available, Non Smoker Car. Trade In Welcome. Price Negotiable, Call Or Visit Our Showroom Now F...

Posted: 11-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$79,800

\$8,580 /yr

09-Sep-2016

1,598 cc

18,650 km

Sedan

Available

\$0 Driveaway, 100% Loan Inclusive Of Insurance. Tip Top Condition, Excellent Fuel Economy And Easy Handling, Flexible Loan Available, Non Smoker Car, Trade In Welcome. Price Negotiable, Flexible Loan ...

Posted: 11-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$76,800

\$8,360 /yr

18-Jul-2016

1,598 cc

13,000 km

Sedan

Available

\$0 Down Payment Drive Away! High Trade In! High Over Trade! Full Agent Maintained Still Under Warranty. Buy With Peace Of Mind! Call Now For fo!

Auto Enterprise Pte Ltd

Posted: 11-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

**Toyota Corolla Altis 1.6A Elegance****\$79,800****\$8,640 /yr****22-Jun-2016****1,598 cc****52,000 km****Sedan****Available**

Accredited Company! As Good As New, Full Agent Serviced With Borneo Motor 5 Years Warranty, Accident Free. Low Mileage And Taken Care By Careful Owner, Buy And Drive With Peace Of Mind. Guarantee Low ...

Fu Yip Motor Trading

Posted: 11-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

**Toyota Corolla Altis 1.6A****\$85,800****\$8,790 /yr****28-Dec-2016****1,598 cc****-****Sedan****Available**

Up To 90% Loan! Flexible Repayment With In House Financing. All Vehicle Inspected By Our Professional Team For Highest Quality With Opt Extended Warranty Available. Owning A Car Is So Much Easier With...

Universe Motoring

Posted: 10-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

**Toyota Corolla Altis 1.6A Elegance (OPC)****\$71,999****\$7,410 /yr****27-Sep-2016****1,598 cc****10,263 km****Sedan****Available**

No Gimmicks! Price Negotiable, Low Mileage 10263km, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call Now For Viewing.

Posted: 09-May-2018 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Photo Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

• Back (1 2 3) Next •

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota altis, Toyota altis Singapore, used Toyota altis Singapore, used Toyota altis, used vehicles Singapore or even buy used Toyota altis Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

HWA SENG SPRAY PAINTING CO

1 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

*Not Notified
11 Days & ?
Resuming After Paint*

DATE OF
ACCIDENT: 09/05/2018

YOUR INSURED

VEHICLE NO: SJC 3932G

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

1pc bootlid	S\$
2pcs bootlid hinges	(S\$60.20/pc)
1pc bootlid rubber	
1pc bootlid upper lock	
1pc bootlid lower lock	
1pc bootlid chrome	
2pcs bootlid reflector	(S\$325.10/pc)
1pc bootlid lock cable	
1pc logo emblem	
1pc emblem 'corolla'	
1pc emblem 'Altis'	
2pcs rear number plate lamp	(S\$62.90/pc)
2pcs taillamp assy	(S\$281.90/pc)
1pc end panel	
1pc spare tyre panel	
1pc rear rear floor panel	
2pcs taillamp panel	(S\$168.20/pc)
1pc rear bumper	
2pcs rear bumper retainer	(S\$104.40/pc)
2pcs rear bumper bracket	(S\$41.70/pc)
2pcs taillamp lower bracket	(S\$62.70/pc)
2pcs rear panel	(S\$1029.70/pc)
2pcs rear panel corner	(S\$111.60/pc)
1pc rear bumper reinforcement	
2pcs rear absorber	(S\$187.10/pc)
1pc rear axle beam	
2pcs rear bearing hub	(S\$637.40/pc)
1pc speaker board	
1pc end panel garnish	
1pc spare tyre board	
2pcs rear bumper reflector	(S\$36.70/pc)
1pc o/s/r panel inner trim	
1pc n/s/r panel inner trim	
1pc n/s/r panel ducting	
2pcs rear panel inner shield	(S\$49.80/pc)
1pc o/s/r pillar inner trim	
1pc n/s/r pillar inner trim	
2pcs rear door striker	(S\$64.30/pc)
1pc exhaust pipe	
1pc exhaust pipe mounting	
1pc exhaust pipe bush	

Rt	655.50	✓
Rt	120.40	x
D11/4	166.40	✓
Rt	382.10	✓
D11/4	24.40	✓
Wap	248.30	✓
CM	650.20	✓
	53.10	?
Rt	52.20	✓
Rt	42.40	✓
Rt	44.10	✓
	125.80	?
CM	563.80	✓
Rt	581.20	✓
Rt/Rn	802.90	✓
	845.00	?
Rt	336.40	✓
Rt	482.00	✓
CM	208.80	✓
Rt	83.40	✓
CM	125.40	✓
Rn	2059.40	✓
Rn	223.20	✓
Rt	361.60	✓
	374.20	?
	2347.10	?
	1274.80	?
	692.80	?
Rn	229.40	✓
CM	349.30	✓
Rn	73.40	x
	415.20	?
	415.20	?
	124.70	?
	99.60	?
	353.50	?
	353.50	?
Rn	128.60	✓
Rt	865.70	?
	37.10	?
	18.10	?
	17390.20	

HWA SENG SPRAY PAINTING CO

2 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

c/f		17390.20	
1pc bonnet		R ₁ 1028.10	✓
2pcs bonnet hinges (S\$50.10/pc)		R ₂ 100.20	✓
1pc bonnet lock		R ₂ 128.90	✓
1pc bonnet cable		T _m 59.50	✓
2pcs headlamp (S\$2009.60/pc)		R ₂ 4019.20	✓
1pc front grille		M ₁ 559.60	✓
1pc front grille emblem		M ₁ 43.10	✓
1pc support panel		R ₂ 977.60	✓
1pc bridge panel		R ₂ 103.10	✓
1pc front cross member		1925.30	?
1pc front bumper		C _M 458.10	✓
1pc front bumper reinforcement		379.20	?
1pc front bumper sponge		91.10	?
2pcs front bumper fog lamp (S\$ 256.90/pc)		C/S C _M 513.80	✓
2pcs front bumper fog lamp cover (S\$88.90/pc)		C/S M ₁ 177.80	✓
1pc front bumper lower grille		139.30	?
2pcs front fender (S\$716.60/pc)		R ₂ 1433.20	✓
2pcs front fender inner shield (S\$163.40/pc)		C/S ? 326.80	
2pc front fender emblem (S\$ 41.70/pc)		M ₂ 83.40	✓
2pcs front wheel house (S\$423.30/pc)		C/S R ₂ 846.60	✓
3pcs horn (S\$110.90/pc)		R ₂ 332.70	✓
1pc radiator assy		R ₂ 1764.00	✓
1pc radiator motor		T _m 439.30	✓
1pc radiator cowl		R ₂ 246.90	✓
1pc radiator fan blade		C _M 149.10	✓
1pc air con condenser		R ₂ 1404.40	✓
1pc alternator		2628.10	?
1pc wiper tank		R ₂ 121.60	✓
1pc wiper tank motor		228.80	?
1pc air con discharge pipe		R ₂ 365.10	✓
1pc air con inlet pipe		R ₂ 663.80	✓
1pc coolant tank		R ₂ 168.90	✓
1pc radiator cap		R ₂ 37.60	✓
1pc bonnet stand		M ₁ 53.30	✓
1pc engine mounting front		188.80	?
1pc engine mounting left		268.90	?
1pc engine mounting right		423.90	?
1pc engine mounting rear		254.80	?
		40524.10	

HWA SENG SPRAY PAINTING CO

3 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

c/f		40524.1
1pc ABS pump	S\$	<i>CM</i> 5245.70 ✓
1pc air cleaner box		<i>CM</i> 888.20 ✓
1pc air cleaner chamber		<i>2.1</i> 133.10 ✓
1pc air flow sensor		537.60 ?
1pc air intake hose		1087.00 ?
1pc ECU unit		2981.60 ?
1pc fuse box		528.70 ?
1pc ABS pipe		<i>DIY 100</i> 728.70 ✓
1pc Intake manifold		<i>CM</i> 833.90 ✓
1pc exhaust manifold		923.70 ?
1pc air cleaner house mounting		248.90 ?
1pc engine wire hardness		3672.20 ?
1pc front engine mounting bracket		182.80 ?
1pc rear engine mounting bracket		76.40 ?
1pc right engine mounting bracket		192.80 ?
1pc left engine mounting bracket		120.80 ?
1pc brake master pump		567.70 ?
1pc brake booster		1898.80 ?
1pc engine valve cover		<i>CM</i> 541.30 ✓?
1pc engine top cover		<i>CM</i> 328.70 ✓
4pcs engine top cover mounting (S\$18.40/pc)		73.60 ?
1pc water pump		326.30 ?
1pc manifold gasket		49.80 ?
4pcs engine injector (S\$266.70/pc)		1066.80 ?
1pc engine injector fuel rail pressure pipe		388.20 ?
1pc throttle body		1835.90 ?
1pc air reservoir intake pipe		128.70 ?
1pc water hose top		<i>PM</i> 46.80 ✓
1pc water hose lower		61.70 ?
1pc water adaptor		54.90 ?
1pc thermostat housing		115.60 ?
2pcs air bag sensor (S\$284.80/pc)		<i>CM</i> 569.60 ✓
		66960.6
	Less 25%	16740.15
		50220.45

HWA SENG SPRAY PAINTING CO

4 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 095744008)

TEL: 64533100

FAX: 62669932

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

c/f

50220.45

Labour & misc charges

Labour to remove and install rear windscreen
Sealant & clip
Inner seal
Labour to remove and install upholstery and roof lining
Vaccum and top up air con gas
Panel knocking
Spray painting
Tuff kote
Wire checkin front and rear
Labour to remove and install engine to faciliate
repair and rear undercarriage
Reprogamme the air bag sensor
Refix exhaust pipe
Towing service (King Dolly)
1pc reverse camera
2 set of number plate and casing (\$55.00/pc)
Labour to remove and install petrol tank
1 set reverse sensor

	160.00	1201
me	80.00	405m
me	60.00	305m
	550.00	1201
	160.00	1001
	4300.00	36001
	3500.00	28001
	450.00	3001
	200.00	801
	800.00	2401
	280.00	1501
	160.00	801
(Bill)	160.00	?
	380.00	?
me	110.00	905m
	160.00	801
Tr	360.00	2005m
	62090.45	

HWA SENG SPRAY PAINTING CO



14/05/2018

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 07 Jun 2018

Preliminary Advice

Insured Vehicle No	: SJC3932G		
TP Vehicle No	: SLX1928Z	Accident Date	: 09/05/2018
Make	: TOYOTA COROLLA ALTIS	Assignment Date	: 15/05/2018
Date of Inspection	: 14/05/2018	Est. Duration of Repair	: 30 days
Inspection At	: Hwa Seng Spray Painting Co (160 SIN MING) 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesfront and rear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	62,090.45
Revised Amount	:S\$	32,795.93
Check Items (Estimated)	:S\$	25,224.15
Total	:S\$	58,020.08

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 19 June 2018 9:24 AM
To: 'Painter Hsh'
Cc: Admin A
Subject: RE: Date of accident 09/05/2018 at Flyover Towards Jurong Island Exit (AYE) involving car number SLX 1928 Z & SJC 3932 G (FWD Ref: 1201800005723)

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Painter Hsh [<mailto:hsh.painter@yahoo.com>]

Sent: Monday, 14 May, 2018 10:22 AM

To: Motor Claims SG - SG Common

Subject: Re: Date of accident 09/05/2018 at Flyover Towards Jurong Island Exit (AYE) involving car number SLX 1928 Z & SJC 3932 G (FWD Ref: 1201800005723)

Dear josey,

Kindly arrange LKK Auto Consultant Pte Ltd.

Thank you.

hwee boon
hwa seng spray painting co.
hp.98630678

On Monday, May 14, 2018 10:05 AM, "motorclaims.sg@fwd.com" <motorclaims.sg@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Hwee Boon,

We refer to your letter dated 14 May 2018 of the PRI Notice of your client's vehicle SLX1928Z.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 5 year plan available online. Limited time offer!	 2.02% p.a. fwd.com.sg save now
--	--	---

From: Painter Hsh [mailto:hsh.painter@yahoo.com]

Sent: Monday, 14 May, 2018 9:58 AM

To: Motor Claims SG - SG Common

Cc: Clara Li Zirong - SGUser

Subject: Date of accident 09/05/2018 at Flyover Towards Jurong Island Exit (AYE) involving car number SLX 1928 Z & SJC 3932 G

Dear sir,

Your insured vehicle no : SJC 3932 G

Kindly arrange your surveyor to conduct survey
on vehicle SLX 1928 Z

Attach with GIA report , LTA search , estimate and insurance cert.

We are look at direct settlement.

Please let us have your list of surveyor

hwee boon
hwa seng spray painting co
hp 98630678

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Claim Audit

AUDIT TRAIL

No.	On	Action	Remarks	By
1	15 May 2018 18:47	Cim Veh Model Changed	(204763) TOYOTA COROLLA ALTIS 1.6 L CVT (A).	[A] HOW MEI KWAN
2	15 May 2018 18:47	Cim Created	Reg No: SLX1928Z, Acct Date: 2018/05/09, Claim Type: TP, Insurer: FWD Singapore Pte. Ltd. (HQ), TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Workshop: Hwa Sen g Spray Painting Co (160 SIN MING)	[A] HOW MEI KWAN
3	15 May 2018 18:47	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):: RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : VICOM Ltd.	[A] HOW MEI KWAN
4	15 May 2018 18:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/24	[A] HOW MEI KWAN
5	15 May 2018 18:47	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
6	15 May 2018 18:49	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] HOW MEI KWAN
7	16 May 2018 10:26	Cim Registration Modified	Poi No:->PNPV2017-00000559-01.	[I] Josey Loh
8	16 May 2018 10:27	Cim Registration Modified	Excess: -> 500.00.	[I] Josey Loh
9	07 Jun 2018 11:44	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/05/24	[A] HOW MEI KWAN
10	11 Sep 2018 09:45	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
11	11 Sep 2018 09:45	Cim Dtl Modified	JPJ Reg. Date: -> 2016/03/10.	[A] JOANNE LEE KHANG MIN
12	11 Sep 2018 09:45	Cim Details Notified		[A] JOANNE LEE KHANG MIN
13	15 Sep 2018 14:00	Label Added	(20005):Direct Settlement .	[A] Asher Sng Rong Yi
14	15 Sep 2018 14:08	Adj Mandate Request	Cur.Req:35607.45:LIABILITY: 100% B:28 4VEH CC OID 3RD QUANTUM: (a) COR : \$31,800.00 + (b) LOR : \$3,800.00 (38days x \$100) + (c) LTA : \$7.45 Total: a+b+c = \$35,607.45 PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

[15/09/2018 14:09] Asher Sng Rong Yi:
MARKET VALUE: \$80,500
LTA REBATE: \$48,299
NETT VALUE: \$32,201

Merimen Billing for this case - Transaction History

Invoice No	Bill Date	Bill Type	Bill Month	Bill Name (Bill to)	Ref 1	Ref 2	Amount
1826607	07/06/2018 11:44	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLX1928Z	SJC3932G	10.70

Print Received Message

This mail is associated with :

***SLX1928Z (1201800005723)**
[SJC3932G]

TP

ANG WEE KIAN

May 9 2018 8:00AM

[Chen Way Yen]

Hwa Seng Spray Painting Co

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 16/10/2018 10:59 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$35607.45) - SLX1928Z - Claim Handler: Clara Li Zi Rong

Approved:35607.45.

Date: 9/5/2018

Ang Wee Kian
16/11 Sim Ming Drive
#05-11 Sim Ming Arcade
Singapore 578722

Attn: Motor Claim Department

Your Ref:

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986

Dear Sirs/Madam,

DIRECT SETTLEMENT

Accident on 04/05/2018 involving Vehicle No. SLX 19282 & SJC 39326
At Flyover Towards Jurong Island Exit (AYE)

I/We refer to my/our letter date

Arising out of the above accident, as a assessment on the damaged to my/our Vehicle No. SLX 19282 was being conducted by your appointed panel surveyor.

Due to the negligence/fault of your insured/driver of Vehicle No. SJC 39326, I/We am/are now claiming against you for the repair and other consequential suffered by me/us.

For the purpose of a amicable settlement, I/We quantified my/our claim as follows:-

a) Cost of repair at	S\$ 31,800.00
b) Loss of use for <u>49</u> days at rate of (<u>\$150 per day</u>)	S\$ 7,350.00
c) Police/ROV Fee	S\$
d) Others <u>LTA Search Fee</u>	S\$ 7.45

Total Cost


S\$ 39,157.45

I/We enclose herewith copies of all relevant documents for your perusal.

Kindly also direct all correspondence or liase with my Repairer's Messrs Hwa Seng Spray Painting Co. relating to the said accident without any further reference to me/us.

Thanking you and awaiting your favourable response.

Yours Faithfully



* 2 days waiting surveyor to conduct survey
* 8 Sundays
* 2 Public Holidays
* 10 days for parts to arrive from Thailand

LETTER OF AUTHORIZATION

To Whom It May Concern

Accident on 09/05/2018 involving SLX 1928Z and SJC3932G
along Flyover Towards Jurong
Island Exit (AYE)

I/We Ang Wee Kian NRIC No. S71000036I
of Blk 17A Telok Blangah Crescent #16-266, Spore 091017
Owner of Motor Vehicle Registration No. SLX 1928Z insured by _____
of AIK Asia Pacific Insurance Aetd under Policy No. 1802135803
do hereby authorize M/s Hwa Seng Spray Painting Co.
as my/our representative with full authority to write, negotiate and settle claim
for damages on my/our behalf against the owner and/or driver of
Motor Vehicle No. SJC 3932G in regard to the abovementioned accident.

I/We also consent to the agreed settlement sum be made in favour of my/our
representative, M/s Hwa Seng Spray Painting Co. and
the said payment be forwarded to them to be construed as full and final discharge of
my/our claim.


Owner Signature & Company Stamp

Date : 9/5/18

RELEASE

Claim Reference:	1201800005723
Surveyor's Reference:	CC4/FWD18008831/Kea3
TP Reference:	SLX 1928Z

We, HWA SENG SPRAY PAINTING COMPANY ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle SLX 1928Z ("Vehicle") to accept the sum of \$35,607.45, being the amount claimed for \$31,800.00 (repair costs), \$3,800.00 (loss of rental/ use), \$ - (loss of income), \$7.45 (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 09/05/2018 (date of accident) at / along FLYOVER TOWARDS JURONG ISLAND EXIT (AYE) (location) involving vehicle no/s. SLX 1928Z and SJC 3932G.

This is pursuant to the inspection conducted on 14/05/2018 (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of SJC 3932G be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 30 day of OCT 2018

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]
For and on behalf of the "Claimant"



ksc
[FWD's appointed surveyor with Co. Stamp]
For and on behalf of FWD Singapore Pte. Ltd.

HWA SENG SPRAY PAINTING CO.

160 Sin Ming Drive, #05-11, Sin Ming Autocity
Singapore 575722
Tel No. : 64533100 Fax No. : 62669932
Buss. Reg. No. : 095744/00B

ANG WEE KIAN
BLK 17A TELOK BLANGAH CRESCENT, #16-28B
091017

Attention : Motor Claim Department
Contact : 92980257

Final Repair Bill : H00032

Date : 28/07/2018
Vehicle Num. : SLX 1928 X
Make/Model : TOYOTA ALTIS
Chassis/Eng# :
Accident Date : 09/05/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		On lump sum basis repair inclusive of spare parts, panel knocking, spray paint and misc charges		31,800.00
		Labour Total S\$:		31,800.00

E. & O.E.

Total S\$: 31,800.00



for HWA SENG SPRAY PAINTING CO.



RICA LEASING PTE LTD

Co Reg No. 200610430K

Registered Address:
125 Joo Sang Road #05-12 Gold Pine Industrial Building
Singapore 380355

Operation Address:
160 Sin Ming Drive, #06-05 Sin Ming AutoCity
Singapore 575722 Tel: 6266 2307 Fax: 6265 2308

VEHICLE RENTAL AGREEMENT

STA No. 25985

HIRER'S PARTICULAR		Veh No: <u>SLD 6674C</u>		Replace Veh No:	
Name: (as in IC) <u>Ang Wei Kian</u>		Mileage Out: <u>2906</u>		Mileage Out:	
NRIC / PASSPORT No: <u>S70000361</u>		Make & Model: <u>Toyota</u>		Make & Model:	
Address (Res): <u>Block 17A Telok Blangah</u>		Auto / Manual: <u>Auto</u>		Auto / Manual:	
<u>Orchard #16-266 Singapore 091017</u>		OUT: Date: <u>9/5/18</u>		OUT: Date:	
Name & Address of Employer:		OUT: Time: <u>10.30am</u>		OUT: Time:	
Occupation: Driving Exp:		RENTAL CHARGES			
D/L No: D/L Type: Local/International		Daily <u>49</u> @ \$150/		\$7,350.00	
Pass Date: <u>07-08-1995</u> Date of Birth: <u>03-01-1970</u>		Weekly @ \$			
Tel: (C) (F) HP/PG		Monthly @ \$			
ADDITIONAL DRIVER'S PARTICULARS		Hours @ \$			
Name: (as in IC)		Others @ \$			
NRIC / PASSPORT No:		CDW @ \$			
Pass Date: Date of Birth:		PAI @ \$			
Address (Res): Tel/Hp:		Delivery Service			
Refundable Deposit:		SUB-TOTAL \$		7,350.00	
Cash/Net/Cheque/VISA/MC Card/No:					
(A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES		EXTENSION			
		Collection Service			
ACCESSORIES CHECK ☐ Ashtray ☐ Cig Lighter ☐ S / Type ☐ STD Tools ☐ Jack ☐ Hub Caps ☐ Radio / Cass ☐ CD/Cartridges ☐ S / RM		Misc.			
		ESTIMATED TOTAL RENTAL \$			
		Sales Person Code:			
		Hirer is responsible for the first \$1,500.00 excess for collision / damage to first party (i.e.) RICA LEASING PTE LTD Vehicle (including windscreen) and also first \$1,500.00 excess for collision / damage to third party's vehicle for each and every accident / damage.			
		Hirer's Signature:			
		Additional Driver's Signature:			

I/We agreed to the terms and conditions above, overleaf and that all information given are true & correct in all respect. My/Our driving licence(s) is/are current and not disqualified from driving. You may charge all amount due on the rental to my/our credit card.

* IMPORTANT

- ONLY PERSONS ABOVE 25 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY RICA LEASING PTE LTD.
- IN THE EVENT OF AN ACCIDENT, THE HIRER OR AUTHORIZED DRIVER:
 - shall report all accidents involving the said vehicle to the Owner immediately.
 - shall take immediate steps to complete and sign Form MAR 1 (Motor Accident Report Form) and do all other acts required in compliance with the "NON INJURY MOTOR ACCIDENT REPORT SCHEME" (the form will be made available when the accident is report to the Owner).
 - shall report to the police within 24 hours from the occurrence, the following types of accidents:
 - injury case;
 - non-injury case involving a Government vehicle, or damage to Government property;
 - non-injury case involving a foreign vehicle (to obtain their motor insurance policy, Passport Number, of the driver, Vehicle number, Log card and Vehicle road tax information);
 - non-injury case involving a pedestrian or cyclist.

RETURN OF VEHICLE: THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER/DRIVER" DURING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE OBSERVED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO RICA LEASING PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	DEPOSIT/REFUND
27/06/2018	14:00	27209			

SIGNATURE OF HIRER/DRIVER



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 09 May 2018 / 14:12:27

Receipt Date/Time : 09 May 2018 / 14:12:27

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180509-001139

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$S)	GST Amount (\$S)	Amount After GST (\$S)
Result of Insurance Enquiry - SJC3932G				
As at 09 May 2018/08.05:00				
Insurance Co: FWD SINGAPORE PTE. LTD.				
1	Insurance Enquiry - SJC3932G Enquiry Fee 20180509141031875604	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	xxxxxxxxxxxx6419	Credit Card:		7.45
		Visa/MasterCard		
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2018 Edit Reg		14 May 2018 00:00 Edit Adj Rpt	S\$31,800.00 Edit Estimates	S\$31,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Chen Way Yen , ID: S78747868								
Main Claimant:	ANG WEE KIAN , ID: S70000361								
Vehicle Reg. No.:	SLX1928Z	Date of Loss:	09/05/2018 08:00 - :59 [25 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800005723	Policy/Cover Note No.:	PNPV2017-00000559-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJC3932G	Policy No. (Claimant):	1800035803						
		Excess:	S\$500.00						
Repairer:	Hwa Seng Spray Painting Co (160 SIN MING) 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY, S75722 Sin Ming - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- FWD_SG (16/10/2018): Alert - Adj Mandate Approved (S\$35607.45) - SLX1928Z - Claim Handler: Clara Li Z... - FWD_SG (04/10/2018): Alert - Adj Mandate Maintained - SLX1928Z - Claim Handler: Clara Li Zi Rong - FWD_SG (24/09/2018): Alert - Adj Mandate Maintained - SLX1928Z - Claim Handler: Josey Loh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX1928Z (1201800005723)
[SJC3932G]
TP
ANG WEE KIAN
May 9 2018 8:00AM
[Chen Way Yen]
Hwa Seng Spray Painting Co

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences				
			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Assessment Reports				
			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/06/18 11:44	Adjuster Immediate Advice	 Load HTM	
Photos/Images				
			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/09/18 14:01	General View	 Load JPG	☒
2	15/09/18 14:01	General View	 Load JPG	☒
3	15/09/18 14:01	General View	 Load JPG	☒
4	15/09/18 14:01	General View	 Load JPG	☒
5	15/09/18 14:01	General View	 Load JPG	☒
6	15/09/18 14:01	General View	 Load JPG	☒
7	15/09/18 14:01	General View	 Load JPG	☒
8	15/09/18 14:01	General View	 Load JPG	☒
9	15/09/18 14:01	General View	 Load JPG	☒
10	15/09/18 14:01	General View	 Load JPG	☒
11	15/09/18 14:01	General View	 Load JPG	☒
12	15/09/18 14:01	General View	 Load JPG	☒
13	15/09/18 14:01	General View	 Load JPG	☒
14	15/09/18 14:01	General View	 Load JPG	☒
15	15/09/18 14:01	General View	 Load JPG	☒
16	15/09/18 14:01	General View	 Load JPG	☒
17	15/09/18 14:01	General View	 Load JPG	☒
18	15/09/18 14:01	General View	 Load JPG	☒
19	15/09/18 14:01	General View	 Load JPG	☒
20	15/09/18 14:01	General View	 Load JPG	☒
21	15/09/18 14:01	General View	 Load JPG	☒
22	15/09/18 14:01	General View	 Load JPG	☒
23	15/09/18 14:01	General View	 Load JPG	☒
24	15/09/18 14:01	General View	 Load JPG	☒
25	15/09/18 14:01	General View	 Load JPG	☒
26	15/09/18 14:01	General View	 Load JPG	☒
27	15/09/18 14:01	General View	 Load JPG	☒
28	15/09/18 14:01	General View	 Load JPG	☒
29	15/09/18 14:01	General View	 Load JPG	☒
30	15/09/18 14:01	General View	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	15/09/18 14:01	General View	 Load JPG	☒
32	15/09/18 14:01	General View	 Load JPG	☒
33	15/09/18 14:01	General View	 Load JPG	☒
34	15/09/18 14:01	General View	 Load JPG	☒
35	15/09/18 14:01	General View	 Load JPG	☒
36	15/09/18 14:01	General View	 Load JPG	☒
37	15/09/18 14:01	General View	 Load JPG	☒
38	15/09/18 14:01	General View	 Load JPG	☒
39	15/09/18 14:01	General View	 Load JPG	☒
40	15/09/18 14:01	General View	 Load JPG	☒
41	15/09/18 14:01	General View	 Load JPG	☒
42	15/09/18 14:01	General View	 Load JPG	☒
43	15/09/18 14:01	General View	 Load JPG	☒
44	15/09/18 14:01	General View	 Load JPG	☒
45	15/09/18 14:01	General View	 Load JPG	☒
46	15/09/18 14:01	General View	 Load JPG	☒
47	15/09/18 14:01	General View	 Load JPG	☒
48	15/09/18 14:01	General View	 Load JPG	☒
49	15/09/18 14:01	General View	 Load JPG	☒
50	15/09/18 14:01	General View	 Load JPG	☒
51	15/09/18 14:01	General View	 Load JPG	☒
52	15/09/18 14:01	General View	 Load JPG	☒
53	15/09/18 14:01	General View	 Load JPG	☒
54	15/09/18 14:01	Odometer Reading	 Load JPG	☒
55	15/09/18 14:01	General View	 Load JPG	☒
56	15/09/18 14:01	General View	 Load JPG	☒
57	15/09/18 14:01	Chassis Number	 Load JPG	☒
58	15/09/18 14:01	General View	 Load JPG	☒
59	15/09/18 14:01	General View	 Load JPG	☒
60	15/09/18 14:01	General View	 Load JPG	☒
61	15/09/18 14:01	General View	 Load JPG	☒
62	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
63	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
64	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
65	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
66	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
67	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
68	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
69	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
70	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
71	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
72	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
73	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
74	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
75	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
76	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
77	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
78	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
79	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
80	15/09/18 14:07	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	15/09/18 14:07	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/18 18:49	TP ESTIMATE + LTA SEARCH	 Load PDF	
2	15/05/18 18:49	TP GIA REPORT	 Load PDF	
3	15/05/18 18:49	EMAIL FROM FWD DD 14.05.2018	 Load PDF	
4	09/06/18 16:57	TP ESTIMATE-MARKED	 Load PDF	
5	11/09/18 10:09	WORKSHOP INVOICE	 Load PDF	
6	11/09/18 10:09	RENTAL RECEIPT	 Load PDF	
7	11/09/18 10:09	LTA SEARCH	 Load PDF	
8	11/09/18 10:09	LOD	 Load PDF	
9	15/09/18 14:10	LTA PARF COE Rebate Details	 Load PDF	
10	05/11/18 08:10	Release Voucher	 Load PDF	
11	05/11/18 08:10	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	16/05/18 10:28	OI GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJC3932G (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SLX1928Z (TP veh)		1.6 L CVT (A)
Date of Accident:	09/05/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	62,090.45
Final Repair Cost	:	\$	31,800.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	3,800.00 38 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	35,607.45

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____100____(%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____0____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hwa Seng Spray Painting Co.	:	\$ 35,607.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

05 Nov
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18008831/KEA3Q2

Date: 05/11/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00000559-01

Claimant Vehicle No: SLX1928Z Insured Vehicle No: SJC3932G

Date of Loss: 09/05/2018 Nature of Claim: TP Claim No: 1201800005723

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX1928Z**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZRX532561
 Reg. Date: 10/03/2016 (Man. Year: 2015) Chassis No: MR053REH104539371
 Colour: Metallic Black Odometer: 46764 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	51,210.45	33,083.45	18,127.00	35.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,880.00	7,770.00	3,110.00	28.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	62,090.45	40,853.45	21,237.00	34.20
Approved Total (Overridden) (S\$)		31,800.00		
Nett Amount (S\$)	62,090.45	31,800.00	30,290.45	48.78
+ Car Rental (38.0 x S\$100.00/day) (S\$)		3,800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		35,607.45		

INSPECTION

Date of Assignment: 14/05/2018

Date Inspected: 14/05/2018 Inspected At:

Hwa Seng Spray Painting Co (160 SIN MING)
 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY
 Singapore 575722

Estimated Period of Repair: 30.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX1928Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	655.50 FL	*655.50 FL
2	2		*BOOTLID HINGES	Repair	120.40 FL	*- FL
3	1		*BOOTLID RUBBER	Distorted / Torn	166.40 FL	*166.40 FL
4	1		*BOOTLID UPPER LOCK	Dented	382.10 FL	*382.10 FL
5	1		*BOOTLID LOWER LOCK	Distorted	24.40 FL	*24.40 FL
6	1		*BOOTLID CHROME	Warped	248.30 FL	*248.30 FL
7	2		*BOOTLID REFLECTOR	Cracked	650.20 FL	*650.20 FL
8	1		*BOOTLID LOCK CABLE	Serviceable	53.10 FL	*- FL
9	1		*LOGO EMBLEM	Necessary	52.20 FL	*52.20 FL
10	1		*EMBLEM COROLLA	Necessary	42.40 FL	*42.40 FL
11	1		*EMBLEM ALTIS	Necessary	44.10 FL	*44.10 FL
12	2		*REAR NUMBER PLATE LAMP	Serviceable	125.80 FL	*- FL
13	2		*TAILLAMP ASSY	Cracked	563.80 FL	*563.80 FL
14	1		*END PANEL	Bent	581.20 FL	*581.20 FL
15	1		*SPARE TYRE PANEL	Bent / Buckled	802.90 FL	*802.90 FL
16	1		*REAR FLOOR PANEL	Bent	845.00 FL	*845.00 FL
17	2		*TAILLAMP PANEL	Bent	336.40 FL	*336.40 FL
18	1		*REAR BUMPER	Bent	482.00 FL	*482.00 FL
19	2		*REAR BUMPER RETAINER	Cracked	208.80 FL	*208.80 FL
20	2		*REAR BUMPER BRACKET	Bent	83.40 FL	*83.40 FL
21	2		*TAILLAMP LOWER BRACKET	Cracked	125.40 FL	*125.40 FL
22	2		*REAR FENDER	Buckled	2,059.40 FL	*2,059.40 FL
23	2		*REAR PANEL CORNER	Buckled	223.20 FL	*223.20 FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	361.60 FL	*361.60 FL
25	2		*REAR ABSORBER	Bent	374.20 FL	*374.20 FL
26	1		*REAR AXLE BEAM	Serviceable	2,347.10 FL	*- FL
27	2		*REAR BEARING HUB	Serviceable	1,274.80 FL	*- FL
28	1		*SPEAKER BOARD	Serviceable	692.80 FL	*- FL
29	1		*END PANEL GARNISH	Dented	229.40 FL	*229.40 FL
30	1		*SPARE TYRE BOARD	Cracked	349.30 FL	*349.30 FL
31	2		*REAR BUMPER REFLECTOR	Serviceable	73.40 FL	*- FL
32	1		*O/S/R PANEL INNER TRIM	Deformed	415.20 FL	*415.20 FL
33	1		*N/S/R PANEL INNER TRIM	Deformed	415.20 FL	*415.20 FL
34	1		*N/S/R PANEL DUCTING	Cracked	124.70 FL	*124.70 FL
35	2		*REAR PANEL INNER SHIELD	Serviceable	99.60 FL	*- FL
36	1		*O/S/R PILLAR INNER TRIM	Serviceable	353.50 FL	*- FL
37	1		*N/S/R PILLAR INNER TRIM	Serviceable	353.50 FL	*- FL
38	2		*REAR DOOR STRIKER	Necessary	128.60 FL	*128.60 FL
39	1		*EXHAUST PIPE	Repair	865.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*EXHAUST PIPE MOUNTING	Serviceable	37.10 FL	*- FL
41	1		*EXHAUST PIPE BUSH	Serviceable	18.10 FL	*- FL
42	1		*BONNET	Bent	1,028.10 FL	*1,028.10 FL
43	2		*BONNET HINGES	Bent	100.20 FL	*100.20 FL
44	1		*BONNET LOCK	Bent	128.90 FL	*128.90 FL
45	1		*BONNET CABLE	Jammed	59.50 FL	*59.50 FL
46	2		*HEADLAMP	Broken	4,019.20 FL	*4,019.20 FL
47	1		*FRONT GRILLE	Missing	559.60 FL	*559.60 FL
48	1		*FRONT GRILLE EMBLEM	Missing	43.10 FL	*43.10 FL
49	1		*SUPPORT PANEL	Bent	977.60 FL	*977.60 FL
50	1		*BRIDGE PANEL	Bent	103.10 FL	*103.10 FL
51	1		*FRONT CROSS MEMBER	Serviceable	1,925.30 FL	*- FL
52	1		*FRONT BUMPER	Cracked	458.10 FL	*458.10 FL
53	1		*FRONT BUMPER REINFORCEMENT	Bent	379.20 FL	*379.20 FL
54	1		*FRONT BUMPER SPONGE	Serviceable	91.10 FL	*- FL
55	1		*FRONT BUMPER FOG LAMP	O/S Cracked	513.80 FL	*256.90 FL
56	1		*FRONT BUMPER FOG LAMP COVER	O/S Missing	177.80 FL	*88.90 FL
57	1		*FRONT BUMPER LOWER GRILLE	Serviceable	139.30 FL	*- FL
58	2		*FRONT FENDER	Buckled	1,433.20 FL	*1,433.20 FL
59	2		*FRONT FENDER INNER SHIELD	Serviceable	326.80 FL	*- FL
60	2		*FRONT FENDER EMBLEM	Necessary	83.40 FL	*83.40 FL
61	1		*FRONT WHEEL HOUSE	O/S Bent	846.60 FL	*423.30 FL
62	3		*HORN	Bent	332.70 FL	*332.70 FL
63	1		*RADIATOR ASSY	Bent	1,764.00 FL	*1,764.00 FL
64	1		*RADIATOR MOTOR	Jammed	439.30 FL	*439.30 FL
65	1		*RADIATOR COWLING	Broken	246.90 FL	*246.90 FL
66	1		*RADIATOR FAN BLADE	Cracked	149.10 FL	*149.10 FL
67	1		*AIR CON CONDENSER	Bent	1,404.40 FL	*1,404.40 FL
68	1		*ALTERNATOR	Dented / Jammed	2,628.10 FL	*2,628.10 FL
69	1		*WIPER TANK	Dented	121.60 FL	*121.60 FL
70	1		*WIPER TANK MOTOR	Serviceable	228.80 FL	*- FL
71	1		*AIR CON DISCHARGE PIPE	Bent	365.10 FL	*365.10 FL
72	1		*AIR CON INLET PIPE	Dented	663.80 FL	*663.80 FL
73	1		*COOLANT TANK	Dented	168.90 FL	*168.90 FL
74	1		*RADIATOR CAP	Serviceable	37.60 FL	*- FL
75	1		*BONNET STAND	Missing	53.30 FL	*53.30 FL
76	1		*ENGINE MOUNTING FRONT	Cracked	188.80 FL	*188.80 FL
77	1		*ENGINE MOUNTING LEFT	Cracked	268.90 FL	*268.90 FL
78	1		*ENGINE MOUNTING RIGHT	Distorted	423.90 FL	*423.90 FL
79	1		*ENGINE MOUNTING REAR	Cracked	254.80 FL	*254.80 FL
80	1		*ABS PUMP	Cracked	5,245.70 FL	*5,245.70 FL
81	1		*AIR CLEANER BOX	Cracked	888.20 FL	*888.20 FL
82	1		*AIR CLEANER CHAMBER	Missing	133.10 FL	*133.10 FL
83	1		*AIR FLOW SENSOR	Serviceable	537.60 FL	*- FL
84	1		*AIR INTAKE HOSE	Serviceable	1,087.00 FL	*- FL
85	1		*ECU UNIT	Dented	2,981.60 FL	*2,981.60 FL
86	1		*FUSE BOX	Cracked	528.70 FL	*528.70 FL
87	1		*ABS PIPE	Distorted / Dented	728.70 FL	*728.70 FL
88	1		*INTAKE MANIFOLD	Cracked	833.90 FL	*833.90 FL
89	1		*EXHAUST MANIFOLD	Serviceable	923.70 FL	*- FL
90	1		*AIR CLEANER HOUSE MOUNTING	Serviceable	248.90 FL	*- FL
91	1		*ENGINE WIRE HARDNESS	Repair	3,672.20 FL	*- FL
92	1		*FRONT ENGINE MOUNTING BRACKET	Distorted	182.80 FL	*182.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*REAR ENGINE MOUNTING BRACKET	Distorted	76.40 FL	*76.40 FL
94	1		*RIGHT ENGINE MOUNTING BRACKET	Distorted	192.80 FL	*192.80 FL
95	1		*LEFT ENGINE MOUNTING BRACKET	Bent	120.80 FL	*120.80 FL
96	1		*BRAKE MASTER PUMP	Serviceable	567.70 FL	*- FL
97	1		*BRAKE BOOSTER	Serviceable	1,898.80 FL	*- FL
98	1		*ENGINE VALVE COVER	Serviceable	541.30 FL	*- FL
99	1		*ENGINE TOP COVER	Cracked	328.70 FL	*328.70 FL
100	4		*ENGINE TOP COVER MOUNTING	Serviceable	73.60 FL	*- FL
101	1		*WATER PUMP	Serviceable	326.30 FL	*- FL
102	1		*MANDIFOLD GASKET	Not Necessary	49.80 FL	*- FL
103	4		*ENGINE INJECTOR	Serviceable	1,066.80 FL	*- FL
104	1		*ENGINE INJECTOR FUEL RAIL PRESSURE PIPE	Serviceable	388.20 FL	*- FL
105	1		*THROTTLE BODY	Serviceable	1,835.90 FL	*- FL
106	1		*AIR RESERVOIR INTAKE PIPE	Serviceable	128.70 FL	*- FL
107	1		*WATER HOSE TOP	Punctured	46.80 FL	*46.80 FL
108	1		*WATER HOSE LOWER	Serviceable	61.70 FL	*- FL
109	1		*WATER ADAPTOR	Serviceable	54.90 FL	*- FL
110	1		*THERMOSTAT HOUSING	Dented	115.60 FL	*115.60 FL
111	2		*AIR BAG SENSOR	Cracked	569.60 FL	*569.60 FL
112	1		*SEALANT & CLIP	Necessary	80.00 FS	*40.00 FS
113	1		*INNER SEAL	Necessary	60.00 FS	*30.00 FS
114	2		*SET OF NUMBER PLATE AND CASING	Dented	110.00 FS	*90.00 FS
115	1		*SET REVERSE SENSOR	Torn	360.00 FS	*200.00 FS
116	1		*REAR CAMERA	Necessary	380.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **67,950.60** **43,974.60**
 - List Item Discount on L Items 25.00/25.00% (S\$) 16,740.15 10,891.15

Total Parts (S\$) **51,210.45** **33,083.45**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE AND INSTALL REAR WINDSCREEN	New	160.00	120.00
2	LABOUR TO REMOVE AND INSTALL UPHOLSTERY AND ROOF LINING	New	550.00	120.00
3	VACCUM AND TOP UP AIR CON GAS	New	160.00	100.00
4	PANEL KNOCKING	New	4,300.00	3,600.00
5	SPRAY PAINTING	New	3,500.00	2,800.00
6	TUFF KOTE	New	450.00	300.00
7	WIRE CHECKIN FRONT AND REAR	New	200.00	80.00
8	LABOUR TO REMOVE AND INSTALL ENGINE TO FACILITATE REPAIR AND REAR UNDERCARRIAGE	New	800.00	240.00
9	REPROGRAMME THE AIR BAG SENSOR	New	280.00	150.00
10	REFIX EXHAUST PIPE	New	160.00	60.00
11	TOWING SERVICE (KING DOLLY)	New	160.00	120.00
12	LABOUR TO REMOVE AND INSTALL PETROL TANK	New	160.00	80.00
Gross Labour Cost (\$\$)			10,880.00	7,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >