

HWA SENG SPRAY PAINTING CO

1 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

*Not Attached
Clamp & ?
Resuming After Paint*

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

1pc bootlid	S\$
2pcs bootlid hinges	(S\$60.20/pc)
1pc bootlid rubber	
1pc bootlid upper lock	
1pc bootlid lower lock	
1pc bootlid chrome	
2pcs bootlid reflector	(S\$325.10/pc)
1pc bootlid lock cable	
1pc logo emblem	
1pc emblem 'corolla'	
1pc emblem 'Altis'	
2pcs rear number plate lamp	(S\$62.90/pc)
2pcs taillamp assy	(S\$281.90/pc)
1pc end panel	
1pc spare tyre panel	
1pc rear rear floor panel	
2pcs taillamp panel	(S\$168.20/pc)
1pc rear bumper	
2pcs rear bumper retainer	(S\$104.40/pc)
2pcs rear bumper bracket	(S\$41.70/pc)
2pcs taillamp lower bracket	(S\$62.70/pc)
2pcs rear panel	(S\$1029.70/pc)
2pcs rear panel corner	(S\$111.60/pc)
1pc rear bumper reinforcement	
2pcs rear absorber	(S\$187.10/pc)
1pc rear axle beam	
2pcs rear bearing hub	(S\$637.40/pc)
1pc speaker board	
1pc end panel garnish	
1pc spare tyre board	
2pcs rear bumper reflector	(S\$36.70/pc)
1pc o/s/r panel inner trim	
1pc n/s/r panel inner trim	
1pc n/s/r panel ducting	
2pcs rear panel inner shield	(S\$49.80/pc)
1pc o/s/r pillar inner trim	
1pc n/s/r pillar inner trim	
2pcs rear door striker	(S\$64.30/pc)
1pc exhaust pipe	
1pc exhaust pipe mounting	
1pc exhaust pipe bush	

DATE OF
ACCIDENT: 09/05/2018

YOUR INSURED

VEHICLE NO: SJC 39 32 G

Rx	655.50	✓
R RT	120.40	x
DIT/4	166.40	✓
Rd	382.10	✓
DIT RTA	24.40	x
Ways	248.30	✓
CM	650.20	✓
	53.10	?
Ru	52.20	✓
Ru	42.40	✓
Ru	44.10	✓
	125.80	?
CM	563.80	✓
R	581.20	✓
RT/RT	802.90	✓
	845.00	?
R	336.40	✓
R	482.00	✓
CM	208.80	✓
R	83.40	✓
CM	125.40	✓
Ru	2059.40	✓
Ru	223.20	✓
R	361.60	✓
	374.20	?
	2347.10	?
	1274.80	?
	692.80	?
Rd	229.40	✓
CM	349.30	✓
su	73.40	x
	415.20	?
	415.20	?
	124.70	?
	99.60	?
	353.50	?
	353.50	?
Ru	128.60	✓
R	865.70	?
	37.10	?
	18.10	?
	17390.20	

HWA SENG SPRAY PAINTING CO

2 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

c/f	17390.20	
1pc bonnet	B ₁ 1028.10	✓
2pcs bonnet hinges (S\$50.10/pc)	B ₁ 100.20	✓
1pc bonnet lock	B ₁ 128.90	✓
1pc bonnet cable	J _m 59.50	✓
2pcs headlamp (S\$2009.60/pc)	B ₁ 4019.20	✓
1pc front grille	M ₁ 559.60	✓
1pc front grille emblem	M ₁ 43.10	✓
1pc support panel	B ₁ 977.60	✓
1pc bridge panel	B ₁ 103.10	✓
1pc front cross member	1925.30	?
1pc front bumper	C _{MT} 458.10	✓
1pc front bumper reinforcement	379.20	?
1pc front bumper sponge	91.10	?
2pcs front bumper fog lamp (S\$ 256.90/pc)	C _{LS} C _{MT} 513.80	✓
2pcs front bumper fog lamp cover (S\$88.90/pc)	C _{LS} M ₁ 177.80	✓
1pc front bumper lower grille	139.30	?
2pcs front fender (S\$716.60/pc)	B ₁ 1433.20	✓
2pcs front fender inner shield (S\$163.40/pc)	C _{LS} ? 326.80	✓
2pc front fender emblem (S\$ 41.70/pc)	M ₁ 83.40	✓
2pcs front wheel house (S\$423.30/pc)	C _{LS} B ₁ 846.60	✓
3pcs horn (S\$110.90/pc)	B ₁ 332.70	✓
1pc radiator assy	B ₁ 1764.00	✓
1pc radiator motor	J _m 439.30	✓
1pc radiator cowl	B ₁ 246.90	✓
1pc radiator fan blade	C _{MT} 149.10	✓
1pc air con condenser	B ₁ 1404.40	✓
1pc alternator	2628.10	?
1pc wiper tank	P ₁ 121.60	✓
1pc wiper tank motor	228.80	?
1pc air con discharge pipe	B ₁ 365.10	✓
1pc air con inlet pipe	P ₁ 663.80	✓
1pc coolant tank	P ₁ 168.90	✓
1pc radiator cap	P ₁ 37.60	✓
1pc bonnet stand	M ₁ 53.30	✓
1pc engine mounting front	188.80	?
1pc engine mounting left	268.90	?
1pc engine mounting right	423.90	?
1pc engine mounting rear	254.80	?
	40524.10	

HWA SENG SPRAY PAINTING CO

3 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

c/f		40524.1
1pc ABS pump	S\$	<i>CM</i> 5245.70 ✓
1pc air cleaner box		<i>CM</i> 888.20 ✓
1pc air cleaner chamber		<i>211</i> 133.10 ✓
1pc air flow sensor		537.60 ?
1pc air intake hose		1087.00 ?
1pc ECU unit		2981.60 ?
1pc fuse box		528.70 ?
1pc ABS pipe		<i>D.Y. / B.</i> 728.70 ✓
1pc Intake manifold		<i>CM</i> 833.90 ✓
1pc exhaust manifold		923.70 ?
1pc air cleaner house mounting		248.90 ?
1pc engine wire hardness		3672.20 ?
1pc front engine mounting bracket		182.80 ?
1pc rear engine mounting bracket		76.40 ?
1pc right engine mounting bracket		192.80 ?
1pc left engine mounting bracket		120.80 ?
1pc brake master pump		567.70 ?
1pc brake booster		1898.80 ?
1pc engine valve cover		<i>CM</i> 541.30 ✓?
1pc engine top cover		<i>CM</i> 328.70 ✓
4pcs engine top cover mounting (S\$18.40/pc)		73.60 ?
1pc water pump		326.30 ?
1pc mandifold gasket		49.80 ?
4pcs engine injector (S\$266.70/pc)		1066.80 ?
1pc engine injector fuel rail pressure pipe		388.20 ?
1pc throttle body		1835.90 ?
1pc air reservoir intake pipe		128.70 ?
1pc water hose top		<i>pu</i> 46.80 ✓
1pc water hose lower		61.70 ?
1pc water adaptor		54.90 ?
1pc thermostat housing		115.60 ?
2pcs air bag sensor (S\$284.80/pc)		<i>CM</i> 569.60 ✓
		66960.6
	Less 25%	16740.15
		50220.45

HWA SENG SPRAY PAINTING CO

4 of 4

160 Sin Ming Drive, #05-11

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Estimate repair cost to TOYOTA ALTIS reg no : SLX 1928 Z

c/f

50220.45

Labour & misc charges

Labour to remove and install rear windscreen
Sealant & clip
Inner seal
Labour to remove and install upholstery and roof lining
Vaccum and top up air con gas
Panel knocking
Spray painting
Tuff kote
Wire checkin front and rear
Labour to remove and install engine to facilitate
repair and rear undercarriage
Reprogramme the air bag sensor
Refix exhaust pipe
Towing service (King Dolly)
1pc reverse camera
2 set of number plate and casing (\$55.00/pc)
Labour to remove and install petrol tank
1 set reverse sensor

	160.00	1201
m	80.00	405m
m	60.00	305m
	550.00	1201
	160.00	1001
	4300.00	36001
	3500.00	28001
	450.00	3001
	200.00	801
	800.00	2401
	280.00	1501
	160.00	801
(Bill)	160.00	?
	380.00	?
m	110.00	905m
	160.00	801
m	360.00	2005m
	62090.45	

HWA SENG SPRAY PAINTING CO

14/05/2018



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: