

Richard

104, ASM 1300 8832, V uas

LKK:
IDAC:

45002

Pre-assign / CCU / FTE

SMT47A SM

DO:

ASSIGNMENT

14/5/2018

Date / Time:

14/5/2018

Registered in Merimen:



Insured Vehicle No.:

YM9847A

Name of Insured:

First Frozen Food

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

12/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Bulirwahanman Kamatchiyu Selva

Driver Tel No.:

98911023

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLK 633Z



INSRS:

WSP:

Tel:

Liability:

RMKS:

bing auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

31/5
17H

SLK 633Z - X:

OI's policy & CI attached

OID reversed and collided onto park vehicle.

RECEIVED 28 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

THIN 6/6 7/6/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: Income statement

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

27/8/18

Confirm with Kennedy

Email

Call

Final Liability:

%

100- (Agreed / Assessed) BOLA S/N No.: NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

6366.50

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

720.00 (\$12 x 60 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

7088.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7088.50

Name 1:

DING AUTO PIE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
28/8/18

REF:

AXA

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHK633Zat Workshop m/s Ding Auto.of 249 Jalan Boon Lay

Insured:

Policy No:

Claims No:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$89000

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLK 633 ZYr Regn: Jan 2017Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Corolla AltisC.C. 1598Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 163576 km

T/Radio: Insured / Std / NI / NA

Eng/No: 1ZR592188C/No: MROS3REH104557504Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16 AchillesR: 205/55 R16 Yokohama

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/05/2018D.O.I. 14/05/2018

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L13 - \$5950+ (Red: \$3460.50 / 37%.)

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Other:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18008832/Vua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 15-05-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 9847A	Veh. Inspected	SLK 633Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00GY2	Excess (\$)	0.00	
Assign From		Assign Date	15/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/05/2018	Inspection Date	14/05/2018	
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

DING AUTO PTE LTD
 Blk 10 Sin Ming Industrial Estate Sector C
 #01-20
 Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

14/05/2018 10:46

JOB-NO: 85008313

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLK633Z

TRANS: AUTO

CHASSIS: MR053REH104557504

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZR592188

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	1,600.00 1200	0.00	1,600.00		Y	
2 RUST PROOFING	1.00	180.00 100	0.00	180.00		Y	
3 TO CHECK & REPAIR WIRING SYSTEM	1.00	120.00 60	0.00	120.00		Y	
4 REMOVE & REFIT FUEL TANK	1.00	120.00 60	0.00	120.00		Y	
5 REMOVE REAR WINDSCREEN	1.00	120.00 50	0.00	120.00		Y	
6 TO REMOVE & REPLACED LHF DOOR & LHR DOOR,TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR	1.00	120.00 60	0.00	120.00		Y	
7 TO REMOVE & REPLACED DOOR WINDSCREEN	1.00	120.00 50	0.00	120.00		Y	
8 R & R SPORT RIM & TRANSFER TYRE TO THE NEW RIM	1.00	120.00 50	0.00	120.00		Y	
9 REMOVE REAR CHAIR	1.00	120.00 50	0.00	120.00		Y	
10 TO PUTTY & SPRAY PAINT OF THE AFFECTED AREAS,FRONT DOOR LHS,REAR DOOR LHS,REAR FENDER LHS,SIDE MIRROR COVER LHS	1.00	1,000.00 800	0.00	1,000.00		Y	
TOTAL:		3,620.00	0.00	3,620.00			

MATERIALS

1 FRONT DOOR LHS CUT ✓	1.00	1,140.00	285.00	855.00 ✓	L	Y	
2 FRONT DOOR OUTER HANDLE LHS CUT ✓	1.00	205.00	51.25	153.75 ✓	L	Y	
3 FRONT DOOR WINDOW FRAME STICKER LHS X NN ✓	1.00	68.00	17.00	51.00	L	Y	
4 FRONT DOOR CHECKER LHS X NN ✓	1.00	155.00	38.75	116.25	L	Y	
5 REAR DOOR LHS CUT ✓	1.00	1,200.00	300.00	900.00 ✓	L	Y	
6 REAR DOOR WINDOW FRAME STICKER LHS X NN ✓	1.00	68.00	17.00	51.00	L	Y	
7 REAR DOOR CHECKER LHS X NN ✓	1.00	165.00	41.25	123.75	L	Y	
8 REAR DOOR WINDOW REGULATOR LHS 2 NN ✓	1.00	170.00	42.50	127.50	L	Y	
9 REAR FENDER LHS DM ✓	1.00	1,085.00	271.25	813.75 ✓	L	Y	
10 REAR FENDER INNER SHIELD LHS 2 NN ✓	1.00	68.00	17.00	51.00	L	Y	
11 REAR FENDER AIR VENT 2 NN ✓	1.00	168.00	42.00	126.00	L	Y	
12 SIDE MIRROR LHS BR ✓	1.00	1,130.00	282.50	847.50 ✓	L	Y	
13 SIDE MIRROR COVER LHS NEC ✓	1.00	82.00	20.50	61.50 ✓	L	Y	
14 SIDE MIRROR LAMP LHS NEC ✓	1.00	130.00	32.50	97.50 ✓	L	Y	
15 REAR FENDER INNER SHIELD CLIP 2 NN ✓	1.00	35.00	0.00	35.00	S	Y	
16 FRONT SPORT RIM LHS CUT ✓	1.00	600.00	0.00	600.00 ✓	S	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
17 REAR SPORT RIM LHS CUT ✓	1.00	600.00	0.00	600.00	S	Y	
TOTAL:		7,069.00	458.50	5,610.50			
TOTAL PARTS & LABOUR:		10,689.00	1,458.50	9,230.50			

EXCESS/LOADING:\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$ \$ _____

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: _____ FAX: _____

Sathya Sai

LKK

14/5/2018

Sebastian yeang @ lkkauto.com

Part by Part

8 days

Question mark photo

Photo before paint

LKK Auto Consultants hence notify the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

SUPPLEMENTRY ITEM

DINGAUTO

BLK 10, #01-20

Sin Ming Industrial Est, Sec C

Singapore 575645

Tel: 6457 5884

Fax: 6453 4227

VEHICLE NO:	SLK 633 Z
-------------	-----------

MODEL:	TOYOTA ALTIS
--------	--------------

CHASSIS NO:	MR053PEH045750
-------------	----------------

INSURANCE:	LKK auto
------------	----------

DATE SURVEY:	14/5/18
--------------	---------

[illegible]

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

L/S

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

14/05/2018 10:46

JOB-NO: 85008313

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLK633Z

TRANS: AUTO

CHASSIS: MR053REH104557504

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZR592188

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	1,600.00	1300	0.00		Y	
2 RUST PROOFING	1.00	180.00	100	0.00		Y	
3 TO CHECK & REPAIR WIRING SYSTEM	1.00	120.00	60	0.00		Y	
4 REMOVE & REFIT FUEL TANK	1.00	120.00	60	0.00		Y	
5 REMOVE REAR WINDSCREEN	1.00	120.00	50	0.00		Y	
6 TO REMOVE & REPLACED LHF.DOOR & LHR DOOR,TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR	1.00	120.00	60	0.00		Y	
7 TO REMOVE & REPLACED DOOR WINDSCREEN	1.00	120.00	50	0.00		Y	
8 R & R SPORT RIM & TRANSFER TYRE TO THE NEW RIM	1.00	120.00	50	0.00		Y	
9 REMOVE REAR CHAIR	1.00	120.00	50	0.00		Y	
10 TO PUTTY & SPRAY PAINT OF THE AFFECTED AREAS,FRONT DOOR LHS,REAR DOOR LHS,REAR FENDER LHS,SIDE MIRROR COVER LHS	1.00	1,000.00	800	0.00		Y	
TOTAL:		3,620.00	0.00	3,620.00			
MATERIALS							
1 FRONT DOOR LHS CUT ✓	1.00	1,140.00	285.00	855.00	L	Y	
2 FRONT DOOR OUTER HANDLE LHS CUT ✓	1.00	205.00	51.25	153.75	L	Y	
3 FRONT DOOR WINDOW FRAME STICKER LHS X	1.00	68.00	17.00	51.00	L	Y	
4 FRONT DOOR CHECKER LHS X	1.00	155.00	38.75	116.25	L	Y	
5 REAR DOOR LHS CUT ✓	1.00	1,200.00	300.00	900.00	L	Y	
6 REAR DOOR WINDOW FRAME STICKER LHS X	1.00	68.00	17.00	51.00	L	Y	
7 REAR DOOR CHECKER LHS X	1.00	165.00	41.25	123.75	L	Y	
8 REAR DOOR WINDOW REGULATOR LHS ?	1.00	170.00	42.50	127.50	L	Y	
9 REAR FENDER LHS DM ✓	1.00	1,085.00	271.25	813.75	L	Y	
10 REAR FENDER INNER SHIELD LHS ?	1.00	68.00	17.00	51.00	L	Y	
11 REAR FENDER AIR VENT ?	1.00	168.00	42.00	126.00	L	Y	
12 SIDE MIRROR LHS BR ✓	1.00	1,130.00	282.50	847.50	L	Y	
13 SIDE MIRROR COVER LHS NEC ✓	1.00	82.00	20.50	61.50	L	Y	
14 SIDE MIRROR LAMP LHS NEC ✓	1.00	130.00	32.50	97.50	L	Y	
15 REAR FENDER INNER SHIELD CLIP ?	1.00	35.00	0.00	35.00	S	Y	
16 FRONT SPORT RIM LHS CUT ✓	1.00	600.00	0.00	600.00	S	Y	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/5/2018

Survey Details:

Date of loss	12-May-18
Date of appointment	14-May-18
Date of survey	14-May-18
Location of survey	Ding Auto Pte Ltd - Sin Ming

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLK 633Z
Make and Model	TOYOTA ALTIS CLASSIC 1.6 CVT
Date of registration	4-Jan-17
Excess	
Market Value	\$ 89,000.00
Parf Rebate	\$ 53,805.00
Nett Loss	\$ 35,195.00

Repair details:

Initial Estimate	\$ 10,869.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,109.00
Check items (estimate)	\$ 339.50
Labour	\$ 2,480.00
Total	\$ 7,928.50
Lump Sum(if applicable)	TBA

Number of days for repair	<u>8 days</u>
---------------------------	---------------

Service Request Details

Claim

S8M00GY2

Reference

None 

Loss Date

May 12, 2018

Request Date

May 14, 2018

Due Date

May 14, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Ding Auto

Jalan
249, Boon Lay
^
9 2394128

Actions

Next Step

Finish the work

[Complete Work](#)[More ▾](#)

Veh In

Vehicle Information

Incident Vehicle Registration #

SLK633Z

Make

TPVD TOYOTA

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YM 9847A (Insd veh)	Model:	TOYOTA
	SLK 633Z (TP veh)		COROLLA ALTIS CLASSIC
Date of Accident:	12/05/2018		1.6 CVT

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,876.64
Final Repair Cost	:	\$	6,366.50
Loss of Use	:	\$	720.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	7,088.50

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks _____ _____ _____			

Payment Instruction: Payee's Breakdown			
1)	DING AUTO PTE LTD	:	\$ 7,088.50

NUR SHAQILAH BTE ABDOL
WAHAB

11/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<< Service Request Details

Claim	S8M00GY2	Actions		Document Type
Reference		Next Step	Finish the work	
CC4/ASM18006832/Vua3s2 		Complete	Work	Document SubType
Loss Date				
May 12, 2018				
Request Date				
May 14, 2018				
Due Date				
May 14, 2019				
Vendor Name				
LKK AUTO CONSULTANTS PTE LTD (TP)				
Type of Loss				
Third Party Vehicle Damage				
Services				
Pending verification - Direct Settlement				
Upload Documents				
Vehicle Information				
Incident Vehicle Registration #		SLK633Z		
Make		Service Address		
TPVD TOYOTA		Model		
COROLLA ALTIS 1.6		Primary Contact/Insured		
FAST FROZEN FOOD				
5 TUAS BAY WALK, 637755, Singapore				
65674755				
Claim Handler				
ANG Richard				
richard.angbs@axa.com.sg				
Additional Instructions				
NON-REPORTED				
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim

S8M00GY2

Reference

CC4/ASM18009832/Vua3s2 

Loss Date

May 12, 2018

Request Date

May 14, 2018

Due Date

May 14, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

NON-REPORTED

Actions

Next Step

Finish the work

Complete

Write

More

App

Vehicle Information

Incident Vehicle Registration #

SLK633Z

Make

Service Address

TPVD TOYOTA

Model

COROLLA ALTIS 1.6

Primary Contact/Insured

FAST FROZEN FOOD

5 TUAS BAY WALK, 637755, Singapore

65674755

Claim Handler

ANG Richard

richard.ang@axa.com.sg

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

CREATED USER

VERSION DATE

ESTIMATED AMOUNT

APPROVED AMOUNT

STATUS

SHARE

CLONE

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Vehicle & Driver Details

Vehicle Registration#SLK633Z

Purchase Datemm/dd/yyyy

Registration StateSINGAPORE

Registration Date *01/04/2017

Mileage163576

Age of Vehicle1

CATEGORYPOLICY INFORMATIONASSESSMENT INFORMATION

Manufacturing Year2016

CATEGORYFINOL INFORMATIONPOST SURVEY INFORMATION

MakeTPVD TOYOTA

Driver NameQUEK SOO CHENG

ModelCOROLLA ALTIS 1.6

COROLLA ALTIS CLASSIC 1.6

Age0

Type

OccupationUnknown

Type of Paint

Education QualificationOther

Chassis NoMR053REH104557504

Driving Experience0

Engine No1ZRX592188

Driver License #

Engine Capacity1598 cc

License Type

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	05/14/2018		General condition	Fair
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unlicensed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	205/55R16	Rear Tyre Size	205/55R16
Front left side	ACHILLES 6mm	Rear left side	YOKOHAMA 6mm
Front right side	ACHILLES 6mm	Rear right side	YOKOHAMA 6mm

SERVICE REQUESTS

MESSAGES

CLAIMS

<< Assessment Details

General & Workshop Details				Vehicle & Driver Details			Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE			
			1	1	FRONT DOOR LHS			Cut	1140		25		855	Reviewing				
			2	1	FRONT DOOR OUTER HANDLE LHS			Cut	205		25		153.75	Reviewing				
			3	1	FRONT DOOR WINDOW FRAME STICKER LHS			Serviceable	0		25		0	Reviewing				
			4	1	FRONT DOOR CHECKER LHS			Serviceable	0		25		0	Reviewing				
			5	1	REAR DOOR LHS			Cut	1200		25		900	Reviewing				
			6	1	REAR DOOR WINDOW FRAME STICKER LHS			Serviceable	0		25		0	Reviewing				
			7	1	REAR DOOR CHECKER LHS			Serviceable	0		25		0	Reviewing				
			8	1	REAR DOOR WINDOW REGULATOR LHS			Serviceable	0		25		0	Reviewing				
			9	1	REAR FENDER LHS			Damaged	1085		25		813.75	Reviewing				

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
☐	10		TO PUTTY & SPRAY PAINT OF THE AFFECTED AREAS, FRONT DOOR LHS, REAR DOOR LHS, REAR FENDER LHS, SIDE MIRROR COVER LHS.	800	0	0	Reviewing		

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		8	
	2	REAR FENDER INNER SHIELD CLIP	Reviewing	0	NOT NECESSARY	
	3	FRONT SUPPORT RIM LHS	Reviewing	600	CUT	
	4	REAR SPORT RIM LHS	Reviewing	600	CUT	

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$7,409.00

Claim Amount \$7,409.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$3,729.00	\$3,729.00
Labour	\$2,480.00	\$2,480.00
Miscellaneous	\$1,200.00	\$1,200.00

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

App

Approves

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

	1	FINAL LUMP SUM	Reviewing	5950		
--	---	----------------	-----------	------	--	--