

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008833/M1pa3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Date: 16-09-2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLV 434Z	Veh. Inspected	SLT 3580A
Policy No.	GA323138/1	Coverage (\$)	0.00
Claim No.	S8M00GI9	Excess (\$)	0.00
Assign From		Assign Date	11/05/2018
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN24A8J0176922	Colour	BROWN
Odometer	57765	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	GOODYEAR	8 mm
L/H Front Tyre	205/60 R16	GOODYEAR	8 mm
R/H Rear Tyre	205/60 R16	GOODYEAR	8 mm
L/H Rear Tyre	205/60 R16	GOODYEAR	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/05/2018	Inspection Date	14/05/2018
Survey held at	1 SOON LEE ST #04-44		
Repairer	SK AUTOMOBILE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			