

6) Date/Time _____ File Return to _____

Catherine Chong (LKK Auto)

From: Abdul Rahman MOHAMAD SALIM (SPF)
<Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Sent: Monday, 14 May, 2018 3:41 PM
To: Catherine Chong (LKK Auto)
Cc: 'Olivia Lau'; Rosalyn TAN (SPF); Frankie THAY (SPF)
Subject: RE: Request Paper Survey
Attachments: SHC1119A LOD of CDGE.pdf; SHC1119A Survey & Photos.pdf

Your Ref: SHC1119A
Our Ref : AEMD/105/009/2018/010

Dear Cath,

Your preceding mail and our assignment on 2 Feb 2018 have reference.

Attached as requested.

Regards

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Saturday, 12 May 2018 3:30 PM
To: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: Request Paper Survey

Dear Mr Abdul Rahman,

Kindly refer to the attachment.

Please assist provide us the LOD for all vehicle for us conduct Paper Survey.

Best Regards,

Catherine Chong | Admin
LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SHC1119A

Our Ref : AEMD/105/009/2018/010

Date : 2 February 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 19 JANUARY 2018 INVOLVING GOVT VEH QX948M AND OTHER VEH SHC1119A

We refer to the above matter.

- 2 Kindly arrange for a Pre-Repair Inspection of vehicle no. SHC1119A at M/s Comfort Delgro Engrg Pte Ltd of 205 Braddell Road, Singapore 579701.
- 3 For appointment kindly contact Tel: 63836280/62148374.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

A FORCE FOR THE NATION

2018/010

COMFORTDELGRO ENGINEERING

Our Ref : T 0118/ SHC1119A /JW(st)
 Your Ref : _____
 Date : 30.01.18

SPF Accident Claims Section
 Automotive Engineering & Management Division
 Police Logistics Department
 No 1 Mount Pleasant Road
 Blk 8 Old Police Academy
 Singapore 298333

Attn : Ms Rosalyn Tan

Dear Sir

CDGE Taxi Claims Dept
 59 Loyang Drive 4th Flr
 Singapore 508969

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road Singapore 579701

Mainline +65 6383 6280
 Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199606048W

Workshops

Braddell
 205 Braddell Road
 Singapore 579701

Loyang
 59 Loyang Drive
 Singapore 508969

Sin Ming
 383 Sin Ming Drive
 Singapore 575717

Pandan
 45 Pandan Road
 Singapore 609286

Ubi
 320 Ubi Road 3
 Singapore 408649

Senoko
 24 Senoko Loop
 Singapore 758156

Sungei Kadut
 7 Sungei Kadut Way
 Singapore 728791

Yishun
 501 Yishun Industrial Park A
 Singapore 768732

WITHOUT PREJUDICE



**ACCIDENT INVOLVING OUR TAXI SHC1119A YOUR INSURED
QX 948M AND OTHER _____ ON 19.01.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHC1119A which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving QX 948M we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	802.50
2	<u>4</u> days Loss of Rental @ \$ 98.25 per day	\$	393.00
3	Survey Report Fees (Surveyed by M/s VAC)	\$	196.88
4	GIA / LTA Search Fee	\$	-
5	GIA / Police Report Fees	\$	-
6	Towing / Medical / Transportation Fees	\$	-
Sub Total :		\$	1,392.38

HIRER'S CLAIM

7	<u>4</u> days Loss of Income @ \$ 80.00 per day	\$	320.00
Total Claims:		\$	1,712.38

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill, survey bill/report & original/ scan photographs : 9 pcs.
 b) LTA search slip/s of : SDG2002Y & SLL9078L
 c) GIA / Police report/s of : SHC1119A
 d) Letter of authority from owner / hirer / operator
 () Witness statement/s () Certificate of Insurance (X) Rental Rate Letter
 (X) Photograph/s of Accident Scene (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Jim Wong

Deputy Manager

CDGE Claims Department

Tel : 6214 8374 Fax: 6214 1843 Email: jimwong@cdge.com.sg

This is a computer generated letter. No signature is required.

COMFORTDELGRO



COMFORTDELGRO ENGINEERING PTE LTD
#205 Braddell Road
Blk C Ext 1 3rd Level
Singapore 579701



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No. 198100329K

SURVEY REPORT

GENERAL INFORMATION

VAC Ref. No.	: 521433	Claim No.	: 305108802
Accident Date	: 19/01/2018	Claim Type	: THIRD PARTY
Assignment Date	: 22/01/2018	Policy No.	:
Survey Date	: 22/01/2018	Finalised Dt.:	
Survey Report Date	: 23/01/2018		

VEHICLE PARTICULARS

Vehicle No.	: SHC1119A	Chassis No.	: KMHET41VMCA821678
Registration Date	: 27/03/2012	Engine No.	: OBSCURED
Make	: HYUNDAI	Engine Cap.	: 1991 CC
Model	: SONATA	Transmission	: AUTO
		Colour	: BLUE

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 419945		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	215/60R60	WESTLAKE	6
FRONT LH	215/60R60	WESTLAKE	6
REAR RH	215/60R60	WESTLAKE	6
REAR LH	215/60R60	WESTLAKE	6

SURVEY CONDUCTED AT

ComfortDelGro Engineering Pte Ltd,
59 Loyang Drive Singapore 508969.
Assignment given by: MVA Chiang (C.D.G.E.)

REMARKS

- [1] Workshop Estimate : S\$ 1,110.72
- [2] Our Adjustment : S\$ 750.00
- [3] Repair Period : 2 days
- [4] We have not authorised repairs. This survey was carried out on without prejudice basis.

VICOM LTD SURVEY REPORT

SHC1119A @ 19/01/2018

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Rear Bumper	Deformed	578.40	578.40
2	10	Rear Bumper Clips	Necessary	22.00	22.00
3	1	Rear Bumper Protector Lh X Hyv	Necessary	38.00	38.00
Subtotal				:	638.40
Less 20 %				:	127.68
TOTAL				:	510.72

SPECIAL NETT ITEM

1	1	Rear Bumper Rubber Mat	Necessary	50.00	50.00
TOTAL				:	50.00

TOTAL FOR SPARE PARTS : 560.72 560.72

VICOM LTD

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Panel beating	350.00	¹⁵⁰ 180.00
2	Spray painting	200.00	180.00
TOTAL FOR LABOUR AND SPRAY PAINTING		550.00	360.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	560.72	560.72
TOTAL FOR LABOUR AND SPRAY PAINTING	550.00	360.00
TOTAL REPAIR COST	1110.72	920.72

VICOM LTD
SURVEY REPORT
Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear damage.

The damages seen during our survey were at rear bumper and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$1,110.72. We adjusted it to S\$920.72.

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at S\$750.00.

The repairs would require a period of 2 working days.



Kamarudin Abdul Kadir
for VICOM Ltd

U/S \$700 / 2 hrs.



Your Ref: AEMD/105/009/2018/010

Date: 21st May 2018

Our Ref: CS1/SPF18008836/K1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SHC 1119A INSURED VEHICLE: QX 948M ACCIDENT DATE: 19/01/2018**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 1119A from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHC 1119A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHC 1119A
Make & Model	: Hyundai Sonata
Year of Registration	: 2012
Chassis Number	: KMHET41VMCA821678
Engine Capacity	: 1991 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1119A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	578.40	578.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER PROTECTOR LH	TO REPAIR SEE LABOUR	38.00	-
	LESS 20% DISCOUNT		-127.68	-120.08
			510.72	480.32
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER PROTECTOR LH.		350.00	150.00
	SPRAY PAINTING.		200.00	180.00
			550.00	330.00
	GRAND TOTAL		1,110.72	860.32

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			700.00
---	--	--	---------------

Report Ref No. CS1/SPF18008836/K1vbs2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.