

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6027 Z

1 pc1 [c	Rear bumper	\$	696.00	✓ dented
1 pc	Rear bumper o/s side bracket	\$	29.00	✓ cracked
1 pc	Rear o/s wheel cover	\$	116.00	✓ broken
		\$	841.00	
	Less 10%	\$	84.10	
		\$	756.90	

S/NETT

1 pc	Rear o/s fender sticker	\$	60.00	✓
	Sundry	\$	50.00	x 10
	To check wheel alignment	\$	80.00	x 10
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, rear bumper	\$	700.00	✓ 360
	To putty and spray painting on rear o/s fender, rear bumper	\$	400.00	✓ 360
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	✓ 50
		\$	2,166.90	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

WA2 LRV
18/5/18 1120
LIS.
2 days.

<p>consultants hence notify er of the following:</p> <ul style="list-style-type: none">• survey before/after spray painting• display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
