

enprint

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Estimate No: EST1800138
Date: 14 May 2018

ATTN: Motor Claim Department

VTC

Veh Reg No: SJY2671A
Make/Model: HONDA CIVIC 1.8L 5AT
Chasis No: JHMFD16309S202197
Reg. Date: 01/07/2009
Your Ref No: SLG1688E

Claim Type: Third Party
Accident Date: 11/05/2018
TP Veh Reg No: SLG1688E

Estimate Repair Cost to Vehicle No :SJY2671A

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID "H" EMBLEM <i>Dented new</i>	35.70 ✓	
2	1 PC BOOT LID "CIVIC" EMBLEM <i>new</i>	39.10 ✓	
3	1 PC BOOT LID LOCK <i>Damaged</i>	195.40 ✓	
4	1 PC BOOT LID LOCK CATCHER <i>new</i>	41.20 ✗	
5	1 PC BOOT LID TRIM <i>new</i>	133.70 ✗	
6	2 PCS BOOT LID HINGES <i>new</i>	156.40 ✗	
7	1 PC BOOT LID RUBBER <i>cut</i>	157.60 ✓	
8	1 PC BOOT LID LAMP R/H <i>cut</i>	228.80 ✓	
9	1 PC BOOT LID LAMP L/H <i>cut</i>	228.80 ✓	
10	1 PC SPARE TYRE COVER <i>Dented</i>	316.00 ✓	
11	1 PC L/H FENDER INNER TRIM <i>new</i>	210.90 ✗	
12	1 PC R/H FENDER INNER TRIM <i>new</i>	210.90 ✗	
13	1 PC REAR PANEL TRIM <i>Dented</i>	89.10 ✓	
14	1 PC SPARE TYRE SPONGE <i>new</i>	199.60 ✗	
15	1 PC R/H TAIL LAMP <i>cracked</i>	308.70 ✓	
16	1 PC L/H TAIL LAMP <i>cracked</i>	308.70 ✓	
17	1 PC REAR PANEL <i>Dented</i>	334.10 ✓	
18	1 PC BUMPER <i>Distorted</i>	638.00 ✓	
19	1 PC L/H BUMPER RETAINER <i>new</i>	28.10 ✓	
20	1 PC R/H BUMPER RETAINER <i>new</i>	28.10 ✓	
21	1 PC EXHAUST PIPE <i>Beats</i>	635.00 ✓	
22	2 PCS EXHAUST PIPE MOUNTING <i>new</i>	56.60 ✗	
23	1 PC BOOT LID "1.8 i-VITEC" EMBLEM <i>new</i>	34.10 ✓	
24	1 PC BOOT LID <i>Dented</i>	660.70 ✓	
		5,275.30	
	Less 20%	1,055.06	4,220.24
	Special Net		
25	1 SET BOOT LID TRIM CLIPS <i>new</i>	40.00 ✗	
26	1 SET L/H FENDER INNER TRIM CLIPS <i>new</i>	40.00 ✗	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/05/2018
TP Veh Reg No: SLG1688E

Estimate No: EST1800138

Date: 14 May 2018

Veh Reg No: SJY2671A

Make/Model: HONDA CIVIC 1.8L 5AT

Chasis No: JHMF16309S202197

Reg. Date: 01/07/2009

Your Ref No: SLG1688E

Estimate Repair Cost to Vehicle No :SJY2671A

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
27	1 SET R/H FENDER INNER TRIM clips <i>new</i>	40.00 <i>+</i>	
28	1 SET BUMPER CLIPS <i>new</i>	40.00 <i>-30</i>	
29	1 SET REVERSE SENSORS <i>Range</i> 230	250.00 <i>200</i>	
		410.00	410.00
	Labour		
30	1 TO CHECK WIRING 1800	50.00 <i>30</i>	
31	1 REMOVE AND REFIT SENSORS	80.00 <i>50</i>	
32	1 TO SPRAY UNDERSEAL	150.00 <i>40</i>	
33	1 TO SPRAY PAINT DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS	1,200.00 <i>80</i>	
34	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 <i>800</i>	
35	1 REMOVE AND REFIT EXHAUST PIPE	180.00 <i>80</i>	
		2,860.00	2,860.00
	Total		SS 7,490.24
	Add GST @ 7%		524.32
	Total Amount Payable		SS 8,014.56

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FOURTEEN AND CENTS FIFTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

total: 5442.80

4/s: 4350

4350

Action hiring
2/s 15/05/18
06 days
07 days