



CAR CITY AUTO CENTRE PTE LTD

Car City Always

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300 FAX: 6782 0300

GST Registration : 200719980C

E-mail : ccacpl@singnet.com.sg

TO: *AYA Insurance pte ltd*
ATTN: MOTOR CLAIMS DEPT

DATE : 14/05/2018

JOB TYPE : *3rd Party claim*

VEH NO : SKL9221B

MARK : TOYOTA

MODEL : ESTIMA AERAS
2.4 A

CHASSIS NO : ACR507028872

ENGINE NO:

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME: *LIM MEE LAN*

ADDRESS:

CONTACT NO H/P:

TEL:

OWNERS INSURER :

POLICY NO:

China Taiping Insurance (S) Pte Ltd

ACCIDENT DATE : *11/05/2018*

DMPCSN/3102961701

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

REQUESTOR CONTACT :

Ho 16787-0300

S/NO	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR WINDSCREEN <i>11</i>	1	\$1,211.70	\$1,211.70 <i>X</i>
2	REAR TAILGATE COVER <i>501500</i>	1	\$1,591.73	\$1,591.73 <i>✓</i>
3	REAR TAILGATE COVER LOCK <i>20</i>	1	\$401.70	\$401.70 <i>✓</i>
4	REAR TAILGATE COVER LOGO <i>111</i>	1	\$61.70	\$61.70 <i>✓</i>
5	REAR TAILGATE COVER EMBLEM "ESTIMA" <i>111</i>	1	\$62.75	\$62.75 <i>✓</i>
6	REAR TAILGATE COVER EMBLEM "AERAS" <i>111</i>	1	\$64.34	\$64.34 <i>✓</i>
7	REAR TAILGATE WEATHER STRIP <i>1001</i>	1	\$396.40	\$396.40 <i>✓</i>
8	REAR BUMPER <i>20/22</i>	1	\$596.20	\$596.20 <i>✓</i>
9	REAR BUMPER RETAINER FRT <i>11</i>	2	\$66.75	\$433.50 <i>X</i>
10	REAR BUMPER RETAINER RR <i>54</i>	2	\$62.40	\$124.80 <i>✓</i>
11	REAR BUMPER SPONGE <i>11</i>	1	\$101.70	\$401.70 <i>X</i>
12	REAR BUMPER CLIP <i>111</i>	8	\$3.89	\$31.12 <i>✓</i>
13	REAR END PANEL <i>11</i>	1	\$691.70	\$691.70 <i>X</i>
14	REAR END PANEL GARNISH <i>11</i>	1	\$311.60	\$311.60 <i>X</i>
15	REAR END PANEL SWITCH KEY <i>11</i>	1	\$197.80	\$197.80 <i>X</i>

PARTS PRICE : *3330.74* \$5,978.74

LESS 25% : *832.69* \$1,494.69

SUB TOTAL PRICE : *2498.06* \$4,484.06

S/NO	DESCRIPTION	QTY	UNIT S/Nett PRICE	TOTAL S/Nett PRICE
1	SEALANT <i>Rear windscreen</i>	2	\$35.00	\$70.00 <i>40</i>
2	REVERSE SENSOR <i>shut</i>	1 <i>for</i>	\$280.00	\$280.00 <i>200</i>
3	SOLAR FILM <i>1-1</i>	1	\$130.00	\$130.00 <i>X</i>

S/N PARTS PRICE :

\$480.00

TOTAL PARTS PRICE :

\$4,964.06

CLAIM DETAIL : LABOURS & SPRAY PAINTING

No	JOBS DESCRIPTION	PRICE	REVISED PRICE	APPR.
1	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE. REAR TAILGATE COVER, REAR BUMPER, REAR END PANEL, REAR SPARE TYRE PANEL; REAR TAILLAMP RH & LH & OTHER.	\$ 1,300.00	<i>600</i>	
2	TO CHECK & REPAIR WIRING SYSTEM, REMOVE & REPLACE DAMAGED WIRE.SIGNAL LIGHT WIRE, ALL LAMP WIRE, SENSOR WIRE & OTHER WIRING.	\$ 60.00	<i>20</i>	
3	TO APPLY ANTI-RUST UNDERCOAT ON REPLACE & REPAIRED PANELS.	\$ 80.00	<i>50</i>	
4	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS. REAR BUMPER, REAR TAILGATE COVER, REAR END PANEL, REAR SPARE TYRE PANEL, REAR FENDER RH, LHETC.	\$ 1,000.00	<i>800</i>	
5	TO REMOVE & REFIT REAR WINDSCREEN GLASS FOR ALL NECESSARY REPAIRS.	\$ 150.00	<i>120</i>	
6	TO REMOVE & REFIT INNER ITEM FOR NECESSARY BODY WORK. FIXING OR PANEL BEATING	\$ 80.00	<i>60</i>	
7	TO REMOVE & REFIT REAR TAILGATE COVER. REAR TAILGATE LOCK INNER & OUTER, REAR TAILGATE COVER HANDLE, WIPER MOTOR, SWITCH, TRIM BOARD & ALL EMBLEMETC.	\$ 120.00	<i>60</i>	

TOTAL LABOUR & SPRAY PAINTING PRICES: \$ 2,790.00

1710

ESTIMATE REPORT

TOTAL LABOUR COST : \$ 2,790.00
TOTAL PARTS COST : \$ 4,964.06
TOTAL REPAIR COST : \$ 7,754.06

APPROVAL DETAILS

EXCESS : *Not Allowed*
NO. OF DAY : 4 *4/5/10*
RE-SURVEY : *2/5/10*
PART BY PART OR LUMP-SUM : *16/5/10*
DATE OF SURVEY : *mercus*
SURVEY BY :
CONTACT NO :
FAX NO. :

NOTE : LUMP-SUM AMOUNT OR COST OF
REPAIR WOULD BE REVISED IF
SUPPLEMENT REPAIR IS REQUIRED

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: