

## CAR CITY AUTO CENTRE PTE LTD

Car City Always

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300 FAX: 6782 0300

GST Registration: 200719980C

E- mail: ccacpl@singnet.com.sg

DATE: 14/05/2018

AYA Ismone Pte Ital ATTN: MOTOR CLAIMS DEPT

JOB TYPE: 3rd Ponty clair

VEH NO: SKL9221B

**ESTIMATE REPORT** 

OWNER'S PARTICULAR LIM MET LAW

MARK: TOYOTA

MODEL: ESTIMA AERAS

2.4 A

ADDRESS:

CHASSIS NO: ACR507028872

6787-0300

ENGINE NO:

\$101.70

\$691.70

\$311.60

\$197.80

\$3.89

CONTACT NO H/P: China Taiping luswanc(s) Ph fty ACCIDENT DATE: 11/05/2018

OWNERS INSURER: DMPCSN310296/70/

POLICY NO:

**QUOTATION SUMMARY** 

**CLAIM DETAIL: PARTS** 

REAR BUMPER SPONGE

REAR END PANEL GARNISH

REAR END PANEL SWITCH KEY

REAR BUMPER CLIP

REAR END PANEL

11

12

13

14

15

REQUESTOR CONTACT:

**UNIT LIST** TOTAL LIST S/NO DESCRIPTION QTY PRICE PRICE REAR WINDSCREEN 11 1 \$1,211.70 \$1,211.70 1 401(m 1 \$1,591.73 \$1,591.73 2 REAR TAILGATE COVER 20 REAR TAILGATE COVER LOCK 1 \$401.70 \$401.70 3 rei REAR TAILGATE COVER LOGO 1 \$61.70 \$61.70 REAR TAILGATE COVER EMBLEM "ESTIMA" 1 \$62.75 \$62.75 5 re REAR TAILGATE COVER EMBLEM "AERAS" 1 \$64.34 rei \$64.34 6 101 REAR TAILGATE WEATHER STRIP \$396.40 \$396.40 7 70/2c 1 \$596.20 \$596.20 8 REAR BUMPER 2 REAR BUMPER RETAINER FRT 111 \$66.75 \$133.50 9 REAR BUMPER RETAINER RR 34 2 \$62.40 \$124.80 10

nu

1 PARTS PRICE:

1

8

1

\$197.80 🖘 \$5,978.74

\$101.70

\$31.12 •

\$691.70

\$311.60 ?

LESS 25%:

\$1,494.69

SUB TOTAL PRICE:

\$4,484.06

S/NO	DESCRIPTION		QTY	UNIT S/Nett PRICE	TOTAL S/Nett PRICE	
1	SEALANT Rear wordsness	rec.	2	\$35.00	\$70.00 40	
2	REVERSE SENSOR	shub	1 500	\$280.00	\$280.00 200	
3	SOLAR FILM	11	1 '	\$130.00	\$130.00	

S/N PARTS PRICE:

TOTAL PARTS PRICE :

\$480.00

\$4,964.06

## **CLAIM DETAIL: LABOURS & SPRAY PAINTING**

No	JOBS DESCRIPTION	PRICE	REVISED PRICE	APPR.
1	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE. REAR TAILGATE COVER, REAR BUMPER, REAR END PANEL, REAR SPARE TYRE PANEL; REAR TAILLAMP RH & LH & OTHER.	\$ 1,300.00	600	
2	TO CHECK & REPAIR WIRING SYSTEM, REMOVE & REPLACE DAMAGED WIRE.SIGNAL LIGHT WIRE, ALL LAMP WIRE, SENSOR WIRE & OTHER WIRING.	\$ 60.00	20	
3	TO APPLY ANTI-RUST UNDERCOAT ON REPLACE & REPAIRED PANELS.	\$ 80.00	50	
4	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS. REAR BUMPER, REAR TAILGATE COVER, REAR END PANEL, REAR SPARE TYRE PANEL, REAR FENDER RH, LHETC.	\$ 1,000.00	Poo	
5	TO REMOVE & REFIT REAR WINDSCREEN GLASS FOR ALL NECESSARY REPAIRS.	\$ 150.00	120	
6	TO REMOVE & REFIT INNER ITEM FOR NECESSARY BODY WORK. FIXING OR PANEL BEATING	\$ 80.00	60	
7	TO REMOVE & REFIT REAR TAILGATE COVER. REAR TAILGATE LOCK INNER & OUTTER, REAR TAILGATE COVER HANDLE, WIPER MOTOR, SWITCH, TRIM BOARD & ALL EMBLEMETC.	\$ 120.00	60	

TOTAL LABOUR & SPRAY PAINTING PRICES: \$ 2,790.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

VEHICLE NO: SKL9221B

## **ESTIMATE REPORT**

TOTAL LABOUR COST : \$ 2,790.00 TOTAL PARTS COST : \$ 4,964.06 TOTAL REPAIR COST: \$ 7,754.06

## **APPROVAL DETAILS**

EXCESS: No. OF DAY: 4

RE-SURVEY: The ship Affer ry-

PART BY PART OR LUMP-SUM:

DATE OF SURVEY : Mercu

SURVEY BY:

CONTACT NO:

FAX NO.:

**LUMP-SUM AMOUNT OR COST OF** 

NOTE: **REPAIR** WOULD BE REVISED IF

SUPPLEMENT REPAIR IS REQUIRED